

A.H.E.R.A.

Management Plan for Asbestos Containing Building Materials

West Linn High School
5464 West A Street
West Linn, OR 97068

TRE Project No. 1020-90

Conducted By:

Prepared by



ASBESTOS MANAGEMENT PLAN

FOR

**West Linn High School
5464 West "A" Street
West Linn, OR 97068**

ASBESTOS PROGRAM COORDINATOR:

**Tim Woodley
(503) 673-7041**

INSPECTION CONDUCTED BY:



P.O. BOX 216 Gladstone OR, 97027 Phone: (503) 557-2396 Fax: 557-3025

WEST LINN-WILSONVILLE SCHOOL DISTRICT

TABLE OF CONTENTS

1. **Introduction/LEA Designate & (Assurances)**
 - Overview of Asbestos
 - AHERA Regulations
2. **Summary of Asbestos Containing Building Materials (ACBM) in this facility**
 - AHERA General Data Sheet
 - Locations & Quantities of Asbestos Containing Building Materials
 - Asbestos Location Diagrams
 - Consultants Cost Estimates for Asbestos Removal
3. **Plan Distribution/Notification**
 - Annual (Employee) Notification Records
 - Annual (Parent/Legal Guardian/Occupant) Notification Records
4. **Notification & Training of Employees/Contractors/Short-Term Workers**
 - Contractor Notification Letter
 - Contractor Notification/Acknowledgment
 - Contractor Asbestos Awareness Training Records
5. **Training Records**
 - LEA Designate/Asbestos Awareness Training Records
 - Maintenance/Custodial Staff
 - Personnel Medical Records Respiratory Protection
6. **Additional Asbestos Material Assessment Reports**
 - Asbestos Sample/Material Location Diagram
 - Asbestos Sample Analysis Data
7. **Additional Asbestos Sample/Assessment Data**
8. **Periodic Surveillance Reports (6-month)**
9. **Three-year Reinspection Reports**
10. **Asbestos Removal Activity/Response Action Recordkeeping**
 - Operations & Maintenance (<3 sq. feet or 3 ln. feet)
 - Small Scale (>3 sq. feet or 3 ln. feet) (<40 ln. feet or 80 sq. feet)
 - Full Scale (>40 ln. feet or 80 sq. feet)
 - Flow Charts to Determine Adequate Response Actions
11. **Operations and Maintenance Plan**
12. **Regulatory Agency Correspondence/Overview of Requirements (EPA, DEQ, Oregon OSHA)**
13. **Certificates (Management Planner, Building Inspector, Project Designer, NVLAP) NIOSH 582, 7400 Method Certification**

INTRODUCTION

Each LEA must develop an asbestos management plan for school buildings under its authority. This plan is to be submitted to the state Governor (or designee), no later than October 12, 1988. LEA's are required to begin implementation of their management plan by July 9, 1989 and to complete in stages. A copy of the plan must be available in the school administrative offices for viewing by the public.

A management plan should be used as a guidance document for asbestos control. A brief description of the elements of the plan as required by AHERA follows. Other sections of the notebook provide detailed information on the various components of the plan.

Management plans should be considered working documents. They set forth a framework for short and long-term actions to be taken by the LEA to protect building occupants. They must be kept up to date (e.g., response actions, dates and results of surveillance).

This survey was performed using non-destructive sampling methods in order to maintain the integrity of occupied spaces. Any unknown or suspect materials revealed during renovation or demolition of the structure should be tested for asbestos content prior to their disturbance.

The management plan represents the combination of the Inspection Report with a game plan for responding to and maintaining the asbestos containing materials. It is a flexible document that you can easily update. It is designed on an AHERA format and currently exceeds state and federal requirements for managing asbestos materials in commercial properties.

The Management Plan is a document the Owner must continue to use and update. The notebook will be an aid for the following activities:

- Identifying and performing initial cleaning
- Scheduling response actions
- Training your personnel
- Maintaining the asbestos containing materials in place
- Learning to budget for asbestos activities
- Setting building asbestos policies
- Notifying affected parties
- Keeping records

Remember this plan is not an encyclopedia of all asbestos facts, nor a recitation of the many rules affecting asbestos, nor a substitute for training.

CONCLUSION

The management plan should provide elaboration on all aspects of the plan. For example, in selecting a response action, justification is necessary for the particular choice, rationale for its prioritization and explanation of the resources required to implement the response should appear in the plan.

LOCAL EDUCATION AGENCY (LEA) GENERAL RESPONSIBILITIES UNDER AHERA


Pursuant to Section 763.84 and Section 763.93 of the EPA Asbestos in Schools Regulation (40 CFR Part 763), each management plan must contain a true and correct statement, signed by the LEA designated person, that certifies that the general LEA responsibilities have been met. This form is provided to assist you in complying with this portion of AHERA.

LEA Name: West Linn / Wilsonville School District
LEA Address: Stafford Rd. West Linn, OR 97068
Designated Person Name: Tim Woodley
Designated Person Address: Stafford Rd. West Linn, OR 97068
Phone number: (503)638-9869

ASSURANCES

1. This AHERA management plan was developed and has been submitted pursuant to the Asbestos Hazard Emergency Response Act of 1986, Public law 99-519; and the United States Environmental Protection Agency Rule: Asbestos Containing Materials in Schools, 40 CFR Part 763; and the undersigned does hereby certify that the LEA has and will ensure the following:
2. The activities of any persons who perform inspections, reinspections, and periodic surveillance, develop and update management plans, and develop and implement response actions, including operations and maintenance, are carried out in accordance with Part 763.
- 3..All custodial and maintenance employees will be properly trained as required in Part 763 and all other applicable Federal and/or State regulations (e.g., the Occupational Safety and Health Administration Asbestos Standard for Construction, the EPA Worker Protection Rule, or applicable State regulations).
4. All workers and building occupants, or their legal guardians, are informed at least once each school year about inspections, response actions, post-response action activities, including periodic reinspection and surveillance activities, that are planned or in progress.
5. All short-term workers (e.g., telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACBM and suspected ACBM assumed to be ACM.
6. All warning labels are posted in accordance with Section 763.95.
7. All management plans are available for inspection and notification of such availability has been provided as specified in the management plan under Section 763.93(g).
8. The undersigned person designated by the LEA pursuant to Section 763.84(g) (1) has received adequate training as stipulated in Section 763.84(g) (2).
9. The LEA has and will consider whether any conflict of interest may arise from the interrelationship among accredited personnel and whether that should influence the selection of accredited personnel to perform activities under Part 763.

Signature



LEA Designated Person, pursuant to
40 CFR 763.93(i) and 763.84

Date:

11-1-99

INTRODUCTION

Each LEA must develop an Asbestos Management Plan for school buildings under its authority. This plan is to be submitted to the state Governor (or designee), no later than October 12, 1988. LEA's are required to begin implementation of their management plan by July 9, 1989 and to complete in stages. A copy of the plan must be available in the school administrative offices for viewing by the public.

A Management Plan should be used as a guidance document for asbestos control. A brief description of the elements of the plan as required by AHERA follows. Other sections of the notebook provide detailed information on the various components of the plan.

Management plans should be considered working documents. They set forth a framework for short and long-term actions to be taken by the LEA to protect building occupants. They must be kept up to date (e.g., response actions, dates and results of surveillance).

This survey was performed using non-destructive sampling methods in order to maintain the integrity of occupied spaces. Any unknown or suspect materials revealed during renovation or demolition of the structure should be tested for asbestos content prior to their disturbance.

The Management Plan represents the combination of the Inspection Report with a game plan for responding to and maintaining the asbestos containing materials. It is a flexible document that you can easily update. It is designed on an AHERA format and currently exceeds state and federal requirements for managing asbestos materials in commercial properties.

The Management Plan is a document the Owner must continue to use and update. The notebook will be an aid for the following activities:

- Identifying and performing initial cleaning
- Scheduling response actions
- Training your personnel
- Maintaining the asbestos containing materials in place
- Learning to budget for asbestos activities
- Setting building asbestos policies
- Notifying affected parties
- Keeping records

Remember this plan is not an encyclopedia of all asbestos facts, nor a recitation of the many rules affecting asbestos, nor a substitute for training.

CONCLUSION

The Management Plan should provide elaboration on all aspects of the plan. For example, in selecting a response action, justification is necessary for the particular choice, rationale for its prioritization and explanation of the resources required to implement the response should appear in the plan.

The Management Plan is viewed as a planning or working document. It not only sets out a course of action for the LEA, but it becomes documentary evidence of progress in implementing asbestos control options. Give the cost and financing information contained in the plan, it provides guidance on matters such as annual and long-term school budgeting and community tax and bond issues. In addition, the Management Plan will help school administrators identify potential funding sources to implement their asbestos control program.

LEA DESIGNATE

Tim Woodley
West Linn-Wilsonville School District 3Jt
22201 S.W. Stafford Road
Tualatin, OR 97068

The Local Education Agency Designate is required by the Final Rules to ensure the School's continuing compliance with the AHERA requirements. The LEA Designates specific requirements are described in 40 CFR Section 763.84 of the Final Rules.

SCHOOL ASBESTOS COORDINATOR

As is option, the School may appoint a school asbestos coordinator to ensure compliance within a specific school. The coordinator's responsibilities parallel those of the LEA Designate.

LEA DESIGNATE DOCUMENTATION

The school district must designate and train a person to ensure compliance with the requirements of Section 763.84 of the Final Rules. The responsibilities of the LEA Designate's signature and statement of acceptance appears in the last TAB of the Management Plan. If the school board or superintendent has formally assigned the LEA Designate with a letter, memorandum, or similar conveyance, a copy should be filed under this Tab.

The West Linn-Wilsonville School District's Superintendent Roger L. Woehl acknowledges the undersigned person to act as the LEA Designate throughout the West Linn-Wilsonville School District.

Signature: Roger L. Woehl

Date: 11/1/99

LEA DESIGNATE

Tim Woodley
West Linn-Wilsonville School District 3Jt
22210 S.W. Stafford Road
Tualatin, OR 97062
(503) 638-9869

LEA DESIGNATE TRAINING

Course Name: AHERA DP

TRAINING

Training Date: 10-14-99

Total hours: _____

Description: _____

LEA DESIGNATE RESPONSIBILITIES

Responsibilities are listed in the federal register included in this section.

Summary of Asbestos Containing Building Materials (ACBM) in this facility.

This section reflects requirements outlined in 40 CFR 763.85 (vi) (B) (c) (d) and (e)

The following subsections contain this required information:

- AHERA General Data Sheet
- Locations and quantities of Asbestos Containing Building Materials
- Asbestos location diagrams
- Consultants cost estimates for asbestos removal

SAMPLE/MATERIAL LOCATION DIAGRAMS

As part of the AHERA Asbestos Inspection the locations of samples collected are recorded on building diagrams. In addition to the sample locations, specific damage areas are recorded where found. The following pages provide the sample location diagrams for the School District. These drawings are organized in the same manner as the inspection/management plan data, i.e., campus one building one is first.

The title block contains the specific state, district, campus, and building or code with a 12 digit number. Next is the District Name, the Campus Name, and finally the Building Name. The next block provides the date the drawing was made, the street number and finally the drawing number.

Location of Caution Label: The AHERA regulations require the use of labels indicating the presence of Asbestos Containing Building Materials (ACBM). The label is to be placed on or near ACBM in routine maintenance areas in all school buildings. When this label is applied in the field the inspector identifies its' location on the sample location diagram. On the drawing, the label symbol contains information about its placement within the routine maintenance area so that it may be readily found by the LEA. The label states the following:

**CAUTION
ASBESTOS. HAZARDOUS.
DO NOT DISTURB
WITHOUT PROPER TRAINING
AND EQUIPMENT**

The presence of sample numbers, crosshatching and damage areas does not mean that all of the areas indicated contain asbestos. These location diagrams are a record of the field inspection only and are meant to show where samples were taken and what areas may be affected if asbestos is present. To determine which areas are affected, a review of the Inspection/Management Plan Data and the Petrographic Results contained in Sections 4 and 5 should be made. If desired, the location diagrams can be highlighted by the school district's asbestos coordinator to indicate the presence of asbestos containing material.

AHERA GENERAL DATA SHEET

SECTION 01314
CERTIFICATION OF NO HAZARDOUS MATERIAL


No final payment shall be made until the Contractor shall file with the Owner, prior to acceptance of the Work, a notarized Certification of Compliance in the following form:

"TO THE BEST OF MY KNOWLEDGE NO HAZARDOUS MATERIAL IS USED IN THE CONSTRUCTION OF THIS PROJECT. MATERIAL SAFETY DATA SHEETS WILL BE PROVIDED AS REQUESTED BY THE OWNER FOR ALL MATERIALS WHICH MAY BE QUESTIONED IN THE FUTURE."

In WITNESS WHEREOF, the undersigned has signed and sealed this instrument this 8th day of JANUARY, 2001.

Firm Name EMERICK CONSTRUCTION
Signature [Handwritten Signature]
Title PROJECT MANAGER

(Attest) [Handwritten Signature]
(SEAL IF CONTRACTOR IS A CORPORATION)



As determined necessary, evidence of compliance may be required to be submitted with and made a part of this Certificate.

END OF CERTIFICATION OF NO HAZARDOUS MATERIAL SECTION

ORIGINAL
Rcv'd 1-10-01

[Handwritten Signature]
A.H.E.R.A Designated Person
01-11-01



MODERN BUILDING SYSTEMS, INC.

"The Smart Choice..."

RECEIVED

NOV 18 1999

HEERY INTERNATIONAL, INC.

Date: November 16, 1999

West Linn S.D.
P.O. Box 35
West Linn, OR 97068

Attn: Cindy Hepting

Re: Modular Classroom Buildings SER# 9924-1A/B/C & SER# 9924-2A/B/C

MODERN BUILDING SYSTEMS, INC. certifies and warrants that no asbestos or asbestos based products are used in the manufacture of our buildings. Also, MODERN BUILDING SYSTEMS, INC. uses standard construction materials that are approved for their specific use and that to the best of our knowledge meet current law on the limits of formaldehyde for that material.

Sincerely,

Shelly Beyel
Sales/Leasing Coordinator

Darin Lee, 3-Rivers
AHERA Mgmt Plan Binder: WLMS site
District Admin

97659 v 001

AHERA GENERAL DATA SHEET

W. Linn HS. - Mo.
Name of School Building West Linn School District Clackamas
LEA (District) County
PO Box 100 West Linn 97068-0100
Address City Zip Code
(503)656-2618 Samuel Nutt (503)638-9869
Building Telephone Number District's Asbestos Program Manager Telephone Number
Public Private State

CONSTRUCTION DATA

Year Built: Before 1930 1930-44 1945-60 1961-75 After 1975 Actual 1924
Additions Dates: 24;27;55;61;62;63;66 Size (Sq. Ft. all floors) 192,654
Construction Type: Steel Wood Concrete Masonry Other
Roof Framing: Steel Wood Concrete
Heating System: Steam Hot Water Forced Air Electric Baseboard Heat Pump Other
Renovation: Yes No Year: 86,87

USE AND OCCUPANCY

Primary Use: School Athletic Facility Office Warehouse
Maintenance Building Other (describe) _____
No. of Occupants: Staff 105 Students 1131 Maint./Custodial Personnel 11

INSPECTOR*

Name Gary Adler

Business Hall-Kimbrell

80026 Exp. Date _____

MANAGEMENT PLANNER*

Name John Newlin

Business Hall-kimbrell

80046 Exp. Date _____

Course Provider Hall-Kimbrell

*Primary person if more than one person.

AHERA GENERAL DATA SHEET

<u>WLHS - Shop</u> Name of School Building	<u>West Linn School District</u> LEA (District)	<u>Clackamas</u> County
<u>PO Box 100</u> Address	<u>West Linn</u> City	<u>97068-0100</u> Zip Code
<u>(503) 656-2618</u> Building Telephone Number	<u>Samuel Nutt</u> District's Asbestos Program Manager	<u>(503) 638-9869</u> Telephone Number
Public <input checked="" type="checkbox"/>	Private <input type="checkbox"/>	State <input type="checkbox"/>

CONSTRUCTION DATA

Year Built: Before 1930 1930-44 1945-60 1961-75 After 1975 Actual 1961

Additions Dates: 1962 Size (Sq. Ft. all floors) 12,764

Construction Type: Steel Wood Concrete Masonry Other

Roof Framing: Steel Wood Concrete

Heating System: Steam Hot Water Forced Air Electric Baseboard Heat Pump Other

Renovation: Yes No Year: 1987

USE AND OCCUPANCY

Primary Use: School Athletic Facility Office Warehouse
Maintenance Building Other (describe) _____

No. of Occupants: Staff 4 Students 120 Maint./Custodial Personnel -0-

INSPECTOR*

Name Gary Adler
Business Hall-Kimbrell
80026 Exp. Date _____

MANAGEMENT PLANNER*

Name John Newlin
Business Hall-kimbrell
80046 Exp. Date _____

Course Provider Hall-Kimbrell

*Primary person if more than one person.

ASHERA GENERAL DATA SHEET

WLHS - Music BLDG
Name of School Building
West Linn School District
LEA (District)
Clackamas
County
PO Box 100
Address
West Linn
City
97068-0100
Zip Code
(503) 656-2618
Building Telephone Number
Samuel Nutt
District's Asbestos
Program Manager
(503) 638-9869
Telephone Number
Public Private State

CONSTRUCTION DATA

Year Built: Before 1930 1930-44 1945-60 1961-75 After 1975 Actual 1980
Additions Dates: N/A Size (Sq. Ft. all floors) 12,715
Construction Type: Steel Wood Concrete Masonry Other
Roof Framing: Steel Wood Concrete
Heating System: Steam Hot Water Forced Air Electric Baseboard Heat Pump Other
Renovation: Yes No Year: N/A

USE AND OCCUPANCY

Primary Use: School Athletic Facility Office Warehouse
Maintenance Building Other (describe) _____
No. of Occupants: Staff 5 Students 120 Maint./Custodial Personnel -0-

INSPECTOR*

Name Gary Adler
Business Hall-Kimbrell
80026 Exp. Date _____

MANAGEMENT PLANNER*

Name John Newlin
Business Hall-kimbrell
80046 Exp. Date _____

Course Provider Hall-Kimbrell

*Primary person if more than one person.

AHERA GENERAL DATA SHEET

WLHS - Press Box
Name of School Building West Linn School District Clackamas
LEA (District) County
PO Box 100 West Linn 97068-0100
Address City Zip Code
(503) 656-2618 Samuel Nutt (503) 638-9869
Building Telephone Number District's Asbestos Telephone Number
Program Manager
Public Private State

CONSTRUCTION DATA

Year Built: Before 1930 1930-44 1945-60 1961-75 After 1975 Actual 1986
Additions Dates: N/A Size (Sq. Ft. all floors) 578
Construction Type: Steel Wood Concrete Masonry Other
Roof Framing: Steel Wood Concrete
Heating System: Steam Hot Water Forced Air Electric Baseboard Heat Pump Other NONE
Renovation: Yes No Year: N/A

USE AND OCCUPANCY

Primary Use: School Athletic Facility Office Warehouse
Maintenance Building Other (describe) _____
No. of Occupants: Staff -0- Students -0- Maint./Custodial Personnel -0-

INSPECTOR*

Name Gary Adler

Business Hall-Kimbrell

80026 Exp. Date _____

Course Provider Hall-Kimbrell

*Primary person if more than one person.

MANAGEMENT PLANNER*

Name John Newlin

Business Hall-kimbrell

80046 Exp. Date _____

AHERA GENERAL DATA SHEET

WHS-69122P
Name of School Building West Linn School District Clackamas
LEA (District) County
PO Box 100 West Linn 97068-0100
Address City Zip Code
(503) 656-2618 Samuel Nutt (503) 638-9869
Building Telephone Number District's Asbestos Telephone Number
Program Manager
Public Private State

CONSTRUCTION DATA

Year Built: Before 1930 1930-44 1945-60 1961-75 After 1975 Actual 1987
Additions Dates: N/A Size (Sq. Ft. all floors) 960
Construction Type: Steel Wood Concrete Masonry Other
Roof Framing: Steel Wood Concrete
Heating System: Steam Hot Water Forced Air Electric Baseboard Heat Pump Other NONE
Renovation: Yes No Year: N/A

USE AND OCCUPANCY

Primary Use: School Athletic Facility Office Warehouse
Maintenance Building Other (describe) _____
No. of Occupants: Staff -0- Students -0- Maint./Custodial Personnel -0-

INSPECTOR*

Name Gary Adler

Business Hall-Kimbrell

80026 Exp. Date _____

Course Provider Hall-Kimbrell

*Primary person if more than one person.

MANAGEMENT PLANNER*

Name John Newlin

Business Hall-kimbrell

80046 Exp. Date _____

AHERA GENERAL DATA SHEET

WLHS - Concession
Name of School Building West Linn School District Clackamas
LEA (District) County
PO Box 100 West Linn 97068-0100
Address City Zip Code
(503)656-2618 Samuel Nutt (503)638-9869
Building Telephone Number District's Asbestos Program Manager Telephone Number
Public Private State

CONSTRUCTION DATA

Year Built: Before 1930 1930-44 1945-60 1961-75 After 1975 Actual 1987
Additions Dates: N/A Size (Sq. Ft. all floors) 178
Construction Type: Steel Wood Concrete Masonry Other
Roof Framing: Steel Wood Concrete
Heating System: Steam Hot Water Forced Air Electric Baseboard Heat Pump Other NONE
Renovation: Yes No Year: N/A

USE AND OCCUPANCY

Primary Use: School Athletic Facility Office Warehouse
Maintenance Building Other (describe) _____
No. of Occupants: Staff -0- Students -0- Maint./Custodial Personnel -0-

INSPECTOR*

Gary Adler
Name
Business Hall-Kimbrell
80026 Exp. Date _____

MANAGEMENT PLANNER*

John Newlin
Name
Business Hall-kimbrell
80046 Exp. Date _____

Course Provider Hall-Kimbrell

*Primary person if more than one person.

SUMMARY DATA SHEET

Facility Name and Address West Linn High School

Preparer Name and Phone No. Kathy Cameron (913) 865-9455 Date 4/27/89

AHERA Damage Category	Type of Asbestos-Containing Building Materials (ACBM)			
	Surfacing	Thermal System Insulation (TSI)		Miscellaneous
		Lineal Feet	Square Feet	
1. Damaged or significantly damaged TSI ACM	21531			
2. Damaged friable surfacing ACM				
3. Significantly damaged friable surfacing ACM				
4. Damaged or significantly damaged friable miscellaneous ACM				
5. ACBM with potential for damage		6092	2927	157055
6. ACBM with potential for significant damage				
7. Other friable ACBM, or friable suspected ACBM				
8. Nonfriable ACBM, or nonfriable suspected ACBM				
• Total ACBM (Total 1 through 8)	Ft ²	21531	2927	157055
	L.F.		6092	
Total Friable ACBM (Total 1 through 7)	Ft ²			
	L.F.			

**LOCATIONS &
QUANTITIES OF
ASBESTOS
CONTAINING BUILDING
MATERIALS**

Campus: 001 West Linn High School

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 217,700

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
Inspection Dates: 07/18/88 to 07/14/89

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 03 ***

SYSTEM: Low Pr. Steam

LOCATION:
All Floors in Building

TYPE OF MATERIAL: Pipe Covering

DAMAGE CATEGORY:	REASON for DAMAGE CATEGORY:	POTENTIAL FOR DISTURBANCE:	SAMPLE#	%ASB
ACBM with Potential for Damage	The material is observed to be in good condition.	Slight	64	55
			65	60
			66	60

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
150 Ft. 4 In. O.D.	\$1,338	\$837	\$2,175
965 Ft. 6 In. O.D.	\$12,526	\$7,826	\$20,352
1133 Ft. 8 In. O.D.	\$16,032	\$11,455	\$27,487
		AREA TOTAL	\$50,014

-----MANAGEMENT PLAN RECOMMENDATION-----

RECOMMENDED RESPONSE ACTION:
O&M Maintain/Monitor

PRIORITY:
3

PREVENTIVE MEASURES:
See Part I and O&M Code: OMA

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 04 ***

SYSTEM: Low Pr. Steam

LOCATION:
All Floors in Building

TYPE OF MATERIAL: MJP on Pipe Covering

DAMAGE CATEGORY:	REASON for DAMAGE CATEGORY:	POTENTIAL FOR DISTURBANCE:	SAMPLE#	%ASB
ACBM with Potential for Damage	The material is observed to be in good condition.	slight	67	40
			68	50
			69	60

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
Inspection Dates: 07/18/88 to 07/14/89

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 217,700

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
212 4 In. O. D.	\$5,955	\$3,309	\$9,264
180 6 In. O. D.	\$6,962	\$4,090	\$11,052
159 8 In. O. D.	\$7,653	\$4,500	\$12,153
		AREA TOTAL	\$32,469

-----MANAGEMENT PLAN RECOMMENDATION-----
 RECOMMENDED RESPONSE ACTION: O&M Maintain/Monitor
 PRIORITY: 3
 PREVENTIVE MEASURES: See Part I and O&M Code: OMA

LEA RESPONSE: ACTION ELECTION: Same as recommended

RESPONSE ACTION SCHEDULE	
START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

 * * * INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 05 * * *

SYSTEM: Dom. Hot Water LOCATION: All Floors in Building TYPE OF MATERIAL: Pipe Covering

DAMAGE CATEGORY: ACEM with Potential for Damage
 REASON for DAMAGE CATEGORY: The material is observed to be in good condition.
 POTENTIAL FOR DISTURBANCE: slight
 SAMPLE# %ASB
 70 45
 71 50
 72 50

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
1766 Ft. 4 In. O.D.	\$15,753	\$9,854	\$25,607
		AREA TOTAL	\$25,607

-----MANAGEMENT PLAN RECOMMENDATION-----
 RECOMMENDED RESPONSE ACTION: O&M Maintain/Monitor
 PRIORITY: 3
 PREVENTIVE MEASURES: See Part I and O&M Code: OMA

LEA RESPONSE: ACTION ELECTION: Same as recommended

RESPONSE ACTION SCHEDULE	
START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

Inspected By: Gary Adler
Certification #: HK30026 St: KS
State Cert #: St:
Gross Square Ft: 217,700

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
Inspection Dates: 07/18/88 to 07/14/89

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 06 ***

SYSTEM: Dom. Hot Water LOCATION: TYPE OF MATERIAL: MJP on Pipe Covering
All Floors in Building

DAMAGE CATEGORY:	REASON for DAMAGE CATEGORY:	POTENTIAL FOR DISTURBANCE:	SAMPLE#	%ASB
ACBM with Potential for Damage	The material is observed to be in good condition.	Slight	73	50
			74	50
			75	60

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
360 4 In. O. D.	\$10,112	\$5,620	\$15,732
		AREA TOTAL	\$15,732

-----MANAGEMENT PLAN RECOMMENDATION-----

RECOMMENDED RESPONSE ACTION: O&M Maintain/Monitor	PRIORITY: 3	PREVENTIVE MEASURES: See Part I and O&M Code: OMA
--	----------------	--

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE	
START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 07 ***

SYSTEM: Dom. Cold Water LOCATION: TYPE OF MATERIAL: Corrugated Pipe Covering
All Floors in Building

DAMAGE CATEGORY:	REASON for DAMAGE CATEGORY:	POTENTIAL FOR DISTURBANCE:	SAMPLE#	%ASB
ACBM with Potential for Damage	The material is observed to be in good condition.	Slight	76	30
			77	30
			78	30

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
Inspection Dates: 07/18/88 to 07/14/89

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 217,700

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
933 Ft. 4 In. O.D.	\$8,322	\$5,206	\$13,528
		AREA TOTAL	\$13,528

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION: O&M Maintain/Monitor
PRIORITY: 3
PREVENTIVE MEASURES: See Part I and O&M Code: OMA

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 08 ***

SYSTEM: Dom. Cold Water LOCATION: All Floors in Building TYPE OF MATERIAL: MJP on Corr. Pipe Cover

DAMAGE CATEGORY:	REASON for DAMAGE CATEGORY:	POTENTIAL FOR DISTURBANCE:	SAMPLE#	%ASB
ACBM with Potential for Damage	The material is observed to be in good condition.	Slight	79	50
			80	50
			81	50

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
202 4 In. O. D.	\$5,674	\$3,153	\$8,827
		AREA TOTAL	\$8,827

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION: O&M Maintain/Monitor
PRIORITY: 3
PREVENTIVE MEASURES: See Part I and O&M Code: OMA

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
Inspection Dates: 07/18/88 to 07/14/89

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 217,700

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 09 ***

SYSTEM: Ceiling Matl. LOCATION: All Floors in Building TYPE OF MATERIAL: Drop or Lay-in Panel

DAMAGE CATEGORY: N/A REASON for DAMAGE CATEGORY: N/A POTENTIAL FOR DISTURBANCE: N/A SAMPLE# 82 %ASB 0

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
64000 Square Feet			
AREA TOTAL			\$0

-----MANAGEMENT PLAN RECOMMENDATION-----
RECOMMENDED RESPONSE ACTION: N/A PRIORITY: 0 PREVENTIVE MEASURES: See Part I and O&M Code

LEA RESPONSE:
ACTION ELECTION:

RESPONSE ACTION SCHEDULE	
START DATE	COMPLETION DATE
N/A	N/A

COMMENTS:

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 10 *** Renovated 1966

SYSTEM: Ceiling Matl. LOCATION: First Floor TYPE OF MATERIAL: Acoustical Tile (1x1)

DAMAGE CATEGORY: N/A REASON for DAMAGE CATEGORY: N/A POTENTIAL FOR DISTURBANCE: N/A SAMPLE# 83 %ASB 0

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
Inspection Dates: 07/18/88 to 07/14/89

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 217,700

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
10000 Square Feet			
AREA TOTAL			\$0

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION:
N/A

PRIORITY:
0

PREVENTIVE MEASURES:
See Part I and O&M Code:

LEA RESPONSE:
ACTION ELECTION:

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
N/A	N/A

COMMENTS:

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 11 ***

SYSTEM: Surfacing Mat.

LOCATION:
First Floor

TYPE OF MATERIAL: Acoustical/Thermal Plaster

DAMAGE CATEGORY:
Damaged or significantly
damaged thermal system
insulating ACM.

REASON for DAMAGE CATEGORY:
The material has undergone a
noticeable degree of contact
damage.

POTENTIAL FOR DISTURBANCE:	SAMPLE#	%ASB
High	84	10
	85	15
	86	10
	87	10
	88	10
	89	25
	90	15
	91	15
	92	20
	93	15

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
Inspection Dates: 07/18/88 to 07/14/89

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 217,700

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
21531 Square Feet	\$371,625	\$57,488	\$429,113
AREA TOTAL			\$429,113

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION: Repair and O&M
PRIORITY: 1
PREVENTIVE MEASURES: See Part I and O&M Code: OMD

LEA RESPONSE:

RESPONSE ACTION SCHEDULE

ACTION ELECTION:
Same as recommended

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 97 ***

SYSTEM: Floor Matl. LOCATION: All Floors in Building TYPE OF MATERIAL: Vinyl Floor Tile

DAMAGE CATEGORY: ACBM with Potential for Damage
REASON for DAMAGE CATEGORY: The material is observed to be in good condition.
POTENTIAL FOR DISTURBANCE: Slight
SAMPLE# 47 %ASB 9

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
50000 Square Feet	\$168,500	\$128,000	\$296,500
AREA TOTAL			\$296,500

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION: O&M Maintain/Monitor
PRIORITY: 3
PREVENTIVE MEASURES: See Part I and O&M Code: OMI, OMZ

LEA RESPONSE:

RESPONSE ACTION SCHEDULE

ACTION ELECTION:
Same as recommended

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

02/16/90

ASHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
Inspection Dates: 07/18/88 to 07/14/89

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 217,700

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 98 ***

SYSTEM: Non-Friable LOCATION: TYPE OF MATERIAL: Transite Siding
All Floors in Building

DAMAGE CATEGORY: REASON for DAMAGE CATEGORY: POTENTIAL FOR DISTURBANCE: SAMPLE# %ASB
ACBM with Potential for Damage The material is observed to be in Slight Assumed
good condition.

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
400 Square Feet	\$2,860	\$2,044	\$4,904
		AREA TOTAL	\$4,904

-----MANAGEMENT PLAN RECOMMENDATION-----

RECOMMENDED RESPONSE ACTION: PRIORITY: PREVENTIVE MEASURES:
O&M Maintain/Monitor 3 See Part I and O&M Code: OMZ

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 99 ***

SYSTEM: Floor Matl. LOCATION: TYPE OF MATERIAL: Vinyl Floor Tile
All Floors in Building

DAMAGE CATEGORY: REASON for DAMAGE CATEGORY: POTENTIAL FOR DISTURBANCE: SAMPLE# %ASB
ACBM with Potential for Damage The material is observed to be in Slight 46 10
good condition.

02/16/90

ASHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 217,700

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
Inspection Dates: 07/18/88 to 07/14/89

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
86055 Square Feet	\$290,005	\$220,301	\$510,306
		AREA TOTAL	\$510,306

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION:
O&M Maintain/Monitor

PRIORITY:
3

PREVENTIVE MEASURES:
See Part I and O&M Code: OMI, OMZ

LEA RESPONSE:

ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

AHERA COMPLIANCE PROGRAM
 *** BOILER ROOM SUMMARY ***
 West Linn S.D. 3JT
 37-0050

CAMPUS : 001 - West Linn High School
 BUILDING : 001 - West Linn High Main Bldg.
 BOILER RM: 1

Inspected By: Gary Adler
 Certification #: HK80026 St: KS
 State Cert #: St:

BOILER

DAMAGE CATEGORY:
 ACM with Potential for Damage

REASON for DAMAGE CATEGORY:
 The material is observed to be in
 good condition.

POTENTIAL FOR DISTURBANCE:
 Slight

%ASB*	SYSTEM ID	LOCATION	MATERIAL DESCRIPTION	MATERIAL QUANTITY
50%	Mech. Insul.	N BOILER E SIDE	Boiler/Tank Insulation	600 Square Feet
50%	Mech. Insul.	N BOILER E SIDE	Boiler/Tank Insulation	
0%	Mech. Insul.	N BOILER E SIDE	Boiler/Tank Insulation	
40%	Mech. Insul.	S BOILER E SIDE	Boiler/Tank Insulation	600 Square Feet
45%	Mech. Insul.	S BOILER E SIDE	Boiler/Tank Insulation	
45%	Mech. Insul.	S BOILER E SIDE	Boiler/Tank Insulation	
40%	Mech. Insul.	DHW TANK E SIDE	Boiler/Tank Insulation	300 Square Feet
50%	Mech. Insul.	DHW TANK E SIDE	Boiler/Tank Insulation	
45%	Mech. Insul.	DHW TANK E SIDE	Boiler/Tank Insulation	
30%	Miscellaneous	GASKET ON B1 E SIDE	Gasket	4 Square Feet

---MANAGEMENT PLAN RECOMMENDATION---

RECOMMENDED RESPONSE ACTION:
 O&M Maintain/Monitor

PRIORITY:
 3

PREVENTIVE MEASURES:
 See Part I and O&M Code: OMZ

LEA RESPONSE:
 ACTION ELECTION:
 Same as recommended

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
Summer 1989	Ongoing

LEA COMMENT:

REMOVED
ALL BOILER RM. INSUL.

02/16/90

AHERA COMPLIANCE PROGRAM
*** BOILER ROOM SUMMARY ***
West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
BOILER RM: 1

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:

JOINTS

DAMAGE CATEGORY:
ACBM with Potential for Damage

REASON for DAMAGE CATEGORY:
The material is observed to be in
good condition.

POTENTIAL FOR DISTURBANCE:
Slight

SMP #ASB*	SYSTEM ID	LOCATION	MATERIAL DESCRIPTION	MATERIAL QUANTITY
50	45% Low Pr. Steam	BETWEEN BOILER 1&2 E SIDE	MJP on Pipe Covering	39 6 In. O. D.
50	45% Low Pr. Steam	BETWEEN BOILER 1&2 E SIDE	MJP on Pipe Covering	25 10 In. O. D.
50	45% Low Pr. Steam	BETWEEN BOILER 1&2 E SIDE	MJP on Pipe Covering	30 12 In. O. D.
50	45% Low Pr. Steam	BETWEEN BOILER 1&2 E SIDE	MJP on Pipe Covering	25 14 In. O.D.
52	25% Dom. Hot Water	BETWEEN BOILER 1&2 E SIDE	MJP on Corr. Pipe Cover	35 4 In. O. D.
52	25% Dom. Hot Water	BETWEEN BOILER 1&2 E SIDE	MJP on Corr. Pipe Cover	22 6 In. O. D.
54	0% Dom. Cold Water	BETWEEN BOILER 1&2 E SIDE	MJP on Corr. Pipe Cover	50 4 In. O. D.
54	0% Dom. Cold Water	BETWEEN BOILER 1&2 E SIDE	MJP on Corr. Pipe Cover	22 6 In. O. D.

---MANAGEMENT PLAN RECOMMENDATION---

RECOMMENDED RESPONSE ACTION:
O&M Maintain/Monitor

PRIORITY:
3

PREVENTIVE MEASURES:
See Part I and O&M Code: OMA

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENT:

02/16/90

AHERA COMPLIANCE PROGRAM
*** BOILER ROOM SUMMARY ***
West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
BOILER RM: 1

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:

PIPING

DAMAGE CATEGORY:
ACBM with Potential for Damage

REASON for DAMAGE CATEGORY:
The material is observed to be in
good condition.

POTENTIAL FOR DISTURBANCE:
Slight

SMP #ASB*	SYSTEM ID	LOCATION	MATERIAL DESCRIPTION	MATERIAL QUANTITY
49	45% Low Pr. Steam	BETWEEN BOILER 1&2 E SIDE	Pipe Covering	150 Ft. 6 In. O.D.
49	45% Low Pr. Steam	BETWEEN BOILER 1&2 E SIDE	Pipe Covering	100 Ft. 10 In. O.D.
49	45% Low Pr. Steam	BETWEEN BOILER 1&2 E SIDE	Pipe Covering	130 Ft. 12 In. O.D.
49	45% Low Pr. Steam	BETWEEN BOILER 1&2 E SIDE	Pipe Covering	50 Ft. 14 In. O.D.
51	6% Dom. Hot Water	BETWEEN BOILER 1&2 E SIDE	Corrugated Pipe Covering	110 Ft. 4 In. O.D.
51	6% Dom. Hot Water	BETWEEN BOILER 1&2 E SIDE	Corrugated Pipe Covering	75 Ft. 6 In. O.D.
53	6% Dom. Cold Water	BETWEEN BOILER 1&2 E SIDE	Corrugated Pipe Covering	150 Ft. 4 In. O.D.
53	6% Dom. Cold Water	BETWEEN BOILER 1&2 E SIDE	Corrugated Pipe Covering	75 Ft. 6 In. O.D.

-----MANAGEMENT PLAN RECOMMENDATION-----

RECOMMENDED RESPONSE ACTION:
O&M Maintain/Monitor

PRIORITY:
3

PREVENTIVE MEASURES:
See Part I and O&M Code: OMA

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENT:

	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
BOILER ROOM ESTIMATED COSTS	\$63,950	\$48,149	\$112,099

02/16/90

AHERA COMPLIANCE PROGRAM
*** BOILER ROOM SUMMARY ***
West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
BOILER RM: 2

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:

BOILER

DAMAGE CATEGORY:
ACBM with Potential for Damage

REASON for DAMAGE CATEGORY:
The material is observed to be in
good condition.

POTENTIAL FOR DISTURBANCE:
Slight

SMP %ASB*	SYSTEM ID	LOCATION	MATERIAL DESCRIPTION	MATERIAL QUANTITY
56	0% Mech. Insul.	DHW TANK E SIDE	Boiler/Tank Insulation	200 Square Feet
57	0% Mech. Insul.	DHW TANK E SIDE	Boiler/Tank Insulation	
58	0% Mech. Insul.	DHW TANK E SIDE	Boiler/Tank Insulation	
59	50% Mech. Insul.	DHW XCHANGE TANK S	Boiler/Tank Insulation	60 Square Feet
60	60% Mech. Insul.	DHW XCHANGE TANK S	Boiler/Tank Insulation	
61	50% Mech. Insul.	DHW XCHANGE TANK S	Boiler/Tank Insulation	

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION:
O&M Maintain/Monitor

PRIORITY:
3

PREVENTIVE MEASURES:
See Part I and O&M Code: OMB

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENT:

02/16/90

AHRA COMPLIANCE PROGRAM
*** BOILER ROOM SUMMARY ***
West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
BOILER RM: 2

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:

JOINTS

DAMAGE CATEGORY:
ACBM with Potential for Damage

REASON for DAMAGE CATEGORY:
The material is observed to be in good condition.

POTENTIAL FOR DISTURBANCE:
Slight

SMP %ASB*	SYSTEM ID	LOCATION	MATERIAL DESCRIPTION	MATERIAL QUANTITY
63	20% Dom. Hot Water	SW CORNER	MJP on Corr. Pipe Cover	30 4 In. O. D.
63	20% Dom. Hot Water	SW CORNER	MJP on Corr. Pipe Cover	25 6 In. O. D.
63	20% Dom. Hot Water	SW CORNER	MJP on Corr. Pipe Cover	19 8 In. O. D.

-----MANAGEMENT PLAN RECOMMENDATION-----
 RECOMMENDED RESPONSE ACTION: O&M Maintain/Monitor
 PRIORITY: 3
 PREVENTIVE MEASURES: See Part I and O&M Code: OMA

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE	
START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENT:

PIPING

DAMAGE CATEGORY:
ACBM with Potential for Damage

REASON for DAMAGE CATEGORY:
The material is observed to be in good condition.

POTENTIAL FOR DISTURBANCE:
Slight

SMP %ASB*	SYSTEM ID	LOCATION	MATERIAL DESCRIPTION	MATERIAL QUANTITY
62	35% Dom. Hot Water	SW CORNER	Corrugated Pipe Covering	175 Ft. 4 In. O.D.
62	35% Dom. Hot Water	SW CORNER	Corrugated Pipe Covering	65 Ft. 6 In. O.D.
62	35% Dom. Hot Water	SW CORNER	Corrugated Pipe Covering	65 Ft. 8 In. O.D.

-----MANAGEMENT PLAN RECOMMENDATION-----
 RECOMMENDED RESPONSE ACTION: O&M Maintain/Monitor
 PRIORITY: 3
 PREVENTIVE MEASURES: See Part I and O&M Code: OMA

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE	
START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENT:

AHERA COMPLIANCE PROGRAM
*** BOILER ROOM SUMMARY ***
West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 001 - West Linn High Main Bldg.
BOILER RM: 2

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:

	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
BOILER ROOM ESTIMATED COSTS	\$13,394	\$9,619	\$23,013

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

CAMPUS : 001 - West Linn High School
BUILDING : 002 - Shop
Inspection Dates: 07/08/88 to 07/14/89

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 12,764

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 01 ***

SYSTEM: Heating Water LOCATION: Ground Floor TYPE OF MATERIAL: MJP on Non-Suspect Pipe

DAMAGE CATEGORY:	REASON for DAMAGE CATEGORY:	POTENTIAL FOR DISTURBANCE:	SAMPLE#	%ASB
N/A	N/A	N/A	94	0
			95	0
			96	0

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
45 4 In. O. D.			
40 6 In. O. D.			
AREA TOTAL			\$0

-----MANAGEMENT PLAN RECOMMENDATION-----

RECOMMENDED RESPONSE ACTION:	PRIORITY:	PREVENTIVE MEASURES:
N/A	0	See Part I and O&M Code:

LEA RESPONSE:
ACTION ELECTION:

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
N/A	N/A

COMMENTS:

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 02 ***

SYSTEM: Dom. Hot Water LOCATION: Ground Floor TYPE OF MATERIAL: MJP on Non-Suspect Pipe

DAMAGE CATEGORY:	REASON for DAMAGE CATEGORY:	POTENTIAL FOR DISTURBANCE:	SAMPLE#	%ASB
N/A	N/A	N/A	97	0
			98	0
			99	0

ASHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 12,764

CAMPUS : 001 - West Linn High School
BUILDING : 002 - Shop
Inspection Dates: 07/08/88 to 04/24/89

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
50 4 In. O. D.			
AREA TOTAL			\$0

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION:
N/A

PRIORITY:
0

PREVENTIVE MEASURES:
See Part I and O&M Code:

LEA RESPONSE:
ACTION ELECTION:

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
N/A	N/A

LEA COMMENTS:

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 03 ***

SYSTEM: Dom. Cold Water

LOCATION:
Ground Floor

TYPE OF MATERIAL: MJP on Non-Suspect Pipe

DAMAGE CATEGORY:
N/A

REASON for DAMAGE CATEGORY:
N/A

POTENTIAL FOR DISTURBANCE:
N/A

SAMPLE#	%ASB
00	0
01	0
02	0

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
50 4 In. O. D.			
AREA TOTAL			\$0

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION:
N/A

PRIORITY:
0

PREVENTIVE MEASURES:
See Part I and O&M Code:

LEA RESPONSE:
ACTION ELECTION:

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
N/A	N/A

LEA COMMENTS:

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 12,764

CAMPUS : 001 - West Linn High School
BUILDING : 002 - Shop
Inspection Dates: 07/08/88 to 07/14/89

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 04 ***

SYSTEM: Ceiling Matl. LOCATION: Ground Floor TYPE OF MATERIAL: Acoustical Tile (1x1)

DAMAGE CATEGORY: N/A REASON for DAMAGE CATEGORY: N/A POTENTIAL FOR DISTURBANCE: N/A SAMPLE# 03 %ASB 0

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
200 Square Feet			
AREA TOTAL			\$0

-----MANAGEMENT PLAN RECOMMENDATION-----
RECOMMENDED RESPONSE ACTION: N/A PRIORITY: 0 PREVENTIVE MEASURES: See Part I and O&M Code:

LEA RESPONSE:
ACTION ELECTION:

RESPONSE ACTION SCHEDULE	
START DATE	COMPLETION DATE
N/A	N/A

COMMENTS:

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 05 ***

SYSTEM: Ceiling Matl. LOCATION: Ground Floor TYPE OF MATERIAL: Drop or Lay-in Panel

DAMAGE CATEGORY: N/A REASON for DAMAGE CATEGORY: N/A POTENTIAL FOR DISTURBANCE: N/A SAMPLE# 04 %ASB 0

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 12,764

CAMPUS : 001 - West Linn High School
BUILDING : 002 - Shop
Inspection Dates: 07/08/88 to 07/14/89

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
11200 Square Feet			
AREA TOTAL			\$0

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION:
N/A

PRIORITY:
0

PREVENTIVE MEASURES:
See Part I and O&M Code:

LEA RESPONSE:
ACTION ELECTION:

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
N/A	N/A

COMMENTS:

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 98 ***

SYSTEM: Non-Friable

LOCATION:
All Floors in Building

TYPE OF MATERIAL: Transite Siding

DAMAGE CATEGORY:
ACBM with Potential for Damage

REASON for DAMAGE CATEGORY:
The material is observed to be in
good condition.

POTENTIAL FOR DISTURBANCE:
Slight

SAMPLE# %ASB
Assumed

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
10 Square Feet	\$72	\$51	\$123
AREA TOTAL			\$123

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION:
O&M Maintain/Monitor

PRIORITY:
3

PREVENTIVE MEASURES:
See Part I and O&M Code: OMZ

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 12,764

CAMPUS : 001 - West Linn High School
BUILDING : 002 - Shop
Inspection Dates: 07/08/88 to 07/14/89

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 99 ***

SYSTEM: Floor Matl. LOCATION: All Floors in Building TYPE OF MATERIAL: Vinyl Floor Tile

DAMAGE CATEGORY: REASON for DAMAGE CATEGORY: POTENTIAL FOR DISTURBANCE: SAMPLE# %ASB
ACBM with Potential for Damage The material is observed to be in Slight 48 10
good condition.

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
11000 Square Feet	\$37,070	\$28,160	\$65,230
		AREA TOTAL	\$65,230

-MANAGEMENT PLAN RECOMMENDATION-

RECOMMENDED RESPONSE ACTION: O&M Maintain/Monitor
PRIORITY: 3
PREVENTIVE MEASURES: See Part I and O&M Code: OMI, OMZ

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE

START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

02/16/90

AHERA COMPLIANCE PROGRAM

West Linn S.D. 3JT
37-0050

Inspected By: Gary Adler
Certification #: HK80026 St: KS
State Cert #: St:
Gross Square Ft: 12,715

CAMPUS : 001 - West Linn High School
BUILDING : 003 - Music Bldg.
Inspection Dates: 07/18/88 to 07/14/89

*** INSPECTION RESULTS UNIFIED SAMPLING AREA NUMBER - 99 ***

SYSTEM: Floor Matl. LOCATION: All Floors in Building TYPE OF MATERIAL: Vinyl Floor Tile

DAMAGE CATEGORY: REASON for DAMAGE CATEGORY: POTENTIAL FOR DISTURBANCE: SAMPLE# %ASB
ACBM with Potential for Damage The material is observed to be in Slight 49 6
good condition.

MATERIAL QUANTITIES	REMOVAL COST	REPLACEMENT COSTS	TOTAL COSTS
10000 Square Feet	\$33,700	\$25,600	\$59,300
		AREA TOTAL	\$59,300

-----MANAGEMENT PLAN RECOMMENDATION-----
RECOMMENDED RESPONSE ACTION: PRIORITY: PREVENTIVE MEASURES:
O&M Maintain/Monitor 3 See Part I and O&M Code: OMI, OMZ

LEA RESPONSE:
ACTION ELECTION:
Same as recommended

RESPONSE ACTION SCHEDULE	
START DATE	COMPLETION DATE
Summer 1989	Ongoing

COMMENTS:

ASBESTOS LOCATION DIAGRAMS

SAMPLE / MATERIAL LOCATION DIAGRAMS

As part of the AHERA Asbestos Inspection the locations of samples collected are recorded on building diagrams. In addition to the sample locations, specific damage areas are recorded where found. The following pages provide the sample location diagrams for the School District. These drawings are organized in the same manner as the inspection/management plan data, i.e. campus one building one is first.

The title block contains the specific state, district, campus, and building or code with a 12 digit number. Next is the District Name, the Campus Name, and finally the Building Name. The next block provides the date the drawing was made, the street number, and finally the H-K drawing number.

The drawing uses several symbols and cross-hatching patterns to illustrate the key elements of the survey information.

SAMPLE LOCATION: The specific locations of samples are found on a point on the drawing leading to a symbol indicating the sample number and the Bulk Sample (BS) Code, which represents the type of material sampled. The Bulk Sample Code descriptions used are as follows:

BS CODE	DESCRIPTION	BS CODE	DESCRIPTION
0	Unknown	26	Transite Pipe
1	Acoustical Plaster	27	Transite Hood
2	Acoustical/Thermal Insul	28	Asbestos Pads
3	Hardwall/Ceiling Plaster	29	Asbestos Glove
4	Vinyl Floor Tile	30	Asbestos Rope
5	Pipe Covering	31	Raw Asbestos
6	Corrugated Pipe Covering	32	Electrical Wiring
7	Wrapped Paper Pipe Cover	33	Fire Hose
8	Boiler/Tank Insulation	34	Fire Door
9	Breeching/Exhaust Packing	35	Fire Suit
10	Woven Paper/Tape	36	Fire Brick
11	Drop or Lay-in Panel	37	Lab Counter Top
12	Acoustical Tile (1x1)	38	Fiber Frack Kiln
13	Fire or Stage Curtain	39	Tongs
14	MJP on Non-Suspect Pipe	40	Poured in Insulation
15	MJP on Pipe Covering	41	Contaminated Soil
16	MJP on Corr. Pipe Cover	42	Tectum
17	MJP on Wrapped Pipe Cover	43	Floor Underlayment
18	Fireproofing	44	Hard Grout
19	Vibration Joint Cloth	45	Mortar
20	Interior Duct Insulation	46	Blown or Scratch Coat
21	Exterior Duct Insulation	47	Oven/Autoclave Lining
22	Blown-in Insulation	48	Brake Lining
23	Stored Insulation	49	Theatre Curtain
24	Debris	50	Transite Siding
25	Gasket	99	Other

DAMAGE AREAS: When the inspector encounters a section of material in a Unified Sampling Area (USA) which contains localized damage in worse condition than the remainder of the same material contained in this USA, a Damage Area indicator is placed on the drawing. This symbol contains specific information about the damaged area.

Type of Material - The BS Code of the material is indicated so that the type of material can be determined. See the previous section for the listing of the BS codes used.

Quantity - The quantity of material which was found to be damaged is also indicated.

Location - The location of the localized damage is indicated in the symbol. This provides assistance in identifying where the damage can be found.

Response Action - This is the code for the recommended AHERA response action. The following codes are used:

1. Isolate Area Immediately
2. Gross Removal
3. Glove Bag Removal
4. Encapsulation
5. Enclosure
6. Repair and O&M
7. O&M and Monitor

CROSSHATCHING: Crosshatching patterns are used to detail the location of ceiling and floor material suspected of containing asbestos. There are three patterns used:

Floor Tile - This pattern is used to indicate floor tile and sheet flooring material suspected of containing asbestos.

Drop / Lay-in, Acoustical - This pattern is used to indicate the locations of a variety of ceiling tiles including, but not limited, to 1' x 1' and 2' x 4' lay-in panels.

Spray / Trowel Applied Materials - This pattern is used to indicate the presence of spray and trowel applied materials such as fireproofing and acoustical plaster.

LOCATION of CAUTION LABEL: The AHERA regulations require the use of labels indicating the presence of Asbestos Containing Building Material (ACBM). The label is to be placed on or near ACBM in routine maintenance areas in all school buildings. When this label is applied in the field the inspector identifies its location on the sample location diagram. On the drawing, the label symbol contains information about its placement within the routine maintenance area so that it may be readily found by the LEA. The label states the following.

CAUTION
ASBESTOS. HAZARDOUS.
DO NOT DISTURB
WITHOUT PROPER TRAINING
AND EQUIPMENT

The presence of sample numbers, crosshatching, and damage areas does not mean that all of the areas indicated contain asbestos. These location diagrams are a record of the field inspection only and are meant to show where samples were taken and what areas may be affected if asbestos is present. To determine which areas are affected, a review of the Inspection / Management Plan Data and the Petrographic Results contained in Sections 4 and 5 should be made. If desired, the location diagrams can be highlighted by the school district's asbestos coordinator to indicate the presence of asbestos containing material.

PSI/Hall-Kimbrell Environmental Services, Inc. Asbestos Petrographic Analysis

CLIENT: WEST LINN SCHOOL DISTRICT

CAMPUS NAME & NUMBER: WEST LINN HIGH SCHOOL (001)

PROJECT #: 572-29-291

BUILDING NAME & NUMBER: SHOP (002)

LOCATION	MATERIAL	SAMPLE NUMBER	CONS	HOMOG	COLOR	TOT ASB	ACT/					WOOL	CEL	MICA	PER	BIND	OTHER 1	OTHER 2
							CHRY	AMO	CRO	ANT	TRE							
Shop Bldg/701	DROP OR LAY-IN PANEL	119044	Y	Y	G	0	0	0	0	0	0	20	40	0	30	10	0	0
Shop Bldg/702	DROP OR LAY-IN PANEL	119045	Y	Y	G	0	0	0	0	0	0	20	40	0	30	10	0	0
Shop Bldg/705	DROP OR LAY-IN PANEL	119046	Y	Y	G	0	0	0	0	0	0	20	40	0	30	10	0	0
Shop Bldg/Rest Room	DROP OR LAY-IN PANEL	119047	Y	Y	G	0	0	0	0	0	0	30	40	0	20	10	0	0
Shop Bldg/Rest Room	DROP OR LAY-IN PANEL	119048	Y	Y	G	0	0	0	0	0	0	30	40	0	20	10	0	0
Shop Bldg/Hall	DROP OR LAY-IN PANEL	119049	Y	Y	G	0	0	0	0	0	0	30	40	0	20	10	0	0
Shop Bldg/704	ACOUSTICAL TILE	119050	Y	Y	G	0	0	0	0	0	0	30	40	0	20	10	0	0
Shop Bldg/704	ACOUSTICAL TILE	119051	Y	Y	G	0	0	0	0	0	0	30	40	0	20	10	0	0
Shop Bldg/704	ACOUSTICAL TILE	119052	Y	Y	G	0	0	0	0	0	0	30	40	0	20	10	0	0
Shop Bldg/Rest Room	LINOLEUM	119053	Y	Y	T	0	0	0	0	0	0	0	60	0	0	30	GM 10	0
Shop Bldg/Rest Room	LINOLEUM	119054	Y	Y	T	0	0	0	0	0	0	0	60	0	0	30	GM 10	0
Shop Bldg/Rest Room	LINOLEUM	119055	Y	Y	T	0	0	0	0	0	0	0	60	0	0	30	GM 10	0
Shop Bldg	VINYL FLOOR TILE	119056	N	Y	W	0	0	0	0	0	0	0	0	0	0	30	CA 70	0
Shop Bldg	VINYL FLOOR TILE	119057	Y	Y	G	0	0	0	0	0	0	0	0	0	0	30	CA 70	0
Shop Bldg	VINYL FLOOR TILE	119058	Y	Y	G	0	0	0	0	0	0	0	0	0	0	30	CA 70	0
Shop Bldg	MASTIC	119059	N	Y	K	0	0	0	0	0	0	0	40	0	0	0	GM 10	TA 50
Shop Bldg	MASTIC	119060	N	Y	K	0	0	0	0	0	0	0	30	0	0	0	GM 20	TA 50
Shop Bldg	MASTIC	119061	N	Y	K	0	0	0	0	0	0	0	10	0	0	0	GM 20	TA 70
Shop Bldg	VINYL FLOOR TILE	119062	Y	Y	E	0	0	0	0	0	0	0	0	0	0	30	CA 70	0
Shop Bldg	VINYL FLOOR TILE	119063	Y	Y	E	0	0	0	0	0	0	0	0	0	0	30	CA 70	0
Shop Bldg	VINYL FLOOR TILE	119064	Y	Y	E	0	0	0	0	0	0	0	0	0	0	30	CA 70	0
Shop Bldg/704	VINYL FLOOR TILE	119065	Y	Y	B	0	0	0	0	0	0	0	0	0	0	30	CA 70	0
Shop Bldg/704	VINYL FLOOR TILE	119066	Y	Y	B	0	0	0	0	0	0	0	0	0	0	30	CA 70	0
Shop Bldg/704	VINYL FLOOR TILE	119067	Y	Y	B	0	0	0	0	0	0	0	0	0	0	30	CA 70	0
Shop Bldg/704	MASTIC	119068	Y	Y	K	10	10	0	0	0	0	0	40	0	0	0	TA 50	0
Shop Bldg/Hall	VINYL FLOOR TILE	119071	Y	Y	G	10	10	0	0	0	0	0	0	0	0	25	CA 65	0
Shop Bldg/Hall	MASTIC	119074	Y	Y	K	30	30	0	0	0	0	0	10	0	0	0	GM 10	TA 50

PSI/Hall-Kimbrell Environmental Service, Inc. Asbestos Petrographic Analysis

CLIENT: WEST LINN SCHOOL DISTRICT

CAMPUS NAME & NUMBER: WEST LINN HIGH SCHOOL (001)

PROJECT #: 572-29-291

BUILDING NAME & NUMBER: MUSIC BUILDING (003)

LOCATION	MATERIAL	SAMPLE NUMBER	CONS	HOMOG	COLOR	TOT ASB	ACT/					WOOL	CEL	MICA	PER	BIND	OTHER 1	OTHER 2
							CHRY	AMO	CRO	ANT	TRE							
Music Bldg/Hall	VINYL FLOOR TILE	119077	Y	Y	G	1	1	0	0	0	0	0	0	0	0	29	CA 70	0
Music Bldg/Hall	MASTIC	119080	Y	Y	K	20	20	0	0	0	0	0	5	0	0	0	GM 15	TA 60
Music Bldg/Rest Rooms	ACOUSTICAL TILE	119083	Y	Y	G	0	0	0	0	0	0	40	50	0	0	10	0	0
Music Bldg/Rest Rooms	ACOUSTICAL TILE	119084	Y	Y	G	0	0	0	0	0	0	40	50	0	0	10	0	0
Music Bldg/Rest Rooms	ACOUSTICAL TILE	119085	Y	Y	G	0	0	0	0	0	0	40	50	0	0	10	0	0

CAUTION
BOILER ROOM
ENTRANCE



Location
of Caution
Label

BS01
00-02


Sample
Location

Bulk Sample
Description


Sample
or
Sample Range




Vinyl
Floor Tile










Drop,
Lay In,
Accoustical











Spray
Applied
Material

























LEGEND:  VINYL FLOOR TILE  DROP, LAY IN, ACCOUSTICAL  SPRAY/TROWEL APPLIED MATERIAL	 CAUTION BOILER ROOM ENTRANCE LOCATION OF CAUTION LABEL	 BS01 00-02 SAMPLE LOCATION	 BSCODE QUANTITY LOCATION DAMAGE AREA	HALL-FIDORELL ENVIRONMENTAL SERVICES 4840 WEST FIFTEENTH STREET LAWRENCE, KANSAS 66044 DATE 10/03/88 001001A	AHERA COMPLIANCE PROGRAM 37-0050-001-001 WEST LINN SCHOOL DISTRICT WEST LINN HIGH SCHOOL BOILER ROOM
	RESPONSE CODE				




LEGEND:  VINYL FLOOR TILE  DROP, LAY IN, ACCOUSTICAL  SPRAY/TROWEL APPLIED MATERIAL	 CAUTION BOILER ROOM ENTRANCE LOCATION OF CAUTION LABEL	 BS01 00-02 SAMPLE LOCATION	 BS08 56 DAMAGE AREA	 RESPONSE CODE	HALL-TOWELL <small>ENGINEERS, ARCHITECTS</small> 4840 WEST FIFTEENTH STREET LAWRENCE, KANSAS 66044 DATE 10/03/88	AHERA COMPLIANCE PROGRAM 37-0050-001-001 WEST LINN SCHOOL DISTRICT WEST LINN HIGH SCHOOL BOILER ROOM #2
	(This row is empty in the original image)					










LEGEND:  VINYL FLOOR TILE  DROP, LAY IN, ACCOUSTICAL  SPRAY/TROWEL APPLIED MATERIAL	 LOCATION OF CAUTION LABEL	 SAMPLE LOCATION	 DAMAGE AREA <small>RESPONSE CODE</small>	HALL TIMBRELL ENVIRONMENTAL SERVICES 4840 WEST FIFTEENTH STREET LAWRENCE, KANSAS 66044 DATE 10/03/88 001001C	AHERA COMPLIANCE PROGRAM 37-0050-001-001 WEST LINN SCHOOL DISTRICT WEST LINN HIGH SCHOOL MAIN FLOOR/BLDG B										
															



BS11
82



LEGEND:  VINYL FLOOR TILE  DROP. LAY IN. ACCOUSTICAL  SPRAY/TROWEL APPLIED MATERIAL	 CAUTION BOILER ROOM ENTRANCE LOCATION OF CAUTION LABEL  BS01 00-02 SAMPLE LOCATION  BSCODE QUANTITY LOCATION DAMAGE AREA <small>RESPONSE CODE</small>	HALL-KIMMEL <small>MEMORIAL SERVICE</small> 4840 WEST FIFTEENTH STREET LAWRENCE, KANSAS 66044	AHERA COMPLIANCE PROGRAM 37-0050-001-001 WEST LINN SCHOOL DISTRICT WEST LINN HIGH SCHOOL 1ST FLOOR/2ND FLOOR BLDG. A
		DATE 10/03/88 0010010	




BS14
94-96

BS14
00-02
BS14
97-99

BS11
04

BS12
03

BS04
4B



LEGEND:



VINYL
FLOOR
TILE



DROP,
LAY IN,
ACCOUSTICAL



SPRAY/TROWEL
APPLIED
MATERIAL

CAUTION
BOILER ROOM
ENTRANCE

LOCATION
OF CAUTION
LABEL

BS01
00-02

SAMPLE
LOCATION

BSCODE QUANTITY
LOCATION

DAMAGE
AREA

RESPONSE
CODE


HALL-KIMBELL ENVIRONMENTAL SERVICES

4840 WEST FIFTEENTH STREET
LAWRENCE, KANSAS 66044

DATE 001002
10/03/88







AHERA
COMPLIANCE PROGRAM


37-0050-001-002
WEST LINN SCHOOL DISTRICT
WEST LINN HIGH SCHOOL
WOOD SHOP



BS04
49






LEGEND:  VINYL FLOOR TILE  DROP, LAY IN, ACCOUSTICAL  SPRAY/TROWEL APPLIED MATERIAL	 LOCATION OF CAUTION LABEL  SAMPLE LOCATION  DAMAGE AREA <small>RESPONSE CODE</small>	HALL-TIMBELL MECHANICAL SERVICES 4840 WEST FIFTEENTH STREET LAWRENCE, KANSAS 66044	AHRA COMPLIANCE PROGRAM 37-0050-001-003 WEST LINN SCHOOL DISTRICT WOODSHOP MUSIC BLDG.
		DATE 10/03/88 001003	




MAIN FLOOR

NOT TO SCALE

LEGEND

-  POSITIVE FLOOR TILE ONLY
-  POSITIVE FLOOR TILE AND MASTIC
-  POSITIVE MASTIC ONLY



DESIGNED BY: S. BETTELYOUN
DRAWN BY: J. JACKMAN
CHECKED BY: P. QUINN
DATE: 01-07-93

 Professional Service Industries, Inc. 4621 S.W. Kelly Avenue Portland, Oregon 97201	PROJECT NO. 572-29-291
	SHEET NO. 291-24
AHERA INSPECTION WEST LINN SCHOOL DISTRICT WEST LINN HIGH SCHOOL - SHOP BLDG MAIN FLOOR	

C	Homogeneous Area	Condition			%Dam	Quantity	S/L	Response Action				Sample Data			Cost Estimates	
		SD	D	PD				OM	REP	REM	CL	Amo	Chry	Other	Repair	Removal
T	STEAM-PIPING		X	X	<5	2248	LF	X	X							
T	STEAM-MJP			X		551	SF	X								
T	DHW-PIPING			X		1766	LF	X								
T	DHW-MJP			X		360	SF	X								
T	DCW-PIPING		X	X	<5	933	LF	X	X							
T	DCW-MJP			X		202	SF	X								
S	ACOUST.PLASTER	X	X		35	21531	SF	X	X	X						
M	FLOOR TILE			X		50000	SF	X								
CA	TRANSITE SIDING			X		400	SF	X								
M	FLOOR TILE			X		86055	SF	X								
T	BR#1-BOILER		X	X	<5	1504	SF	X	X							
T	BR-MJP		X	X	<5	248	SF	X	X							
T	BR-PIPING		X	X	<5	840	LF	X	X							
T	BR-#2-DH20 TANK			X		60	SF	X								
T	BR-MJP			X		74	SF	X								
T	BR-PIPING			X		305	LF	X								
Codes:																
T - Thermal																
S - Surfacing																
M - Misc																
CA - Transite																


C	Homogeneous Area	Condition			%ACM	Quantity	S/L	Response Action				Sample Data			Cost Estimates	
		SD	D	PD				OM	REP	REM	CL	Amo	Chry	Other	Repair	Removal
CA	TRANSITE SIDING			X		10	SF	X								
M	FLOOR TILE			X		1100	SF	X								
Codes:																
T - Thermal																
S - Surfacing																
M - Misc																
CA - Transite																

POS VINYL FLOOR TILE
119077

POS MASTIC
119080




CEILING PANEL
119083-84 NEG

CEILING PANEL
119085 NEG



MAIN FLOOR
NOT TO SCALE

LEGEND

-  POSITIVE FLOOR TILE ONLY
-  POSITIVE FLOOR TILE AND MASTIC
-  POSITIVE MASTIC ONLY



DRYWALL
123456-78

BULK SAMPLE TYPE

SAMPLE IDENTIFICATION NUMBER

DESIGNED BY:
S. BETTELYOUN

DRAWN BY:
J. JACKMAN

CHECKED BY:
P. QUINN

DATE:
01-07-93

PSI Professional Service Industries, Inc.
4621 S.W. Kelly Avenue
Portland, Oregon 97201

PROJECT NO.
572-29-291

SHEET NO.
291-23

AMERA INSPECTION
WEST LINN SCHOOL DISTRICT
WEST LINN HIGH SCHOOL - MUSIC BLDG
MAIN FLOOR

**CONSULTANTS COST
ESTIMATES FOR
ASBESTOS REMOVAL**

DISTRICT COST SUMMARY

PROJECT NUMBER: 37-0050
 DISTRICT NAME: West Linn S.D. 3JT

	REMOVAL COST	REINSULATION COST	COMBINED COST
CAMPUS: (001) West Linn High School			
BUILDING: (001) West Linn High Main Bldg.	\$1,000,662	\$521,450	\$1,522,112
BUILDING: (002) Shop	\$37,142	\$28,211	\$65,353
BUILDING: (003) Music Bldg.	\$33,700	\$25,600	\$59,300
BUILDING: (004) Press Box	\$0	\$0	\$0
BUILDING: (005) Garage	\$0	\$0	\$0
BUILDING: (006) Concessions	\$0	\$0	\$0
CAMPUS TOTALS	\$1,071,504	\$575,261	\$1,646,765
CAMPUS: (002) Bolton Middle School			
BUILDING: (001) Bolton Middle School Main	\$210,024	\$155,749	\$365,773
BUILDING: (002) Play Shed	\$0	\$0	\$0
CAMPUS TOTALS	\$210,024	\$155,749	\$365,773
CAMPUS: (003) Cedaroak Park Drive			
BUILDING: (001) Cedaroak Park Main Bldg	\$136,022	\$94,263	\$230,285
BUILDING: (002) Cedaroak Park 4-9	\$261,423	\$66,275	\$327,698
BUILDING: (003) Cedaroak Park 1-3	\$174,282	\$44,183	\$218,465
BUILDING: (004) Cedaroak Park 12-16	\$30,209	\$22,948	\$53,157
BUILDING: (005) Cedaroak Park 17-22	\$29,872	\$22,692	\$52,564
CAMPUS TOTALS	\$631,808	\$250,361	\$882,169
CAMPUS: (004) Stafford Primary School			
BUILDING: (001) Stafford Primary Main Bldg	\$141,357	\$103,448	\$244,805
BUILDING: (002) Trailer 1	\$0	\$0	\$0
BUILDING: (003) Trailer 2	\$0	\$0	\$0
BUILDING: (004) Play Shed	\$0	\$0	\$0
BUILDING: (005) Maint Building	\$0	\$0	\$0
CAMPUS TOTALS	\$141,357	\$103,448	\$244,805
CAMPUS: (005) Sunset Primary School			
BUILDING: (001) Sunset Primary Main Bldg	\$365,187	\$198,836	\$564,023
CAMPUS TOTALS	\$365,187	\$198,836	\$564,023
CAMPUS: (006) Williamette			
BUILDING: (001) Williamette Main Bldg	\$376,182	\$176,628	\$552,810
CAMPUS TOTALS	\$376,182	\$176,628	\$552,810
CAMPUS: (007) Wilsonville Primary School			
BUILDING: (001) Wilsonville Primary Main B	\$16,507	\$11,747	\$28,254
BUILDING: (002) Modular #1	\$0	\$0	\$0
BUILDING: (003) Modular #2	\$337	\$256	\$593
BUILDING: (004) Maint Building	\$0	\$0	\$0
BUILDING: (005) Library	\$10,713	\$2,138	\$12,851
CAMPUS TOTALS	\$27,557	\$14,141	\$41,698
CAMPUS: (008) Inza R. Wood Middle School			
BUILDING: (001) Inza R. Wood Main Bldg	\$71,393	\$54,220	\$125,613
BUILDING: (002) Maint Building	\$0	\$0	\$0
CAMPUS TOTALS	\$71,393	\$54,220	\$125,613
CAMPUS: (009) Administration Building			
BUILDING: (001) Administration Building	\$2,962	\$2,274	\$5,236

NOTE: Please see the 'Cost Estimates' section of Part I for a full explanation of the cost estimates presented here

DISTRICT COST SUMMARY

PROJECT NUMBER: 37-0050

DISTRICT NAME: West Linn S.D. 3JT

	REMOVAL COST	REINSULATION COST	COMBINED COST
CAMPUS TOTALS	\$2,962	\$2,274	\$5,236
DISTRICT TOTALS	\$2,897,974	\$1,530,918	\$4,428,892

NOTE: Please see the 'Cost Estimates' section of Part I for a full explanation of the cost estimates presented here

PLAN DISTRIBUTION/NOTIFICATION

This section reflects requirements outlined in 40 CFR 763.84 & 763.93 (10)

The following subsections contain this required information:

- Annual (employee) notification records.
- Annual (parent/legal guardian/occupant/employee) notification records

ACTION: You must send an annual notification to parent, teacher, and employee organization.

Short-term workers must be informed as to the location of ASBM in the school building.

FORMS: N/A

PLAN DISTRIBUTION/NOTIFICATION

AHERA requires that the LEA notify all building occupants, workers, contractors, and parents or legal guardians of school children. There are three key elements to the Notification program and they are Initial Notification, Annual Notification must include a discussion of:

- Inspections
- Re-inspections
- Surveillance
- Response actions
- Post-response action activity
- Availability of management plan

The LEA designate can realize benefits from the notification program because informed occupants are less likely to disturb the material and will report problem situations.

Contract workers (short-term) who will come in contact with ACBM during their work must be informed of the presence of ACBM. In addition, under various right-to-know laws, all workers must be informed of the potential for contact with hazardous materials such as asbestos.

There are three key areas of notification:

INITIAL NOTIFICATION OF THE MANAGEMENT PLAN AVAILABILITY

At the implementation of the Management Plan, notification to parent, teacher and employee organization of the availability of the plan is to be enacted. Enclosed is a list of steps that are to be taken to provide adequate notifications.

ANNUAL NOTIFICATION

On an annual basis, the parent, teacher and employee organization shall receive notification reiterating the availability of the plan and other asbestos activities that will occur or have occurred. The annual notification is included in the steps to be taken.

NOTIFICATION OF THE AVAILABILITY OF THE MANAGEMENT PLAN

The Initial and Annual Notification should follow these procedural steps:

- Step 1: Notify in writing the president of the parent, teacher and employee organization about the availability of the management plan. This is to be done when the plan is submitted to Governor's designate (October 1988).
- Step 2: If in the event there are no organizations for either parent, teachers or employees, other logical information devices will be used. A newspaper notice is an acceptable media to comply to the AHERA rules.
- Step 3: The notification will explain the location and availability of the management plan, at no cost to review and how to receive a copy (i.e., \$.10 per page black & white or \$50 per copy). A summary of each school inspection report may be included in the letter initially and annually if desired.
- Step 4: The notification will include all response actions scheduled, all response actions previously undertaken in the past calendar year, notice of inspections, periodic surveillance and other pertinent asbestos management activities that are planned or in progress.
- Step 5: Recordkeeping: A dated copy of each notification is to be kept. In addition, a signed receipt from a certified letter should be kept (optional). Keep all records under TAB 13.

**ANNUAL (EMPLOYEE)
NOTIFICATION
RECORDS**

EMPLOYEE NOTIFICATION LETTER

Dear Employee:

An environmental health & safety consulting firm completed a study to determine the presence, location, and quantity of asbestos-containing materials at the West Linn-Wilsonville School District. The facilities were inspected in accordance with the Environmental Protection Agency guidelines for asbestos-containing materials (i.e., 40 CFR 763). This study is available for your review in the main office of each facility.

Asbestos poses a widespread concern for everyone since it was used extensively in buildings and homes constructed up to the late 1970's for insulation, acoustical purposes, and/or fire retardation. During that time, asbestos was a government-approved building material and considered almost a miracle substance because of its fire retardant and insulating properties. Airborne asbestos fibers are a health hazard and have been linked with different types of abdominal and lung cancers. We are, therefore, committed to taking corrective measures, when and where appropriate, and our asbestos control efforts will be based on the advise of experts knowledgeable in asbestos abatement techniques.

It is very important that all maintenance, custodial, and production employees read carefully the list of known and suspect asbestos-containing materials located in the main office. Please note the location of asbestos-containing material and avoid any unnecessary disturbance of the material. West Linn-Wilsoville School District has also designed an Operations & Maintenance Plan to ensure that the remaining asbestos-containing materials at our facility remain in good condition. The Asbestos Operations and Maintenance Plan includes specific requirements for the safe handling and removal of asbestos-containing material and should be consulted prior to beginning any work on or near asbestos-containing materials.

By signing this document, you are acknowledging only that you have been informed of the known asbestos-containing materials in the West Linn-Wilsonville School District, the Asbestos Operations & Maintenance Plan for safe handling of asbestos-containing materials, and that you are aware that asbestos may produce adverse health effects if proper control techniques are not used. Our goal is to provide everyone with training and knowledge so that exposure to our employees and contractors does not occur. Our policy of hiring licensed asbestos abatement contractor to perform all work involving asbestos-containing materials will continue.

Please sign and return a copy of this letter. If you have any questions or concerns, please contact me.


Sincerely,

Asbestos Program Manager

Signature _____
Printed Name _____

Date _____
Social Security No. _____

**ANNUAL
(PARENT/LEGAL
GUARDIAN/OCCUPANT)
NOTIFICATION
RECORDS**



West Linn-Wilsonville School District 3JT

ADMINISTRATION BUILDING

P.O. Box 35 · West Linn, Oregon 97068 · (503) 638-9869 or Fax (503) 638-9878

January 4, 2000

Dear Parents and Students:


In our efforts to comply with Federal and State requirements regarding asbestos management; and to ensure a safe learning environment for the patrons of West Linn-Wilsonville Schools, please be advised that all district facilities except Boeckman Creek Primary, Athey Creek Middle, Wilsonville High and Rosemont Ridge Middle contain varying amounts of known asbestos-containing materials.

The District employs the services of a professional asbestos management firm who has completed a study to determine the presence, location and quantity of asbestos-containing materials in all district facilities. The facilities have been recently re-inspected in accordance with the Environmental Protection Agency guidelines for asbestos-containing materials and this study, as well as all historic data regarding asbestos, is available for your review in the main office of each facility.

West Linn-Wilsonville Schools is committed to providing safe schools for all students and employees in our district and we thank you for your attention to this important issue.

Sincerely,

DEPARTMENT OF OPERATIONS


Tim K. Woodley, Director
Asbestos Program Manager

NOTIFICATION & TRAINING OF EMPLOYEES, CONTRACTORS/SHORT-TERM WORKERS

This section reflects requirements outlined in 40 CFR 763.92 (a)(1), (2)(iv) & 763.84 (b)

The following subsections contain this required information:

- Contractor/Employee Notification Letter
- Contractor Notification/Acknowledgement
- Contractor Asbestos Awareness Training Records

Notification and Labeling

Once the presence of ACM has been established in a facility a notification and warning program should be initiated. The notification and warning program serves two purposes

- It alerts affected parties to a potential hazard in the building
- It provides basic information on avoiding the hazard

Building occupants, employees and others who are aware of the presence of ACM are less likely to disturb the material and cause fiber release. Note, however, that the AHERA Rule requirements for notification are limited to sending written notices to employees, parent and teachers (or organizations representing these groups if such organization exist.) The notices must announce the existence and location of the management plan.

Notification

Notification of building occupants and other affected individuals can be accomplished several ways. Two common techniques are

- Distributing notices
- Holding awareness or informational seminars

The distribution of notices is an effective means of altering building occupants about the presence of asbestos. Memos or letters can be tailored to specific parties, and verification that notification was received is easily accomplished. For example, in a large multi-tenant facility, the building owner can send detailed reports to the management of individual companies, while distributing similar informational memos to building occupants.

Awareness or informational seminars can be designed to follow written notification. They serve to expand on relevant information while allowing those attending to raise questions. These seminars can be developed at the same time as other training programs, and typically last no more than several hours.

Regardless of notification format chosen, building occupants could be provided with the following information:

- What asbestos is and how it is typically used
- Health effects of associated exposure
- What type(s) of ACM are present in the facility
- The exact location(s) of these materials
- How individuals can avoid disturbing ACM
- How to recognize and report damage

SHORT-TERM WORKER NOTIFICATION

Information regarding the location of ACM must be provided for all short term workers who come into the building according to the AHERA Final Rules. To comply with this requirement, LEA should inform all short-term workers that the management plan must be reviewed prior to working in the building.

This can be accomplished by the following:

- All workers are to report to the school administrative office prior to starting any activities, review the plan, and sign a statement that they have done so.

**CONTRACTOR
NOTIFICATION LETTER**

CONTRACTOR NOTIFICATION LETTER

West Linn-Wilsonville School District hired an environmental health & safety consulting firm to complete a study to determine the presence, location, and quantity of asbestos-containing materials at the West Linn-Wilsonville School District. Our schools were inspected in accordance with Environmental Protection Agency guidelines for asbestos-containing materials (i.e., 40 CFR Part 763). This study is available for your review in the Central Records Library.

The purpose of this letter is to advise you as to where the known asbestos-containing materials are located at the West Linn-Wilsonville School District, and to refer you to the Asbestos Survey for identification of the presence, location, and quantity of asbestos-containing materials throughout our facility. The survey is located in the Main Office and it is essential that you familiarize yourself in the contents of the survey and the asbestos described in the Operations & Maintenance Plan prior to beginning any work in this facility.

The West Linn-Wilsonville School District has an Operations and Maintenance Plan which provides our employees and contractors with the proper knowledge to institute safe practices for the elimination of potential airborne fibers. One key element of this program includes periodic air testing to ensure that asbestos fiber concentrations are maintained well below the EPA indoor air quality level. Whenever known or suspected asbestos-containing materials are impacted, air quality testing will be conducted.

By way of background, the term "asbestos" describes a group of minerals, including actinolite, amosite, anthophyllite, chrysotile, crocidolite, and tremolite that are related to each other as fibrous inorganic hydrated mineral silicates. These minerals have been valued as a natural resource with hundreds of applications in manufacturing, construction and consumer products. Their fibrous forms allow them to be made of cloth, felt, gaskets, rope or to be used for reinforcement in cements, asphalt, and plastic. They are nonflammable, withstand high temperature and have a high-tensile strength. Three forms of asbestos products are typically found in buildings 1) surfacing materials; 2) thermal materials; and 3) miscellaneous materials such as ceiling tiles, floor tiles and shingles.

Asbestos poses a widespread concern for everyone since it was used extensively in buildings and homes constructed with insulation, acoustical treatments and/or fire protection. Asbestos was installed as a government-approved building material and was considered almost a miracle substance because of its many physical properties. However, airborne asbestos fibers are a health hazard and have been linked with different types of abdominal and lung cancers. We are therefore committed to taking corrective measures wherever appropriate, and our asbestos control efforts will be based on the advice of experts knowledgeable in asbestos abatement techniques.

Asbestos fibers tend to be retained by the lungs and can cause a variety of diseases, some of which are not evident for 20 years or more after initial exposure.

If you have any questions or concerns, please contact the APM, Tim Woodley, at: (503) 673-7041.

Thank you in advance for your cooperation.

Sincerely,

Asbestos Program Manager

**CONTRACTOR /
NOTIFICATION /
ACKNOWLEDGMENT**

Contractor Notification / Acknowledgement

The West Linn-Wilsonville School District facilities have been determined to contain asbestos. Your work may bring you into close proximity to known or suspected asbestos-containing materials. Please refer to the Asbestos Building Survey and List of Routine Maintenance Areas for descriptions of asbestos-containing material in the specific areas you will be working in.

WORKING WITH ASBESTOS CAN BE DANGEROUS. INHALING ASBESTOS FIBERS HAS BEEN LINKED WITH VARIOUS TYPES OF CANCER. IF YOU SMOKE AND INHALE ASBESTOS FIBERS, THE CHANCE THAT YOU WILL DEVELOP LUNG CANCER IS GREATER THAN THAT OF THE NON-SMOKING PUBLIC.

Disturbance of the asbestos-containing materials may cause release of asbestos fibers into the air. The work you are about to perform should not disturb and/or damage these materials. Any such activity is prohibited without the use of engineered control procedures and employees trained in their use (DEQ certified asbestos abatement workers and/or supervisors). An asbestos work order must be granted by the LEA before performing any task that might result in the disturbance of asbestos-containing materials. The only contractors that are permitted to intentionally disturb asbestos containing material are those that have received an Oregon Asbestos Abatement Contractor license.

By signing this document you are acknowledging that you have been informed of the known locations and health hazards associated with asbestos-containing materials in the West Linn-Wilsonville School District. You are also acknowledging that you understand that only licensed asbestos abatement contractors and certified asbestos abatement employees may intentionally disturb asbestos-containing material. If you encounter damaged materials that you believe might contain asbestos, you are responsible for notifying the APM prior to any activities that might results in the release of asbestos fibers.

SIGNATURE: _____ DATE: _____

PRINTED NAME: _____ SS#: _____

COMPANY: _____

**CONTRACTOR
ASBESTOS AWARENESS
TRAINING RECORDS**

TRAINING

This section reflects requirements outlined in 40 CFR 763.84 (2), 763.92 (a) (v), (2)

The following subsections contain this required information:

- LEA Designate/Asbestos Awareness Training Records
- Maintenance/Custodial Staff
- Personnel Medical Records (if applicable)

ACTION: You must train your custodian and maintenance employees. Prior to the start of the O & M Plan, there is a 2 hour awareness training and 14 additional hours of training for workers who may come in contact with asbestos.

FORM: N/A

EMPLOYEE AND WORKER TRAINING

Training workers to use special procedures and work practices is a key to a successful asbestos management program. The training requirements differ between OSHA and AHERA, primarily in that OSHA has no specific number of training hours. There is also a difference in various state training programs.

All LEA maintenance and custodial staff, as well as contract workers, who work in a building containing ACBM are required to receive at a minimum a two-hour awareness training seminar. Any of these workers who will disturb ACBM must receive an additional 14 hours of training. Workers engaged in large-scale, long-duration ACBM activities in K-12 schools must receive 24 hours of training and become "Accredited Asbestos Workers". They must also receive an annual 8-hour refresher course. In Washington State the training program is 36 hours for "Accredited Workers".

The time intervals for the awareness education and 14 hours additional training of the employees are not specified by EPA regulations. However, it is highly recommended that both the two-hour awareness seminar and the additional 14 hours of training be given annually. All employees must receive the two-hour awareness training within 60 days of beginning work or, if they will come into contact with ACBM, before they begin their activities. Intervals should be checked for compliance with state and local rules and regulations. Many private companies and LEAs have all workers who contact ACBM attend the 24-hour training to provide the highest level of worker training. A sample employee training records form is included in this section.

LEA DESIGNATE

The local Education Agency designated person (asbestos program manager) is the responsible person on behalf of the school district to ensure that the management plan and the AHERA rules are followed and, even more importantly, to protect the health of the building occupants and the environment.

Every LEA must designate a person and train them with the basic knowledge of the following:

- Health effects of asbestos
- Detection, identification and assessment of asbestos containing materials
- Options for controlling asbestos containing building materials
- Asbestos management programs
- State and Federal regulations

There is no approved course or length of training set by the EPA. Some people are of the opinion that the LEA designate should take a 5 day Accredited Inspector/Management Planner course. This

TRAINING

is the highest level of accredited training for non-workers. Because the LEA designate is the most responsible party in the asbestos management process, taking this course when available makes sense. There are 3 day courses to train LEA designates and even 1 day courses.

TWO-HOUR AWARENESS TRAINING

The required LEA two-hour awareness training program should include the information given to the occupants for the general information sessions and mailings and should include:

- Uses and forms of ACBM
- Health effects of asbestos
- Location of ACBM in building
- Recognition of problems such as damage, deterioration, or delamination of ACM
- Name and telephone number of the APM
- General understanding of the asbestos management program
- Overview of work practices and procedures to be followed by personnel who will
- Contact ACBM

WORKERS WHO CONTACT ACBM

All employees and contract personnel who contact ACBM through cleaning maintenance or emergencies must have at least an additional 14 hours of training (16 hours total). Three types of training for workers who contact ACBM can be identified:

- Training for custodians involved in cleaning and simple maintenance tasks
- Training for maintenance workers involved in general maintenance and more complex repair tasks
- Training for workers who may conduct limited asbestos abatement (removal, enclosure, and encapsulation) or whose work involves direct (intentional) contact with ACBM

All three types of training should include general discussions of the uses and health effects of asbestos, the location of ACBM in the building, the overall asbestos control program, and the asbestos management program.

The additional 14-hour training program should also include:

- Physical characteristics of asbestos
- Methods and procedures for handling and disposing ACBM
- Medical monitoring and surveillance requirements
- Personal protection, including respiratory protection and protective clothing
- Working knowledge of the asbestos management program, including safety, access, and reinspection
- Equipment availability and uses including wet cleaning, HEPA vacuuming, steam cleaning, etc.
- Hands-on training in use of respirators, personal protection, work practices, and fiber control

TRAINING

- Importance of record-keeping and employee record generation requirements
- Requirements for clearing work-order through the APM for of all renovation and ACBM disturbance activities
- Nonasbestos safety considerations
- Training and licensing requirements by state and local agencies

ACCREDITED ASBESTOS WORKER TRAINING

The training requirement for an accredited asbestos worker includes a 24-hour, or three-day course. The course should include lectures, demonstrations, at least six hours of hands-on training, individual respirator fit-testing, course review, and an examination. EPA recommends the use of audio-visual materials to complement lectures where appropriate.

The training course should adequately address the following:

- Physical characteristics of asbestos
- Potential health effects related to asbestos exposure
- Employee personal protective equipment
- State-of-the-art work practices
- Personal hygiene
- Additional safety hazards
- Medical monitoring
- Air monitoring
- Relevant federal, state, and local regulatory requirement, procedures, and standards.
- Establishment of respiratory protection programs
- Course review

The worker must receive a passing grade of 70% on an examination with 50 multiple-choice questions.

TEACHING QUALIFICATIONS

The 2 and 14-hour training programs can be conducted by any qualified person trained in asbestos control and management. The EPA stresses the use of the most qualified people available. The 24-hour training program for workers must be an EPA-accredited training course. A sample form for recording individual worker training is included in this section.

CONTRACT SERVICES


Where custodial and maintenance services are performed under contract with a service company, the building owner must ensure that the service company's staff has been properly trained for working with ACBM. Training will include successful completion of courses on asbestos control and special programs that meet the requirements for the LEA staff discussed above. The company's respirator and medical surveillance programs should be reviewed. In addition, the company performance should be verified with other customers, particularly owners of buildings containing ACBM.

If the service company meets the training and performance requirements, an initial session should be held with the company's supervisors and workers to inform them of the location of ACBM in the building and of all building-specific operating procedures. The APM assumes responsibility for ensuring that the service company adheres to all aspects of the asbestos management program.

**LEA
DESIGNATE/ASBESTOS
AWARENESS TRAINING
RECORDS**

Course Title: AHERA DP TRAINING
 Date(s): 10-14-99
 Location: WEST LINN - WILSONVILLE
SCHOOL DISTRICT
ADMINISTRATION BLDG,

PAC PRO Safety & Health Services
 660 N.W. Bella Vista Drive ♦ Gresham, Oregon 97030
 Phone: 503-666-6693 ♦ Fax: 503-665-3143



Attendance Roster

PLEASE PRINT your name clearly, as you want it to appear on your certificate.

Name	Company	Phone Number
1. Jeri Nelson	WL - WV School Dist.	673-7013
2. Tim Woodley	School District	673-7041
3.		
4.		
5.		
6.		
7.		
8.		
9.		
10.		
11.		
12.		
13.		
14.		
15.		
16.		
17.		
18.		
19.		
20.		

"Safety for a Worldwide Workplace"


Certificate of Completion

Presented by
Three Rivers Environmental, Inc.

Jeri Nelson

has successfully completed a
Designated Person
training course in accordance with
EPA AHERA 40 CFR, Part 763, Subpart E.

October 14, 1999
West Linn - Wilsonville School District
22210 SW Stafford Road
West Linn, Oregon 97068



Instructor

Three Rivers Environmental, Inc. 545 W. Arlington Gladstone, Oregon 97027 (503)-557-2396

Certificate of Completion

Presented by
Three Rivers Environmental, Inc.

Tim Woodley

has successfully completed a
Designated Person
training course in accordance with
EPA AHERA 90 CFR Part 763, Subpart E.


October 14, 1990
West Linn - Wilsonville School District
22210 SW Stafford Road
West Linn, Oregon 97068

Harvey McGill
Instructor

Three Rivers Environmental, Inc. 545 W. Arlington Gladstone, Oregon 97027 (503)-557-2396

MAINTENANCE / CUSTODIAL STAFF

Course Title: ASBESTOS AWARENESS
 Date(s): 03-26-01
 Location: WEST LINN-WILSONVILLE S.D.



PAC PRO Safety & Health Services
 660 N.W. Bella Vista Drive ♦ Gresham, Oregon 97030
 Phone: 503-666-6693 ♦ Fax: 503-665-3143


Attendance Roster

PLEASE PRINT your name clearly, as you want it to appear on your certificate.

SIGNATURE	PRINTED NAME	PHONE NUMBER
1. <i>David Jolliffe</i>	David Jolliffe	539-5826
2. <i>Terry L. Sturman</i>	Terry L. Sturman	630-3675
3. <i>Robin Nolan</i>	Robin Nolan	631-4832
4. <i>Reynaldo R Espino</i>	REYNALDO R ESPINO	675-8260
5. <i>Vicki Holtcamp</i>	Vicki Holtcamp	638-4460
6. <i>Claude Koch</i>	Claude Koch	653-9482
7. <i>Colin Wall</i>	COLIN WALL	723-1453
8. <i>Tim Lacey</i>	Tim Lacey	772-7105
9. <i>Linda Jacobs</i>	Linda Jacobs	636-2698
10. <i>Leo Moser</i>	Leo Moser	435-2979
11. <i>Jerry Hoxen</i>	Jerry Hoxen	635-9272
12. <i>Cheryl Somner</i>	Cheryl Somner	673-7265
13. <i>Gwyned A Nolan</i>	Gwyned A Nolan	673-7013
14. <i>Carol Zuercher</i>	CAROL ZUERCHER	673-7013
15. <i>Jeri Nelson</i>	Jeri Nelson	673-7013
16. <i>John Erickson</i>	John Erickson	632-4421
17. <i>SERGIO BARROSO</i>	<i>SERGIO BARROSO</i>	723-0614
18. <i>ELIDA VARROQUIN</i>	<i>ELIDA</i>	
19. <i>Aly Castro</i>	Aldagunda Castro	430-77-81
20. <i>Jesse Angel Rosas</i>	Jesse A. Rosas	691-89-39

"Safety for a Worldwide Workplace"

Course Title: ASBESTOS AWARENESS
 Date(s): 03-26-01
 Location: WEST LINN-WILSONVILLE S.D.



PAC PRO Safety & Health Services
 660 N.W. Bella Vista Drive ♦ Gresham, Oregon 97030
 Phone: 503-666-6693 ♦ Fax: 503-665-3143

Attendance Roster

PLEASE PRINT your name clearly, as you want it to appear on your certificate.

SIGNATURE	PRINTED NAME	PHONE NUMBER
1. <i>David Jolliffe</i>	David Jolliffe	539 5826
2. <i>Terry L. Sturman</i>	Terry L. Sturman	630-3675
3. <i>Robin Nolan</i>	Robin Nolan	631-4832
4. <i>Reynaldo R. Espino</i>	REYNALDO R ESPINO	675-8260
5. <i>Vicki Holtcamp</i>	Vicki Holtcamp	638-4460
6. <i>Claude Koch</i>	Claude Koch	653-9482
7. <i>Colin Wall</i>	COLIN WALL	723-1453
8. <i>Tim Lucy</i>	Tim Lucy	772-7105
9. <i>Linda Jacobs</i>	Linda Jacobs	636-2698
10. <i>Leo Moser</i>	Leo Moser	435-2979
11. <i>Cheryl Sommer</i>	Cheryl Sommer	635 9272
12. <i>Cheryl Sommer</i>	Cheryl Sommer	673-7265
13. <i>Gwyneth A. Nolin</i>	Gwyneth A. Nolin	673-7013
14. <i>Carol Zuecher</i>	CAROL ZUECHER	673-7013
15. <i>Jeri Nelson</i>	Jeri Nelson	673-7013
16. <i>John Erickson</i>	John Erickson	632-4421
17. <i>SERGIO BARROSO</i>	SERGIO BARROSO	723-0614
18. <i>ELDORA VARROQUIN</i>	ELDORA VARROQUIN	
19. <i>Aly Castro</i>	Aldagunda Castro O.	430-17-81
20. <i>Jesse Angel Dasas</i>	Jesse A. Dasas	691-89-39

"Safety for a Worldwide Workplace"

Course Title: ASBESTOS AWARENESS
 Date(s): 02-16-01
 Location: WEST LINN-WILSONVILLE S.D.
WEST LINN, OR



PAC PRO Safety & Health Services
 660 N.W. Bella Vista Drive ♦ Gresham, Oregon 97030
 Phone: 503-666-6693 ♦ Fax: 503-665-3143

Attendance Roster

PLEASE PRINT your name clearly, as you want it to appear on your certificate.

SIGNATURE	PRINTED NAME	PHONE NUMBER
<i>Vicki Yeomans</i>	VICKI YEOMANS	673-7043
<i>Steve Lewallen</i>	Steve Lewallen	" "
<i>John W. Hartley Jr</i>	John W. HARTLEY Jr	673-7100
<i>Refugio Luna</i>	REFUGIO LUNA	774-6428
<i>Larry Johnson</i>	LARRY JOHNSON	625-4547
<i>Larry Fodge</i>	LARRY FODGE	678-1494
<i>Kevin Washington</i>	Kevin Washington	794-9452
<i>Ron D Moser</i>	Ron D Moser	653-1832
<i>Bertel Rigg</i>	Bertel Rigg	570-0466
<i>Doug Nimrod</i>	DOUG NIMROD	998-7252
<i>Rocky Bounds</i>	Rocky Bounds	831-1027
<i>Mickey Mouse</i>	mickey mouse	824-3105
<i>Allan Perrine</i>	Allan Perrine	656-6685
<i>Garrett H. King</i>	Garrett H. King	557-8506
<i>Tom Nixon</i>	TOM NIXON	682-8434
<i>Lester Barber</i>	LESTER BARBER	625 1906
17.		
18.		
19.		
20.		

"Safety for a Worldwide Workplace"

Course Title: ASBESTOS AWARENESS
 Date(s): 02-16-01
 Location: WEST LINN-WILSONVILLE S.D.
WEST LINN, OR



PACPRO Safety & Health Services
 660 N.W. Bella Vista Drive ♦ Gresham, Oregon 97030
 Phone: 503-666-6693 ♦ Fax: 503-665-3143


Attendance Roster

PLEASE PRINT your name clearly, as you want it to appear on your certificate.

SIGNATURE	PRINTED NAME	PHONE NUMBER
1. <u>ROBERT STEWARD</u>	<u>Robert Steward</u>	<u>N/A</u>
2. <u>Robin K McIntosh</u>	<u>Robin K McIntosh</u>	<u>503-722-9775</u>
3. <u>F E Ransom</u>	<u>Frank E Ransom</u>	<u>760 7086</u>
4. <u>Harold & Pauley</u>	<u>HAROLD PAULEY</u>	<u>503 725 7166</u>
5. <u>BLAINE CHRISTOPHER</u>	<u>BLAINE CHRISTOPHER</u>	<u>503 771-8127</u>
6. <u>PEPPO TORRESS</u>	<u>PEPPO TORRESSA</u>	<u>503 6418439</u>
7. <u>Terry Casey</u>	<u>Terry Casey</u>	<u>673-7436</u>
8. <u>Kim Vaehler</u>	<u>Kim Vaehler</u>	<u>673-7013</u>
9. <u>Linda Varsandar</u>	<u>Linda Varsandar</u>	<u>666-1975</u>
10. <u>JESUS LUNA</u>	<u>JESUS LUNA</u>	<u>803-7060</u>
11. <u>JOSE LUNA</u>	<u>JOSE LUNA</u>	<u>998-7252</u>
12.		
13.		
14.		
15.		
16.		
17.		
18.		
19.		
20.		

"Safety for a Worldwide Workplace"

Course Title: ASBESTOS AWARENESS
 Date(s): 02-16-01
 Location: WEST LINN · WILSONVILLE S.D.
WEST LINN, OR



PAC PRO Safety & Health Services
 660 N.W. Bella Vista Drive ♦ Gresham, Oregon 97030
 Phone: 503-666-6693 ♦ Fax: 503-665-3143

Attendance Roster

PLEASE PRINT your name clearly, as you want it to appear on your certificate.

SIGNATURE	PRINTED NAME	PHONE NUMBER
1. <i>Mary Cromwell</i>	503-65-2636 Mary Cromwell	650-2636
2. <i>Darryl Cromwell</i>	Darryl Cromwell	503-65-2636
3. <i>Nancy Behineski</i>	Nancy Behineski	655-7192
4. <i>Bill Ray</i>	Bill Ray	650-3842
5. <i>Mark L. Rainey</i>	MARK L. RAINEY	673-7013
6.		
7.		
8.		
9.		
10.		
11.		
12.		
13.		
14.		
15.		
16.		
17.		
18.		
19.		
20.		

"Safety for a Worldwide Workplace"

**ASBESTOS AWARENESS TRAINING
FEBRUARY 21, 2000**

Smith, Jason
Moser, Leo
Simmons, Phil
Riggan, Butch
Pauley, Harold
Deatherage, Ryan
Wart, James
Herring, William
Hartley, John
Johnson, Larry
Wall, Colin
Griffin, James
Luna, Jose
Bounds, Rocky
Luna, Jesus
Luna, Refugio
Washington, Kevin
Somner, Cheryl
Koch, Claude
Baer, David
Raine, Mark
Olson, Terry
Garza, Pam
Yeomans, Vicki
Nolan, Robin
Hines, Gary
Lewallen, Steve
Ray, Bill
Peter, Jim
Cromwell, Darryl
Nixon, Tom
Daley, John
Jacobs, Linda
Vachter, Kim
Sturman, Terry
Simmons, Joe
Thomas, David
Christopher, Blaine
Howard, Jerry
Whitney, Clair

Course Title: ARRESTORS AWARENESS
 Date(s): 02/2000
 Location: WEST LINN/WILSONVILLE
SCHOOL DIST ADMIN BLDG.
WEST LINN OR



PAC PRO Safety & Health Services
 660 N.W. Bella Vista Drive ♦ Gresham, Oregon 97030
 Phone: 503-666-6693 ♦ Fax: 503-665-3143


Attendance Roster

PLEASE PRINT your name clearly, as you want it to appear on your certificate.

SIGNATURE	PRINTED NAME	PHONE NUMBER
1. Jason D Smith	Jason D Smith	503-682-7521
2. Leo Moser	Leo Moser	435-2979
3. Phil Simmons	Phil Simmons	570-9753
4. Butch Ribber	Butch Ribber	570-0460
5. Harold R Pauley	HAROLD R PAULEY	775-7166
6. Ryan Deatherage	Ryan Deatherage	557-7347
7. James H. Went	James H. Went	632-6892
8. William J Herring	WILLIAM HERRING	632-4582
9. John W Hartley Jr	John W HARTLEY Jr	698-4771
10. Larry Johnson	LARRY JOHNSON	695-4541
11. Colin Wall	COLIN WALL	232-2157
12. James A Griffin	JAMES A GRIFFIN	656-4088
13. Jose F. Luna	JOSE F. LUNA	259-9483
14. Rocky Boudis	Rocky Boudis	582-8506
15. Jesus Jung	Jesus Jung	259-9453
16. Patricia Luna	Patricia Luna	848-9287
17. Kevin Washington	Kevin Washington	794-9452
18. Cheryl Sommer	Cheryl Sommer	250-7019
19. Claude Koch	Claude Koch	658-9482
20. David J Rose	David J Rose	632-3868

"Safety for a Worldwide Workplace"

Course Title: ASBESTOS AWARENESS
 Date(s): 02/21/00
 Location: WEST LINN/WILSONVILLE
SCHOOL DIST. ADMIN. BLDG.
WEST LINN, OR



PAC PRO Safety & Health Services
 660 N.W. Bella Vista Drive ♦ Gresham, Oregon 97030
 Phone: 503-666-6693 ♦ Fax: 503-665-3143

Attendance Roster

PLEASE PRINT your name clearly, as you want it to appear on your certificate.

SIGNATURE	PRINTED NAME	PHONE NUMBER
<i>Mark L. Rainey</i>	MARK L. RAINey	673-7013
<i>Terry Olson</i>	Terry Olson	
<i>Pam Garza</i>	Pam Garza	
<i>Vicki Yeomans</i>	VICKI YEOMANS	
<i>Robin Nolan</i>	Robin Nolan	
<i>Gary Hines</i>	GARY HINES	
<i>Steve Lewallen</i>	Steve Lewallen	673-7909
<i>Bill Ray</i>	BILL RAY	673-7845
<i>Jim Peter</i>	Jim Peter	656-6665
<i>Darryl Cromwell</i>	Darryl Cromwell	650-2636
<i>Thomas Nixon</i>	THOMAS NIXON	682-8434
<i>John L. Daley</i>	John L. Daley	631-8603
<i>Binda Schuck</i>	Binda Schuck	636-2698
<i>Kim Vaechter</i>	Kim Vaechter	656-5429
<i>Terry C. Sturman</i>	Terry C. Sturman	630-3675
<i>Joe Simmons</i>	Joe Simmons	673-7016
<i>David Thomas</i>	DAVID THOMAS	673-7013
<i>Blaine Christopher</i>	BLAINE CHRISTOPHER	771-8127
<i>Jerry Howard</i>	Jerry Howard	673-7503
<i>Clair Whitney</i>	CLAIR WHITNEY	722-1249

"Safety for a Worldwide Workplace"

**ASBESTOS AWARENESS
MARCH 20, 2000**

Gaffney, Les
Sherman, Walt
Chavarin, Freddy
Steward, Robert
Cromwell, Gary
Zuercher, Carol
Dvorak, Mark
Rose, Thelma
Lasit, Sharon
Espino, Reynaldo
Nolin, Gwynn
Nimrod, Doug
Varsandar, Linda
Holtcamp, Vicki
Bettineski, Nancy
Moser, Ronald
Boyle, Lester
Casey, Terry
Perrine, Allan
Torres, Pedro
Nelson, Jeri
Joliffe, Dave

Course Title: ASBESTOS AWARENESS
 Date(s): 3/20/00
 Location: WEST LINN SCHOOL DIST.
ADMINISTRATION BLDG.
WEST LINN, OR



PAC PRO Safety & Health Services
 660 N.W. Bella Vista Drive • Gresham, Oregon 97030
 Phone: 503-666-6693 • Fax: 503-665-3143

Attendance Roster

PLEASE PRINT your name clearly, as you want it to appear on your certificate.

SIGNATURE	PRINTED NAME	PHONE NUMBER
1. Les O. Raffney	LES O. RAFFNEY	503-762-4086
2. Walter Stewart	WALTER STEWART	503-552-2859
3. Yarrowing	TREND THORNTON	
4. R. Stewart	ROBERT STEWART	11/4
5. Dan / General	GARY [unclear]	690 2056
6. Carol Zurek	CAROL ZUREK	1030-7575
7. Mark Ivorak	MARK IVORAK	457-7430
8. Thelma Rose	THELMA ROSE	686-3094
9. Sharon Laatz	SHARON LAATZ	673-7155
10. Reynaldo R. Espino	REYNALDO R. ESPINO	675-8260
11. Richard N. [unclear]	RICHARD N. [unclear]	455-1069
12. David [unclear]	DAVID NIMROD	824-3105
13. Linda Vassandor	LINDA VASSANDOR	666-1975
14. Vicki Holikamp	VICKI HOLIKAMP	638-4460
15. Nancy Behrnski	NANCY BEHRNSKI	655-4879
16. Ronald D. Mose	RONALD D. MOSE	623-1532
17. Terry Gacey	TERRY GACEY	529-9409
18. Terry Gacey	TERRY GACEY	529-9409
19. Allan Ferrine	ALLAN FERRINE	656-6685
20. DEPRO 102120's S.		

Course Title: ASBESTOS AWARENESS
 Date(s): 3/20/00
 Location: WEST LINN SCHOOL DIST
ADMINISTRATION BLDG.
WEST LINN, OR



PACPRO Safety & Health Services
 660 NW Bella Vista Drive • Gresham, Oregon 97030
 Phone: 503-666-6693 • Fax: 503-666-3143

Attendance Roster

PLEASE PRINT your name clearly, as you want it to appear on your certificate.

SIGNATURE	PRINTED NAME	PHONE NUMBER
1. <u>[Signature]</u>	<u>Dave Joliffe</u>	
2. <u>[Signature]</u>	<u>Jerry Nelson</u>	<u>678-7013</u>
3.		
4.		
5.		
6.		
7.		
8.		
9.		
10.		
11.		
12.		
13.		
14.		
15.		
16.		
17.		
18.		
19.		
20.		

Feb

**PERSONNEL MEDICAL
RECORDS (if applicable)**

MEDICAL MONITORING

OR-OSHA Division 3 – 1926.1101 (m); (n)(3)

A medical surveillance program must be made available to workers employed in the construction industry who are:

- exposed to asbestos at or above the PEL (0.1 f/cc – 8TWA) or Excursion Limit (1.0 f/cc – 30 min.) for 30 or more days per year;
or
- engaged in Class I, II, and/or III asbestos work for 30 or more days per year;
or
- required by the rules to wear a negative-pressure respirator.

All other employees who are or will be exposed to asbestos at or above the action level must be covered by a medical surveillance program.

Medical examinations must be given on the following schedule:

- **prior to assignment** to an area where negative-pressure respirators are worn; or
- within 10 working days following the thirtieth day of exposure **annually thereafter**.
- if an examining physician determines that any test(s) should be more often than the annual schedule.

Examinations must include:

- medical and work history;
- standardized questionnaire; abbreviated questionnaire;
- physical examination;
- chest X-ray (this is based on the doctor's discretion and analyzed by a specialist);
- pulmonary function test; and,
- any other examination deemed necessary.

The employer must maintain an accurate record for each employee, including:

- name and social security number;
- copy of medical examination;
- physician's written opinions;
- any medical complaints related to asbestos;
- maintain the record for 30 years beyond termination

Employee access to information: the employer shall provide a copy of the physician's written opinion to the employee within 30 days from its receipt.

Physicians written opinion: Employers must instruct the physician not to reveal in the written opinion given to the employer specific findings or diagnoses unrelated to occupational asbestos exposure.

RESPIRATORY PROTECTION

OR-OSHA Division 3 – 1926.1101 (h)

Respirators must be worn under the following conditions:

- during the time necessary to install or implement engineering controls and work practices to bring exposures to below the PEL and/or excursion limit
- in operations where controls are not feasible i.e. maintenance and repair activities
- where controls have not reduced exposure levels below the PEL and/or excursion limit
- in emergencies
- in all regulated areas, and
- whenever employee exposure exceeds PEL and/or excursion limit.
- Whenever employer cannot do an appropriate negative exposure assessment of an asbestos abatement project.

PERIODIC SURVEILLANCE

This section reflects requirements outlined in 40 CFR 763.92 (3) (b) (2) (i-iii)

- ACTION:** Check the condition of the asbestos-containing materials (ACM) at least every 6 months.
- TRAINING:** None required; O & M or Inspector suggested.
- FORM:** Use the form included in this Section.

A well-run asbestos management program must include periodic surveillance of the ACBM. Periodic surveillance is the scheduled observation of asbestos materials to determine if any damage or deterioration occurred since the previous observation. Because much of the ACBM is observed daily by the school staff during normal work and also because many areas are not accessible, slight changes in the condition of the ACBM occurring over time may not be readily apparent.

Some building owners conduct monthly surveillance. AHERA requires surveillance in K-12 schools at no greater than six month intervals, and this is a prudent minimal frequency for any Owner. This periodic surveillance can save the building owner considerable time money, and embarrassment in the event of ACBM deterioration or damage. Moreover, properly conducted surveillance provides a great deal of comfort to building workers and occupants.

SURVEILLANCE PERSONNEL:

AHERA establishes no training requirements for the persons conducting the periodic surveillance. Any employee or contractor selected by the Asbestos Program Coordinator is allowed to conduct the surveillance. Three Rivers Environmental Inc. recommends that the observer either take a 16-hour Operations and Maintenance course or a 3-day inspector course. The individual should be knowledgeable of the building's construction, previous inspections and surveillances, generation of records, conditions to be observed, and personal protections. It is the Owner's responsibility to ensure that the surveillance does not cause an exposure of safety problem for the person conducting this activity.

DATA REQUIREMENTS:

All areas with ACBM or suspected ACBM must be visually examined in each periodic surveillance. A record of the surveillance date and the person conducting the surveillance, as well as any changes in ACBM conditions, must be recorded. This requires the person to be knowledgeable of earlier ACBM conditions. The records generated by this periodic inspection must be filed in the Management Plan at the Owner's administrative office. It is recommended that the reports to be filed in the administrative office be submitted to the Asbestos Program Coordinator for review.

SURVEILLANCE CONCERNS:

The person conducting the periodic surveillance must observe the same major factors that were observed in the original inspection and that were used to assess the material's conditions. The six items to be evaluated are:

- Deterioration or delamination of the materials.
- Physical damage to the material or adjacent areas.
- Water damage of any material in the area.
- Air-stream effects
- Exposure, accessibility and activity changes.
- Changes in building use.

PERIODIC SURVEILLANCE

RECORDKEEPING:

File Periodic Surveillance Reports under TAB 8 and utilize the appropriate form.

COMMUNICATIONS:

Any changes in conditions or notable circumstance should be communicated to the Asbestos Program Coordinator. The updated information is to be included in the Management Plan and in the annual notification letters.

for
9.14.00

AHERA

Six Month Periodic Surveillance

WEST LINN SCHOOL DISTRICT #3Jt OF

West Linn High School
5464 West "A" Street
West Linn, OR 97068

Project No. 1020-109

ROBERT C. MONTGOMERY
AHERA Inspector

Robert C. Montgomery 5-17-00
Signature & Date

#98-09212, ORE
Certification # & State

ROBERT C. MONTGOMERY
Management Planner

Robert C. Montgomery 5-18-00
Signature & Date

MP-00-8795, ORE
Certification # & State

Prepared by:



PERIODIC SURVEILLANCE REPORT

Page #: 1 of 5

TRE Job#: 1020-109

Client: West Linn School District

Campus: West Linn High School

Address: 5464 West "A" Street

Building: Main

Date of Surveillance: May 2000

Person Conducting Surveillance: Robert Montgomery

Material Description: Boiler/Tank Insulation/Mechanical Insulation

Homogeneous area(s): HK USA #01

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

Material Description: Gasket

Homogeneous area(s): HK USA #01

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Corrugated Pipe Cover

Homogeneous area(s): HK USA #01

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 2 of 5
TRE Job#: 1020-109

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street.

Building: Main
Date of Surveillance: May 2000

Person Conducting Surveillance: Robert Montgomery

Material Description: Boiler/Tank Insulation

Homogeneous area(s): HK USA #02

Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Hot Water/MJP on Corrugated Pipe Covering

Homogeneous area(s): HK USA #02

Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Hot Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #02

Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #03

Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #04

Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Hot Water/Pipe Covering

Homogeneous area(s): HK USA #05

Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Hot Water/MJP on Pipe Covering

Homogeneous area(s): HK USA #06

Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #07

Last Material Condition: Good New Material Description: Same
Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 3 of 5
TRE Job#: 1020-109

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: May 2000

Person Conducting Surveillance: Robert Montgomery

Material Description: Domestic Cold Water/MJP on Corrugated Pipe Covering

Homogeneous area(s): HK USA #08

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Acoustical Thermal Plaster

Homogeneous area(s): HK USA #11

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #50

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #50

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #52

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #53

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #54

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #55

Last Material Condition: Good New Material Description: Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 4 of 5
TRE Job#: 1020-109

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: May 2000

Person Conducting Surveillance: Robert Montgomery

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #56

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #57

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #58

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Cold Water/MJP on Corrugated Pipe Covering

Homogeneous area(s): HK USA #59

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/Pipe Covering

Homogeneous area(s): HK USA #60

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Pipe Covering

Homogeneous area(s): HK USA #61

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Vinyl Floor Tile

Homogeneous area(s): HK USA #97

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Transite Siding

Homogeneous area(s): HK USA #98

Last Material Condition: Good New Material Description: Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 5 of 5
TRE Job#: 1020-109

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: May 2000

Person Conducting Surveillance: Robert Montgomery

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #99
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #99
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Transite Siding
Homogeneous area(s): HK USA #98
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: TSI Hard Fittings, Mag Line Over Corrugated Pipe Covering
Homogeneous area(s): 50 hard fittings, 40 ln. ft. under S. wing of high school
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: MJP on Pipe Covering (12" O.D.)
Homogeneous area(s): 1 sq. ft. TSI damaged exposed in gym (E. side above landing)
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Sheet vinyl
Homogeneous area(s): 290 sq. ft. torn sheet vinyl between cafeteria & stairs to commons area
Last Material Condition: Good New Material Description: Same
Change in material condition: No



June 2, 2000

West Linn-Wilsonville School District
 Attention: Tim Woodley
 P.O. Box 35
 West Linn, OR 97068

Dear Mr. Woodley,

Three Rivers Environmental, Inc. appreciates the opportunity that we had to conduct your AHERA Re-inspection of asbestos containing building materials. This reinspection consisted of the review and updating of all AHERA records under current regulatory guidelines and the inspection and assessment of all asbestos containing materials in eight schools with addition of the Administration Building within West Linn-Wilsonville School District. The review of all AHERA records and the assessments of all asbestos containing building materials were performed by an accredited AHERA Building Inspector and Management Planner.

The following are the "Areas of Concern" for each individual school and the materials that were located that are in need of immediate attention.

West Linn High School:-

Material: TSI hard fittings, mag lines over corrugated pipe covering
Assessment noted: 50 hard fittings, 40 ln. ft. under S. wing of high school
Recommended Response Action: Immediately isolate, restrict access, clean-up debris and maintain in an intact and undamaged condition.

Material: MJP on pipe covering (12" O.D.)
Assessment noted: 1 sq. ft. TSI damaged exposed in gym (E. side above landing)
Recommended Response Action: Repair and maintain in an intact and undamaged condition.

West Linn High School cont.

Material: Sheet vinyl
Assessment noted: 290 sq. ft. torn sheet vinyl between cafeteria & stairs to commons area
Recommended Response Action: Abate, repair flooring and replace

Willamette Primary-

Material: TSI hard fittings
Assessment noted: 1 sq. ft., 1 damaged hard fitting, wall intrusion, cracks at hanger location.
Recommended Response Action: Repair and maintain in an intact and undamaged condition.

Wilsonville Primary-

Material: Floor tile, 12x12
Assessment noted: 7 ln. or sq. ft. of tile cracked severely at stress line.
Recommended Response Action: Remove and repair damaged tiles and maintain in an intact and undamaged condition.

Inza R. Wood Primary-

Material: Hard fitting, mag
Assessment noted: 1 hard fitting slightly damaged in mechanical room
Recommended Response Action: Repair and maintain in an intact and undamaged condition.

West Linn High School (Bolton Campus)-

Material: Corrugated pipe covering
Assessment noted: 1 sq. ft. exposed TSI pipe covering in basement storage room
Recommended Response Action: Repair and maintain in an intact and undamaged condition.

Cedar Oak Park Primary-

Material: Vibration joint cloth

Assessment noted: 2 sq. ft. damaged corners in fan room (West)

Recommended Response Action: Remove or repair and maintain in an intact and undamaged condition.

Material: TSI air cell piping

Assessment noted: 1 sq. ft. damaged TSI in boiler room, S. wall

Recommended Response Action: Remove or repair and maintain in an intact and undamaged condition.

Administration Building-

Material: Woven paper tape

Assessment noted: 8 sq. ft. of damaged paper tape on walls in boiler room

Recommended Response Action: Repair or replace and maintain in an intact or undamaged condition.

AHERA

Periodic Surveillance Report

for

WEST LINN-WILSONVILLE SCHOOL DISTRICT 3JT

WEST LINN HIGH SCHOOL
5464 West "A" St.
West Linn, OR 97068

Project No. 1020-40

April 1999

Prepared by



P.O. Box 216 Arlington Gladstone, Oregon 97027 (503) 557-2396

PERIODIC SURVEILLANCE REPORT

Page #: 1 of 5
TRE Job#: 1020-40

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: April 1999

Person Conducting Surveillance: Matthew Johnson

Material Description: Boiler/Tank Insulation/Mechanical Insulation

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Gasket

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Corrugated Pipe Cover

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 2 of 5
TRE Job#: 1020-40

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: April 1999

Person Conducting Surveillance: Matthew Johnson

Material Description: Boiler/Tank Insulation

Homogeneous area(s): HK USA #02

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Corrugated Pipe Covering

Homogeneous area(s): HK USA #02

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #02

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #03

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #04

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/Pipe Covering

Homogeneous area(s): HK USA #05

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Pipe Covering

Homogeneous area(s): HK USA #06

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #07

Last Material Condition: Good New Material Description: Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 3 of 5
TRE Job#: 1020-40

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: April 1999

Person Conducting Surveillance: Matthew Johnson

Material Description: Domestic Cold Water/MJP on Corrugated Pipe Covering

Homogeneous area(s): HK USA #08

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Acoustical Thermal Plaster

Homogeneous area(s): HK USA #11

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #50

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #50

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #52

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #53

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #54

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #55

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 4 of 5
TRE Job#: 1020-40

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: April 1999

Person Conducting Surveillance: Matthew Johnson

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #56
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering
Homogeneous area(s): HK USA #57
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering
Homogeneous area(s): HK USA #58
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Cold Water/MJP on Corrugated Pipe Covering
Homogeneous area(s): HK USA #59
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Hot Water/Pipe Covering
Homogeneous area(s): HK USA #60
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Hot Water/MJP on Pipe Covering
Homogeneous area(s): HK USA #61
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #97
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Transite Siding
Homogeneous area(s): HK USA #98
Last Material Condition: Good New Material Description: Same
Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 5 of 5
TRE Job#: 1020-40

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: April 1999

Person Conducting Surveillance: Matthew Johnson

Material Description: Vinyl Floor Tile

Homogeneous area(s): HK USA #99

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Vinyl Floor Tile

Homogeneous area(s): HK USA #99

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Transite Siding

Homogeneous area(s): HK USA #98

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Signature _____

November 30, 1998

Joe Simmons
West Linn-Wilsonville School District
Administration Building
P.O. Box 35
West Linn, OR 97068

Subject: AHERA 6 Month Reinspection Areas of Concern::

Dear Mr. Simmons:

Three Rivers Environmental has completed the AHERA 3 Year Reinspection. The list below are areas that need to be addressed in the Operation and Maintenance Plan and scheduled for repair or removal:

Bolton Middle School:

Boiler Room:	3 sq. ft. previous encapsulation delaminating needs bridging.
Custodial Office:	1 sq. ft. exposed piping. 1 sq. ft. exposed seam.
Hallway/Storage (N. of boiler room)	2 sq. ft. previous encapsulation delaminating needs bridging.
Weight Room:	1 sq. ft. damaged Hard Fitting. 1 sq. ft. exposed seam.

West Linn High School:

Boiler Room:	3 sq. ft. exposed boiler insulation with debris. 2 sq. ft. exposed cold water piping.
--------------	--

Willamette Primary:

Elect. Room Below Cafe:	1 sq. ft. exposed Hard Fitting.
-------------------------	---------------------------------

Inza R. Wood:

Kitchen Supply Closet:	2 sq. ft. damaged Hard Fittings.
------------------------	----------------------------------

Should you have questions or comments, please contact me at your convenience.

Respectfully submitted,

Jeff Smith
Three Rivers Environmental

AHERA

Periodic Surveillance Report

for

WEST LINN-WILSONVILLE SCHOOL DISTRICT 3JT

WEST LINN HIGH SCHOOL
5464 West "A" Street
West Linn, OR

Project No. 1020-12

August 1997

Prepared by



P.O. Box 216 Gladstone, Oregon 97027 (503) 557-2396

PERIODIC SURVEILLANCE REPORT

Page #: 1 of 1
TRE Job#: 1020-12

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Music
Date of Surveillance: August 1997

Person Conducting Surveillance: Glenn Bryant

Material Description: Vinyl Floor Tile

Homogeneous area(s): HK USA #99

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Signature GB.

PERIODIC SURVEILLANCE REPORT

Client: West Linn School District

Page #: 1 of 1

TRE Job#: 1020-12

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Shop
Date of Surveillance: August 1997

Person Conducting Surveillance: Glenn Bryant

Material Description: Transite Siding

Homogeneous area(s): HK USA #98

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Vinyl Floor Tile

Homogeneous area(s): HK USA #99

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Signature GB.

PERIODIC SURVEILLANCE REPORT

Page #: 1 of 5
TRE Job#: 1020-12

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: August 1997

Person Conducting Surveillance: Glenn Bryant

Material Description: Boiler/Tank Insulation/Mechanical Insulation

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Gasket

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Corrugated Pipe Cover

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 2 of 5
TRE Job#: 1020-12

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: August 1997

Person Conducting Surveillance: Glenn Bryant

Material Description: Boiler/Tank Insulation

Homogeneous area(s): HK USA #02

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Corrugated Pipe Covering

Homogeneous area(s): HK USA #02

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #02

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #03

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #04

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/Pipe Covering

Homogeneous area(s): HK USA #05

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Pipe Covering

Homogeneous area(s): HK USA #06

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #07

Last Material Condition: Good New Material Description: Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 3 of 5
TRE Job#: 1020-12

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: August 1997

Person Conducting Surveillance: Glenn Bryant

Material Description: Domestic Cold Water/MJP on Corrugated Pipe Covering
Homogeneous area(s): HK USA #08
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Acoustical Thermal Plaster
Homogeneous area(s): HK USA #11
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #50
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering
Homogeneous area(s): HK USA #50
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #52
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #53
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering
Homogeneous area(s): HK USA #54
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #55
Last Material Condition: Good New Material Description: Same
Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 4 of 5
TRE Job#: 1020-12

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: August 1997

Person Conducting Surveillance: Glenn Bryant

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #56

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #57

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #58

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Cold Water/MJP on Corrugated Pipe Covering

Homogeneous area(s): HK USA #59

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/Pipe Covering

Homogeneous area(s): HK USA #60

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Pipe Covering

Homogeneous area(s): HK USA #61

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Vinyl Floor Tile

Homogeneous area(s): HK USA #97

Last Material Condition: Good New Material Description: Same

Change in material condition: No

Material Description: Transite Siding

Homogeneous area(s): HK USA #98

Last Material Condition: Good New Material Description: Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 5 of 5
TRE Job#: 1020-12

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: August 1997

Person Conducting Surveillance: Glenn Bryant

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #99
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #99
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Transite Siding
Homogeneous area(s): HK USA #98
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Signature GB

AHERA

Periodic Surveillance Report

for

WEST LINN-WILSONVILLE SCHOOL DISTRICT 3JT

WEST LINN HIGH SCHOOL
5464 West "A" Street
West Linn, OR

Project No. 1020-10

February 1997

Prepared by



P.O. Box 216 Gladstone, Oregon 97027 (503) 557-2396

PERIODIC SURVEILLANCE REPORT

Page #: 1 of 1
TRE Job#: 1020-10


Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Music
Date of Surveillance: Feb. 1997

Person Conducting Surveillance: Glenn Sutherby

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #99
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Signature 

PERIODIC SURVEILLANCE REPORT

Page #: 1 of 5
TRE Job#: 1020-10

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: Feb. 1997

Person Conducting Surveillance: Glenn Sutherby

Material Description: Boiler/Tank Insulation/Mechanical Insulation

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Gasket

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Corrugated Pipe Cover

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 2 of 5
TRE Job#: 1020-10

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: Feb. 1997

Person Conducting Surveillance: Glenn Sutherby

Material Description: Boiler/Tank Insulation

Homogeneous area(s): HK USA #02

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Corrugated Pipe Covering

Homogeneous area(s): HK USA #02

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #02

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #03

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #04

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/Pipe Covering

Homogeneous area(s): HK USA #05

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Pipe Covering

Homogeneous area(s): HK USA #06

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #07

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 3 of 5
TRE Job#: 1020-10

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: Feb. 1997

Person Conducting Surveillance: Glenn Sutherby

Material Description: Domestic Cold Water/MJP on Corrugated Pipe Covering
Homogeneous area(s): HK USA #08
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Acoustical Thermal Plaster
Homogeneous area(s): HK USA #11
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #50
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering
Homogeneous area(s): HK USA #50
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #52
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #53
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering
Homogeneous area(s): HK USA #54
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #55
Last Material Condition: Good New Material Description: Same
Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 4 of 5
TRE Job#: 1020-10

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: Feb. 1997

Person Conducting Surveillance: Glenn Sutherby

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #56
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering
Homogeneous area(s): HK USA #57
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering
Homogeneous area(s): HK USA #58
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Cold Water/MJP on Corrugated Pipe Covering
Homogeneous area(s): HK USA #59
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Hot Water/Pipe Covering
Homogeneous area(s): HK USA #60
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Domestic Hot Water/MJP on Pipe Covering
Homogeneous area(s): HK USA #61
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #97
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Transite Siding
Homogeneous area(s): HK USA #98
Last Material Condition: Good New Material Description: Same
Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Page #: 5 of 5
TRE Job#: 1020-10

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: Feb. 1997


Person Conducting Surveillance: Glenn Sutherby

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #99
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #99
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Transite Siding
Homogeneous area(s): HK USA #98
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Signature



PERIODIC SURVEILLANCE REPORT

Page #: 1 of 1
TRE Job#: 1020-10

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street


Building: Shop
Date of Surveillance: Feb. 1997

Person Conducting Surveillance: Glenn Sutherby

Material Description: Transite Siding
Homogeneous area(s): HK USA #98
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #99
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Signature



AHERA

Periodic Surveillance Report

for

WEST LINN-WILSONVILLE SCHOOL DISTRICT 3JT

WEST LINN HIGH SCHOOL
5464 West "A" St.
West Linn, OR

Project No. 1020-08

January 1996

Prepared by



170 E Arlington Gladstone, Oregon 97027 (503) 656-4601



**THREE RIVERS
ENVIRONMENTAL**

PERIODIC SURVEILLANCE REPORT

Page #: 1 of 5
TRE Job#: 1020-08

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: Jan. 1996

Person Conducting Surveillance: Jeff Smith

Material Description: Boiler/Tank Insulation/Mechanical Insulation

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Gasket

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Domestic Hot Water/MJP on Corrugated Pipe Cover

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Domestic Hot Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #01

Last Material Condition: Good **New Material Description:** Same
Change in material condition: No



PERIODIC SURVEILLANCE REPORT

Page #: 2 of 5
TRE Job#: 1020-08

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: Jan. 1996

Person Conducting Surveillance: Jeff Smith

Material Description: Boiler/Tank Insulation

Homogeneous area(s): HK USA #02

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Corrugated Pipe Covering

Homogeneous area(s): HK USA #02

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #02

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering

Homogeneous area(s): HK USA #03

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering

Homogeneous area(s): HK USA #04

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/Pipe Covering

Homogeneous area(s): HK USA #05

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Hot Water/MJP on Pipe Covering

Homogeneous area(s): HK USA #06

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering

Homogeneous area(s): HK USA #07

Last Material Condition: Good **New Material Description:** Same

Change in material condition: No



PERIODIC SURVEILLANCE REPORT

Page #: 3 of 5
TRE Job#: 1020-08

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: Jan. 1996

Person Conducting Surveillance: Jeff Smith

Material Description: Domestic Cold Water/MJP on Corrugated Pipe Covering
Homogeneous area(s): HK USA #08
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Acoustical Thermal Plaster
Homogeneous area(s): HK USA #11
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #50
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering
Homogeneous area(s): HK USA #50
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #52
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #53
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering
Homogeneous area(s): HK USA #54
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #55
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No



PERIODIC SURVEILLANCE REPORT

Page #: 4 of 5
TRE Job#: 1020-08

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: Jan. 1996

Person Conducting Surveillance: Jeff Smith

Material Description: Low Pressure Steam/Pipe Covering
Homogeneous area(s): HK USA #56
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Low Pressure Steam/MJP on Pipe Covering
Homogeneous area(s): HK USA #57
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Domestic Cold Water/Corrugated Pipe Covering
Homogeneous area(s): HK USA #58
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Domestic Cold Water/MJP on Corrugated Pipe Covering
Homogeneous area(s): HK USA #59
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Domestic Hot Water/Pipe Covering
Homogeneous area(s): HK USA #60
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Domestic Hot Water/MJP on Pipe Covering
Homogeneous area(s): HK USA #61
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #97
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No

Material Description: Transite Siding
Homogeneous area(s): HK USA #98
Last Material Condition: Good **New Material Description:** Same
Change in material condition: No



PERIODIC SURVEILLANCE REPORT

Page #: 5 of 5
TRE Job#: 1020-08

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Main
Date of Surveillance: Jan. 1996

Person Conducting Surveillance: Jeff Smith

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #99
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #99
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Transite Siding
Homogeneous area(s): HK USA #98
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Signature



PERIODIC SURVEILLANCE REPORT

Page #: 1 of 1
TRE Job#: 1020-08

Client: West Linn School District

Campus: West Linn High School
Address: 5464 West "A" Street

Building: Music
Date of Surveillance: Jan. 1996

Person Conducting Surveillance: Jeff Smith

Material Description: Vinyl Floor Tile

Homogeneous area(s): HK USA #99

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

Signature



PERIODIC SURVEILLANCE REPORT

Page #: 1 of 1
TRE Job#: 1020-08

Client: West Linn School District


Campus: West Linn High School
Address: 5464 West "A" Street

Building: Shop
Date of Surveillance: Jan. 1996

Person Conducting Surveillance: Jeff Smith

Material Description: Transite Siding
Homogeneous area(s): HK USA #98
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Material Description: Vinyl Floor Tile
Homogeneous area(s): HK USA #99
Last Material Condition: Good New Material Description: Same
Change in material condition: No

Signature 

RECORDKEEPING (Asbestos Removal Activity/Response Action Recordkeeping)

This section reflects requirements outlined in 40 CFR 763.91 & 763.94 (d) (e) (f) (g) (h)

The following subsections contain this required information

- Flow charts to determine adequate response actions
- Operations & Maintenance (<3 sq. ft. or <3 ln. ft.)
- Small scale/short duration (>3 sq. ft. or 3 ln. ft.) or (>40 ln. ft. or 80 sq. ft.)

ACTION: All asbestos-related activities must be recorded.

TRAINING: LEA Designate must ensure that program is enacted and maintained.

FORMS: Understand how to use all the recordkeeping forms.

The purpose of the record-keeping system is three-fold:

- To ensure maximum protection of all persons in the building.
- To provide detailed, retrievable records of all events.
- To provide the needed records in event of a law suit.

In essence, the AHERA regulations required that everything done with regards to asbestos in a facility must be documented by the facility's owner so that the training and exposure of all persons involved in the work can be documented and the fate of all ACBM can be determined.

The recordkeeping requirements described in 40 CFR 763.94 are quite explicit in regards to the LEA's recordkeeping responsibilities. Although some records are required to be kept up to six years, they may be required beyond six years (as long as 20 to 40 years) in the event of a law suit. Thus, all records should be maintained in a retrievable state for up to 40 years (or let's just say don't ever throw them away).

Location: Records must be kept in the administrative offices of both the actual building and the LEA. If these are in the same building, it is advisable that a duplicate set of records should be established in a different location in the event of fire or other damage.

The following activities or occurrences require detailed documentation. A brief description is given here. Refer to the appropriate TAB number in the management Plan for exact AHERA requirements and sample forms for compiling information. Narratives of pertinent record keeping data and tab locations.

Tab 10 **Response Actions Selected:** records of all preventative measures, major abatement activities.

Tab 8 **Periodic Surveillance:** conducted at a minimum of six-month intervals to determine any damage or deterioration of ACBM.

Tab 9 **Reinspection:** conducted every three years by an accredited inspector.

Tab 11 **Operations and Maintenance:** initial, periodic and emergency cleanings; minor and major fiber release episodes; maintenance procedures for ACBM.

RECORDKEEPING (Asbestos Removal Activity/Response Action Recordkeeping)

Tab 5 **Medical Surveillance:** annual examination of any person who will contact ACBM in their work. Keep copies of examination forms.

Tab 5 **Training:** 2-hour awareness training for all custodial staff, 14 hours additional for those who will disturb ACBM; recommended annually.

MEMO FOR THE RECORD

Under CFR 40 763.94 and 763.85 (b) (1)

Records of abatement, surveys, inspections and reinspection may be archived and maintained in a centralized location in the administrative office.

All inspection activities and/or asbestos abatement records prior to the May/June 1995 3-year Inspection are stored in a large box in the Asbestos Program Manager's office or some other designated location.

**OPERATIONS &
MAINTENANCE
(≤ 3 Sq. feet or 3 ln. feet)**

SMALL SCALE

(>3 sq. feet or 3 ln. feet)
(<40 ln. feet or 80 sq. feet)

FAXED
4-11-00

9 PAGES

ASN-3

QUARTERLY REPORT FORM



USED WITH THE ANNUAL NON-FRIABLE AND FRIABLE NOTIFICATIONS

For DEQ use only	
Date Received	_____
Project Number	_____

Instructions: This form is used in conjunction with Department of Environmental Quality (DEQ) Form ASN-2 and ASN-7 (Annual Notice of Intent to remove smaller friable asbestos projects and annual notice of intent to remove non-friable asbestos projects). This form is used to summarize the projects done using these plans. This Report shall only apply to projects where the scope of each removal does not exceed 40 linear or 80 square feet of friable asbestos removal or for non-friable projects being performed by a School, College, or Facility or where a contractor is performing this work for a School, College, or a Facility. Large friable asbestos removal projects may not be subdivided to accommodate this size limitation.

Due Dates: (per OAR 340-032-5630)	1 st Quarter due April 15	3 rd Quarter due October 15
	2 nd Quarter due July 15	4 th Quarter due January 15

Contractor, Facility Owner, School Rep. IRS Environmental of Oregon, Inc. Phone: 693-6388

Quarter and Calendar Year for this Report: 1st Qtr: X 2nd Qtr: _____ 3rd Qtr: _____ 4th Qtr: _____ Year: _____

Mailing Address: 755 SW Dennis Avenue, Hillsboro, Oregon Washington 97123
Street or PO Box City County Zip

Contact Person: Bruce Korum Title: President Phone: 693-6388

List of Projects:

In the boxes below, list the smaller friable asbestos removal projects (40 linear or 80 square feet or less) that you performed during the quarter. Or, list the non-friable asbestos removal projects that you performed at a School, College, or Facility during the quarter. (More boxes are on the other side. If you need to report more projects, make copies of the back side of this form)

8788

Job site address:	<u>1914 SW Park, PORTLAND</u>		
Description of Facility:	<u>College Hall</u>	Type of Asbestos:	<u>DUCT PAPER</u>
Project start date:	<u>1-15-00</u>	Completion date:	<u>1-15-00</u>
Name of Certified Worker:	<u>RON CHAFF</u>	Certification No.:	<u>08787</u>
Name of Worker Doing Non-friable Removal:	_____		
Amount of Friable asbestos removed:	LF: _____	SF: <u>8</u>	_____
Amount of Non-friable Asbestos Removed:	Square Footage: _____	Year to date:	_____

Questions? Contact the DEQ at 1-800-452-4011 for the number of your local DEQ regional office.

SIGN THIS FORM AND SEND IT TO:
 The DEQ Asbestos Control Section at 2020 SW 4th, Ste. 400, Portland, Oregon 97201, or FAX to (503) 229-5265.
 (NOTE: Persons working outside the Northwest region must send this form to the Eastern or Western Regional DEQ office)

Name: Bruce Korum (Print) Signature: Bruce Korum

Date: 4-11-00 Phone: 693-6388

FROM : IPS ENVIRONMENTAL

FAX NO. : 503 693 7221

Apr. 12 2000 08:26AM P4

8864

Job site address: 2313 SW Arnold Portland
 Description of Facility: RESIDENCE Type of Asbestos: VINYL
 Project start date: 3-20-00 Completion date: 3-20-00
 Name of Certified Worker: ROBERT NOVAK Certification No. 08794
 Name of Worker Doing Non-friable Removal: _____
 Amount of Friable asbestos removed: LF: 75 SF: _____
 Amount of Non-friable Asbestos Removed: Square Footage: _____ Year to date: _____

* 8862

Job site address: 5464 WEST A ST, WEST LINN
 Description of Facility: SCHOOL - WEST LINN HS Type of Asbestos: FLOOR TILE & DEBRIS
 Project start date: 3-22-00 Completion date: 3-22-00
 Name of Certified Worker: _____ Certification No. 08594
 Name of Worker Doing Non-friable Removal: VINCE CHAVEZ
 Amount of Friable asbestos removed: LF: _____ SF: 40
 Amount of Non-friable Asbestos Removed: Square Footage: _____ Year to date: _____

8877

Job site address: 735 SW STARK, PORTLAND
 Description of Facility: BANK BUILDING Type of Asbestos: PIPE INSULATION
 Project start date: 3-22-00 Completion date: 3-22-00
 Name of Certified Worker: VINCE CHAVEZ Certification No. 08594
 Name of Worker Doing Non-friable Removal: _____
 Amount of Friable asbestos removed: LF: 23 SF: _____
 Amount of Non-friable Asbestos Removed: Square Footage: _____ Year to date: _____

8885

Job site address: 7000 SW WILSON AVE BEAVERTON
 Description of Facility: SCHOOL - Highland Park MS Type of Asbestos: PIPE FITTINGS
 Project start date: 3-27-00 Completion date: 3-27-00
 Name of Certified Worker: RON CHIAFF Certification No. 08787
 Name of Worker Doing Non-friable Removal: _____
 Amount of Friable asbestos removed: LF: 4 SF: _____
 Amount of Non-friable Asbestos Removed: Square Footage: _____ Year to date: _____

8887

Job site address: 6300 SW NICOL RD PORTLAND
 Description of Facility: SCHOOL Type of Asbestos: FITTINGS
 Project start date: 3-27-00 Completion date: 3-27-00
 Name of Certified Worker: RON CHIAFF Certification No. 08787
 Name of Worker Doing Non-friable Removal: _____
 Amount of Friable asbestos removed: LF: 10 SF: _____
 Amount of Non-friable Asbestos Removed: Square Footage: _____ Year to date: _____

ASBESTOS ABATEMENT SUMMARY

Project #: 1020-101

Job Location: WEST LINN HIGH SCHOOL Floor: MAIN / Basement

Project: REMOVAL OF 18 HARD FITTINGS

For pipe provide: Total linear feet 18 LF and pipe size 2" x 1"

For other materials provide: Total square feet: _____

Type of ACM: TSI

Start Date: 3-8-00 Completion Date: 3-8-00

Methods to Control Emissions: Glove Bag, WET METHOD, HAM VAC.

Give name of Contractor or Subcontractor:

Name: TSI

Address: 13600 NE 10th AVENUE

City: VANCOUVER State: WA. Zip: 98685

Phone: 360/574-8400 Contact person: Darren Watts

Name of Monitoring Lab: TRB.

Anticipated Disposal Site: Hillsboro Landfill, Hillsboro, OR

Supervisor in charge of job: Jesse James

Cert. #: 08651 Exp. Date: 9-22-00 Phone: _____

Asbestos Program Manager: Tim Woodley

Training date: _____ Exp. date: _____ Phone: _____

- O&M (less than 3 ln. 3 sq. ft.)
- Small scale
- Large scale

Attach pre-abatement and post-abatement air sample results

ASBESTOS ABATEMENT SUMMARY
Project #: 1020-100

Job Location: WEST WIND HIGH SCHOOL Floor: MAIN, WOOD SHOP FOYER

Project: PATCH & REPAIR, VAT REMOVAL, REINCAPSULATION
TSI HARD FITTINGS

For pipe provide: Total linear feet 8 and pipe size 2"

For other materials provide: Total square feet: 20

Type of ACM: DUPL FLOOR TILE MASTIC, TSI MAG HARD FITTINGS

Start Date: 3-22-00 Completion Date: 3-22-00

Methods to Control Emissions: WET METHODS, HEPA UAC.

Give name of Contractor or Subcontractor:

Name: IRS ENVIRONMENTAL OF OREGON

Address: 755 SW DENNIS AVENUE

City: HILLSBORD State: OR. Zip: 97123

Phone: (503) 693-6388 Contact person: BRUCE KORUM

Name of Monitoring Lab: THREE RIVERS ENVIRONMENTAL INC.

Anticipated Disposal Site: HILLSBORD LANDFILL

Supervisor in charge of job: VINCE CHAVEZ

Cert. #: 08594 Exp. Date: 06-02-00 Phone: 693-6388

Asbestos Program Manager: TIM WOODLEY

Training date: _____ Exp. date: _____ Phone: _____

- O&M (less than 3 in. 3 sq. ft.)
- Small scale
- Large scale

Attach pre-abatement and post-abatement air sample results



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-100

ATTN: Tim Woodley

P.O. NO: Verbal

CONTRACTOR: I.R.S. Environmental

REPORT NO: 6

PROJECT: West Linn High School Cafeteria/ library, wood shop foyer, patch & repair, removal TSI reincapsulation

PAGE NO: 1 OF 1

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100f/mm^2-1300

Sample ID No: 1	Sample ID No: 2	Sample ID No: B1	Sample ID No: B2
Laboratory No: RM00-0064	Laboratory No: RM00-0065	Laboratory No: RM00-0066	Laboratory No: RM00-0067
Sample Location: Felipe T. Tellez 534-23-9827 EL	Sample Location: Felipe T. Tellez 534-23-9827 P	Sample Location: Blank	Sample Location: Blank
Work Performed: Patch & Repair 1/2 Face	Work Performed: Patch & Repair 1/2 Face	Work Performed: N/A	Work Performed: N/A
Date Sampled: 3/22/00	Date Sampled: 3/22/00	Date Sampled: 3/22/00	Date Sampled: 3/22/00
Sampled by: R. Montgomery	Sampled by: R. Montgomery	Sampled by: R. Montgomery	Sampled by: R. Montgomery
Pump No: LV-09	Pump No: LV-09	Pump No: N/A	Pump No: N/A
Start Time: 07:30	Start Time: 08:10	Start Time: N/A	Start Time: N/A
Stop Time: 08:00	Stop Time: 08:40	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 30	Minutes Sampled: 30	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 2	Start Flow Rate (LPM): 2	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2	Stop Flow Rate (LPM): 2	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2	Average Flow Rate (LPM): 2	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 60 L	Volume: 60 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 3/22/00	Date Analyzed: 3/22/00	Date Analyzed: 3/22/00	Date Analyzed: 3/22/00
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 1/100	Total Fibers: 1/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: LOD	Coefficient of Variation: LOD	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: 0.0079 f/cc	Fibers/cc: 0.0079 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Robert Montgomery

P.O. Box 216 Gladstone Oregon, 97027 Office: (503) 557-2396 Fax: (503) 557-3025



PROJ. No: 1020-100

DATE: 3-22-00 Pg. 1 of 2

See air monitoring reports of this date

ASBESTOS PROJECT CHECKLIST

PROJECT NAME: WEST LINN HIGH SCHOOL, SHEET VINYL PATCH/REPAIR, REMOVAL, TSI HARD FITTING RE-ENCAPSULATION

PROJ. MGR: ROBERT C. MONTGOMERY

ON SITE: 0700 OFF SITE: 0920

OWNER PROVIDED ON-SITE CONTACT:

CONTRACTOR: IRS ENVIRONMENTAL

NAME: _____

SUPERVISOR: VINCE CHAVEZ

Intent to remove ACM on site and complete? YES

Date Pre-abatement samples taken: _____

Disposal site: HILLSBORO LANDFILL, HILLSBORO

AREA ISOLATION

CORRECTION
REQUIRED

NO YES

BARRICADES & SIGNS: ()
 AIRLOCKS: () N/A ()
 COVERINGS ON FLOORS & WALLS: () N/A ()
 NON-MOVABLE EQUIP. COVERED: () N/A ()
 ALL OPENINGS SEALED: () N/A ()
 AIR HANDLING EQUIP. OFF/SEALED: () N/A ()

PERSONNEL & METHODS

CORRECTION
REQUIRED

NO YES

WORKER PROTECTION ADEQUATE: ()
 PERSONAL AIR MONITORS USED: ()
 PROTECTIVE CLOTHING: ()
 PERSONNEL USING DECON: () N/A ()
 EQUIP. MAINTAINED PROPERLY: ()
 WETTING, PRIOR & DURING: ()
 EXCESSIVE DEBRIS: ()
 BAGGING OPERATION: ()
 NEGATIVE AIR ADEQUATE: () N/A ()
 DECON ADEQUATE: () N/A ()
 CLEAN ROOM ADEQUATE: () N/A ()
 SHOWER FILTERED AND ADEQUATE: () N/A ()

Respiratory Protection in use:

1/2 Face Full Face () PAPR () Type C ()

PROJECT MANAGEMENT LOG

0700: ABATEMENT CREW, CONSISTING OF VINCE CHAVEZ, FELIPE T. TELLEZ AND MIGUEL TELLEZ ARE ON SITE AND PREPARING TO PATCH & REPAIR THE NUMEROUS AREAS OF FLOOR TILE WHICH ARE DAMAGED.

0845: CREW FINISHED WITH SHEET VINYL REPAIR AND HAS MOVED OVER TO THE WOOD SHOP. AFTER OPENING UP THE CEILING WE DISCOVERED (1) N/F WHICH HAD FALLEN OFF (WHICH WAS PROMPTLY WETTED AND BAGGED). A TOTAL OF 9 N/F WERE DISCOVERED ALL WERE RE-ENCAPSULATED WITH A THICK COAT OF GRAY PAINT - AFTER MISTING WITH WATER.

0900: THE CREW HAS ABOUT FINISHED.

SIGNATURE

Robert C. Montgomery
ROBERT C. MONTGOMERY



THREE RIVERS
ENVIRONMENTAL

PROJECT MANAGEMENT LOG

PROJ. No: 1020-100

DATE: 300.00 Pg. 2 of 2

See air monitoring reports of this date

0915: DURING THE REPAIR WORK WE DISCOVERED THAT THE ORIGINAL FLOOR TILE WAS COVERED UP WITH PLYWOOD AND SHEET VINYL. THE 9X9 FL. TILE EXTENDS THROUGHOUT ALL AREAS OF THE FIRST FLOOR. THE CREW HAS FINISHED AND IS PREPARING TO DEMOLISH AND HEAD OVER TO STAFFORD.

~~0920: SET UP AND CALIBRATED HI 1800M~~

0920: DEPARTED

SIGNATURE

ASBESTOS ABATEMENT SUMMARY

Project #: 1020-~~32~~ 104

Job Location: W. L. W. SD. Wt. HS

Floor: Basement

Project: Removal of 6 HP

For pipe provide: Total linear feet 600.00 ft. and pipe size 1 1/2"

For other materials provide: Total square feet: _____

Type of ACM: TS1

Start Date: 3-9-00

Completion Date: 3-9-00

Methods to Control Emissions: Glove Bag, Hepa Vac, Wet Method

Give name of Contractor or Subcontractor:

Name: Keystone Contracting

Address: 417 NW 209th

City: Ridgeland State: WA. Zip: _____

Phone: _____ Contact person: _____

Name of Monitoring Lab: TRC

Anticipated Disposal Site: Hillsboro Land Fill

Supervisor in charge of job: Bob Craft

Cert. #: S-08539 Exp. Date: 4-00 Phone: _____

Asbestos Program Manager: Tim Woodley

Training date: _____ Exp. date: _____ Phone: _____

- O&M (less than 3 ln. 3 sq. ft.)
- Small scale
- Large scale

Attach pre-abatement and post-abatement air sample results



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-104

ATTN: Tim Woodley

P.O. NO: Verbal

CONTRACTOR: Keystone Contracting

REPORT NO: 1

PROJECT: West Linn High School
Removal of 6 hard fittings

PAGE NO: 1 OF 2

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100</math>f/mm²<math>-1300

Sample ID No	Sample ID No	Sample ID No	Sample ID No
1	2	3	B1
Laboratory No: IJ00-0049	Laboratory No: IJ00-0050	Laboratory No: IJ00-0051	Laboratory No: IJ00-0052
Sample Location: 10' N. of S. wall of mechanical room AD	Sample Location: 6' S. of entrance to mechanical room AD	Sample Location: Bob Craft 568-15-46-49 P	Sample Location: Blank
Work Performed: N/A	Work Performed: N/A	Work Performed: Glovebag 1/2 face	Work Performed: N/A
Date Sampled: 3/9/00	Date Sampled: 3/9/00	Date Sampled: 3/9/00	Date Sampled: 3/9/00
Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones
Pump No: HV-23	Pump No: HV-22	Pump No: LV-03	Pump No: N/A
Start Time: 16:30	Start Time: 16:30	Start Time: 16:55	Start Time: N/A
Stop Time: 18:30	Stop Time: 18:30	Stop Time: 17:25	Stop Time: N/A
Minutes Sampled: 120	Minutes Sampled: 120	Minutes Sampled: 30	Minutes Sampled: N/A
Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 2	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 2	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 2	Average Flow Rate (LPM): N/A
Volume: 1200 L	Volume: 1200 L	Volume: 60 L	Volume: N/A L
Date Analyzed: 3/9/00	Date Analyzed: 3/9/00	Date Analyzed: 3/9/00	Date Analyzed: 3/9/00
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 12/100	Total Fibers: 7/100	Total Fibers: 1.5/100	Total Fibers: 0/100
Coefficient of Variation: 0.59	Coefficient of Variation: LOQ	Coefficient of Variation: LOD	Coefficient of Variation: N/A
Fibers/cc: 0.0047 f/cc	Fibers/cc: <0.0039 f/cc	Fibers/cc: 0.012 f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Area sample prior to abatement, AD-Area sample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Irvin Jones



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-104
 ATTN: Tim Woodley P.O. NO: Verbal
 CONTRACTOR: Keystone Contracting REPORT NO: 1
 PROJECT: West Linn High School PAGE NO: 2 OF 2
 Removal of 6 hard fittings

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100-<f/mm2<-1300

Sample ID No: B2	Sample ID No:	Sample ID No:	Sample ID No:
Laboratory No: LJ00-0053	Laboratory No:	Laboratory No:	Laboratory No:
Sample Location: Blank	Sample Location:	Sample Location:	Sample Location:
Work Performed: N/A	Work Performed:	Work Performed:	Work Performed:
Date Sampled: 3/9/00	Date Sampled:	Date Sampled:	Date Sampled:
Sampled by: I. Jones	Sampled by:	Sampled by:	Sampled by:
Pump No: N/A	Pump No:	Pump No:	Pump No:
Start Time: N/A	Start Time:	Start Time:	Start Time:
Stop Time: N/A	Stop Time:	Stop Time:	Stop Time:
Minutes Sampled: N/A	Minutes Sampled:	Minutes Sampled:	Minutes Sampled:
Start Flow Rate (LPM): N/A	Start Flow Rate (LPM):	Start Flow Rate (LPM):	Start Flow Rate (LPM):
Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):
Average Flow Rate (LPM): N/A	Average Flow Rate (LPM):	Average Flow Rate (LPM):	Average Flow Rate (LPM):
Volume: N/A L	Volume: L	Volume: L	Volume: L
Date Analyzed: 3/9/00	Date Analyzed:	Date Analyzed:	Date Analyzed:
Graticule Field Area: 0.00817	Graticule Field Area:	Graticule Field Area:	Graticule Field Area:
Total Fibers: 0/100	Total Fibers:	Total Fibers:	Total Fibers:
Coefficient of Variation: N/A	Coefficient of Variation:	Coefficient of Variation:	Coefficient of Variation:
Fibers/cc: N/A f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc

Abbreviations: AP-Area sample prior to abatement, AD-Area sample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Irvin Jones



PROJ. No: 1020-104

DATE: 6-9-00 Pg. 1 of 1

See air monitoring reports of this date

VISUAL INSPECTION REPORT

PROJECT NAME: W.L. H.S.

PROJ. MANAGER: Irvin Jones

OWNER PROVIDED ON-SITE CONTACT:

AREA OF INSPECTION:
(Location of Containment)

NAME: John (Custodian)

S.E. CORNER OF MECH. RM

LEA DESIGNATE: _____

IN UPPER AREA (6 HF

CONTRACTOR: KEYSTONE CONTRACTING

GLASS BATHED

SUPERVISOR: BOB CRAFT

REGULATED AREA

DISPOSAL SITE: HILLSBORO LANDFILL

CORRECTION
REQUIRED
Negative Pressure Enclosure: NO YES

PRE ABATEMENT SAMPLE RESULTS: (If Applicable)

PERSONAL AIR MONITORS USED: ()
PROTECTIVE CLOTHING: ()
PERSONNEL USING DECON: () N/A ()
EXCESSIVE DEBRIS: ()
ENCAPSULATION ADEQUATE: ()
CRITICAL BARRIERS ADEQUATE: ()
NEGATIVE AIR ADEQUATE: () N/A ()
DECON ADEQUATE: () N/A ()
CLEAN ROOM ADEQUATE: () N/A ()
SHOWER FILTERED AND ADEQUATE: () N/A ()

DATE: _____

ANALYTICAL RESULTS: PCM TEM

Personal Protective Equipment Worn By Inspector inside
Regulated Area:

Respirator: 1/2 Face Full Face () PAPR () Type C ()
Disposable Coveralls: ()

SAMPLE NO. RESULTS (FIBERS/CC or STRUCTURES)

SAMPLE NO.	RESULTS (FIBERS/CC or STRUCTURES)
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____

Time of Inspection: _____

PASS: FAIL:

VISUAL INSPECTION LOG (List any exceptions found during this inspection including; visible debris, location of debris found, containment integrity, excessive airborne encapsulant, damaged areas, etc.)

- 1) HAD SEVERAL SPOTS TO RECLEAN.
- 2)

THREE RIVERS ENVIRONMENTAL representative certifies that he has visually inspected the specific work area (as mentioned above) and verifies that the inspection has been thorough and to the best of his knowledge and belief, has found no asbestos containing dust or debris.

NAME: IRVIN JONES

SIGNATURE: Irvin Jones



Project Log

CLIENT: W.L.W. S.D.

TRE JOB NO: 1020-36 104

ATTN: Tim Woodley

PURCHASE ORDER NO:

CONTRACTOR: Keystone Contracting

REPORT DATE:

PROJECT: W.L. H.S.
6 HF REMOVAL

PAGE NO: 1 OF 2

- 1310 CONTRACTED BY FRANK OF "PIPING TUBING INSTALLATION"
FRANK ASKED WHY WE DIDNT COMPLETE REMOVAL
OF THE HARD FITTINGS, I (TREVIN JONES OF TRE) TOLD
HIM I WOULD BE THERE TO LOOK AT IT.
- 1325 TRE (TREVIN JONES) ARRIVED AT WEST LINDA HIGH
SCHOOL MET WITH FRANK, LOOKED AT HF IN
MECHANICAL RM AND TOLD HIM WE WOULD ARRANGE
TO GET THEM OUT TONIGHT.
- 1355 TRE ARRIVED AT TRE OFFICE. MADE PHONE CONTACT
WITH JESSY NELSON (W.L.W.S.D) TO INFORM HER OF OUR INTENTION.
CONTACTED LARRY TINGLEY (KEYSTONE CONTRACTOR) WILL SEND A
CREW DOWN.
- 1400 PAPER WORK COMPLETED FOR JOB.
- 1515 BOB CRAFT KEYSTONE CONTRACTING ARRIVED AT TRE
OFFICE. SUB 15-4649
- 1540 TRA & KEYSTONE DEPARTED FOR W. L. H.S.
- 1605 ARRIVED AT W. L. H.S.
- 1615 SET UP GHOVE BAGS AND PUMPS FOR JOB.
- 1630 CALIBRATED NU-22 & NU-23 STOPPED SAMPLES
1 & 2
- 1640 CHECKED GHOVE BAGS NOT EVEN ATTEMPTED TO
SEAL. HAD MICH SEAL THEM.
- 1655 ~~START~~ STARTED GHOVE BAGGING.
- 1700 HARD FITTINGS REMOVED, HAVE TO FINISH UP
- 1710 KEYSTONE ON BREAK
- 1710 KEYSTONE LEAVING EQUIPMENT.
- 1800 KEYSTONE OFF SITE.
- 1830 CALIBRATED NU-23 & NU-22 STOPPED SAMPLES 1 & 2

Report by: _____



Project Log

THREE RIVERS
ENVIRONMENTAL

CLIENT: W.L. W.S.D.

ATTN: Tim Woodley

CONTRACTOR: Keystone Contracting

PROJECT: WL HS
6 HP Removal

TRE JOB NO: 1020-36 104

PURCHASE ORDER NO:

REPORT DATE:

PAGE NO: 2 OF 2

1840 TRE DEMOBILIZED.

1845 OH Equipment off site

1853 CONTACTED John (custodian).

1902 TRE OFF SITE.

Report by: Janis Jones
Janis Jones

ASBESTOS ABATEMENT SUMMARY

Work Order No.: 1020-87

Job Location: WEST LION HIGH SCHOOL Floor: Basement

Project: TSI REMOVAL COACHES OFFICE

For pipe provide: Total linear feet 5' ± 14ft and pipe size 2"

For other materials provide: Total square feet: _____

Type of ACM: TSI

Start Date: 11-11-99 Completion Date: 11-11-99

Methods to Control Emissions: Containment of Criticals, WBT METHOD

Give name of Contractor or Subcontractor:

Name: TRJ. INC

Address: 19645 SE SUNNYSIDE RD. B30

City: BORING State: OREGON Zip: 97009

Phone: 658-6606 Contact person: JULIANNA

Name of Monitoring Lab: THREE RIVERS ENVIRONMENTAL

Anticipated Disposal Site: NORTHERN WASCO CO. LANDFILL

Supervisor in charge of job: RODRIGUEZ, LIZAURO

Project Manager: IRVIN JONES

Name: IRVIN ^{JONES} JONES Date: 11-11-99 Phone: 557-2396

Asbestos Program Manager: _____

Name: Tim Woodskog Date: 11-11-99 Phone: 673-7041

Attach pre-abatement and post-abatement air sample results



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-82

ATTN: Tim Woodley

P.O. NO: Verbal

CONTRACTOR: Insulation Removal Corp.

REPORT NO: 1

PROJECT: West Linn High School
Coaches office

PAGE NO: 1 OF 1

Method of analysis: NIOSH 7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100<f/mm2<1300

SampleIDNo: 1	SampleIDNo: 2	SampleIDNo: B1	SampleIDNo: B2
LaboratoryNo: IJ99-0421	LaboratoryNo: IJ99-0422	LaboratoryNo: IJ99-0423	LaboratoryNo: IJ99-0424
Sample Location: E. end of coaches office BG	Sample Location: At door of coaches office outside door BG	Sample Location: Blank	Sample Location: Blank
Work Performed: N/A	Work Performed: N/A	Work Performed: N/A	Work Performed: N/A
Date Sampled: 11/11/99	Date Sampled: 11/11/99	Date Sampled: 11/11/99	Date Sampled: 11/11/99
Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones
PumpNo: HV-03	PumpNo: HV-09	PumpNo: N/A	PumpNo: N/A
Start Time: 15:25	Start Time: 15:25	Start Time: N/A	Start Time: N/A
Stop Time: 17:33	Stop Time: 17:33	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 128	Minutes Sampled: 128	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 1280 L	Volume: 1280 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 11/11/99	Date Analyzed: 11/11/99	Date Analyzed: 11/11/99	Date Analyzed: 11/11/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 7/100	Total Fibers: 5/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: LOQ	Coefficient of Variation: LOQ	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: <0.0037 f/cc	Fibers/cc: <0.0037 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative airexhaust, PA-postabatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Irvin Jones



PROJ. No: 1020 -82

DATE: 11-11-99 Pg. 1 of

See air monitoring reports of this date

ASBESTOS PROJECT CHECKLIST

PROJECT NAME: WEST LINN HIGH School

PROJ. MGR: Jones, Irvin

ON SITE: 1455 OFF SITE: 1755

OWNER PROVIDED ON-SITE CONTACT:

CONTRACTOR: IRC

NAME: Gary (Janitor)

SUPERVISOR: Redríguez, Lizardo

Intent to remove ACM on site and complete? Yes.

Date Pre-abatement samples taken: N/A.

Disposal site: Northway Wasco CO. LAND FILL

**PERSONNEL &
METHODS**

**CORRECTION
REQUIRED**

NO YES

WORKER PROTECTION ADEQUATE:
 PERSONAL AIR MONITORS USED:
 PROTECTIVE CLOTHING:
 PERSONNEL USING DECON: N/A
 EQUIP. MAINTAINED PROPERLY:
 WETTING, PRIOR & DURING:
 EXCESSIVE DEBRIS:
 BAGGING OPERATION:
 NEGATIVE AIR ADEQUATE: N/A
 DECON ADEQUATE: N/A
 CLEAN ROOM ADEQUATE: N/A
 SHOWER FILTERED AND ADEQUATE: N/A

Respiratory Protection in use:

1/2 Face Full Face PAPR Type C

AREA ISOLATION

**CORRECTION
REQUIRED**

NO YES

BARRICADES & SIGNS:
 AIRLOCKS: N/A
 COVERINGS ON FLOORS & WALLS:
 NON-MOVABLE EQUIP. COVERED:
 ALL OPENINGS SEALED:
 AIR HANDLING EQUIP. OFF/SEALED:

PROJECT MANAGEMENT LOG

1455 TRC. ARRIVED ON SITE. CONTACTED Construction. HAD Both Gates UNLOCKED.

1525 CALIBRATED HV-03 & HV-09. STARTED SAMPLES 1/2.

1535 IRC ON SITE. Redríguez, Lizardo Supervisor. Gonzalez BAUDILLO Worker.

1544 IRC STARTED SET UP.

1605 CONTACTED GARY (Janitor) let him know we would BE working

1607 CHECK ON PROGRESS. 17% Complete WITH CRITICALS.

SIGNATURE: [Signature]



THREE RIVERS ENVIRONMENTAL


PROJECT MANAGEMENT LOG


PROJ. No: 1020- 82

DATE: 11-11-99 Pg. 2 of

See air monitoring reports of this date

- 1630 - CHECKED BAG AND CRITICALS EVERYTHING IS GOOD, READY TO START ABATMENT.
- 1640 - ABATMENT LOW STARTED.
- 1718 - ABATMENT COMPLETE.
- 1719 - INSPECTION COMPLETE (VACUUMED TOPS OF CEILING). SHEET ROCK BROKEN.
- 1733 - CALIBRATED HV-03; HV-09 STOPPED SAMPLE 1 & 2
- 1739 - CLEAN UP COMPLETE.
- 1750 - DEMOBILIZED. IRC OFF SITE
- 1755 - TRB OFF SITE (LOCKED TWO GATES).

SIGNATURE: 
Irvin Jones



Insulation Removal Corporation

INVOICE

Billed To:

Three Rivers Environmental
P.O. Box 216

Gladstone, OR 97027

Project Name/Location

West Linn High School
5464 West A Street
West Linn, OR 97068

Invoice # 10808

Invoice Date 10/31/99

Due Date 11/30/99

Details Glovebag Pipe Insulation *10-29-99*

Your Job/P.O. #

Our Job # 5384.00

Description**Quantity Units****Price****Amount**

Asbestos Abatement Services As Quoted

1.00 Each

740.0000

740.00

Net Invoice Amount

\$740.00

Terms: Net 30. A service charge of 1.5% will be assessed on all past due accounts. APR is 18%. Minimum service charge is

Page #

1

ASBESTOS ABATEMENT SUMMARY
Work Order No.: 1020-80

Job Location: West Linn High School Floor: 1st

Project: Removal of approximately 25' of TSI & 5 hard fittings

For pipe provide: Total linear feet 25 and pipe size 4"

For other materials provide: Total squarefeet: _____

Type of ACM: TSI

Start Date: 10-29-99 Completion Date: 10-29-99

Methods to Control Emissions: Enclosure (glove bags & HEPA vac)

Give name of Contractor of Subcontractor:

Name: Insulation Removal Corporation

Address: 19645 S.E. Sunnyside Rd.

City: Boring State: Oregon Zip: 97009

Phone: (503) 658-6608 Contact person: JulieAnn A.

Name of Monitoring Lab: Three Rivers Environmental, Inc.

Anticipated Disposal Site: Northern Wasco County Landfill

Supervisor in charge of job: Lizauro C. Rodriguez

Project Manager: _____

Name: Irvin Jones Date: 10-29-99 Phone: (503) 557-2396

Asbestos Program Manager: West Linn-Wilsonville School District 3Jt

Name: Joe Simmons Date: 10-29-99 Phone: (503) 673-7013

Attach pre-abatement and post-abatement air sample results



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-80

ATTN: Tim Woodley

P.O. NO: Verbal

CONTRACTOR: Insulation Removal Corp.

REPORT NO: 1

PROJECT: West Linn High School

PAGE NO: 1 OF 2

TSI & H.F. Pipe Insulation Rmvl.

Method of analysis: NIOSH 7400 Limit of Detection: 5.5Fibers. Limit of Quantification: 10.0fibers. Specification Range: 100<f/mm2<1300

SampleIDNo: 1	SampleIDNo: 2	SampleIDNo: 3	SampleIDNo: B1
LaboratoryNo: IJ99-0416	LaboratoryNo: IJ99-0417	LaboratoryNo: IJ99-0418	LaboratoryNo: IJ99-0419
Sample Location: S.W. corner of mezzanine BG	Sample Location: Center of containment AD	Sample Location: S.W. corner of mezzanine AD	Sample Location: Blank
Work Performed N/A	Work Performed N/A	Work Performed N/A	Work Performed N/A
Date Sampled: 10/29/99	Date Sampled: 10/29/99	Date Sampled: 10/29/99	Date Sampled: 10/29/99
Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones
Pump No: HV-23	Pump No: HV-22	Pump No: HV-23	Pump No: N/A
Start Time: 19:00	Start Time: 20:20	Start Time: 21:00	Start Time: N/A
Stop Time: 21:00	Stop Time: 22:20	Stop Time: 22:30	Stop Time: N/A
Minutes Sampled: 120	Minutes Sampled: 120	Minutes Sampled: 90	Minutes Sampled: N/A
Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): N/A
Volume: 1200 L	Volume: 1200 L	Volume: 900 L	Volume: N/A L
Date Analyzed: 10/29/99	Date Analyzed: 10/29/99	Date Analyzed: 10/29/99	Date Analyzed: 10/29/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 8/100	Total Fibers: 9.5/100	Total Fibers: 5.5/100	Total Fibers: 0/100
Coefficient of Variation: LOQ	Coefficient of Variation: LOQ	Coefficient of Variation: LOQ	Coefficient of Variation: N/A
Fibers/cc: <0.0039 f/cc	Fibers/cc: <0.0039 f/cc	Fibers/cc: <0.0052 f/cc	Fibers/cc: N/A f/cc

Abbreviations AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Irvin Jones



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-80

ATTN: Tim Woodley

P.O. NO: Verbal

CONTRACTOR: Insulation Removal Corp.

REPORT NO: 1

PROJECT: West Linn High School

PAGE NO: 2 OF 2

TSI & H.F. Pipe Insulation Rmvl.

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0 fibers; Specification Range: 100<l/mm2<1300

SampleIDNo: B2	SampleIDNo:	SampleIDNo:	SampleIDNo:
LaboratoryNo: IJ99-0420	LaboratoryNo:	LaboratoryNo:	LaboratoryNo:
Sample Location: Blank	Sample Location:	Sample Location:	Sample Location:
Work Performed: N/A	Work Performed:	Work Performed:	Work Performed:
Date Sampled: 10/29/99	Date Sampled:	Date Sampled:	Date Sampled:
Sampled by: I. Jones	Sampled by:	Sampled by:	Sampled by:
PumpNo: N/A	PumpNo:	PumpNo:	PumpNo:
StartTime: N/A	StartTime:	StartTime:	StartTime:
Stop Time: N/A	Stop Time:	Stop Time:	Stop Time:
Minutes Sampled: N/A	Minutes Sampled:	Minutes Sampled:	Minutes Sampled:
Start Flow Rate (LPM): N/A	Start Flow Rate (LPM):	Start Flow Rate (LPM):	Start Flow Rate (LPM):
Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):
Average Flow Rate (LPM): N/A	Average Flow Rate (LPM):	Average Flow Rate (LPM):	Average Flow Rate (LPM):
Volume: N/A L	Volume: L	Volume: L	Volume: L
Date Analyzed: 10/29/99	Date Analyzed:	Date Analyzed:	Date Analyzed:
Graticule Field Area: 0.00817	Graticule Field Area:	Graticule Field Area:	Graticule Field Area:
Total Fibers: 0/100	Total Fibers:	Total Fibers:	Total Fibers:
Coefficient of Variation: N/A	Coefficient of Variation:	Coefficient of Variation:	Coefficient of Variation:
Fibers/cc: N/A f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc

Abbreviations: AP-Area sample prior to abatement, AD-Area sample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Irvin Jones

THREE RIVERS ENVIRONMENTAL

VISUAL INSPECTION REPORT

PROJECT NAME: WEST LINN HIGH SCHOOL

PROJ. MANAGER: IRVIN JONES

N.E. CORNER OF GYM. (MEZANINE)

AREA OF INSPECTION:
(Location of Containment)

OWNER PROVIDED ON-SITE CONTACT:

N.E. MEZANINE OF GYM.

NAME: JOHN DAILY

"STEAM LINES, AND FLOOR AREA"

LEA DESIGNATE: TIM WOOLEY

CONTRACTOR: INSULATION REMOVAL CORPORATION

SUPERVISOR: LEZAURO C. RODRIGUEZ

REGULATED AREA CORRECTION REQUIRED

DISPOSAL SITE: NORTHERN WASCO COUNTY

Negative Pressure Enclosure: NO YES

LAND FILL

PRE ABATEMENT SAMPLE RESULTS:

(If Applicable)

PERSONAL AIR MONITORS USED: ()

DATE: _____

PROTECTIVE CLOTHING: ()

ANALYTICAL RESULTS: PCM TEM

PERSONNEL USING DECON: () N/A ()

SAMPLE NO. RESULTS (FIBERS/CC or STRUCTURES)

EXCESSIVE DEBRIS: ()

ENCAPSULATION ADEQUATE: ()

CRITICAL BARRIERS ADEQUATE: ()

NEGATIVE AIR ADEQUATE: () N/A ()

DECON ADEQUATE: () N/A ()

CLEAN ROOM ADEQUATE: () N/A ()

SHOWER FILTERED AND ADEQUATE: () N/A ()

SAMPLE NO.	RESULTS (FIBERS/CC or STRUCTURES)
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____

N/A

Personal Protective Equipment Worn By Inspector inside Regulated Area:

Respirator: 1/2 Face Full Face () PAPR () Type C ()

Disposable Coveralls:

Time of Inspection: _____

PASS:

FAIL:

VISUAL INSPECTION LOG (List any exceptions found during this inspection including: visible debris, location of debris found, containment integrity, excessive airborne encapsulant, damaged areas, etc.)

ONE 1/2" SPOT OF TSI ON 4" PIPE. WAS CLEANED. LOOKS GOOD

THREE RIVERS ENVIRONMENTAL representative certifies that he has visually inspected the specific work area (as mentioned above) and verifies that the inspection has been thorough and to the best of his knowledge and belief, has found no asbestos containing dust or debris.

NAME: IRVIN JONES

SIGNATURE: Irvin Jones



PROJ. No: 100-80

DATE: 10-29-99 Pg. 1 of

See air monitoring reports of this date

ASBESTOS PROJECT CHECKLIST

PROJECT NAME: WEST LINN HIGH SCHOOL

PROJ. MGR: IRVIN JONES

ON SITE: 1752 OFF SITE:

OWNER PROVIDED ON-SITE CONTACT:

CONTRACTOR: INSULATION REMOVAL CORPORATION

NAME: JOHN DAILY

SUPERVISOR: LIZAURO C. RODRIGUEZ

Intent to remove ACM on site and complete? Yes

Date Pre-abatement samples taken: N/A.

Disposal site: NORTHERN WASCO COUNTY LAND FILL

AREA ISOLATION

CORRECTION
REQUIRED

NO YES

BARRICADES & SIGNS:

AIRLOCKS: N/A

COVERINGS ON FLOORS & WALLS:

NON-MOVABLE EQUIP. COVERED: N/A

ALL OPENINGS SEALED:

AIR HANDLING EQUIP. OFF/SEALED:

PERSONNEL &
METHODS

CORRECTION
REQUIRED

NO YES

WORKER PROTECTION ADEQUATE:

PERSONAL AIR MONITORS USED:

PROTECTIVE CLOTHING:

PERSONNEL USING DECON: N/A

EQUIP. MAINTAINED PROPERLY:

WETTING, PRIOR & DURING:

EXCESSIVE DEBRIS:

BAGGING OPERATION:

NEGATIVE AIR ADEQUATE: N/A

DECON ADEQUATE: N/A

CLEAN ROOM ADEQUATE: N/A

SHOWER FILTERED AND ADEQUATE: N/A

Respiratory Protection in use:

1/2 Face Full Face PAPR Type C

PROJECT MANAGEMENT LOG

1730: IRC ARRIVED AT TRE OFFICE. LIZAURO RODRIGUEZ (SUPERVISOR) & BAUDEKIO GONZALEZ (WORKER).

1737: IRC & TRE (IRVIN JONES) DEPARTED THREE RIVERS ENVIRONMENTAL OFFICE, IN ROUTE TO WEST LINN HIGH SCHOOL.

1752: IRC & TRE ARRIVED AT WEST LINN HIGH SCHOOL

1755: IRC & TRE DISCUSSED SCOPE OF WORK. BOTH AGREED

1603: IRC PREPARING CONTAINMENT FOR BLUE BAKING. TRE STARTED PAPER WORK

SIGNATURE:
IRVIN JONES



Project Log

CLIENT: W.L. W. SD 3JT

TRE JOB NO: 1020-80

ATTN: TIM WOOLLEY

PURCHASE ORDER NO:

CONTRACTOR: IRC

REPORT DATE:

PROJECT: WEST LINN HIGH School

PAGE NO: 2 OF 2

AB HF & PIPE INSULATION REMOVAL

1840: TRE BROUGHT EQUIPMENT INTO SCHOOL Two HU-Pumps
ONE MICROSCOPE ONE QUICK FIX, 20, 20MM CASSETTS (RM)
TWO EXTENSION CORDS.

1900 CALIBRATED HU-23 STARTED SAMPLE #1 SW CORNER
OF MAZANINE.

2010 CONTAINMENT COMPLETE. GLOVE BAGS HUNG. READY TO START
ABATEMENT. IRC ON BREAK. TRE CHECKED GLOVE BAGS
LOOKS GOOD.

2020 IRC BACK FROM BREAK READY TO START ABATEMENT.

2020 CALIBRATED HU-22 STARTED SAMPLE #2 CENTER OF
CONTAINMENT.

2022 IRC STARTED ABATEMENT OF 5 HARD FITTINGS AND
APPROXIMATELY 25' OF PIPE INSULATION.

2100 CALIBRATED HU-23. STOPPED SAMPLE #1, STARTED SAMPLE
#3 SAME LOCATION AS SAMPLE #1.

2110 ABOUT 70% COMPLETE.

2145 ABATEMENT COMPLETE. CLEAN UP COMMENCING.

2215 ABATEMENT LOOKS GOOD. COMMENCING CLEAN UP.


2230 CLEAN UP COMPLETE.

2235 IRC OFF SITE.

2242 TRE OFF SITE.

2303 TRE (IRVIN JONES) AT TRE OFFICE.

Report by:


IRVIN JONES

FULL SCALE
(>40 ln. feet or 80 sq. feet)

ASBESTOS ABATEMENT SUMMARY
Work Order No.: 1020-45

Job Location: WEST LINN SCHOOL Floor: BOILER Rm, BASEMENT

Project: GLOVE BAG OF TSI IN BOILER Rm AND BOYS LOCKER Rm,
ABATEMENT OF MASTIC IN BOILER ROOM

For pipe provide: Total linear feet 240 LN FT and pipe size 4"

For other materials provide: Total square feet: 40 SQ FT

Type of ACM: TSI, SURF.

Start Date: MAY 7 1999 Completion Date: MAY 21, 1999

Methods to Control Emissions: GLOVE BAG, WET METHODS, HEPA VACUUM

Give name of Contractor or Subcontractor:

Name: KEYSTONE CONTRACTING INC.

Address: 417 NW 209th ST.

City: RIDGEFIELD State: WA, Zip: 98642

Phone: (360) 887-0868 Contact person: LARRY TINGLEY

Name of Monitoring Lab: THREE RIVERS ENVIRONMENTAL

Anticipated Disposal Site: HILLSBORD LANDFILL, HILLSBORD OR.

Supervisor in charge of job: BOB CRAFT, ROD STENSrud

Project Manager: MATT JOHNSON, ROBERT MONTGOMERY

Name: _____ Date: MAY, 7th, 18th, 21st 99 Phone: (503) 557-2396

Asbestos Program Manager: JOE SIMMONS

Name: _____ Date: _____ Phone: (503) 638-8869

Attach pre-abatement and post-abatement air sample results



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-45

ATTN: Joe Simmons

P.O. NO: Verbal

CONTRACTOR: Keystone Contracting, Inc. REPORT NO: 3

PROJECT: West Linn High School
Patch & Repair-Locker Room

PAGE NO: 1 OF 2

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 100fibers; Specification Range: 100-</math>f/mm2-</math>1300

SampleIDNo: 1	SampleIDNo: 2	SampleIDNo: 3	SampleIDNo: B1
LaboratoryNo: RM99-0256	LaboratoryNo: RM99-0257	LaboratoryNo: RM99-0258	LaboratoryNo: RM99-0259
Sample Location: 20' SE of W. double doors, boy's locker room AD	Sample Location: 40' N. of E. ramp entrance, boy's locker AD	Sample Location: Dale Dean 519-94-1112 EL	Sample Location: Blank
Work Performed: N/A	Work Performed: N/A	Work Performed: TSI Glovebag 1/2 face	Work Performed: N/A
Date Sampled: 5/21/1999	Date Sampled: 5/21/1999	Date Sampled: 5/21/1999	Date Sampled: 5/21/1999
Sampled by: R. Montgomery	Sampled by: R. Montgomery	Sampled by: R. Montgomery	Sampled by: R. Montgomery
PumpNo: HV-09	PumpNo: HV-03	PumpNo: LV-05	PumpNo: N/A
Start Time: 16:00	Start Time: 16:00	Start Time: 16:45	Start Time: N/A
Stop Time: 18:00	Stop Time: 18:00	Stop Time: 17:15	Stop Time: N/A
Minutes Sampled: 120	Minutes Sampled: 120	Minutes Sampled: 30	Minutes Sampled: N/A
Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 2	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 2	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 2	Average Flow Rate (LPM): N/A
Volume: 1200 L	Volume: 1200 L	Volume: 60 L	Volume: N/A L
Date Analyzed: 5/21/1999	Date Analyzed: 5/21/1999	Date Analyzed: 5/21/1999	Date Analyzed: 5/21/1999
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 7/100	Total Fibers: 9/100	Total Fibers: 2.5/100	Total Fibers: 0/100
Coefficient of Variation: LOQ	Coefficient of Variation: LOQ	Coefficient of Variation: LOD	Coefficient of Variation: N/A
Fibers/cc: <0.0039 f/cc	Fibers/cc: <0.0039 f/cc	Fibers/cc: 0.196 f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Robert Montgomery



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-45

ATTN: Joe Simmons

P.O. NO: Verbal

CONTRACTOR: Keystone Contracting, Inc. REPORT NO: 3

PROJECT: West Linn High School
Patch & Repair-Locker Room

PAGE NO: 2 OF 2

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers, Limit of Quantification: 10.0fibers, Specification Range: 100-</math>f/mm2</math>-1300

Sample ID No: B2	Sample ID No:	Sample ID No:	Sample ID No:
Laboratory No: RM99-0260	Laboratory No:	Laboratory No:	Laboratory No:
Sample Location: Blank	Sample Location:	Sample Location:	Sample Location:
Work Performed: N/A	Work Performed:	Work Performed:	Work Performed:
Date Sampled: 5/21/1999	Date Sampled:	Date Sampled:	Date Sampled:
Sampled by: R. Montgomery	Sampled by:	Sampled by:	Sampled by:
Pump No: N/A	Pump No:	Pump No:	Pump No:
Start Time: N/A	Start Time:	Start Time:	Start Time:
Stop Time: N/A	Stop Time:	Stop Time:	Stop Time:
Minutes Sampled: N/A	Minutes Sampled:	Minutes Sampled:	Minutes Sampled:
Start Flow Rate (LPM): N/A	Start Flow Rate (LPM):	Start Flow Rate (LPM):	Start Flow Rate (LPM):
Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):
Average Flow Rate (LPM): N/A	Average Flow Rate (LPM):	Average Flow Rate (LPM):	Average Flow Rate (LPM):
Volume: N/A L	Volume: L	Volume: L	Volume: L
Date Analyzed: 5/21/1999	Date Analyzed:	Date Analyzed:	Date Analyzed:
Graticule Field Area: 0.00817	Graticule Field Area:	Graticule Field Area:	Graticule Field Area:
Total Fibers: 0/100	Total Fibers:	Total Fibers:	Total Fibers:
Coefficient of Variation: N/A	Coefficient of Variation:	Coefficient of Variation:	Coefficient of Variation:
Fibers/cc: N/A f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasampleduring abatement, C-Clearance, P-Personalsample from breathing zone, EL-Excursion limit, NAE-Negativeaire exhaust, PA-postabatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Robert Montgomery

ASBESTOS ABATEMENT SUMMARY

Work Order No.: 1020-41

Job Location: WEST LINN HIGH SCHOOL Floor: MAIN BLDG, NW WING

Project: REMOVAL & DISPOSAL OF TSI BOILER/TANK INS., TSI LINE INSULATION

ACBM FLOOR TILE AND MASTIC AND ACBM WINDOW CASING AND CAULK THROUGHOUT BOYS LOCKER RM, BOILER RM, HVAC MECH SPACE TUNNELS AND ENTIRE NW SECTION OF SCHOOL
For pipe provide: Total linear feet 5980 and pipe size 2", 4", 6"

For other materials provide: Total square feet: 76,700

Type of ACM: TSI, MISC, SURE

Start Date: 22 MARCH 1999 Completion Date: 30 JULY 1999

Methods to Control Emissions: FULL CONTAINMENT, WET METHODS, HEPA VACUUM

Give name of Contractor or Subcontractor:

Name: PERFORMANCE ABATEMENT SERVICES

Address: 8015 SW HUNZIKER RD.

City: TILGARD State: ORE. Zip: 97223

Phone: (503) 620-7933 Contact person: MICHAEL STOCKER

Name of Monitoring Lab: THREE RIVERS ENVIRONMENTAL

Anticipated Disposal Site: HILLSBORO LANDFILL, HILLSBORO OR.

Supervisor in charge of job: MICHAEL SWAYZE

Project Manager: MATT JOHNSON, SAMM BLOCK, JOEL SHERIDAN

Name: Date: 22 MAR. - 30 JUL 99 Phone: (503) 557-2396

Asbestos Program Manager: JOE SIMMONS

Name: Date: Phone: (503) 638-8869

Attach pre-abatement and post-abatement air sample results

SUB-CONTRACTOR :

ROSE CITY CONTRACTING INC
8900 SW BURNHAM RD. #E-3
TILGARD OR. 97223
(503) 624-6527



Air Sample Analysis Report

CLIENT: Rose City Contracting

TRE JOB NO: 1490-12

ATTN: Andy Chaff

P.O. NO: Verbal

CONTRACTOR: Rose City Contracting

REPORT NO: 1

PROJECT: West Linn High School

PAGE NO: 1 OF 1

Method of analysis: NIOSH 7400 Limit of Detection: 5.5 Fibers Limit of Quantification: 10.0 fibers Specification Range: 100</math>/math>f/mm²<math><1300

SampleIDNo: 1	SampleIDNo: 2	SampleIDNo: B1	SampleIDNo: B2
LaboratoryNo: JS99-0045	LaboratoryNo: JS99-0046	LaboratoryNo: JS99-0047	LaboratoryNo: JS99-0048
Sample Location: Luis Reyes 673-92-7401 P	Sample Location: Luis Reyes 673-92-7401 P	Sample Location: Blank	Sample Location: Blank
Work Performed: Tile 1/2 mask	Work Performed: Tile 1/2 mask	Work Performed: N/A	Work Performed: N/A
Date Sampled: 6/28/99	Date Sampled: 6/28/99	Date Sampled: 6/28/99	Date Sampled: 6/28/99
Sampled by: Armondo	Sampled by: Armondo	Sampled by: J. Sheridan	Sampled by: J. Sheridan
PumpNo: N/A	PumpNo: N/A	PumpNo: N/A	PumpNo: N/A
StartTime: 07:00	StartTime: 12:00	StartTime: N/A	StartTime: N/A
StopTime: 12:00	StopTime: 17:00	StopTime: N/A	StopTime: N/A
Minutes Sampled: 300	Minutes Sampled: 300	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 750 L	Volume: 750 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 1/100	Total Fibers: 25/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: LOD	Coefficient of Variation: 0.44	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: 0.0063 f/cc	Fibers/cc: 0.016 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prio to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative airc exhaust, PA-post abatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting

TRE JOB NO: 1490-12

ATTN: Andy Chaff

P.O. NO: Verbal

CONTRACTOR: Rose City Contracting

REPORT NO: 2

PROJECT: West Linn High School

PAGE NO: 1 OF 1

Method of analysis: NIOSH 17400 Limit of Detection: 5.5 Fibers; Limit of Quantification: 100 fibers; Specification Range: 100 f/mm^2 - 1300

Sample ID No: 1	Sample ID No: 2	Sample ID No: B1	Sample ID No: B2
Laboratory No: JS99-0049	Laboratory No: JS99-0050	Laboratory No: JS99-0048	Laboratory No: JS99-0049
Sample Location: Luis Reyes 673-92-7401 P	Sample Location: Luis Reyes 673-92-7401 P	Sample Location: Blank	Sample Location: Blank
Work Performed: Tile & mastic 1/2 mask	Work Performed: Tile & mastic 1/2 mask	Work Performed: N/A	Work Performed: N/A
Date Sampled: 6/29/99	Date Sampled: 6/29/99	Date Sampled: 6/29/99	Date Sampled: 6/29/99
Sampled by: Armondo	Sampled by: Armondo	Sampled by: J. Sheridan	Sampled by: J. Sheridan
Pump No: N/A	Pump No: N/A	Pump No: N/A	Pump No: N/A
Start Time: 07:00	Start Time: 12:00	Start Time: N/A	Start Time: N/A
Stop Time: 12:00	Stop Time: 17:00	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 300	Minutes Sampled: 300	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 750 L	Volume: 750 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 14.5/100	Total Fibers: 10/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: 0.55	Coefficient of Variation: 0.63	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: 0.0091 f/cc	Fibers/cc: 0.0063 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Area sample prior to abatement, AD-Area sample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting

TRE JOB NO: 1490-12

ATTN: Andy Chaff

P.O. NO: Verbal

CONTRACTOR: Rose City Contracting

REPORT NO: 3

PROJECT: West Linn High School

PAGE NO: 1 OF 1

Method of analysis: NIOSH 7400 Limit of Detection: 5.5Fibers. Limit of Quantification: 10.0fibers. Specification Range: 100<f/mm2<1300

SampleIDNo: 1	SampleIDNo: 2	SampleIDNo: B1	SampleIDNo: B2
LaboratoryNo: JS99-0053	LaboratoryNo: JS99-0054	LaboratoryNo: JS99-0055	LaboratoryNo: JS99-0056
Sample Location: Miguel Tellez 472-37-2902 P	Sample Location: Miguel Tellez 472-37-2902 P	Sample Location: Blank	Sample Location: Blank
Work Performed Tile & mastic 1/2 mask	Work Performed Tile & mastic 1/2 mask	Work Performed N/A	Work Performed N/A
Date Sampled: 6/30/99	Date Sampled: 6/30/99	Date Sampled: 6/30/99	Date Sampled: 6/30/99
Sampled by: Armondo	Sampled by: Armondo	Sampled by: J. Sheridan	Sampled by: J. Sheridan
PumpNo: N/A	PumpNo: N/A	PumpNo: N/A	PumpNo: N/A
Start Time: 07:00	Start Time: 12:00	Start Time: N/A	Start Time: N/A
Stop Time: 12:00	Stop Time: 17:00	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 300	Minutes Sampled: 300	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 750 L	Volume: 750 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 14/100	Total Fibers: 12.5/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: 0.55	Coefficient of Variation: 0.58	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: 0.0088 f/cc	Fibers/cc: 0.0079 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting

TRE JOB NO: 1490-12

ATTN: Andy Chaff

P.O. NO: Verbal

CONTRACTOR: Rose City Contracting

REPORT NO: 4

PROJECT: West Linn High School

PAGE NO: 1 OF 1

Method of analysis: NIOSH 7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100-f/mm2<1300

SampleIDNo: 1	SampleIDNo: 2	SampleIDNo: B1	SampleIDNo: B2
LaboratoryNo: JS99-0057	LaboratoryNo: JS99-0058	LaboratoryNo: JS99-0059	LaboratoryNo: JS99-0060
Sample Location: Angel Barraza 544-27-1222 P	Sample Location: Angel Barraza 544-27-1222 P	Sample Location: Blank	Sample Location: Blank
Work Performed: Tile & mastic 1/2 mask	Work Performed: Tile & mastic 1/2 mask	Work Performed: N/A	Work Performed: N/A
Date Sampled: 7/6/99	Date Sampled: 7/6/99	Date Sampled: 7/6/99	Date Sampled: 7/6/99
Sampled by: Armondo	Sampled by: Armondo	Sampled by: J. Sheridan	Sampled by: J. Sheridan
PumpNo: N/A	PumpNo: N/A	PumpNo: N/A	PumpNo: N/A
Start Time: 07:00	Start Time: 12:00	Start Time: N/A	Start Time: N/A
Stop Time: 12:00	Stop Time: 17:00	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 300	Minutes Sampled: 300	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 750 L	Volume: 750 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 14.5/100	Total Fibers: 16/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: 0.55	Coefficient of Variation: 0.53	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: 0.0091 f/cc	Fibers/cc: 0.010 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting

TRE JOB NO: 1490-12

ATTN: Andy Chaff

P.O. NO: Verbal

CONTRACTOR: Rose City Contracting

REPORT NO: 5

PROJECT: West Linn High School

PAGE NO: 1 OF 1

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100<f/mm2<1300

SampleIDNo: 1	SampleIDNo: 2	SampleIDNo: B1	SampleIDNo: B2
LaboratoryNo: JS99-0061	LaboratoryNo: JS99-0062	LaboratoryNo: JS99-0063	LaboratoryNo: JS99-0064
Sample Location: Miguel Tellez 472-37-2901 P	Sample Location: Miguel Tellez 472-37-2901 P	Sample Location: Blank	Sample Location: Blank
Work Performed: Tile & mastic 1/2 mask	Work Performed: Tile & mastic 1/2 mask	Work Performed: N/A	Work Performed: N/A
Date Sampled: 7/7/99	Date Sampled: 7/7/99	Date Sampled: 7/7/99	Date Sampled: 7/7/99
Sampled by: Armondo	Sampled by: Armondo	Sampled by: J. Sheridan	Sampled by: J. Sheridan
Pump No: N/A	Pump No: N/A	Pump No: N/A	Pump No: N/A
Start Time: 07:00	Start Time: 12:00	Start Time: N/A	Start Time: N/A
Stop Time: 12:00	Stop Time: 17:00	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 300	Minutes Sampled: 300	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 750 L	Volume: 750 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 20/100	Total Fibers: 10.5/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: 0.48	Coefficient of Variation: 0.62	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: 0.013 f/cc	Fibers/cc: 0.0066 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting
 ATTN: Andy Chaff
 CONTRACTOR: Rose City Contracting
 PROJECT: West Linn High School

TRE JOB NO: 1490-12
 P.O. NO: Verbal
 REPORT NO: 6
 PAGE NO: 1 OF 1

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers. Limit of Quantification: 10.0fibers. Specification Range: 100</math>/math>f/mm2<1300

SampleIDNo: 1	SampleIDNo: B1	SampleIDNo: B2	SampleIDNo: 2
LaboratoryNo: JS99-0065	LaboratoryNo: JS99-0066	LaboratoryNo: JS99-0067	LaboratoryNo: *
Sample Location: Luis Reyes 673-92-7401 P	Sample Location: Blank	Sample Location: Blank	Sample Location: Missing
Work Performed Tile & mastic 1/2 mask	Work Performed N/A	Work Performed N/A	Work Performed *
Date Sampled: 7/8/99	Date Sampled: 7/8/99	Date Sampled: 7/8/99	Date Sampled: *
Sampled by: Armondo	Sampled by: J. Sheridan	Sampled by: J. Sheridan	Sampled by: *
PumpNo: N/A	PumpNo: N/A	PumpNo: N/A	PumpNo: *
Start Time: 07:00	Start Time: N/A	Start Time: N/A	Start Time: *
Stop Time: 12:00	Stop Time: N/A	Stop Time: N/A	Stop Time: *
Minutes Sampled: 300	Minutes Sampled: N/A	Minutes Sampled: N/A	Minutes Sampled: *
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): *
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): *
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): *
Volume: 750 L	Volume: N/A L	Volume: N/A L	Volume: * L
Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99	Date Analyzed: 7/13/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 17.5/100	Total Fibers: 0/100	Total Fibers: 0/100	Total Fibers: *
Coefficient of Variation: 0.61	Coefficient of Variation: N/A	Coefficient of Variation: N/A	Coefficient of Variation: *
Fibers/cc: 0.011 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc	Fibers/cc: * f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-postabatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: *Sample #2 from 7/8/99 has been lost

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting
 ATTN: Andy Chaff
 CONTRACTOR: Rose City Contracting
 PROJECT: West Linn High School

TRE JOB NO: 1490-12
 P.O. NO: Verbal
 REPORT NO: 7
 PAGE NO: 1 OF 1

Method of analysis: NIOSH 17400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100<f/mm2<1300

Sample ID No: 1	Sample ID No: 2	Sample ID No: B1	Sample ID No: B2
Laboratory No: JS99-0163	Laboratory No: JS99-0164	Laboratory No: JS99-0291	Laboratory No: JS99-0292
Sample Location: Angel Borraza 544-27-1222 P	Sample Location: Angel Borraza 544-27-1222 P	Sample Location: Blank	Sample Location: Blank
Work Performed: Tile & mastic removal	Work Performed: Tile & mastic removal	Work Performed: N/A	Work Performed: N/A
Date Sampled: 7/9/99	Date Sampled: 7/9/99	Date Sampled: 7/9/99	Date Sampled: 7/9/99
Sampled by: A. Reyes	Sampled by: A. Reyes	Sampled by: J. Sheridan	Sampled by: J. Sheridan
Pump No: 1	Pump No: 1	Pump No: N/A	Pump No: N/A
Start Time: 07:00	Start Time: 12:00	Start Time: N/A	Start Time: N/A
Stop Time: 12:00	Stop Time: 17:00	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 300	Minutes Sampled: 300	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 750 L	Volume: 750 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 7.5/100	Total Fibers: 10.5/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: LOQ	Coefficient of Variation: 0.62	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: 0.0047 f/cc	Fibers/cc: 0.0066 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting

TRE JOB NO: 1490-12

ATTN: Andy Chaff

P.O. NO: Verbal

CONTRACTOR: Rose City Contracting

REPORT NO: 8

PROJECT: West Linn High School

PAGE NO: 1 OF 1

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers Limit of Quantification: 10.0fibers. Specification Range: 100</math>f/mm²<math>1300

SampleIDNo:	SampleIDNo:	SampleIDNo:	SampleIDNo:
1	2	B1	B2
LaboratoryNo: JS99-0165	LaboratoryNo: JS99-0166	LaboratoryNo: JS99-0293	LaboratoryNo: JS99-0294
Sample Location: Miguel Telles 412-37-2901 P	Sample Location: Miguel Telles 412-37-2901 P	Sample Location: Blank	Sample Location: Blank
Work Performed: Tile & mastic removal	Work Performed: Tile & mastic removal	Work Performed: N/A	Work Performed: N/A
Date Sampled: 7/12/99	Date Sampled: 7/12/99	Date Sampled: 7/12/99	Date Sampled: 7/12/99
Sampled by: A. Reyes	Sampled by: A. Reyes	Sampled by: J. Sheridan	Sampled by: J. Sheridan
PumpNo: 1	PumpNo: 1	PumpNo: N/A	PumpNo: N/A
Start Time: 07:00	Start Time: 12:00	Start Time: N/A	Start Time: N/A
Stop Time: 12:00	Stop Time: 17:00	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 300	Minutes Sampled: 300	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 750 L	Volume: 750 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 19/100	Total Fibers: 14.5/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: 0.49	Coefficient of Variation: 0.55	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: 0.012 f/cc	Fibers/cc: 0.0091 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting

TRE JOB NO: 1490-12

ATTN: Andy Chaff

P.O. NO: Verbal

CONTRACTOR: Rose City Contracting

REPORT NO: 9

PROJECT: West Linn High School

PAGE NO: 1 OF 1

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 100fibers; Specification Range: 100</math>f/mm2<math>1300

Sample ID No: 1	Sample ID No: 2	Sample ID No: B1	Sample ID No: B2
Laboratory No: JS99-0295	Laboratory No: JS99-0296	Laboratory No: JS99-0295	Laboratory No: JS99-0296
Sample Location: Miguel Telles 412-37-2901 P	Sample Location: Miguel Telles 412-37-2901 P	Sample Location: Blank	Sample Location: Blank
Work Performed: Tile & mastic removal	Work Performed: Tile & mastic removal	Work Performed: N/A	Work Performed: N/A
Date Sampled: 7/13/99	Date Sampled: 7/13/99	Date Sampled: 7/13/99	Date Sampled: 7/13/99
Sampled by: A. Reyes	Sampled by: A. Reyes	Sampled by: J. Sheridan	Sampled by: J. Sheridan
Pump No: 1	Pump No: 1	Pump No: N/A	Pump No: N/A
Start Time: 07:00	Start Time: 12:00	Start Time: N/A	Start Time: N/A
Stop Time: 12:00	Stop Time: 17:00	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 300	Minutes Sampled: 300	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 750 L	Volume: 750 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 8/100	Total Fibers: 9/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: LOQ	Coefficient of Variation: LOQ	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: 0.0050 f/cc	Fibers/cc: 0.0057 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Area sample prior to abatement, AD-Area sample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting

TRE JOB NO: 1490-12

ATTN: Andy Chaff

P.O. NO: Verbal

CONTRACTOR: Rose City Contracting

REPORT NO: 10

PROJECT: West Linn High School

PAGE NO: 1 OF 1

Method of analysis: NIOSH 7400 Limit of Detection: 5.5Fibers Limit of Quantification: 10.0fibers Specification Range: 100<f/mm2<1300

SampleIDNo: 1	SampleIDNo: 2	SampleIDNo: B1	SampleIDNo: B2
LaboratoryNo: JS99-0169	LaboratoryNo: JS99-0170	LaboratoryNo: JS99-0297	LaboratoryNo: JS99-0298
Sample Location: Angel Borraza 544-87-1222 EX	Sample Location: Angel Borraza 544-87-1222 P	Sample Location: Blank	Sample Location: Blank
Work Performed Tile & mastic removal	Work Performed Tile & mastic removal	Work Performed N/A	Work Performed N/A
Date Sampled: 7/19/99	Date Sampled: 7/19/99	Date Sampled: 7/19/99	Date Sampled: 7/19/99
Sampled by: A. Reyes	Sampled by: A. Reyes	Sampled by: J. Sheridan	Sampled by: J. Sheridan
Pump No: 1	Pump No: 1	Pump No: N/A	Pump No: N/A
Start Time: 11:30	Start Time: 12:00	Start Time: N/A	Start Time: N/A
Stop Time: 12:00	Stop Time: 16:30	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 30	Minutes Sampled: 270	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 75 L	Volume: 675 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 20/100	Total Fibers: 5/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: 0.48	Coefficient of Variation: LOQ	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: 0.13 f/cc	Fibers/cc: 0.0035 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting

TRE JOB NO: 1490-12

ATTN: Andy Chaff

P.O. NO: Verbal

CONTRACTOR: Rose City Contracting

REPORT NO: 11

PROJECT: West Linn High School

PAGE NO: 1 OF 2

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100<f/mm2<1300

SampleIDNo: 1	SampleIDNo: 2	SampleIDNo: 3	SampleIDNo: B1
LaboratoryNo: JS99-0171	LaboratoryNo: JS99-0172	LaboratoryNo: JS99-0173	LaboratoryNo: JS99-0299
Sample Location: Jose Sanchez 542-55-4880 EX	Sample Location: Jose Sanchez 542-55-4880 P	Sample Location: Jose Sanchez 542-55-4880 P	Sample Location: Blank
Work Performed: Tile & mastic removal	Work Performed: Tile & mastic removal	Work Performed: Tile & mastic removal	Work Performed: N/A
Date Sampled: 7/20/99	Date Sampled: 7/20/99	Date Sampled: 7/20/99	Date Sampled: 7/20/99
Sampled by: A. Reyes	Sampled by: A. Reyes	Sampled by: A. Reyes	Sampled by: J. Sheridan
PumpNo: 1	PumpNo: 1	PumpNo: 1	PumpNo: N/A
Start Time: 07:00	Start Time: 07:30	Start Time: 12:30	Start Time: N/A
Stop Time: 07:30	Stop Time: 12:30	Stop Time: 17:30	Stop Time: N/A
Minutes Sampled: 30	Minutes Sampled: 300	Minutes Sampled: 300	Minutes Sampled: N/A
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A
Volume: 75 L	Volume: 750 L	Volume: 750 L	Volume: N/A L
Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 9/100	Total Fibers: 15.5/100	Total Fibers: 17.5/100	Total Fibers: 0/100
Coefficient of Variation: LOQ	Coefficient of Variation: 0.53	Coefficient of Variation: 0.51	Coefficient of Variation: N/A
Fibers/cc: 0.057 f/cc	Fibers/cc: 0.0097 f/cc	Fibers/cc: 0.010 f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negativeaire exhaust, PA-post abatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting

TRE JOB NO: 1490-12

ATTN: Andy Chaff

P.O. NO: Verbal

CONTRACTOR: Rose City Contracting

REPORT NO: 11

PROJECT: West Linn High School

PAGE NO: 2 OF 2

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 100fibers; Specification Range: 100<f/mm2<1300

Sample ID No: B2	Sample ID No:	Sample ID No:	Sample ID No:
Laboratory No: JS99-0300	Laboratory No:	Laboratory No:	Laboratory No:
Sample Location: Blank	Sample Location:	Sample Location:	Sample Location:
Work Performed: N/A	Work Performed:	Work Performed:	Work Performed:
Date Sampled: 7/20/99	Date Sampled:	Date Sampled:	Date Sampled:
Sampled by: J. Sheridan	Sampled by:	Sampled by:	Sampled by:
Pump No: N/A	Pump No:	Pump No:	Pump No:
Start Time: N/A	Start Time:	Start Time:	Start Time:
Stop Time: N/A	Stop Time:	Stop Time:	Stop Time:
Minutes Sampled: N/A	Minutes Sampled:	Minutes Sampled:	Minutes Sampled:
Start Flow Rate (LPM): N/A	Start Flow Rate (LPM):	Start Flow Rate (LPM):	Start Flow Rate (LPM):
Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):
Average Flow Rate (LPM): N/A	Average Flow Rate (LPM):	Average Flow Rate (LPM):	Average Flow Rate (LPM):
Volume: N/A L	Volume: L	Volume: L	Volume: L
Date Analyzed: 7/27/99	Date Analyzed:	Date Analyzed:	Date Analyzed:
Graticule Field Area: 0.00817	Graticule Field Area:	Graticule Field Area:	Graticule Field Area:
Total Fibers: 0/100	Total Fibers:	Total Fibers:	Total Fibers:
Coefficient of Variation: N/A	Coefficient of Variation:	Coefficient of Variation:	Coefficient of Variation:
Fibers/cc: N/A f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc

Abbreviations: AP-Areasample prio to abatement, AD-Area sample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting
ATTN: Andy Chaff
CONTRACTOR: Rose City Contracting
PROJECT: West Linn High School

TRE JOB NO: 1490-12
P.O. NO: Verbal
REPORT NO: 12
PAGE NO: 1 OF 2

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers. Limit of Quantification: 10.0fibers; Specification Range: 100<f/mm2<1300

SampleIDNo:	SampleIDNo:	SampleIDNo:	SampleIDNo:
1	2	3	B1
LaboratoryNo: JS99-0174	LaboratoryNo: JS99-0175	LaboratoryNo: JS99-0176	LaboratoryNo: JS99-0177
Sample Location: Jose Sanchez 542-55-4880 EX	Sample Location: Jose Sanchez 542-55-4880 P	Sample Location: Jose Sanchez 542-55-4880 P	Sample Location: Blank
Work Performed: Tile & mastic removal	Work Performed: Tile & mastic removal	Work Performed: Tile & mastic removal	Work Performed: N/A
Date Sampled: 7/22/99	Date Sampled: 7/22/99	Date Sampled: 7/22/99	Date Sampled: 7/22/99
Sampled by: A. Reyes	Sampled by: A. Reyes	Sampled by: A. Reyes	Sampled by: J. Sheridan
PumpNo: 1	PumpNo: 1	PumpNo: 1	PumpNo: N/A
Start Time: 07:00	Start Time: 07:30	Start Time: 12:30	Start Time: N/A
Stop Time: 07:30	Stop Time: 12:30	Stop Time: 17:30	Stop Time: N/A
Minutes Sampled: 30	Minutes Sampled: 300	Minutes Sampled: 300	Minutes Sampled: N/A
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A
Volume: 75 L	Volume: 750 L	Volume: 750 L	Volume: N/A L
Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99	Date Analyzed: 7/27/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 6/100	Total Fibers: 12.5/100	Total Fibers: 42.5/100	Total Fibers: 0/100
Coefficient of Variation: LOQ	Coefficient of Variation: 0.58	Coefficient of Variation: 0.36	Coefficient of Variation: N/A
Fibers/cc: 0.038 f/cc	Fibers/cc: 0.0079 f/cc	Fibers/cc: 0.026 f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-postabatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting

TRE JOB NO: 1490-12

ATTN: Andy Chaff

P.O. NO: Verbal

CONTRACTOR: Rose City Contracting

REPORT NO: 12

PROJECT: West Linn High School

PAGE NO: 2 OF 2

Method of analysis: NIOSH 7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100<f/mm2<1300

Sample ID No: B2	Sample ID No:	Sample ID No:	Sample ID No:
Laboratory No: JS99-0178	Laboratory No:	Laboratory No:	Laboratory No:
Sample Location: Blank	Sample Location:	Sample Location:	Sample Location:
Work Performed: N/A	Work Performed:	Work Performed:	Work Performed:
Date Sampled: 7/22/99	Date Sampled:	Date Sampled:	Date Sampled:
Sampled by: J. Sheridan	Sampled by:	Sampled by:	Sampled by:
Pump No: N/A	Pump No:	Pump No:	Pump No:
Start Time: N/A	Start Time:	Start Time:	Start Time:
Stop Time: N/A	Stop Time:	Stop Time:	Stop Time:
Minutes Sampled: N/A	Minutes Sampled:	Minutes Sampled:	Minutes Sampled:
Start Flow Rate (LPM): N/A	Start Flow Rate (LPM):	Start Flow Rate (LPM):	Start Flow Rate (LPM):
Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):
Average Flow Rate (LPM): N/A	Average Flow Rate (LPM):	Average Flow Rate (LPM):	Average Flow Rate (LPM):
Volume: N/A L	Volume: L	Volume: L	Volume: L
Date Analyzed: 7/27/99	Date Analyzed:	Date Analyzed:	Date Analyzed:
Graticule Field Area: 0.00817	Graticule Field Area:	Graticule Field Area:	Graticule Field Area:
Total Fibers: 0/100	Total Fibers:	Total Fibers:	Total Fibers:
Coefficient of Variation: N/A	Coefficient of Variation:	Coefficient of Variation:	Coefficient of Variation:
Fibers/cc: N/A f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc

Abbreviations: AP-Area sample prior to abatement, AD-Area sample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: **Joel Sheridan**



Air Sample Analysis Report

CLIENT: Rose City Contracting
 ATTN: Andy Chaff
 CONTRACTOR: Rose City Contracting
 PROJECT: West Linn High School

TRE JOB NO: 1490-13
 P.O. NO: Verbal
 REPORT NO: 1
 PAGE NO: 1 OF 1

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100<f/mm2<1300

SampleIDNo: 1	SampleIDNo: B1	SampleIDNo: B2	SampleIDNo:
LaboratoryNo: JS99-0277	LaboratoryNo: JS99-0278	LaboratoryNo: JS99-0279	LaboratoryNo:
Sample Location: Armondo Reyes 521-05-2847 P	Sample Location: Blank	Sample Location: Blank	Sample Location:
Work Performed Transite clean-up 1/2 mask	Work Performed N/A	Work Performed N/A	Work Performed:
Date Sampled: 8/10/99	Date Sampled: 8/10/99	Date Sampled: 8/10/99	Date Sampled:
Sampled by: Armondo	Sampled by: J. Sheridan	Sampled by: J. Sheridan	Sampled by:
Pump No: N/A	Pump No: N/A	Pump No: N/A	Pump No:
Start Time: 03:00	Start Time: N/A	Start Time: N/A	Start Time:
Stop Time: 07:00	Stop Time: N/A	Stop Time: N/A	Stop Time:
Minutes Sampled: 240	Minutes Sampled: N/A	Minutes Sampled: N/A	Minutes Sampled:
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM):
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM):
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM):
Volume: 600 L	Volume: N/A L	Volume: N/A L	Volume: L
Date Analyzed: 8/11/99	Date Analyzed: 8/11/99	Date Analyzed: 8/11/99	Date Analyzed:
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area:
Total Fibers: 18/100	Total Fibers: 0/100	Total Fibers: 0/100	Total Fibers:
Coefficient of Variation: 0.5	Coefficient of Variation: N/A	Coefficient of Variation: N/A	Coefficient of Variation:
Fibers/cc: 0.014 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc	Fibers/cc: f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: Contractor's samples

Analyzed by: Joel Sheridan



Air Sample Analysis Report

CLIENT: Rose City Contracting
 ATTN: Andy Chaff
 CONTRACTOR: Rose City Contracting
 PROJECT: West Linn High School

TRE JOB NO: 1490-13
 P.O. NO: Verbal
 REPORT NO: 2
 PAGE NO: 1 OF 1

Method of analysis: NIOSH 7400 Limit of Detection: 5.5Fibers, Limit of Quantification: 10.0fibers, Specification Range: 100<f/mm2<1300

SampleIDNo: 1	SampleIDNo: B1	SampleIDNo: B2	SampleIDNo:
LaboratoryNo: JS99-0280	LaboratoryNo: JS99-0281	LaboratoryNo: JS99-0282	LaboratoryNo:
Sample Location: Luis Reyes 673-92-7401 P	Sample Location: Blank	Sample Location: Blank	Sample Location:
Work Performed: Transite clean-up 1/2 mask	Work Performed: N/A	Work Performed: N/A	Work Performed:
Date Sampled: 8/11/99	Date Sampled: 8/11/99	Date Sampled: 8/11/99	Date Sampled:
Sampled by: Armondo	Sampled by: J. Sheridan	Sampled by: J. Sheridan	Sampled by:
PumpNo: N/A	PumpNo: N/A	PumpNo: N/A	PumpNo:
Start Time: 11:00	Start Time: N/A	Start Time: N/A	Start Time:
Stop Time: 12:00	Stop Time: N/A	Stop Time: N/A	Stop Time:
Minutes Sampled: 60	Minutes Sampled: N/A	Minutes Sampled: N/A	Minutes Sampled:
Start Flow Rate (LPM): 2.5	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM):
Stop Flow Rate (LPM): 2.5	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM):
Average Flow Rate (LPM): 2.5	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM):
Volume: 150 L	Volume: N/A L	Volume: N/A L	Volume: L
Date Analyzed: 8/11/99	Date Analyzed: 8/11/99	Date Analyzed: 8/11/99	Date Analyzed:
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area:
Total Fibers: 10/100	Total Fibers: 0/100	Total Fibers: 0/100	Total Fibers:
Coefficient of Variation: 0.63	Coefficient of Variation: N/A	Coefficient of Variation: N/A	Coefficient of Variation:
Fibers/cc: 0.031 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc	Fibers/cc: f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personalsample from breathing zone, EL-Excursion limit, NAE-Negativeaire exhaust, PA-postabatementareaisample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: Contractor's samples

Analyzed by: Joel Sheridan

ASBESTOS ABATEMENT SUMMARY
Work Order No.: 1020-67

Job Location: WEST LINN HIGH SCHOOL Floor: EXCAVATION AREA

Project: TSI REMOVAL TUNNEL SYSTEM EXPOSED DURING
EXCAVATION OF NW CORNER OF ROTUNDA

For pipe provide: Total linear feet 250 WFT and pipe size 4"

For other materials provide: Total square feet: _____

Type of ACM: TSI, DEBRIS

Start Date: 9-24-99 Completion Date: 9-24-99

Methods to Control Emissions: WET METHODS

Give name of Contractor or Subcontractor:

Name: KEYSTONE CONTRACTING INC.

Address: 417 NW 209TH STREET

City: RIDGEFIELD State: WA. Zip: 98642

Phone: (360) 887-0868 Contact person: LARRY TINGLEY

Name of Monitoring Lab: THREE RIVERS ENVIRONMENTAL

Anticipated Disposal Site: HILLSBORD LANDFILL, HILLSBORD OR.

Supervisor in charge of job: DALE DEAN

Project Manager: ROBERT MONTGOMERY

Name: _____ Date: 9-24-99 Phone: (503) 557-2396

Asbestos Program Manager: JOE SIMMONS

Name: _____ Date: _____ Phone: (503) 638-8869

Attach pre-abatement and post-abatement air sample results



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-67
 ATTN: Joe Simmons P.O. NO: Verbal
 CONTRACTOR: Keystone Contracting, Inc. REPORT NO: 1
 PROJECT: West Linn High School Excavation Area
 TSI removal in tunnel PAGE NO: 1 OF 2

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0 fibers; Specification Range: 100<f/mm2<1300

SampleIDNo: 1	SampleIDNo: 2	SampleIDNo: 3	SampleIDNo: 4
LaboratoryNo: RM99-0873	LaboratoryNo: RM99-0874	LaboratoryNo: RM99-0875	LaboratoryNo: RM99-0876
Sample Location: 25' SW of rotunda W. side excavation area AD	Sample Location: 20' W. of rotunda W. side excavation site AD	Sample Location: Carlos Mendoza 610-28-9238 EL	Sample Location: Carlos Mendoza 610-28-9238 P
Work Performed N/A	Work Performed N/A	Work Performed Glovebag 1/2 face	Work Performed Glovebag 1/2 face
Date Sampled: 9/22/99	Date Sampled: 9/22/99	Date Sampled: 9/22/99	Date Sampled: 9/22/99
Sampled by: R. Montgomery	Sampled by: R. Montgomery	Sampled by: R. Montgomery	Sampled by: R. Montgomery
PumpNo: HV-23	PumpNo: HV-22	PumpNo: LV-03	PumpNo: LV-03
Start Time: 17:40	Start Time: 17:45	Start Time: 19:00	Start Time: 19:30
Stop Time: 19:45	Stop Time: 19:45	Stop Time: 19:30	Stop Time: 21:45
Minutes Sampled: 125	Minutes Sampled: 120	Minutes Sampled: 30	Minutes Sampled: 135
Start Flow Rate (LPM): 12	Start Flow Rate (LPM): 12	Start Flow Rate (LPM): 2	Start Flow Rate (LPM): 2
Stop Flow Rate (LPM): 12	Stop Flow Rate (LPM): 12	Stop Flow Rate (LPM): 2	Stop Flow Rate (LPM): 2
Average Flow Rate (LPM): 12	Average Flow Rate (LPM): 12	Average Flow Rate (LPM): 2	Average Flow Rate (LPM): 2
Volume: 1500 L	Volume: 1440 L	Volume: 60 L	Volume: 270 L
Date Analyzed: 9/23/99	Date Analyzed: 9/23/99	Date Analyzed: 9/23/99	Date Analyzed: 9/23/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 6/100	Total Fibers: 2.5/100	Total Fibers: 2.5/100	Total Fibers: 12/100
Coefficient of Variation: LOQ	Coefficient of Variation: LOD	Coefficient of Variation: LOD	Coefficient of Variation: 0.59
Fibers/cc: <0.0031 f/cc	Fibers/cc: <0.0033 f/cc	Fibers/cc: 0.020 f/cc	Fibers/cc: 0.021 f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negativeaire exhaust, PA-postabatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Robert Montgomery

Air Sample Analysis Report



CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-67

ATTN: Joe Simmons

P.O. NO: Verbal

CONTRACTOR: Keystone Contracting, Inc. REPORT NO: 1

PROJECT: West Linn High School
Excavation Area
TSI removal in tunnel

PAGE NO: 2 OF 2

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100-<f/mm2<1300

Sample ID No: 5	Sample ID No: 6	Sample ID No: B1	Sample ID No: B2
Laboratory No: RM99-0877	Laboratory No: RM99-0878	Laboratory No: RM99-0879	Laboratory No: RM99-0880
Sample Location: 25' SW of rotunda in excavation area AD	Sample Location: 20' W. of rotunda in excavation area AD	Sample Location: Blank	Sample Location: Blank
Work Performed: N/A	Work Performed: N/A	Work Performed: N/A	Work Performed: N/A
Date Sampled: 9/22/99	Date Sampled: 9/22/99	Date Sampled: 9/22/99	Date Sampled: 9/22/99
Sampled by: R. Montgomery	Sampled by: R. Montgomery	Sampled by: R. Montgomery	Sampled by: R. Montgomery
Pump No: HV-23	Pump No: HV-22	Pump No: N/A	Pump No: N/A
Start Time: 19:45	Start Time: 19:45	Start Time: N/A	Start Time: N/A
Stop Time: 21:45	Stop Time: 21:45	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 120	Minutes Sampled: 120	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 12	Start Flow Rate (LPM): 12	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 12	Stop Flow Rate (LPM): 12	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 12	Average Flow Rate (LPM): 12	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 1440 L	Volume: 1440 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 9/23/99	Date Analyzed: 9/23/99	Date Analyzed: 9/23/99	Date Analyzed: 9/23/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 8/100	Total Fibers: 17.5/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: LOQ	Coefficient of Variation: 0.51	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: <0.0033 f/cc	Fibers/cc: 0.0060 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Robert Montgomery



PROJ. No: 1020-67
 DATE: 9-22-99 Pg. 1 of 2
 See air monitoring reports of this date

ASBESTOS PROJECT CHECKLIST

PROJECT NAME: WEST LIND HIGHS SCHOOL, TSI
REMOVAL TUNNEL EXCAVATION AT NEW
CONSTRUCTION SITE.
 OWNER PROVIDED ON-SITE CONTACT:
 NAME: JOE SIMMONS

PROJ. MGR: ROBERT C. MONTGOMERY
1730
 ON SITE: 5:30 OFF SITE: 2300
 CONTRACTOR: KEYSTONE CONTRACTING
 SUPERVISOR: DALE DEAN

Intent to remove ACM on site and complete? YES
 Date Pre-abatement samples taken: _____
 Disposal site: HILLSBORO LANDFILL, HILLSBORO OR

	CORRECTION REQUIRED	
	NO	YES
<u>PERSONNEL & METHODS</u>		
WORKER PROTECTION ADEQUATE:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PERSONAL AIR MONITORS USED:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PROTECTIVE CLOTHING:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PERSONNEL USING DECON:	<input type="checkbox"/>	<input type="checkbox"/>
EQUIP. MAINTAINED PROPERLY:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
WETTING, PRIOR & DURING:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
EXCESSIVE DEBRIS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
BAGGING OPERATION:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
NEGATIVE AIR ADEQUATE:	<input type="checkbox"/>	<input type="checkbox"/>
DECON ADEQUATE:	<input type="checkbox"/>	<input type="checkbox"/>
CLEAN ROOM ADEQUATE:	<input type="checkbox"/>	<input type="checkbox"/>
SHOWER FILTERED AND ADEQUATE:	<input type="checkbox"/>	<input type="checkbox"/>
Respiratory Protection in use:		
1/2 Face <input checked="" type="checkbox"/> Full Face <input type="checkbox"/> PAPR <input type="checkbox"/> Type C <input type="checkbox"/>		

<u>AREA ISOLATION</u>	CORRECTION REQUIRED	
	NO	YES
BARRICADES & SIGNS:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
AIRLOCKS:	<input type="checkbox"/>	<input type="checkbox"/>
COVERINGS ON FLOORS & WALLS:	<input type="checkbox"/>	<input type="checkbox"/>
NON-MOVABLE EQUIP. COVERED:	<input type="checkbox"/>	<input type="checkbox"/>
ALL OPENINGS SEALED:	<input type="checkbox"/>	<input type="checkbox"/>
AIR HANDLING EQUIP. OFF/SEALED:	<input type="checkbox"/>	<input type="checkbox"/>

PROJECT MANAGEMENT LOG

1730: ARRIVED AT WEST LIND HIGH SCHOOL TO ASSESS THE AMOUNT OF TSI PIPE TO REMOVE. DALE DEAN SUPERVISOR, CARLOS MENDOZA, JOE SIMMONS & BOB C ARE THE MEMBERS FROM KEYSTONE ASSIGNED TO ABATE THIS MATERIAL. CERTIFICATION/MEDICALS CURRENT

1740: STARTED/CALIBRATED HV-23 WITH SAMPLE #1 20' SW OF ROTUNDA ON THE CONSTRUCTION SITE.

1745: STARTED/CALIBRATED HV-22 WITH SAMPLE #2 20' W OF ROTUNDA ON THE CONSTRUCTION SITE. DALE DEAN AND I WALKED OFF THE AMOUNT OF PIPING EXPOSED AND CONSERVATIVELY PUT THE LENGTH ABOVE 80' L.F. THE PLAN IS TO CUT AND WRAP EXPOSED NIDES THEN DIG-OUT WHAT HASNT BEEN EXPOSED.

SIGNATURE: [Signature]

Project Log



THREE RIVERS
ENVIRONMENTAL

CLIENT:

TRE JOB NO:

ATTN:

PURCHASE ORDER NO:

CONTRACTOR:

REPORT DATE:

PROJECT:

PAGE NO: OF

1830: THE CREW IS CUTTING AND WRAPPING NUMEROUS SECTIONS. THEY HAVE GLOVE BAGGED THE JOBS AND HAVE TAPED OFF THE ENDS SO AS TO FACILITATE CUTTING OF THE LINES.

1900: ~~STILL~~ QUITE A BIT OF AS DEBRIS IS SCATTERED THROUGHOUT THE IMMEDIATE AREA, AND REQUIRES QUITE A BIT OF WEETING AND RETRIEVING. STARTED EL ON CARLOS.

1930 PULLED THE EL SAMPLE OF CARLOS MENDOZA

1945: RE-CALIBRATED AND PULLED SAMPLES #1 AND #2 RESTARTED AND CALIBRATED SAMPLE #5 ON HU-23 AND SAMPLE #6 ON HU-22 SAME LOCATIONS.

2000: CREW IS NOW CUTTING AND WRAPPING LINES WHICH ARE ACCESSIBLE. THE LINES WHICH ARE ABOVE GROUND ARE BEING GLOVE BAGGED AND CLEANED AS THEY GO. TO COMPLETE THE JOB WILL REQUIRE THE REMAINING SLAB TO BE PULLED OFF AND THE DEBRIS REMOVED FROM THE CHASE BEFORE ALL OF THE ASSUMED MATERIAL CAN BE REMOVED.

2030: DALE AND JOSE ARE DISCOVERING MORE AND MORE TSI LINE AS THEY PREPARE EXPOSED PIPE TO BE CUT.

2045: CARLOS HAS FINISHED CUTTING ALL THE EXPOSED TSI LINE AND ALL OF THE CREW IS NOW BAGGING AND WRAPPING FREE PIPING TO BE LOADED AND REMOVED.

2100: CREW IS STILL BAGGING MATERIAL AND EXPOSING MORE PIPE.

2130: THE EXPOSED PIPE HAS BEEN CLEANED AND STACKED. TOMMORROW THE EXCAVATION CREW WILL NEED TO PEEL BACK MORE OF THE CEMENT AND EXPOSE THE REMAINING TSI LINES.

2200: THE BAGGING OPERATION IS GOING FINE, WE'VE SLOWED A BIT BECAUSE OF THE AMOUNT OF DEBRIS AND THE REBAR WITHIN THE AREA.

2230: FINAL CLEAN-UP AND LOADING OF DEBRIS IS BEING ACCOMPLISHED. FINAL INSP. WILL FOLLOW.

2245: PREPARING TO DEMOBOLIZE.

2300: DEPARTING THE HIGH SCHOOL

Report by:

Robert C. Young



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District **TRE JOB NO:** 1020-67
ATTN: Joe Simmons **P.O. NO:** Verbal
CONTRACTOR: Keystone Contracting, Inc. **REPORT NO:** 2
PROJECT: West Linn High School **PAGE NO:** 1 OF 3
 Excavation Area
 TSI removal in tunnel

Method of analysis: NIOSH 7400 Limit of Detection: 5.5 Fibers; Limit of Quantification: 10.0 fibers; Specification Range: 100<f/mm2<1300

Sample ID No:	Sample ID No:	Sample ID No:	Sample ID No:
1	2	3	4
Laboratory No: IJ99-0342	Laboratory No: IJ99-0343	Laboratory No: IJ99-0344	Laboratory No: IJ99-0345
Sample Location: Sam Hammond 546-45-3305 P	Sample Location: N.E. corner of covered slab, tunnel area AD	Sample Location: Center of abatement area AD	Sample Location: Sam Hammond 546-45-3305 P
Work Performed: TSI rmvl. glovebag 1/2 face	Work Performed: N/A	Work Performed: N/A	Work Performed: TSI rmvl. glovebag 1/2 face
Date Sampled: 9/24/99	Date Sampled: 9/24/99	Date Sampled: 9/24/99	Date Sampled: 9/24/99
Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones
Pump No: LV-07	Pump No: HV-07	Pump No: HV-04	Pump No: HV-07
Start Time: 09:30	Start Time: 09:45	Start Time: 09:45	Start Time: 10:30
Stop Time: 10:30	Stop Time: 11:45	Stop Time: 11:45	Stop Time: 11:00
Minutes Sampled: 60	Minutes Sampled: 120	Minutes Sampled: 120	Minutes Sampled: 30
Start Flow Rate (LPM): 2	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 2
Stop Flow Rate (LPM): 2	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 2
Average Flow Rate (LPM): 2	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 2
Volume: 120 L	Volume: 1200 L	Volume: 1200 L	Volume: 60 L
Date Analyzed: 10/2/99	Date Analyzed: 10/2/99	Date Analyzed: 10/2/99	Date Analyzed: 10/2/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 1.5/100	Total Fibers: .5/100	Total Fibers: 1/100	Total Fibers: .5/100
Coefficient of Variation: LOD	Coefficient of Variation: LOD	Coefficient of Variation: LOD	Coefficient of Variation: LOD
Fibers/cc: <0.0031 f/cc	Fibers/cc: <0.0033 f/cc	Fibers/cc: 0.020 f/cc	Fibers/cc: 0.021 f/cc

Abbreviations: AP-Areasample prio to abatement, AD-Area sampled during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Irvin Jones



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District **TRE JOB NO:** 1020-67
ATTN: Joe Simmons **P.O. NO:** Verbal
CONTRACTOR: Keystone Contracting, Inc. **REPORT NO:** 2
PROJECT: West Linn High School **PAGE NO:** 2 OF 3
 Excavation Area
 TSI removal in tunnel

Method of analysis: NIOSH 7400 Limit of Detection: 5.5 Fibers; Limit of Quantification: 10.0 fibers; Specification Range: 100<f/mm2<1300

Sample ID No:	Sample ID No:	Sample ID No:	Sample ID No:
5	6	7	8
Laboratory No: IJ99-0346	Laboratory No: IJ99-0347	Laboratory No: IJ99-0348	Laboratory No: IJ99-0349
Sample Location: Sam Hammond 546-45-3305 P	Sample Location: N.E. corner of covered slab, tunnel area AD	Sample Location: Center of abatement area AD	Sample Location: Sam Hammond 546-45-3305 P
Work Performed: TSI rmvl. glovebag 1/2 face	Work Performed: N/A	Work Performed: N/A	Work Performed: TSI rmvl. glovebag 1/2 face
Date Sampled: 9/24/99	Date Sampled: 9/24/99	Date Sampled: 9/24/99	Date Sampled: 9/24/99
Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones
Pump No: LV-07	Pump No: HV-04	Pump No: HV-04	Pump No: LV-07
Start Time: 12:15	Start Time: 12:20	Start Time: 09:45	Start Time: 13:45
Stop Time: 13:45	Stop Time: 14:50	Stop Time: 11:45	Stop Time: 14:45
Minutes Sampled: 90	Minutes Sampled: 150	Minutes Sampled: 120	Minutes Sampled: 60
Start Flow Rate (LPM): 2	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 2
Stop Flow Rate (LPM): 2	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 2
Average Flow Rate (LPM): 2	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 2
Volume: 180 L	Volume: 1500 L	Volume: 1200 L	Volume: 1200 L
Date Analyzed: 10/2/99	Date Analyzed: 10/2/99	Date Analyzed: 10/2/99	Date Analyzed: 10/2/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 3/100	Total Fibers: 1.5/100	Total Fibers: 1/100	Total Fibers: 3/100
Coefficient of Variation: LOD	Coefficient of Variation: LOD	Coefficient of Variation: LOD	Coefficient of Variation: LOD
Fibers/cc: 0.0094 f/cc	Fibers/cc: <0.0031 f/cc	Fibers/cc: <0.0031 f/cc	Fibers/cc: 0.012 f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit,
 NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Irvin Jones



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-67

ATTN: Joe Simmons

P.O. NO: Verbal

CONTRACTOR: Keystone Contracting, Inc. REPORT NO: 2

PROJECT: West Linn High School
Excavation Area
TSI removal in tunnel

PAGE NO: 3 OF 3

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers; Limit of Quantification: 10.0fibers; Specification Range: 100<-f/mm2<-1300

SampleIDNo: 9	SampleIDNo: 10	SampleIDNo: B1	SampleIDNo: B2
LaboratoryNo: IJ99-0350	LaboratoryNo: IJ99-0351	LaboratoryNo: IJ99-0352	LaboratoryNo: IJ99-0353
Sample Location: N.E. corner of covered slab, tunnel area AD	Sample Location: N.E. corner of abatement AD	Sample Location: Blank	Sample Location: Blank
Work Performed: N/A	Work Performed: N/A	Work Performed: N/A	Work Performed: N/A
Date Sampled: 9/24/99	Date Sampled: 9/24/99	Date Sampled: 9/24/99	Date Sampled: 9/24/99
Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones
Pump No: HV-07	Pump No: HV-04	Pump No: N/A	Pump No: N/A
Start Time: 15:00	Start Time: 15:00	Start Time: N/A	Start Time: N/A
Stop Time: 16:00	Stop Time: 16:00	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 60	Minutes Sampled: 60	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 600 L	Volume: 600 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 10/2/99	Date Analyzed: 10/2/99	Date Analyzed: 10/2/99	Date Analyzed: 10/2/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 6.5/100	Total Fibers: 2.5/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: LOQ	Coefficient of Variation: LOD	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: <0.0079 f/cc	Fibers/cc: <0.0079 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negativeairexhaust, PA-postabatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Irvin Jones

ASBESTOS PROJECT CHECKLIST

PROJECT NAME: WEST LINN HIGH SCHOOL

PROJ. MGR: ILVIN JONES

ON SITE: 0910 OFF SITE:

OWNER PROVIDED ON-SITE CONTACT:

CONTRACTOR: Keystone Contracting

NAME: BRAD RAYMOND

SUPERVISOR: Dale

Intent to remove ACM on site and complete? Yes

Date Pre-abatement samples taken:

Disposal site: Hillsboro Land Fill

PERSONNEL & METHODS

CORRECTION REQUIRED

NO YES

WORKER PROTECTION ADEQUATE: ()
 PERSONAL AIR MONITORS USED: ()
 PROTECTIVE CLOTHING: ()
 PERSONNEL USING DECON: () N/A ()
 EQUIP. MAINTAINED PROPERLY: () N/A ()
 WETTING, PRIOR & DURING: ()
 EXCESSIVE DEBRIS: () ()
 BAGGING OPERATION: () ()
 NEGATIVE AIR ADEQUATE: () N/A ()
 DECON ADEQUATE: () N/A ()
 CLEAN ROOM ADEQUATE: () N/A ()
 SHOWER FILTERED AND ADEQUATE: () N/A ()

Respiratory Protection in use:

1/2 Face Full Face () PAPR () Type C ()

AREA ISOLATION

CORRECTION REQUIRED

NO YES

BARRICADES & SIGNS: ()
 AIRLOCKS: () N/A ()
 COVERINGS ON FLOORS & WALLS: () N/A ()
 NON-MOVABLE EQUIP. COVERED: () N/A ()
 ALL OPENINGS SEALED: () N/A ()
 AIR HANDLING EQUIP. OFF/SEALED: () N/A ()

PROJECT MANAGEMENT LOG

0700 - ARRIVE AT TRB OFFICE (ILVIN JONES)
 0810 - Keystone Contracting Arrived TRB, THREE ONE Supervisor & Two Workers.
 0812 - TRB Contacted Keystone Supervisor. Supervisor ASKED FOR permit to Remove TRB. WOR Keystone Had ONE. Contacted DARRIN DARRIN Contracted Keystone. Keystone IN PROCESS OF TRYING TO GET ONE.
 0900 - Keystone Departed TRB IN ROUTE TO W.L.H.S.
 0910 - TRB Departed TRB IN ROUTE TO W.L.H.S.

SIGNATURE: Ilvin Jones

Ilvin Jones



PROJ. No: 1020-67


DATE: 9-24-89 Pg. 2 of 3

See air monitoring reports of this date

PROJECT MANAGEMENT LOG

- 0920 TRE Irwin Jones Arrived on Site with H.S. (Keystone on Site).
- 0930 TRR. Looked at ARCA approx 190' of piping left to accomplish Abatement on
- 0950 Two Workers Sam Hammond & Hector with
- 0940 Calibrated HV-07 started Sample 2 - NW. Corner of Slab at Buildings Edge
- 1015 Calibrated HV-07 started Sample 3. Center of Abatement Project.
- 1030 Received Notification of Perm. from Keystone
- 1040 TRR (Darren Lee) on Site. Brought Copy of Permit to Abated. Dept.
- 1105 Keystone off Site to lunch.
- 1135 Darren Lee (TRR) off Site
- 1147. Keystone Back on Site.
- 1200 Keystone Preparing to continue with Abatement of 75'.
- 1148. Calibrated HV-07 & HV-07 started Samples 6 & 7.
- 1300 About 40' of pipe Abated. Progress is slow. HAVE TO GLOBE BAG THEN CUT AND THEN WRAP & ATTACH LABELS.
- 1305 Keystone Supervisor in contracted Zone.
- 1402 Dale (on Site Supervisor for Keystone) leave to call OFFICE. STILL ON SITE.
- 1430 Keystone on Break
- 1445 Keystone Back at work (working)
- 1500 Calibrated HV-04 & HV-07 started Samples 9 & 10
- 1550 TSI Removal completed. Commencing Clean up

Late Entry

SIGNATURE: 
Irwin Jones




PROJECT MANAGEMENT LOG

1600 Calibrated HV-07 & HV-04. STOPPED Both
Pumps, Pulled Samples

1605 Clean up Almost finished Keystone
& taking up tools.

1630 Keystone & TRR OFF SITE. TRR IN ROUTE
TO Wilsonville. Picking up Per Darren Lee
Direction for AP Samples & Portable.

SIGNATURE: 
Irvin Jones

ASBESTOS ABATEMENT SUMMARY
Work Order No.: 1020-64

Job Location: WEST Linn HIGH SCHOOL Floor: CONST. SITE NW END.

Project: ASBESTOS MATERIAL RECOVERY, NW END OF ROTUNDA
DEMOLITION SITE.

For pipe provide: Total linear feet N/A and pipe size N/A

For other materials provide: Total square feet: 40 SQ FT

Type of ACM: TSI DEBRIS

Start Date: 8 SEPT 1999 Completion Date: 8 SEPT 1999

Methods to Control Emissions: WET METHODS

Give name of Contractor of Subcontractor:

Name: ROSE CITY CONTRACTING INC.

Address: 8900 SW. BURNHAM RD. # E-3

City: TILGARD State: OR. Zip: 97223

Phone: (503) 624-6527 Contact person: _____

Name of Monitoring Lab: THREE RIVERS ENVIRONMENTAL

Anticipated Disposal Site: HILLSBORD LANDFILL, HILLSBORD OR.

Supervisor in charge of job: JOSE RODRIQUEZ

Project Manager: ROBERT MONTGOMERY

Name: _____ Date: SEPT 8-99 Phone: (503) 557-2396

Asbestos Program Manager: JOE SIMMONS

Name: _____ Date: _____ Phone: 638-8869

Attach pre-abatement and post-abatement air sample results

Air Sample Analysis Report



CLIENT: West Linn-Wilsonville School District **TRE JOB NO:** 1020-64
ATTN: Joe Simmons **P.O. NO:** Verbal
CONTRACTOR: Rose City Contracting **REPORT NO:** 1
PROJECT: West Linn High School **PAGE NO:** 1 OF 1
 Asbestos Material Recovery
 Construction Site

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers, Limit of Quantification: 10.0fibers, Specification Range: 100<f/mm2<1300

Sample ID No	Sample ID No	Sample ID No	Sample ID No
1	2	B1	B2
Laboratory No: RM99-0817	Laboratory No: RM99-0818	Laboratory No: RM99-0819	Laboratory No: RM99-0820
Sample Location: Jose Rodriguez 613-92-5726 EL	Sample Location: Jose Rodriguez 613-92-5726 P	Sample Location: Blank	Sample Location: Blank
Work Performed: Asbestos debris clean-up 1/2 face	Work Performed: Asbestos debris clean-up 1/2 face	Work Performed: N/A	Work Performed: N/A
Date Sampled: 9/8/99	Date Sampled: 9/8/99	Date Sampled: 9/8/99	Date Sampled: 9/8/99
Sampled by: R. Montgomery	Sampled by: R. Montgomery	Sampled by: R. Montgomery	Sampled by: R. Montgomery
Pump No: LV-06	Pump No: LV-06	Pump No: N/A	Pump No: N/A
Start Time: 15:50	Start Time: 16:25	Start Time: N/A	Start Time: N/A
Stop Time: 16:20	Stop Time: 17:10	Stop Time: N/A	Stop Time: N/A
Minutes Sampled: 30	Minutes Sampled: 45	Minutes Sampled: N/A	Minutes Sampled: N/A
Start Flow Rate (LPM): 2	Start Flow Rate (LPM): 2	Start Flow Rate (LPM): N/A	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 2	Stop Flow Rate (LPM): 2	Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 2	Average Flow Rate (LPM): 2	Average Flow Rate (LPM): N/A	Average Flow Rate (LPM): N/A
Volume: 60 L	Volume: 90 L	Volume: N/A L	Volume: N/A L
Date Analyzed: 9/8/99	Date Analyzed: 9/8/99	Date Analyzed: 9/8/99	Date Analyzed: 9/8/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 101.5/43	Total Fibers: 38.5/100	Total Fibers: 0/100	Total Fibers: 0/100
Coefficient of Variation: 0.26	Coefficient of Variation: 0.37	Coefficient of Variation: N/A	Coefficient of Variation: N/A
Fibers/cc: 1.85 f/cc	Fibers/cc: 0.20 f/cc	Fibers/cc: N/A f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit,
 NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments:

Analyzed by: Robert Montgomery



PROJ. No: 1020-64

DATE: 9-8-99 Pg. 1 of 2

See air monitoring reports of this date

ASBESTOS PROJECT CHECKLIST

PROJECT NAME: WEST LINN HIGH SCHOOL,
RECOVERY OF AS DEBRIS

PROJ. MGR: ROBERT C. MONTGOMERY

ON SITE: 1530 OFF SITE: _____

OWNER PROVIDED ON-SITE CONTACT:
NAME: JOE SIMMONS

CONTRACTOR: ROSE CITY INC.

SUPERVISOR: JOE RODRIGUEZ

Intent to remove ACM on site and complete? YES
Date Pre-abatement samples taken: N/A
Disposal site: HILLSBORO LANDFILL

PERSONNEL & METHODS

CORRECTION REQUIRED

NO YES

WORKER PROTECTION ADEQUATE: ()
PERSONAL AIR MONITORS USED: ()
PROTECTIVE CLOTHING: ()
PERSONNEL USING DECON: () N/A ()
EQUIP. MAINTAINED PROPERLY: () N/A ()
WETTING, PRIOR & DURING: ()
EXCESSIVE DEBRIS: () N/A ()
BAGGING OPERATION: ()
NEGATIVE AIR ADEQUATE: () N/A ()
DECON ADEQUATE: () N/A ()
CLEAN ROOM ADEQUATE: () N/A ()
SHOWER FILTERED AND ADEQUATE: () N/A ()

<u>AREA ISOLATION</u>	<u>CORRECTION REQUIRED</u>	
	NO	YES
BARRICADES & SIGNS:	<input checked="" type="checkbox"/>	()
AIRLOCKS:	() <u>N/A</u>	()
COVERINGS ON FLOORS & WALLS:	() <u>N/A</u>	()
NON-MOVABLE EQUIP. COVERED:	() <u>N/A</u>	()
ALL OPENINGS SEALED:	() <u>N/A</u>	()
AIR HANDLING EQUIP. OFF/SEALED:	() <u>N/A</u>	()

Respiratory Protection in use:
1/2 Face Full Face () PAPR () Type C ()

PROJECT MANAGEMENT LOG

1530: ON SITE AT WEST LINN HIGH SCHOOLS, FOUND THE AREA IN QUESTION I WILL SHOW THE ABATEMENT CREW THE AREAS TO BE CLEANED AND WE WILL TAKE CARE OF IT.

1545: SHOWED THE CREW WHAT IT IS THAT WE ARE RECOVERING, THEY ARE USING WET METHODS TO CONTROL THE AS AND DEPOSITING IT IN LARGE BAGS.

1550: CALIBRATED/STARTED SAMPLER / ON LV-DB, JOSE RODRIGUEZ IS BEING MONITORED. RUDALDO LOPEZ IS THE OTHER WORKER.

1600: ARMANDO ROIZ from ROSE CITY ALSO ARRIVED TO ASSIST IN THE ASBESTOS CLEAN-UP.

SIGNATURE: Robert C. Montgomery
ROBERT C. MONTGOMERY

THREE RIVERS
ENVIRONMENTAL

PROJECT MANAGEMENT LOG


1630: I ENLISTED THE ASSISTANCE OF THE TRACK HOE OPERATOR TO SCRAPE BACK A 20' X 10' AREA 8-12" DEEP IN THE AREA WHICH EXPOSED AT LEAST 1/2 BAG FULL OF STOS WHICH WAS BURIED. THE CREW IS NOW CLEANING UP THE REST OF THE EXPOSED MATERIAL.

1700: I INFORMED THE TRACK HOE OPERATOR THAT NOT ALL OF THE ASBESTOS WAS RECOVERED AND IF LARGE CLUMPS COME UP DURING EXCAVATION TO INFORM US AND WE'D TAKE CARE OF IT.

1700: CALIBRATED / SAMPLE #2 BEFORE REMOVING THE SAMPLE FROM LV-06. INFORMED THE CREW WE WOULD MEET AT CEDAR OAK PRIMARY AT 1730.

1715: DEPARTED THE HIGH SCHOOL.

SIGNATURE


ROBERT C. MONTGOMERY

ASBESTOS ABATEMENT SUMMARY
Work Order No.: 1020-80

Job Location: West Linn High School Floor: 1st

Project: Removal of approximately 25' of TSI & 5 hard fittings

For pipe provide: Total linear feet 25 and pipe size 4"

For other materials provide: Total square feet: _____

Type of ACM: TSI

Start Date: 10-29-99 Completion Date: 10-29-99

Methods to Control Emissions: Enclosure (glove bags & HEPA vac)

Give name of Contractor or Subcontractor:

Name: Insulation Removal Corporation

Address: 19645 S.E. Sunnyside Rd.

City: Boring State: Oregon Zip: 97009

Phone: (503) 658-6608 Contact person: JulieAnn A.

Name of Monitoring Lab: Three Rivers Environmental, Inc.

Anticipated Disposal Site: Northern Wasco County Landfill

Supervisor in charge of job: Lizauro C. Rodriguez

Project Manager: _____

Name: Irvin Jones Date: 10-29-99 Phone: (503) 557-2396

Asbestos Program Manager: West Linn-Wilsonville School District 3Jt

Name: Joe Simmons Date: 10-29-99 Phone: (503) 673-7013

Attach pre-abatement and post-abatement air sample results



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-80

ATTN: Tim Woodley

P.O. NO: Verbal

CONTRACTOR: Insulation Removal Corp.

REPORT NO: 1

PROJECT: West Linn High School

PAGE NO: 1 OF 2

TSI & H.F. Pipe Insulation Rmvl.

Method of analysis: NIOSH 7400 Limit of Detection: 5.5 Fibers Limit of Quantification: 10.0 fibers Specification Range: 100<l/mm2<1300

Sample ID No:	Sample ID No:	Sample ID No:	Sample ID No:
1	2	3	B1
Laboratory No: IJ99-0416	Laboratory No: IJ99-0417	Laboratory No: IJ99-0418	Laboratory No: IJ99-0419
Sample Location: S.W. corner of mezzanine BG	Sample Location: Center of containment AD	Sample Location: S.W. corner of mezzanine AD	Sample Location: Blank
Work Performed: N/A	Work Performed: N/A	Work Performed: N/A	Work Performed: N/A
Date Sampled: 10/29/99	Date Sampled: 10/29/99	Date Sampled: 10/29/99	Date Sampled: 10/29/99
Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones	Sampled by: I. Jones
Pump No: HV-23	Pump No: HV-22	Pump No: HV-23	Pump No: N/A
Start Time: 19:00	Start Time: 20:20	Start Time: 21:00	Start Time: N/A
Stop Time: 21:00	Stop Time: 22:20	Stop Time: 22:30	Stop Time: N/A
Minutes Sampled: 120	Minutes Sampled: 120	Minutes Sampled: 90	Minutes Sampled: N/A
Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): 10	Start Flow Rate (LPM): N/A
Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): 10	Stop Flow Rate (LPM): N/A
Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): 10	Average Flow Rate (LPM): N/A
Volume: 1200 L	Volume: 1200 L	Volume: 900 L	Volume: N/A L
Date Analyzed: 10/29/99	Date Analyzed: 10/29/99	Date Analyzed: 10/29/99	Date Analyzed: 10/29/99
Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817	Graticule Field Area: 0.00817
Total Fibers: 8/100	Total Fibers: 9.5/100	Total Fibers: 5.5/100	Total Fibers: 0/100
Coefficient of Variation: LOQ	Coefficient of Variation: LOQ	Coefficient of Variation: LOQ	Coefficient of Variation: N/A
Fibers/cc: <0.0039 f/cc	Fibers/cc: <0.0039 f/cc	Fibers/cc: <0.0052 f/cc	Fibers/cc: N/A f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasampled during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement area sample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection

Comments: <Sample calculated at Limit of Quantification (10 fibers/100 fields)

Analyzed by: Irvin Jones



Air Sample Analysis Report

CLIENT: West Linn-Wilsonville School District TRE JOB NO: 1020-80

ATTN: Tim Woodley

P.O. NO: Verbal

CONTRACTOR: Insulation Removal Corp.

REPORT NO: 1

PROJECT: West Linn High School

PAGE NO: 2 OF 2

TSI & H.F. Pipe Insulation Rmvl.

Method of analysis: NIOSH7400 Limit of Detection: 5.5Fibers Limit of Quantification: 10.0fibers Specification Range: 100</math>f/mm²<1300


Sample ID No: B2	Sample ID No:	Sample ID No:	Sample ID No:
Laboratory No: IJ99-0420	Laboratory No:	Laboratory No:	Laboratory No:
Sample Location: Blank	Sample Location:	Sample Location:	Sample Location:
Work Performed: N/A	Work Performed:	Work Performed:	Work Performed:
Date Sampled: 10/29/99	Date Sampled:	Date Sampled:	Date Sampled:
Sampled by: I. Jones	Sampled by:	Sampled by:	Sampled by:
Pump No: N/A	Pump No:	Pump No:	Pump No:
Start Time: N/A	Start Time:	Start Time:	Start Time:
Stop Time: N/A	Stop Time:	Stop Time:	Stop Time:
Minutes Sampled: N/A	Minutes Sampled:	Minutes Sampled:	Minutes Sampled:
Start Flow Rate (LPM): N/A	Start Flow Rate (LPM):	Start Flow Rate (LPM):	Start Flow Rate (LPM):
Stop Flow Rate (LPM): N/A	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):	Stop Flow Rate (LPM):
Average Flow Rate (LPM): N/A	Average Flow Rate (LPM):	Average Flow Rate (LPM):	Average Flow Rate (LPM):
Volume: N/A L	Volume: L	Volume: L	Volume: L
Date Analyzed: 10/29/99	Date Analyzed:	Date Analyzed:	Date Analyzed:
Graticule Field Area: 0.00817	Graticule Field Area:	Graticule Field Area:	Graticule Field Area:
Total Fibers: 0/100	Total Fibers:	Total Fibers:	Total Fibers:
Coefficient of Variation: N/A	Coefficient of Variation:	Coefficient of Variation:	Coefficient of Variation:
Fibers/cc: N/A f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc	Fibers/cc: f/cc

Abbreviations: AP-Areasample prior to abatement, AD-Areasample during abatement, C-Clearance, P-Personal sample from breathing zone, EL-Excursion limit, NAE-Negative air exhaust, PA-post abatement areasample, BG-Background, LOQ-Limit of Quantification, LOD-Limit of Detection



Comments:

Analyzed by: Irvin Jones


POSSIBLE RESPONSE ACTIONS



FRIABLE SURFACING, TSI OR FRIABLE MISCELLANEOUS ACM WITH POTENTIAL FOR DAMAGE (CAT 2) (CAT 5)



Decision Tree for Determination of Physical Assessment Categories



Physical Assessment Categories

- Cat 1 : Damaged or Significantly damaged thermal system insulation ACBM
- Cat 2 : Damaged friable surface ACBM
- Cat 3 : Significantly damaged friable surfacing ACBM
- Cat 4 : Damaged or significantly damaged friable miscellaneous ACBM
- Cat 5 : ACBM with potential for damage
- Cat 6 : ACBM with potential for significant damage
- Cat 7 : Any remaining friable ACBM or friable suspected ACBM

SMALL SCALE SHORT DURATION

This section reflects requirements outlined in 40 CFR 763.91 and 763.95

The idea of small scale, short duration projects are jobs involving **small quantities** of asbestos. Generally, these are projects where the **primary intent** is not to disturb asbestos and if disturbed, worker exposure levels are not to exceed the **PEL (0.1 f/cc)**.

DEQ/EPA

DEQ described small scale short duration activities as maintenance work that does not require a certified supervisor to oversee the work. IF the maintenance work is less than 3 square or 3 linear feet of friable material at any one time then certification is not required, nor is notification to the Department. (OSHA still requires some training).

DEQ does require that all persons disturbing asbestos be certified if they are not doing maintenance work and/or they disturb more than 3 square or 3 linear feet of friable material at any one tie.

DEQ/EPA defines "small scale short duration activities" means a task for which the removal of asbestos is not the primary objective of the job, is less than 3 square or 3 linear feet, including, but not limited to:

- removal of small quantities of insulation on beams or above ceilings;
- replacement of a gasket on a valve;
- installation or removal of a small section of wallboard;
- removal of thermal system insulation not to exceed amounts greater than those which can be contained in a single glove bag.
- minor repair to damaged thermal system insulation which does not require removal
- repair to wallboard;
- replacement of a gasket on a valve;
- repair involving encapsulation, enclosure or removal, to small amounts of friable material in performance of emergencies of routine maintenance activity and not intended solely as asbestos abatement. Such work may not exceed amounts greater than those which can be contained in a single prefabricated mini-enclosure. Such an enclosure shall conform spatially and geometrically to the localized work area, in order to perform its intended containment function.

AHERA (schools K-12) defines small scale job according to EPA's definition listed above. Those activities that will fit inside a single glove bag or mini-enclosure; no more than 3 square or 3 linear feet of ACM. Neither a supervisor or clearances are required, but it does need to be recorded.

OR-OSHA/OSHA

OR-OSHA does not really have a definition for small scale short duration activities that would be recognized as such by DEQ. OR-OSHA's versions of small scale short duration/maintenance activities could be classified as Class III, Class I, or Class II asbestos work.

IF a person is doing maintenance activities then it is **Class III** asbestos work. If a worker intends to disturb TSI or surfacing material, but it is not the primary purpose of the work, then they must use the general work practices outlined OR-OSHA asbestos rules 1926.1101 (g) (9).

- A competent person-who has complete a minimum 16-hour/AHERA type course. (However we are still bound by the DEQ that if we disturb more than 3 square/linear feet then certified supervisor/workers must be used.)
- OR-OSHA specifies that the following work procedure s can be used:
 - standard glovebags on straight runs of piping
 - negative air glovebags
 - negative air glove boxes
 - water spray process systems
 - negative air mini-enclosure
 - approved alternate methods
- OR-OSHA still requires than an adjacent equipment room or area to the regulated area be available for the decontamination of employees and their contaminated equipment. The area needs to be of appropriate size so as not to spread contamination and the floor covered with an impermeable drop cloth. A three chamber decontamination unit/hygiene facility is not required as long as the total work involves less than 25 linear or 10 square feet.

If a person intends to disturb TSI or surfacing material, then it is **Class I** asbestos work regardless of the size of the project. The worker must use the work practices outlined OR-OSHA asbestos rules 1926.1110 (g) (4) & (5).

- A competent person/a supervisor-who has completed an EPA/DEQ five day supervisor course.
- OR-OSHA specifies that the following work procedures can be used:
 - negative pressure exposure (NPE)
 - standard glovebags on straight runs of piping
 - negative air glovebags
 - negative air glove boxes
 - water spray process systems
 - negative air mini-enclosure
 - approved alternate methods
 - a three-chamber decontamination unit/hygiene facility is not required as long as the total work involves less than 25 linear or 10 square feet. An adjacent equipment room or area to the regulated area must be available for the decontamination area.

If a person intends to disturb asbestos material that is not TSI or surfacing material, the it is **Class II** asbestos work regardless of the size of the project. This includes flooring (vinyl, sheet vinyl, asphalt), roofing (shingles built-up, felts), cement asbestos (transite), gaskets, wallboard, construction mastics, etc.

- A competent person/a supervisor-who has completed an EPA/DEQ five day supervisor course. (However DEQ does not require a certified supervisor if the material is kept non-friable.)
- The worker must use the general work practices outlined OR-OSHA asbestos rule 1925.1101 (g) (7) & (8).

- An adjacent equipment room or area to the regulated area must be available for the decontamination area. A three-chamber decontamination unit/hygiene facility is not required.

7. OPERATIONS AND MAINTENANCE PLAN

TABLE OF CONTENTS

	PAGE
I. INTRODUCTION.....	1
II. DEFINITIONS	1
III. PROGRAM ELEMENTS	
A. WORKER PROTECTION.....	1
B. TRAINING.....	2
C. INITIAL CLEANING	3
D. ADDITIONAL CLEANING.....	3
E. OPERATIONS AND MAINTENANCE ACTIVITIES.....	3
F. WASTE DISPOSAL	7
G. RECORDKEEPING.....	8
H. WARNING LABELS	8
I. BUILDING INVENTORY.....	9
J. PERIODIC SURVEILLANCE	9
K. EMERGENCY RESPONSE	9
L. EQUIPMENT LIST	9
M. AIR MONITORING PLAN.....	11
N. MEDICAL MONITORING	11
O. O&M CODES.....	12
IV. FORMS	

I. INTRODUCTION

With the enactment of the Asbestos Hazard Emergency Response Act regulations, Local Education Agencies are charged with producing a plan of action that will facilitate the safe and effective management of asbestos materials in their school systems. The most effective way of managing the problem is to completely remove all asbestos-containing materials from the building, thus removing the problem in its entirety. In some cases, however, this wholesale removal is not economically feasible or even desirable from a building usage standpoint. When asbestos-containing materials can not be completely removed, a comprehensive Operations and Maintenance Program as required by 40 CFR 763.91 will allow the local education agency to control the asbestos problem until removal of the materials is feasible.

II. DEFINITIONS

Several definitions pertinent to an Operations and Maintenance Program are identified in 40 CFR 763.83. These are as follows:

Asbestos-Containing Material (ACM) when referring to school buildings means any material which contains more than one percent asbestos.

Asbestos-Containing Building Material (ACBM) means surfacing ACM, thermal system insulation ACM, or miscellaneous ACM that is found in or on interior structural members or other parts of a school building.

Asbestos Debris means pieces of ACBM that can be identified by color, texture, or composition; or means dust, if the dust is determined by an accredited inspector to be ACM.

Operations and Maintenance Program means a program of work practices to maintain friable ACBM in good condition, to insure cleanup of asbestos fibers previously released, and to prevent further release by minimizing and controlling damage to friable ACBM.

Fiber Release Episode means any uncontrolled or unintentional disturbance of ACBM resulting in visible emissions.

Friable, when referring to material in a school building, means that the material, when dry, may be crumbled, pulverized, or reduced to powder by hand pressure, and includes previously non-friable material after such previously non-friable material becomes damaged to the extent that, when dry, it may be crumbled, pulverized or reduced to powder by hand pressure.

High-Efficiency Particulate Air (HEPA) refers to a filtering system capable of trapping and retaining at least 99.97% of all non-dispersed particles 0.3 millimeters in diameter or larger.

Removal means the taking out or the stripping of substantially all ACBM from a damaged area, a functional space, or a homogeneous area in a school building.

Repair means returning damaged ACBM to an undamaged condition or to an intact state so as to prevent fiber release.

Response Action means a method, including removal, encapsulation, enclosure, repair, operations and maintenance, that protects human health and the environment from friable ACBM.

Routine Maintenance Area is an area, such as a boiler room or mechanical room, that is not normally frequented by students and in which maintenance employees or contract workers regularly conduct maintenance activities.

III. PROGRAM ELEMENTS

A. WORKER PROTECTION

40 CFR 763.91(b) serves to extend the protection provided by 40 CFR 763.121 (for worker protection during asbestos abatement projects) to employees of local education agencies who perform Operations and Maintenance and repair activities involving ACM who are not covered by the OSHA Asbestos Construction Standard 29 CFR 1926.58. This standard will be adhered to during all Operations and Maintenance or repair operations involving the disturbance of friable ACBM.

During initial cleaning (and additional cleaning as necessary) of all buildings, those employees performing the cleaning will be supplied with and will use the following personal protective equipment:

Disposable Coveralls - a "Tyvek" brand or similar disposable coverall will be worn over the clothes to prevent capturing asbestos fibers on the clothing.

Respirator - an individual personalized respirator will be provided to all workers doing the cleaning. The respirator will be appropriately fit-tested to ensure that it functions effectively for that individual. Each respirator will be supplied with disposable cartridges approved for asbestos dust by NIOSH and will be worn at all times during the cleanup operation.

Following cleanup each day, all used disposable respiratory cartridges and coveralls will be disposed of in six-mil asbestos disposal bags.

B. TRAINING

Prior to the implementation of any Operations and Maintenance provisions of the Management Plan, all members of the maintenance and custodial staff who, during the performance of their duties, may work in a building containing ACBM will receive general awareness training of not less than two hours in duration. As well, similar training will be given to all new maintenance/custodial personnel within 60 days of their start date. As per 40 CFR 763.92 (a)(i-v), the accepted course for this level of training is "Developing an Operations and Maintenance Plan" given by Hall-Kimbrell Environmental Services, Inc., 4840 West 15th Street, Lawrence, Kansas, 66044, and will include as a minimum:

- Information on asbestos, its forms, and uses.
- Information on the health affects of asbestos exposure.
- Locations of ACBM in the school buildings in which they work.
- Recognition of damage, deterioration, and delamination of ACBM.

- Name and telephone number of the LEA person designated to carry out LEA responsibilities under 40 CFR 763.84.
- Availability and location of the Management Plan.

All members of the maintenance/custodial staff who are likely to conduct any activities that may disturb ACBM will receive the previously described general awareness training and an additional 14 hours as required by 40 CFR 763.92 (2)(i-iv). The accepted course for this level of additional training is "Operations and Maintenance Training" given by Hall-Kimbrell Environmental Services, 4840 West 15th Street, Lawrence, Kansas, 66044, and will include as a minimum:

- Descriptions of proper methods of handling ACBM.
- Information on the use of respiratory protection as contained in the EPA/NIOSH Guide to Respiratory Protection for the Asbestos Abatement Industry, September 1986 (EPA 560-OPTS-86-001), and other personal protective equipment and measures.
- The provisions of the following pieces of legislation:
 - 40 CFR 763.91, Appendices A, B, C, D of Subpart E
 - EPA regulations in 40 CFR Part 763, Subpart G
 - EPA regulations in 40 CFR Part 61, Subpart M
 - OSHA regulations in 29 CFR 1926.58
- Hands-on training in the use of respiratory protection, other personal protective equipment and measures, and good work practices.

All types of training will emphasize the necessity to not disturb ACBM or assumed ACBM during routine maintenance activities. Employees will be instructed on the following at a minimum:

- Avoid performing any activities on ACM or assumed ACM that may cause abrasion or physical deterioration of the material. This includes sanding, nailing, drilling, cutting, or otherwise damaging the material.

- Avoid damaging ACM during maintenance activities NOT directly involving the ACM such as installing drapes, carpets, moving furniture, etc.
- To always use a HEPA-vacuum and wet methods to clean up asbestos dust or debris. NEVER use a regular vacuum or dry method.
- To avoid any activities that may inadvertently release asbestos fibers into the air such as removing ventilation filters, drying and/or shaking the filters, and removing suspended ceiling tiles below ACM without taking the proper precautions and using the proper personal protective equipment.

C. INITIAL CLEANING

In accordance with 40 CFR 763.91, all buildings under the direction of the School District will undergo an initial cleaning process prior to commencing with any response actions, with the exception of Operations and Maintenance and repair, as detailed in the Inspection Report/Management Plan Data. The initial cleaning will be done in all areas of all buildings where friable ACBM, damaged or significantly damaged thermal system ACM, or friable suspected ACBM assumed to be ACM, were determined to be present following the completion of an inspection, sampling and analysis program performed in accordance with 40 CFR 763.85 through 40 CFR 763.87.

The following procedures will be followed for the initial cleaning of all appropriate areas of each building:

1. All carpets will be HEPA vacuumed and/or steam cleaned.
2. All horizontal surfaces including sills, frames, door tops, wall protrusions, signs, air vents, suspended light fixtures, and other immovable fixtures will be HEPA vacuumed. Following HEPA vacuuming, the same areas will be wet cleaned in order to remove any residual fibers not picked up during the vacuuming process.
3. All walls will be wet wiped, except for those with sprayed-on or trowelled-on materials or with other applications with high liquid absorption potential.

4. All uncarpeted floors will be wet mopped.
5. All debris, filters, wet mop heads, dust mops, cloths, etc., will be sealed, while still wet, in leak-tight containers. Disposal containers will be six-mil polyethylene bags labelled in such a fashion that they illustrate their usage as asbestos storage containers. These bags will be kept in a single location, in a routine maintenance area in each building and will always be kept closed and tied. When the bag becomes full, it will be tied shut and placed into another six-mil bag and tied again. Full bags will be placed in a 55-gallon steel or fiberboard drum. When full, the drum will be transported to an EPA-approved asbestos landfill site and the material will be disposed of as asbestos-containing waste.

D. ADDITIONAL CLEANING

In all areas where friable ACM exists, normal daily cleaning procedures will be altered as necessary to ensure that fiber entrainment in the air will be minimized. Sweeping and dry mopping will not be allowed in areas containing friable ACM. Until all ACM is removed from ceilings, etc., all daily mopping will be carried out with dampened, disposable mop heads. These mop heads will not be used in asbestos-free areas and will be changed at the end of the day and disposed of as asbestos-contaminated waste in six-mil polyethylene disposal bags. In addition, certain areas will receive additional cleaning on a regular basis as per the O&M supplement at the end of this section.

E. OPERATIONS AND MAINTENANCE ACTIVITIES

1. Small-Scale, Short Duration Activities and Minor Fiber Release Episodes

Appendix B to Subpart E of 40 CFR 763.91 defines small-scale, short duration maintenance activities as, but not limited to:

- Removal of ACM insulation on pipes
- Removal of small quantities of ACM insulation on beams or above ceilings
- Removal of ACM gaskets on a valve

- Removal or installation of a small section of drywall

- Installation of electrical conduits through or proximate to ACM.

Small scale is further subdefined in Appendix B of Subpart E as:

- Removal of small quantities of ACM only if required as part of maintenance activity not intended as asbestos abatement
- Removal of ACM thermal system insulation in quantities no greater than can be contained in one glove bag
- Minor repairs to damaged thermal system insulation requiring no removal.
- Repairs to ACM wallboard
- Repairs involving encapsulation, enclosure, or removal, to small amounts of friable ACM only if required in performance of an emergency or a routine maintenance activity not intended as asbestos abatement. The work may not exceed amounts greater than those which can be contained in a single prefabricated mini-enclosure. This enclosure must conform spatially and geometrically to the localized work area, in order to perform its intended containment function.

Section 40 CFR 763.91 (f)(i) defines a minor fiber release episode as the falling or dislodging of less than or equal to three square or linear feet of friable ACBM.

During the process of performing small-scale, short duration asbestos renovation or maintenance tasks, the following procedures will be utilized:

- The area will be isolated with physical barriers, whenever possible, restricting entry only to those persons necessary to perform the task. Warning signs will be posted at all entry points to the area.
- All HVAC ducts, windows, and other sources of air circulation to the area will be sealed. Where necessary, the air handling systems will be shut off or modified to meet this need.
- If a fiber release has occurred, the entire area will be precleaned using those techniques described in *Section C. under*

Initial Cleaning. HEPA vacuum and/or wet methods will always be employed for any type of cleaning. All workers directly involved with the cleaning will always use the prescribed personal protective equipment.

- All objects in the area will be removed from the area to protect them from contamination during the maintenance activity. Where it is not possible or feasible to move the objects, the objects will be completely covered with six-mil polyethylene plastic sheeting prior to commencement of the maintenance activity. This will include all fixtures and other components that exist in the immediate work area.
- Next, a layer of six-mil polyethylene plastic sheeting will be placed on the floor beneath the item or area affected by the maintenance activity. This sheeting will be at least one foot wide and long for each foot above the floor where the work is to be conducted, but will not under any circumstances, be less than six feet by six feet. When the work area is confined by walls, the plastic sheeting will extend up the walls at least one foot, and will be sealed along the top edges with duct tape.
- All work activities involving the ACM will be performed using wet methods, HEPA vacuums, glove bags, mini-enclosures, and/or protective clothing as appropriate to the maintenance activity. These methods are detailed in *Section E-3 of Operations and Maintenance Activities.*
- All repair work done on the damaged or affected ACM will be done with materials such as asbestos-free spackling, plaster, cement, or insulation. The existing ACM affected by the maintenance activity will be sealed with latex paint or an encapsulant, or the appropriate response action as identified in the Management Plan will be implemented.
- All asbestos-containing debris will be saturated with amended water and sealed in double six-mil polyethylene disposal bags. These bags will be labelled as ACM and will be disposed of at an EPA

approved landfill site. All plastic, duct tape, etc., used to cover objects, floors, etc., will be treated as asbestos-contaminated waste and will be disposed of in like manner.

2. Maintenance Activities other than Small Scale, Short Duration and Major Fiber Release Episodes.

Section 40 CFR 763.91 (f)(2) defines a major fiber release episode as the falling or dislodging of more than three square or linear feet of friable ACM.

For those maintenance activities other than small scale, short duration or for a major fiber release episode, all response actions will be designed by persons accredited to design response actions and conducted by persons accredited to conduct response actions.

Regardless of the response action designed for the specific activity or repair, the areas involving the work will be sealed off and restricted with signs posted, and prepared for the work in a manner consistent with the procedures outlined for small-scale short duration activities in *Section E-1 of Operations and Maintenance Activities*.

3. ACM Removal Procedures

a. Wet Methods.

Regardless of the removal method employed, wet methods will always be used where practical during any maintenance activity that involves the disturbance of ACM. In some cases, wet methods will not be employed (working on live electrical equipment, for example) and this will be determined prior to the commencement of the activity.

At all times, amended water will be used as the wetting agent. Amended water is water that has a surfactant added that restricts evaporation and enhances the penetration of the water into the ACM. Commercially available products such as those containing a concentrate of a 50-50 mixture of polyoxyethylene esters and polyoxyethylene ethers with three percent emulsifier will be used. These products

will be added to normal tap water and used as per manufacturer's instructions.

Amended water will be applied to all ACM using an airless sprayer to minimize disturbance of the ACM. During the maintenance or repair activity, the material will continue to be wetted, as needed, to ensure that all ACM is wet during the activity and remains wet until final disposal.

b. Glove Bag Techniques

The glove bag techniques will be used for removal of ACM on small scale activities mainly involving pipes, valves, Tees, fixtures, or other small components of mechanical systems as detailed in Appendix B of Subpart E of 40 CFR 763. Prior to installation and use of the glove bag, signs will be posted and the work area will be sealed off and prepared as detailed in *Section E-1 of Operations and Maintenance Activities*. The worker(s) performing the glove bag operation will be equipped with a disposable Tyvek-type suit and a personal respirator equipped with disposable cartridge filters NIOSH approved for use with asbestos dust.

After performing all preparatory work and donning personal-protective equipment, the glove bag is cut along the sides to fit around the pipe or fixture to be worked on. All tools necessary to perform the work, as well as a quantity of bridging encapsulant, are inserted into the attached inside pocket of the bag.

The glove bag is then attached around the work area by folding the open edges together and sealing with staples and tape. The side edges of the glove bag are then sealed using duct tape and/or Velcro ties to form a tight seal. The bottom seam of the bag is also taped to ensure its integrity. Once a tight seal is obtained, the end of a smoke tube is inserted through the marked entry port and a small amount of smoke is squeezed into the bag. After tape sealing the port (and removing the smoke tube), the bag is gently squeezed to allow the smoke to exit through any available leak holes. Leaks identified in this way are sealed with more duct tape, the entry port is opened, and

the bag is squeezed lightly to remove excess smoke. Next, the portable sprayer nozzle is put through the port and the work area is completely wetted with amended water. The nozzle is removed and the HEPA vacuum hose is inserted into the port and sealed tightly with duct tape.

The worker's arms are inserted into the armholes and gloves and the ACM is removed from the work area. When necessary, the amended water spray nozzle is inserted into the bag during removal to ensure that the ACM is kept wet at all times.

When all necessary ACM is removed and the item cleaned of all visible material, a spray nozzle from the encapsulant sprayer is inserted and the pipe fixtures, etc., are sprayed with encapsulant. The rough edges of the cut ACM are then coated/sealed with the bridging encapsulant.

The worker then removes his arms from the armholes and turns on the HEPA vacuum, to remove air from the bag. As the air is being removed from the bag, the bag is squeezed near the top, and twist sealed and taped closed. The HEPA vacuum is turned off, the nozzle removed, and the entry port is sealed tightly. Then the bag is cut along the top and removed from the working area, then placed in a six-mil polyethylene bag for disposal with other contaminated waste materials.

c. Mini-Enclosures

This methodology is employed in areas where glove bags are not practical, such as for the removal of asbestos from a small ventilation system or a short length of duct as detailed in Appendix B of Subpart E of 40 CFR 763.

The mini-enclosure will vary in construction, shape, and size, depending upon the specific requirements of an individual activity. In general, all mini-enclosures will be constructed according to the following criteria:

- The structure will consist of six-mil polyethylene plastic sheeting supported by a preconstructed

framework of 2" by 4" studs formed around the work area. The plastic will be stapled and taped to the framework. Two layers of sheeting will be used, one attached to the studs on the inside of the mini-enclosure and the other on the outside.

- The structure will be minimized in size so as to allow entry to only the number of workers directly involved with the maintenance activity. Where possible, the number of workers will be restricted to one or two maximum.
- The floor inside the mini-enclosure will be covered with two layers of six-mil plastic and will extend no less than one foot up each wall where it will be tape sealed to the wall's plastic. All penetrations into or through the mini-enclosure, such as pipe runs, will be sealed with duct tape.
- A small change room (approximately three feet by three feet by seven feet) will be constructed contiguous to the mini-enclosures. Entry to the change room and from the change room to the mini-enclosure will be through double plastic-sheeted entryways. The first layer of plastic in the entryway will be sealed to the doorway at the top and on the right side, the second layer will be sealed at the top and on the left side.
- After completing the maintenance or repair activity, the worker will enter the change room, HEPA vacuum his disposable coveralls, and remove them prior to leaving the change room. He will then wet wipe his respirator, leaving it on until exiting the change room.
- During the ACM removal, the workers will wear protective coveralls and dual cartridge respirators NIOSH-rated for asbestos dust. Wet methods of removal using amended water will be used at all times in the mini-enclosure. As in glove bag removal,

following the removal of ACM the working areas will be sprayed with encapsulant and exposed cut ACM will be coated with a bridging encapsulant when appropriate.

- Next, all debris in the mini-enclosure will be placed in double six-mil polyethylene bags labelled appropriately for disposal of ACM. The bags will be wet cleaned before removal from the work area through the change room. All interior surfaces of the mini-enclosure will then be cleaned using HEPA vacuum and or wet cleaning techniques.
- Inside the mini-enclosure, the air will be sprayed with water using an airless sprayer. The worker will start at the top and spray the entire volume down to the floor level in order to remove any airborne asbestos fibers prior to dismantling the mini-enclosure.
- The worker will then proceed to the change room and HEPA vacuum his coveralls and clean and spray the room in the same fashion as the mini-enclosure. He will then wet wipe his respirator while still wearing it, HEPA-vacuum and remove his coveralls, and exit the change room.
- The mini-enclosure will then be dismantled from the outside by removing the plastic and bundling it inwards, rolling it, and placing it in a six-mil bags, labelled for asbestos-contaminated waste and disposed of appropriately. The 2" by 4" studs will be dismantled and stored for further use.
- Following the dismantling of the mini-enclosure the worker removes his respirator and disposes of the cartridges as asbestos-contaminated waste.

F. WASTE DISPOSAL

All asbestos-containing waste material is double-bagged in six-mil polyethylene plastic bags. These

bags are preprinted to show that they contain asbestos-containing material. Asbestos waste is kept in a controlled location in a routine maintenance area of the facility. Filled bags of waste are carried to this area and placed in sealable metal or fiber 55-gallon drums. When the drums are full, they are sealed, labelled, and transported to a landfill site approved for asbestos by EPA. Upon arrival at the landfill site, the bags are removed from the drums and handed over to the landfill operator. The drums are wet wiped and returned to the school for re-use. The drums are not re-used if, upon opening, it is observed that one or more of the bags has ruptured inside of the drum. In this case, the drum is resealed and disposed of along with all bags inside of it.

The waste containers are transported to the landfill site in a covered, lockable vehicle and all transported containers are accompanied by a proper chain of custody form that details the origin of the material, date and quantities of transport, types of containers and destination of containers. If transported by a third party hauler, information on the hauler is also included on the form. The chain of custody form is signed at each transfer point and after final transport to the landfill site, a copy of the form is maintained in our records as evidence of receipt at the site. A sample copy of this form is included.

Prior to any transportation of asbestos-containing material, notification will be made to the following parties:

1. Regional US EPA office - written notification will be sent detailing the name and location of the landfill site to be used and the approximate weight and volume of asbestos involved.
2. EPA Certified Landfill Site - Prior to each transport the landfill supervisor will be notified of the weight and volume of the material, the expected date and time of arrival at the site, and the types of containers to be transported.

G. RECORDKEEPING

Permanent records will be kept regarding Operations and Maintenance activities in facilities under the control of the LEA. These include:

1. Whenever any cleaning activity as prescribed in 40 CFR 763.91 (c) is undertaken records will contain the name of the individuals performing the cleaning, the dates of the cleaning, the locations cleaned, the methods utilized, and any other information pertinent to that particular cleaning episode. A copy of the O&M Cleaning Report Form is attached.
2. Whenever any Operations and Maintenance activity is undertaken as outlined in 40 CFR 763.91 (d) records will contain the name and duties of each person involved; the start and completion date and time of the activity; the locations where the activity occurred; a description of the activity; preventive measures used; amount (if any) of ACM removed; and the name and location of the storage or disposal site for the ACM. A copy of the Small-Scale O&M Activity Report Form is attached.
3. Whenever a major activity as described in 40 CFR 763.91 (e) is undertaken, records will indicate the name, signature, state of accreditation, and accreditation number of each person involved; the start and completion date and time; the locations where the activity occurred; a description of the activity; preventive measures used; whether ACBM was removed; and the name and location of the storage or disposal site for the removed material. A copy of the Major O&M Activity Report Form is attached.
4. For every fiber release episode described in 40 CFR 763.91 (f), the records will detail the date, time, and location of the episode; the method of repair; preventive measures or response action taken; the names of those persons doing the work; whether ACBM was removed; and the name and location of the storage or disposal site for the removed material. A copy of the Fiber Release Episode Report Form is attached.
5. Copies of all inspection reports, results and amendments will be kept in the file with the Operations and Maintenance Program and activity reports. This also includes results of any re-inspections or

periodic surveillance as prescribed in 40 CFR 763.85 (b) and 40 CFR 763.92 (b).

6. Current lists of all custodians and maintenance personnel including name, address, date of hire, asbestos training course, and dates, as well as copies of certificates from any special related courses taken by the employees. A copy of the Maintenance/Custodial Staff Training Report Form is attached.
7. A current list of all areas where asbestos removal, enclosures, or encapsulation has taken place. A copy of the Asbestos Abatement Activity Record Form is attached.
8. A current inventory of equipment available for Operations and Maintenance activities.
9. Copies of ACM disposal records and/or chain of custody documentation.

All records will be maintained in a single location at the LEA site. Copies of all records and information pertinent to individual facilities will also be maintained at those facilities by the designated campus asbestos coordinator.

H. WARNING LABELS

Warning labels will have been attached immediately adjacent to any friable and non-friable ACBM and assumed ACM located in routine maintenance areas as per 40 CFR 763.95. The labels will be of a size, print, and color which is readily visible to persons entering an area containing ACBM. The labels will read as follows:

CAUTION

ASBESTOS HAZARDOUS

DO NOT DISTURB WITHOUT PROPER

TRAINING AND EQUIPMENT

I. BUILDING INVENTORY - ALL ACM

See "List of School Buildings and ACM Status" in Section: Management Plan Introduction.

J. PERIODIC SURVEILLANCE

All facilities will undergo a semi-annual surveillance in order to detect deterioration taking place on any ACM in the facility. This will consist of a visual evaluation of the materials and specific records will be maintained detailing the material type, damage, or deterioration noted, as well as any repair or response action undertaken. This semi-annual surveillance will be performed utilizing the protocol defined in the "plan for periodic surveillance" in the management plan.

K. EMERGENCY RESPONSE

In the event of the occurrence of an asbestos-related emergency in a facility under the direction of the LEA, the following procedures will be employed:

1. Immediately upon notice of the emergency, the party involved will vacate the area of involvement and immediately contact the LEA Coordinator and/or his designee at the facility.
2. If the person(s) observing the incident is trained to handle ACM activities, that person(s) will take action to immediately isolate the area of involvement from the rest of the building by evacuating any unnecessary personnel from the area, turning off or isolating all air-moving equipment in the area, isolating the area by closing all entryways, and posting warning signs indicating the presence of a hazardous area.
3. If the person(s) observing the incident is not trained to handle ACM activities, that person will immediately contact a member of the staff who has the appropriate training and alert that person to the problem. The trained staff member will then proceed to take the actions indicated in 2.

4. If the occurrence is of such a size that a response action must be designed by an accredited designer, no further work will be done and the area will remain isolated as in 2. until the appropriate response action can be determined. Otherwise, the appropriate repair/maintenance activity will commence following the performance of the procedures detailed in *Section E-1 of Operations and Maintenance Activities*.
5. Following completion of the repair/maintenance activities, the appropriate forms will be completed as per *Section G-7 Recordkeeping*. These forms will become a part of the permanent Operations and Maintenance records.

L. EQUIPMENT LIST

An Operations and Maintenance Plan involves "specialized" equipment and supplies to resolve and/or control the problems. The materials can be purchased from a number of asbestos or industrial safety supply houses and some can be found in hardware stores. The following materials and equipment are commonly associated with successful operations and maintenance planning.

OPERATIONS AND MAINTENANCE PLANNING MATERIALS AND EQUIPMENT LIST

1. Tyvek disposable coveralls
2. Rubber gloves
3. Half-face dual cartridge negative pressure respirators with NIOSH-approved cartridges
4. Safety goggles
5. Surfactant
6. Misting spray bottle
7. Misting spray tank
8. Dust mop/broom
9. Polyethylene sheeting (six-mil)
10. Asbestos disposal bags (six-mil)
11. Fiber or metal disposal drums
12. Glove bags
13. HEPA Vacuum with attachments
14. Duct tape
15. Hand tools
16. Warning signs and labels
17. Scrim cloth for pipe wrap
18. Foil tape for pipe wrap
19. Encapsulant - bridging and penetrating
20. Smoke tube kits

OPERATIONS AND MAINTENANCE PLANNING
COST AND MATERIALS CHECKLIST

ITEMS	PURCHASED		PER BUILDING	
	Initial	Ongoing	Unit Cost	Quantity
Disposable Tyvek Coveralls w/Hood Bottles X-large				
Rubber gloves				
Half-face negative pressure dual cartridge respirators				
Respirator filters				
Safety goggles				
Surfactant				
Misting spray bottle				
Misting spray tank				
Polyethylene sheeting (six-mil)				
Asbestos disposal bags (six-mil)				
Fiber disposal drums				
Glove bags				
HEPA vacuum with attachments: vacuum bags vacuum filters cone attachment				
Vacuum bags				
Vacuum filters				
Cone attachment				
Duct tape				
Hand tools				
"DANGER: ASBESTOS..." signs & labels				
Scrim cloth for pipe wrap				
Foil tape for pipe wrap				
Encapsulant - penetrating - bridging				
Smoke tube kits				

M. AIR MONITORING

A requirement of 40 CFR 763.91 is that the LEA ascertain, through monitoring or historical data, the airborne concentration of asbestos fibers during all maintenance and repair activities involving ACBM or assumed ACBM. Coverage of EPA's worker protection rule at 40 CFR 763.121 is extended to maintenance and custodial staff at schools who perform Operations and Maintenance activities.

These regulations establish a Permissible Exposure Limit (PEL) of 0.2 fibers per cubic centimeter (f/cm³) over 8-hours for abatement project workers and an action level of 0.1 f/cm³ that, once met or exceeded, triggers a number of required work practices including air monitoring, regulated work areas, engineering and work practice controls, respiratory protection, protective clothing, hygiene facilities and practices, training, medical surveillance and recordkeeping.

In response to the requirement of these regulations, 8-hour "time weighted average" air sampling will be conducted in all routine maintenance areas and in general occupancy areas of all buildings so that initial background concentrations of asbestos resulting from the existence of the ACBM may be determined. As well, during any small-scale, short-duration maintenance activity involving ACM, air monitoring will be performed as follows:

- Personal samples will be collected from the breathing zone of the employee(s) performing the maintenance activity.
- Area samples will be collected in the vicinity of the maintenance activity so that a determination may be made of the level of contamination expected to be produced in surrounding areas as a result of the activity.

All air monitoring will be done in accordance with 40 CFR 763.121 including collection on 0.8 micrometer 25-millimeter filters mounted in an open-face filter holder and analysis using the NIOSH 7400 method. The samples will be taken for the determination of the 8-hour time weighted average concentrations and ceiling concentrations of asbestos fibers.

Following analysis of the air filters, results of all analyses will be recorded on the O&M Maintenance Activity form for inclusion in the Operations and Maintenance Program's permanent records. A copy of the Air Monitoring Data and Log is attached.

N. MEDICAL MONITORING

Medical monitoring is required for all employees working on or around ACBM where exposure is likely to exceed the OSHA action level of 0.1 f/cm³, 8-hour TWA during the course of work. This is required through 40 CFR 763.91's extension of EPA's Worker Protection Rule at 40 CFR 763.121 to maintenance and custodial staff at schools who perform operations and maintenance activities.

This medical monitoring program will be provided to all persons at the cost of the LEA as required by the regulations. The program will consist of the following elements:

- Preplacement Examination - will be provided within 30 days of commencement of employment and will include a medical history, chest X-ray, and pulmonary function test as per 40 CFR 763.121(J)(2).
- Annual Examinations - will be provided at least annually and will include medical history, chest X-ray, and pulmonary function tests as per 40 CFR 763.121(J)(3).
- Termination Examination - will be provided within 30 days pre or post termination date and will include medical history, chest X-ray, and pulmonary function tests as per 40 CFR 763.121(J)(4).

Where determined by medical examination that an individual cannot work while wearing a respirator, that person will not be required or allowed to perform maintenance activities involving ACBM.

Medical records will be maintained in the personnel files and be made available to the Environmental Protection Agency, the Assistant Secretary of Labor for Occupational Safety and Health, the Director of NIOSH, authorized physicians, and upon the request of the employee (or former employee) to his physician. All records will be maintained for at least 20 years as required by 40 CFR 763.121(f)(6).

OPERATIONS AND MAINTENANCE CODES

The following codes are intended for use as reference to the general requirements for Preventive Measures by material types. The codes are referenced in the inspection results location of the Management Plan and are presented here for convenience.

The codes given are for all friable ACBM and non-friable ACBM that have the potential to become friable during school maintenance activities involving the material. In all cases, the description of activities in the Operations and Maintenance Codes refers back to the specific requirements detailed in the Operations and Maintenance program and 40 CFR 763.

OMA - Pipe Insulations and Mudded Joint Fittings

Work area preparation and cleaning must in accordance with the requirement of 40 CFR 763.91(d).

Repair minor dents and tears in the protective jacket with duct tape or bridging encapsulant with glass cloth reinforcement. Duct tape should only be used for temporary control until the bridging encapsulant is installed.

For small-scale, short-duration activities, if glove bag removal is not feasible, wrap uncovered pipe insulation with protective jackets consisting of a bridging encapsulant with glass cloth reinforcement. If a glove bag is used, it must be used in accordance with *Section E-3 of Operations and Maintenance Activities*.

Wrap moderately water damaged or contact damaged pipe insulations with new protective jackets, or re-insulate affected areas. Eliminate the source of the water damage. Any activity

other than small-scale, short-duration requires design by a person accredited to design response actions. The activity must be undertaken by those accredited to perform them. Therefore, those types of activities will not be undertaken on a routine basis.

Monitor the condition of the asbestos-containing materials, under procedures outlined in the "Plan for Periodic Surveillance" located in the Management Plan.

Clean area, as necessary, using procedures detailed in *Section D of Additional Cleaning*.

OMB - Insulation on Boilers, Breeching, Ducts, etc.

Work area preparation and cleanup must be in accordance with the requirements of 40 CFR 763.91 (d).

Repair minor dents and tears in insulation on boilers and breeching with a bridging encapsulant with glass cloth reinforcement. Duct tape or non-asbestos mastic should only be used for temporary control until the protective jacket is applied.

Wrap uncovered insulations with new protective jackets or coverings consisting of a bridging encapsulant with glass cloth reinforcement.

Minor damage to duct work insulated with ACM should be repaired with a bridging encapsulant with glass cloth reinforcement. Duct tape or non-asbestos mastic should only be used for temporary control until the protective jacket is applied.

If any small-scale removal is required as a part of the repair process or maintenance activity, then a glove bag or mini-enclosure must be used as described in *Section E-3 of Operations and Maintenance Activities*. Clean the area, as necessary, using procedures detailed in *Section D of Additional Cleaning*.

Monitor the condition of the asbestos-containing materials, under procedures outlined in the "Plan for Periodic Surveillance" located in the Management Plan.

OMC - Fireproofing

Work area preparation and cleaning must be in accordance with the requirements of 40 CFR 763.91(d).

The fireproofing may be sprayed with an encapsulant if the fireproofing is well-bonded to its substrate and is less than one inch thick. This is to be considered a temporary control measure with a life expectancy of five to six years. Test results have shown that, due to the impact of the spray, spraying with an encapsulant can, on occasion, cause more fibers than a gross wet removal project. ACM removal, enclosure or encapsulation, can only be performed if it is classified as a small-scale, short-duration maintenance activity NOT intended as asbestos abatement as defined in Appendix B to Subpart E of 40 CFR 763.91. In cases where the activity is not small-scale, the activity must be designed and performed by an accredited person.

Use caution when work involved hanging ducts, conduit or pipes, etc. from surfaces sprayed with fireproofing. Avoid disturbing fireproofing whenever possible.

All materials must be monitored as detailed in the section "Plans for Periodic Surveillance" located in the Management Plan.

Clean the area, as necessary, using procedures detailed in *Section D of Additional Cleaning*.

OMD - Acoustical Plasters (Sprayed On/Trowelled On)

If the plaster is in good condition, with no delamination, deterioration or signs of water damage, it should be left alone but carefully monitored for signs of change in status. This must be performed as detailed in the "Plan for Periodic Surveillance" in the Management Plan.

If the plaster is water damaged and/or is becoming delaminated from the substrate, it should be removed rather than encapsulated. Encapsulation can make the condition worse by increasing the rate of delamination. The source of the water damage must be eliminated. Unless the required removal is a part of a required small-scale, short-duration maintenance activity then the removal/repair must be designed and performed by an accredited person.

Avoid disturbing acoustical plaster by not hanging plants, drilling holes in the ceiling, moving furniture, etc. Work area preparation and cleanup for all types of maintenance work must be in accordance with the requirements of 40 CFR 763.912(d). When the plaster must be disturbed, mist the affected area with amended water and use a HEPA vacuum to collect fibers being released.

All materials must be monitored as detailed in the section "Plans for Periodic Surveillance" located in the Management Plan.

Clean the area, as necessary, using procedures detailed in *Section D of Additional Cleaning*.

OMF - Debris

Work area preparation and cleanup must be in accordance with the requirements of 40 CFR 763.91(f) for minor fiber release episodes (three square or linear feet or less of friable ACM).

Small amounts can be cleaned up using a HEPA vacuum and wet wiping or set mopping. Dispose of larger pieces by misting and carefully moving the pieces to an asbestos disposal bag to be properly discarded. Repair of the damaged material that resulted in the debris must be performed as per 40 CFR 763.91 (f)(iv).

OMG - Ceiling Tiles

Work area preparation and cleanup must be in accordance with the requirements of 40 CFR 763.91(f) for minor fiber release episodes (three square or linear feet or less of friable ACM).

When ceiling tiles are noted as asbestos-containing materials, precautions can be taken to greatly minimize exposure from the tiles.

Whenever the tiles are cut, broken, or damaged, they should be disposed of properly and replaced by new tiles. Replacement tiles must be asbestos free. Tiles should never be broken to fit into an asbestos disposal bag. Any activity other than small-scale, short-duration maintenance activities must be designed and performed by an accredited person.

All materials must be monitored as detailed in the section "Plans for Periodic Surveillance" located in the Management Plan.

OMH - Tape/Woven Paper

Work area preparation and cleanup must be in accordance with the requirements of 40 CFR 763.91(f).

Asbestos-containing tape is used primarily for sealing seams on duct work. Loose or frayed ends of the tape must be wetted with amended water, cut, and properly disposed. Care must be taken not to damage the tape by ripping or tearing it during this procedure.

Damaged tape should be carefully painted with a bridging encapsulant with minimal overspray or overbrushing. When the tape must be disturbed, mist it with amended water (unless the disturbance is due to the encapsulation process) and use a HEPA vacuum to collect fibers being released.

OMI - Miscellaneous/ Cementitious Materials

Fiber release from cementitious (non-friable) materials is normally extremely low, unless these materials are broken, drilled, sanded or otherwise disturbed. During disturbance, the material should be thoroughly dampened and a HEPA vacuum used to collect fibers being released. Work area preparation and cleanup must be in accordance with 40 CFR 763.91(d). Some examples of cementitious materials that may contain asbestos are:

- Floor tiles
- Tile underlay
- Wall plasters (some)
- Transite pipes
- Scratch coats
- Drywall plaster (some)
- Transite panelling
- Linoleum
- Asbestos cement pipes

OMZ - Other Materials

This code applies to miscellaneous ACM that rarely creates a significant problem but can pose an exposure risk when being damaged or removed. Listed are some of the asbestos-containing materials that fall into this classification. If an asbestos-containing material is not directly addressed in the operations and maintenance codes, an operations and maintenance procedure may be applied using one or more of the codes that involve similar materials. All disposal must be in accordance with *Section F of Waste Disposal*.

Batt Insulation - Cutting or tearing the asbestos-layered paper backing can cause fiber release. Wet the backing with amended water and wear a half-face respirator if batting needs to be cut or moved.

Friable Wallboard - Precautions must be taken to minimize exposure from the wallboard. Replace broken or damaged wallboard with a non-asbestos material. If removal is necessary, wet the material and try to remove it in one piece. The wallboard must never be broken up to fit into an asbestos disposal bag.

Vibration Joint Cloth - Vibration joint cloth is most often found on duct work near air handlers. Loose or frayed ends should be wet with amended water or a diluted encapsulant. Carefully cut and remove the joint cloth and dispose of properly.

Earth Floors - When mechanical insulations located in crawl spaces or tunnels deteriorate or are damaged, the earth floors beneath them can become contaminated. Often the asbestos materials are broken up and ground into the loose earth by maintenance workers performing work in these areas. All work involving contaminated soil must be designed and performed by accredited persons.

Vinyl Asbestos Floor Tiles (VAT) - Damaged, vinyl floor tiles can become friable and could present a problem when a small-scale, short-duration maintenance activity requires removal of small areas of VAT, work area preparation and cleaning must be in accordance with 40 CFR 763.91 (d). Mix amended water to a slightly stronger than normal strength. Spray the entire surface of the tiles to be removed, wait six to eight hours and repeat the spraying. Most vinyl

asbestos tile glues are water soluble and the tiles will loosen so that they may be physically removed, placed in a sealed plastic bag, and disposed of as asbestos waste. When the tiles are loose, the ends will curl up or under. Always dispose of the paper underlay material with the VAT, as it usually contains asbestos. In most cases, VAT removal will be designed and performed by accredited persons.

INITIAL/ADDITIONAL CLEANING RECOMMENDATIONS

(Supplement to O&M Plan)

This section is provided as a supplement to the Operations and Maintenance Plan included in this document, as required by 40 CFR 763.91 (c) and 763.93 (e)(9).

The AHERA regulations require that each LEA which after inspection was found to contain areas with friable ACBM, damaged or significantly damaged thermal system insulation ACM, or friable suspected ACBM assumed to be ACM, the area(s) will be asbestos cleaned at least once after the completion of the inspection and before the initiation of any response action other than O&M Procedures or repair. The procedures for the required cleaning are found in 40 CFR 41852; however, a more detailed description is found in the body of the O&M Plan, "Initial Cleaning".

Hall-Kimbrell and the accredited Management Planner agree with the EPA to the need for a thorough asbestos cleaning of the areas described above. That initial cleaning measure is necessary in order to collect and remove as much of the settled asbestos dust and fibers as possible that have been deposited over the past months or years. However, all materials containing asbestos should not be treated equally under this provision, since depending on the material's degree of friability, accessibility, asbestos content, condition, and other variables, the amount of asbestos contamination in and around the area will vary greatly. The accredited inspector performed an assessment of the materials taking into consideration these and other variables which contribute to the likelihood/probability of routine or accidental fall out and possible building occupant exposure. The relative degree of exposure potential and, therefore, past fall out probability are inter-related in that a material whose damage category has been determined to

be damaged or significantly damaged has a very high probability of having produced a higher degree of area contamination than a similar material with a rating of "potential for damage".

In order to aid the school district in understanding the relative degrees of exposure and/or contamination potential and probability, Hall-Kimbrell has provided three (3) priority ranking categories. Hall-Kimbrell's recommendation for cleaning in and around the areas is as follows:

Priority 1 Materials/Areas

- A) Initial cleaning as described in the O&M Plan as soon as feasible but in no event later than July 9, 1989.
- B) Additional cleaning as was performed initially at least once every two months until materials are abated.

Priority 2 Materials/Areas

- A) Initial cleaning as described in O&M Plan no later than July 9, 1989. NOTE: For economic efficiency, the LEA should perform the initial cleaning at the same time as the Priority I materials/areas are cleaned.
- B) Additional cleaning, as was performed initially, at least once every six months thereafter until materials are abated.

Priority 3 Materials/Areas

Since these materials are either non-friable ACBM, non-friable assumed ACM, or other well-bound miscellaneous material with a low likelihood of exposure potential or contamination under routine use, Hall-Kimbrell does not feel that initial nor additional cleaning is absolutely necessary. However, since past renovations, remodeling, or other possible disturbance may have occurred and unknown to Hall-Kimbrell the school district should use its best judgement based on past activities in determining whether these Priority III materials should be treated otherwise.

LEA Response to Cleaning Recommendations


The AHERA regulations require that the LEA provide a response to the management planner's cleaning recommendations. If you agree with the recommendations provided and agree to conduct the necessary cleaning based on the schedule recommended indicate by checking the first block. If you do not agree and plan to carry out an alternative, additional cleaning schedule, please indicate by checking the second block and provide a description of the cleaning plan the LEA will perform.

I do agree with the recommendations and cleaning schedule and will carry out the plan according to that schedule.

I do not agree with the recommended schedule for additional cleaning and elect the following:

Initial cleaning will be performed prior to the initiation of any response act other than O&M or repair.
Additional cleaning will be performed when it is deemed necessary by the LEA.


By: LEA Designated Person:



Signature

Samuel Nutt
Name

By: Management Planner



Signature

John Newlin
Name

OPERATIONS AND MAINTENANCE PROGRAM

FORMS

ASBESTOS ABATEMENT ACTIVITY RECORD*

District Name: _____ Campus Name: _____

LEA Asbestos Coordinator: _____ Phone: _____

Building Name	Abatement Location	Abatement Method	Extent of Abatement	Abatement Contractor	Date of Abatement	Abatement Cost	All ACM Removed

* This record includes all asbestos abatement undertaken that was not associated with a small-scale maintenance activity

ACM WASTE DISPOSAL
CHAIN OF CUSTODY RECORD

Campus _____

Building: _____

Asbestos Coordinator _____

Address: _____

Phone _____

Material Summary

Material Origin: _____ Date of Release: _____

Container Type(s): _____

Quantity: _____

Total No. of Containers: _____

Total Quantity: Volume _____ Weight _____

Drums Sealed: Yes No Not Applicable

Bags Doubled & Tied: Yes No Not Applicable

Containers Labeled: Yes No

Material Destination

Name of Landfill Site: _____ Address: _____

Landfill Site Supervisor: _____ Phone: _____

EPA Certified for Asbestos Disposal: YES / NO*

If NO, Explain: _____

CHAIN OF CUSTODY

Relinquished By	Date and Time	Received By	Date and Time	Carrier

O & M CLEANING REPORT

Campus: _____ Building: _____

Locations: _____ Date(s): _____

Staff Assigned

Name	Title	Duties

Cleaning Methods

Location	Methods Used

Comments: _____

Signature: _____

Date: _____

SMALL-SCALE O & M ACTIVITY REPORT

Campus: _____

Building: _____

Location: _____

Date: _____ / _____ / _____
start stop

Time: _____ / _____

Maintenance Activity

Description of Activity: _____

ACM Removed: YES / NO Quantity: _____ Removal Method: _____
 Disposal/Storage Site: _____ Site Supvr: _____
 Address: _____ Phone: _____

Equipment/Preventive Measures

- | | | | |
|---|--|--|---|
| <input type="checkbox"/> Area Isolated | <input type="checkbox"/> Signs Posted | <input type="checkbox"/> HEPA Vacuum | <input type="checkbox"/> Isolate Air Handlers |
| <input type="checkbox"/> Tyvek Suits | <input type="checkbox"/> Respirators | <input type="checkbox"/> Goggles | <input type="checkbox"/> Poly sheeting |
| <input type="checkbox"/> Disposal Bags | <input type="checkbox"/> Disposal Drums | <input type="checkbox"/> Duct Tape | <input type="checkbox"/> Tools(detail below) |
| <input type="checkbox"/> Encapsulant-Bridging | <input type="checkbox"/> Encapsulant-penetr. | <input type="checkbox"/> Minienclosure | <input type="checkbox"/> Change Room |
| <input type="checkbox"/> Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Amended Water | <input type="checkbox"/> Repair Materials(detail below) |

Tools and Repair Materials-List All

_____	_____	_____
_____	_____	_____
_____	_____	_____

Staff Assigned

Name	Title	Duties	Date/Time	
			start	finish

Further Action Necessary: _____

Comments: _____

FIBER RELEASE EPISODE REPORT

Campus: _____

Building: _____

Location: _____

Date: _____ Time: _____

Description of Episode: _____

Type of Episode(Major or Minor): _____

Person Identifying Episode: _____

Corrective Action

Method of Repair / Response Action: _____

ACM Removed: YES / NO Quantity: _____ Removal Method: _____

Disposal/Storage Site: _____ Site Supvr: _____
 Address: _____ Phone: _____

Equipment/Preventive Measures

- | | | | |
|---|--|--|---|
| <input type="checkbox"/> Area Isolated | <input type="checkbox"/> Signs Posted | <input type="checkbox"/> HEPA Vacuum | <input type="checkbox"/> Isolate Air Handlers |
| <input type="checkbox"/> Tyvek Suits | <input type="checkbox"/> Respirators | <input type="checkbox"/> Goggles | <input type="checkbox"/> Poly sheeting |
| <input type="checkbox"/> Disposal Bags | <input type="checkbox"/> Disposal Drums | <input type="checkbox"/> Duct Tape | <input type="checkbox"/> Tools(detail below) |
| <input type="checkbox"/> Encapsulant-Bridging | <input type="checkbox"/> Encapsulant-penetr. | <input type="checkbox"/> Minienclosure | <input type="checkbox"/> Change Room |
| <input type="checkbox"/> Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Amended Water | <input type="checkbox"/> Repair Materials(detail below) |
| <input type="checkbox"/> Gross Removal(attach info on contractor, and all activity details) | <input type="checkbox"/> Notify Asbestos Coordinator | | |

Tools and Repair Materials-List All

_____	_____	_____
_____	_____	_____
_____	_____	_____

Staff Assigned

Name	Title	Accreditation(if applic.)		Duties	Date/Time	
		State	Number		start	finish

Further Action Necessary: _____

Comments: _____

MAJOR O & M ACTIVITY REPORT

Campus: _____

Building: _____

Location: _____

start stop
Date: _____ / _____

Time: _____ / _____

Maintenance Activity

Response Plan Designer: _____ State of Accred./Accred. #: _____

Description of Activity: _____

ACM Removed: YES / NO Quantity: _____ Removal Method: _____

Disposal/Storage Site: _____ Site Supvr: _____
 Address: _____ Phone: _____

Equipment/Preventive Measures

- | | | | |
|---|--|--|---|
| <input type="checkbox"/> Area Isolated | <input type="checkbox"/> Signs Posted | <input type="checkbox"/> HEPA Vacuum | <input type="checkbox"/> Isolate Air Handlers |
| <input type="checkbox"/> Tyvek Suits | <input type="checkbox"/> Respirators | <input type="checkbox"/> Goggles | <input type="checkbox"/> Poly sheeting |
| <input type="checkbox"/> Disposal Bags | <input type="checkbox"/> Disposal Drums | <input type="checkbox"/> Duct Tape | <input type="checkbox"/> Tools(detail below) |
| <input type="checkbox"/> Encapsulant-Bridging | <input type="checkbox"/> Encapsulant-penetr. | <input type="checkbox"/> Minienclosure | <input type="checkbox"/> Change Room |
| <input type="checkbox"/> Enclosure | <input type="checkbox"/> Glove Bag | <input type="checkbox"/> Amended Water | <input type="checkbox"/> Repair Materials(detail below) |
- Gross Removal(attach info on contractor, and all activity details)

Tools and Repair Materials-List All

_____	_____	_____
_____	_____	_____
_____	_____	_____

Staff Assigned

Name	Title	Accreditation		Duties	Date/Time	
		State	Number		start	finish

Further Action Necessary: _____

Comments: _____

Supvr Signature: _____


Date: _____

Certificate of Completion

This is to certify that
Darren Lee
has satisfactorily completed
4 hours of refresher training as a
Management Planner

in compliance with TSCA Title II
AHERA Accredited

Sep 23, 1999



Training Coordinator

Exp. Date: Sep 22, 2000



Prezant



Cert. #99-1933

Conducted at:


PacPro - Gresham, OR

Prezant Associates, Inc. • 330 Sixth Avenue North, Suite 200 • Seattle, Washington 98109 • (206) 281-8858

Certificate of Completion

This is to certify that
Jeffrey Smith
has satisfactorily completed
One half-day refresher training as a
Building Inspector
in compliance with TSCA Title II
AHERA Accredited

Sep 15, 1997



Training Administrator

Exp. Date: Sep 15, 1998



Cert. # 97-3959


Conducted at:
Pac Pro Safety
Holiday Inn / Portland, OR

Certificate of Completion

This is to certify that
Jeff Smith
has satisfactorily completed
4 hours of refresher training as a
Management Planner

in compliance with TSCA Title II
AHERA Accredited

Sep 23, 1999



Training Coordinator

Exp. Date: Sep 22, 2000



Prezant



Cert. #99-1934

Conducted at:

PacPro - Gresham, OR


Prezant Associates, Inc. • 330 Sixth Avenue North, Suite 200 • Seattle, Washington 98109 • (206) 281-8858

Certificate of Completion

This is to certify that
Jeffrey Smith
has satisfactorily completed
One day of refresher training as a
Project Designer

in compliance with TSCA Title II
AHERA Accredited

Aug 28, 1999



Wendy Powell
Training Coordinator

Exp. Date: Aug 27, 2000



Cert. # 991785

Conducted at:


Three Rivers Environmental, Inc. -
Gladstone, OR

Prezant Associates, Inc. • 330 Sixth Avenue North, Suite 200 • Seattle, Washington 98109 • (206) 281-8858

Certificate of Completion

This is to certify that
Glenn R. Bryant
has satisfactorily completed
4 hours of refresher training as a
Building Inspector
in compliance with TSCA Title II
AHERA Accredited

Oct 21, 1999



Training Coordinator

Exp. Date: Oct 20, 2000



Prezant



Cert. #99-2209

Conducted at:
Pac Pro Portland, OR

Prezant Associates, Inc. • 330 Sixth Avenue North, Suite 200 • Seattle, Washington 98109 • (206) 281-8858

Certificate of Completion

Med-Tox Northwest
certifies that

Glenn Bryant

has successfully completed 32 hours of

Sampling and Evaluating Airborne Asbestos Dust
NIOSH 582 Equivalent
on this 22nd day of March 1996

Carol Evans
Instructor

Ken Kaufmann
Training Director

Certificate No. 960339N

CERTIFICATE OF COMPLETION

PRESENTED BY
COLE & ASSOCIATES, TRAINING & CONSULTING, INC.

ROBERT C. MONTGOMERY


HAS SUCCESSFULLY COMPLETED THE

**SAMPLING AND EVALUATING AIRBORNE ASBESTOS
DUST (NIOSH 582 EQUIVALENT COURSE)
TRAINING COURSE**

HELD ON THE 19TH THROUGH THE 22ND OF JANUARY 1999,
IN BELLEVUE WASHINGTON.
EXAM DATE: JANUARY 22, 1999



<i>Joan Cole</i>	<i>Anne Hudson</i>
TRAINING ADMINISTRATOR	INSTRUCTOR
3514-99-01-02	January 22, 2000
CERTIFICATION NUMBER	DATE OF EXPIRATION



Certificate of Completion

This is to certify that

Robert C. Montgomery

has satisfactorily completed
24 hours training as a

Building Inspector

in compliance with TSCA Title II/AHERA Accredited

Dec 16 - 18, 1998

Conducted at: PacPro - Portland, OR

Lynn Pedone
Training Administrator

Exp. Date: Dec 18, 1999



Cert. # 98-09212

Exam Date: Dec 18, 1998

Prezant Associates, Inc. • 330 Sixth Avenue North, Suite 200 • Seattle, Washington 98109 • (206) 281-8858

Certificate of Completion

Presented by

PAC PRO Safety & Health Services

Irvin D. Jones


*has successfully completed a 32-Hour
Sampling and Evaluating Airborne Asbestos Dust
NIOSH 582 Equivalent Course.*

June 21-23, 1999



Portland, Oregon

Certification Number: PP699-582-02

Examination Date: June 23, 1999



Training Administrator

Instructor


PAC PRO Safety & Health Services 660 NW Bella Vista Drive Gresham, Oregon 97030 (503)-666-6693

Certificate of Completion

Irvin D. Jones

has successfully completed the requisite training and examination for
accreditation under TSCA Title II
EPA AHERA (Asbestos Hazard Emergency Response Act),
and ASHARA Model Accreditation Program requirements

as presented by
Clayton Environmental Consultants



Garry Rossing
INSTRUCTOR

Course Date: **09/21/99** through **09/23/99**

Certification # **244-88-8571** Examination Date: **09/23/99**

Certificate Expiration Date: **09/22/00**

Clayton
ENVIRONMENTAL
CONSULTANTS


Clayton Environmental Consultants is a Division of Clayton Group Services, Inc.
11675 SW 66th Ave. Portland, Oregon 97223 •(503) 968-2112 •fax (503) 968-2213

United States Department of Commerce
National Institute of Standards and Technology

NVLAP[®]

ISO/IEC GUIDE 25:1990
ISO 9002:1987

Certificate of Accreditation



ENVIRONMENTAL HAZARDS SERVICES, L.L.C.
RICHMOND, VA

is recognized under the National Voluntary Laboratory Accreditation Program for satisfactory compliance with criteria established in Title 15, Part 285 Code of Federal Regulations. These criteria encompass the requirements of ISO/IEC Guide 25 and the relevant requirements of ISO 9002 (ANSI/ASQC Q92-1987) as suppliers of calibration or test results. Accreditation is awarded for specific services, listed on the Scope of Accreditation for:

BULK ASBESTOS FIBER ANALYSIS

December 31, 1999

Effective through

A handwritten signature in black ink, appearing to read "Jan L. Galt".

For the National Institute of Standards and Technology

NVLAP Lab Code: 101882-0



American Association for Laboratory Accreditation

SCOPE OF ACCREDITATION TO ISO/IEC GUIDE 25-1990

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 White Pine Road

Richmond, VA 23237

Irma Faszewski Phone: 804 275 4788

ENVIRONMENTAL

Valid To: August 31, 2000

Certificate Number: 0716-01

In recognition of the successful completion of the A2LA evaluation process, accreditation is granted to this laboratory to perform recognized EPA methods using the following testing technologies and in the analyte categories identified below:

Testing Technologies: Atomic Absorption/ICP-AES Spectrometry, Atomic Absorption-Flame, Hazardous Waste Characteristics Tests

Nonpotable Water

Metals: Al, Sb, As, Ba, Be, Cd, Ca, Cr, Co, Cu, Fe, Pb, Mg, Mn, Hg, Mo, Ni, K, Se, Ag, Na, Tl, Sn, Ti, V, Zn-

per EPA test methods SW 6010, 7420, 7470

Solid/Hazardous Waste

Metals: Al, Sb, As, Ba, Be, Cd, Ca, Cr, Co, Cu, Fe, Pb, Mg, Mn, Hg, Mo, Ni, K, Se, Ag, Na, Tl, Sn, Ti, V, Zn

per EPA test methods SW 6010, 7420, 7470

Hazardous Waste Characteristics Test: TCLP

per EPA test method SW 1311

Environmental Lead: soil, paint chips (residue), dust, air, building debris

sample preparation

per EPA test methods SW3050A (soils, building debris); 3050A modified (paints, wipes)

per NIOSH test method 7082 (air)

per EPA test method 600/R-93/200 (sonification - air, paint, soil)

sample analysis

per EPA test methods SW 6010A, 7420

per NIOSH methods 7082, 7300



ADMIN COPY



Office: 503-650-8370 - Fax 503-650-8371 - P.O. Box 519 - Gladstone, OR 97027

Environmental Safety & Health Services

CLIENT: WEST LINN WILSONVILLE SCHOOL DISTRICT
FACILITY: WEST LINN HIGH SCHOOL
INSPECTION DATES: 12/03/01

ASBESTOS SURVEY
REPORT DATE: Dec., 2001
INSPECTOR: Darren Lee
CERT. NUMBER: OR-00-6082
NVLLAP CERT: 101882-0

ASBESTOS INVESTIGATIVE REPORT

Sample #:	Material Description:	Sample Location:	HSA#	Total Asbestos:
WLH-01	Ceiling Tile (1x1) Spline	Dance Studio	01	0%
WLH-01	Ceiling Tile (1x1) Spline	Dance Studio	01	0%
WLH-01	Ceiling Tile (1x1) Spline	Dance Studio	01	0%

ANALYTICAL METHOD: Polarized Light Microscopy, EPA Method 600/M4-82-020

STANDARDS: OSHA / EPA, one percent (1%) asbestos by weight is considered asbestos containing.

NOTE: HSA numbers represent homogeneous materials or materials which appear similar in construction and matrix.



P.O. Box 519 - Gladstone, OR 97027

CHAIN OF CUSTODY

Page 1 of 1

Attention: GARREN D. LEE
 Company Name: GLACIER ENV. INC.
 Mailing Address: P.O. BOX 519
GLADSTONE, OR 97027
 TEL: (503) 650-8370 FAX: (503) 650-8371

SAMPLE TYPE

ASBESTOS

PLM (Bulk) PLM X-RAY
 PCM (Air) TEM (Air)
Sample Group Positive stop

LEAD

AA Flame (air)
 AA Flame (Paint, Wipe)
 TCLP
 EPA 100/500 Series (Drinking Water)

SAMPLE TURNAROUND

Standard (5 day)
 Priority (3 day)
 Rush (24 hour)

Other (specify): 24 HR TURN

~~Client~~ Client Number: 01624
 P.O. Number: _____
 Project Number: WEST LINN H.S.
 Date Sampled: 12/6/01
 Date Submitted: 12/10/01
 Special Instructions: _____


Sample ID	Date	Positive Stop	Sample Description	Sample Location	Quantity (SF/LF)	Volume	Result
<u>WLHS-001</u>	<u>12-6-01</u>	<u>*</u>	<u>CEILING TILE</u>	<u>DANCE STUDIO</u>			
<u>" - 002</u>	<u>"</u>	<u>"</u>	<u>" "</u>	<u>" "</u>			
<u>" - 003</u>	<u>"</u>	<u>"</u>	<u>" "</u>	<u>" "</u>			

Sampled By: (Sign) 	Relinquished By: (Sign) 	Date <u>12-6-01</u>	Time <u>11:05</u>	Received By: (Sign) 	Date <u>12/10/01</u>	Time <u>12:20pm</u>
				LAB:		


Certificate of Completion

This is to certify that
Darren D. Lee
has satisfactorily completed
4 hours of refresher training as a
Building Inspector
in compliance with TSCA Title II
AHERA Accredited

October 25, 2000


Training Coordinator

Date Expires Oct 25, 2001



Cert. # 00-6082

Conducted at:
Pac Pro Safety & Health Services



Prezant

Prezant Associates, Inc. • 330 Sixth Avenue North, Suite 200 • Seattle, Washington 98109 • (206) 281-8858



12750 SW Pacific Highway, Ste 210, Tigard, OR 97223

(503) 968-2533

FAX: (503) 968-0523



200509-0

Bulk Sample Analysis for Asbestos

WEC Project #: P01-398
Client Project#: 01624

Report #: 7000
Report Date: 12/11/01

Client: **Glacier Environmental Inc.**
P.O. Box 519
Gladstone, Oregon 97027

Samples: 3 # Layers: 3

Collected Date: 12/6/01
Collected By: CLIENT
TAT: 24 Hour
Analysis By: T.Hubbard
Analysis Date: 12/11/01
Received By: Hubbard
Received Date: 12/10/01

Project Name/Location: West Linn H.S.

Client ID#	WEC ID#	Location	Layer						
WLHS-001	PB01-2074	Dance Studio	1 of 1						
Asbestos									
None Detected		Friable/Non Friable Fibrous? Homo- Friable Yes No genous	Material Color Ceiling Tile Off-White						
% Asbestos: 0%									
Other Fibrous Materials									
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Type</th> <th>%</th> </tr> </thead> <tbody> <tr> <td>Cellulose</td> <td style="text-align: center;">3%</td> </tr> <tr> <td>Mineral Wool</td> <td style="text-align: center;">70%</td> </tr> </tbody> </table>		Type	%	Cellulose	3%	Mineral Wool	70%	% Other Fibrous Materials: 73% % Non Fibrous Materials: 27%	
Type	%								
Cellulose	3%								
Mineral Wool	70%								
Sample Comments:									

Client ID#	WEC ID#	Location	Layer						
WLHS-002	PB01-2075	Dance Studio	1 of 1						
Asbestos									
None Detected		Friable/Non Friable Fibrous? Homo- Friable Yes No genous	Material Color Ceiling Tile Off-White						
% Asbestos: 0%									
Other Fibrous Materials									
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Type</th> <th>%</th> </tr> </thead> <tbody> <tr> <td>Cellulose</td> <td style="text-align: center;">2%</td> </tr> <tr> <td>Mineral Wool</td> <td style="text-align: center;">73%</td> </tr> </tbody> </table>		Type	%	Cellulose	2%	Mineral Wool	73%	% Other Fibrous Materials: 75% % Non Fibrous Materials: 25%	
Type	%								
Cellulose	2%								
Mineral Wool	73%								
Sample Comments:									

Bulk Sample Analysis for Asbestos

WEC Project #: P01-398
Client Project#: 01624

Report #: 7000
Report Date: 12/11/01

Client ID# WLHS-003	WEC ID# PB01-2076	Location Dance Studio	Layer 1 of 1							
Asbestos		Friable/Non Friable	Homo- Fibrous? Yes No	Material Ceiling Tile						
None Detected				Color Off-White						
Other Fibrous Materials		% Asbestos: 0%								
		% Other Fibrous Materials: 73%								
		% Non Fibrous Materials: 27%								
<table border="1"> <tr> <th>Type</th> <th>%</th> </tr> <tr> <td>Cellulose</td> <td>3%</td> </tr> <tr> <td>Mineral Wool</td> <td>70%</td> </tr> </table>		Type	%	Cellulose	3%	Mineral Wool	70%	Sample Comments:		
Type	%									
Cellulose	3%									
Mineral Wool	70%									

Comments:

Analyst James Halliday Date 12/11/01
QC James Halliday Date 12/11/01

Analysis performed by EPA Method 600/R-93/116. All quantities reported are based on visual estimation by PLM, unless point-counting method is requested and noted for the sample. Test report relates only to items tested and must not be used by client to claim product endorsement by NVLAP or any agency of the U.S. Government. Test reports must not be reproduced without the approval of WEC Inc., and are subject to WEC Inc. General Terms and Conditions (see reverse).

United States Department of Commerce
National Institute of Standards and Technology

NVLAP[®]

ISO/IEC GUIDE 25:1990
ISO 9002:1987

Certificate of Accreditation



WHITE ENVIRONMENTAL CONSULTANTS, INC.
TIGARD, OR

is recognized under the National Voluntary Laboratory Accreditation Program for satisfactory compliance with criteria established in Title 15, Part 285 Code of Federal Regulations. These criteria encompass the requirements of ISO/IEC Guide 25 and the relevant requirements of ISO 9002 (ANSI/ASQC Q92-1987) as suppliers of calibration or test results. Accreditation is awarded for specific services, listed on the Scope of Accreditation for:

BULK ASBESTOS FIBER ANALYSIS

March 31, 2002

Effective through

David E. Alderman

For the National Institute of Standards and Technology

NVLAP Lab Code: 200509-0

Asbestos Investigative Report

WEST LINN HIGH SCHOOL
(TRIP HOUSE)
5290 WEST "A" ST.
WEST LINN, OR.

TRE Project No. 1020-88

January 2000

Conducted By:

Three Rivers Environmental, Inc.

Prepared for
**WEST LINN-WILSONVILLE
SCHOOL DISTRICT 3JT**

Attention: Tim Woodley

Prepared by



Table of Contents

1. Introduction

2. Investigative Methods
 - Summary of Investigation

3. Asbestos Material Summary
(Identified Homogeneous Areas)

4. Bulk Sample & Positive Material Location Diagrams

5. Photographs of Sampled Materials

6. Bulk Sample Inventory
 - Chain of Custody

7. Laboratory Analysis Results

8. Accreditations / Certifications

9. Record Keeping



W.L.W.S.D. WEST LINN HIGH - TRIP HOUSE
ASBESTOS SURVEY TRE# 1020-88
5290 WEST "A" St. WEST LINN, OR..

INTRODUCTION
JANUARY 12 2000
PAGE 1 OF 1

Introduction

January, 2000

Three Rivers Environmental, Inc., under the direction of Tim Woodley performed an asbestos survey to identify specific asbestos containing materials (ACMs) that may be present at 5290 West "A" St. West-Linn, Or.

Field investigation was conducted by EPA accredited asbestos inspector Irvin Jones and Robert Montgomery of this office on January 12 2000.

The purpose of this survey was to provide information in order to meet the AHERA asbestos sampling protocol as stated in 40 CFR 763.86. This sampling protocol is required for all asbestos surveys under Oregon Department of Environmental Quality, prior to performing any renovation or demolition activities.

In addition, this survey meets the "Good Faith" inspection requirements as stated in Oregon Occupational Safety and Health Code, General Industry Standard OAR 437-02-1910.100, Identification. Under the regulation, the Owner of a building to be renovated or demolished is required to provide a written statement as to whether the materials to be disturbed contain asbestos.

The inspection consisted of visual and tactile examination of all accessible portions of the surveyed area. All observed suspect asbestos containing materials were sampled in accordance with the Asbestos Hazard Emergency Response Act (AHERA) protocol, and submitted for laboratory analysis. All asbestos sample analysis was performed by American Industrial Hygiene Association (AIHA) and National Volunteer Laboratory Accreditation Program (NVLAP) Accredited Laboratories.

The results of our asbestos survey indicate that the structure located at the above mentioned address does contain asbestos building materials.

Please contact us with any questions or comments regarding the contents of this report.

Sincerely;

Darren D. Lee
Vice President
Three Rivers Environmental, Inc.

INVESTIGATIVE METHODS

A walk through inspection of all accessible areas of the facilities are performed to identify suspect asbestos-containing-building-materials (ACBM) and presumed-asbestos-containing-materials (PACM). A thorough investigation of suspect ACBM in hidden spaces are also conducted. Materials which may be buried on the property were not investigated.

During any scheduled demolition activities, given that materials different from those identified, may be uncovered during the demolition process. If such suspect materials are discovered, samples of these materials should be collected and analyzed for asbestos content before these materials are disturbed.

Upon identifying a suspect material, its location and type are noted. Samples are obtained, placed in plastic bags, and labeled with a number. Samples are collected to achieve a representative characterization of the visible suspect asbestos-containing materials found.

All samples are taken within EPA guidelines to minimize potential contamination to the surrounding area. Bulk samples location, notes, photographs, and observations are made on-site at the time of sampling. All applicable sample collection data are transferred to a corresponding Chain-of-Custody sample data sheet. Chain-of-Custody sheets are located behind the Bulk Asbestos Sample Analysis Sheet within our survey.

For all asbestos samples, the bulk sample identification number indicates the building from which the sample was taken, the numerical sequence in which the samples are taken, the layer of the material (if applicable), and the homogeneous sampling (HSA).

For Example: IPB-008a-25

IPB	Inpatient Building
008	Homogeneous Sampling Area (HSA)
a/b/c	layer designation
25	25th sample taken

The amount of asbestos in the sample is shown along with an observation of the condition of the material. Approximately <1% in the bulk materials is the limit of Polarized Light Microscopy (PLM) detection for most laboratories. If the microscopist can see no fibers in the sample, the result is reported as "No Asbestos Detected (NAD)."

The bulk suspect ACM samples are analyzed by Environmental Hazards Services, Inc., a National Voluntary Laboratory Accreditation Program (NVLAP) accredited laboratory. The analytical technique is polarized light microscopy (PLM) with dispersion staining. All analyses are performed by trained optical mineralogy technicians competent in bulk asbestos identification. Environmental Hazards Services, Inc. also participates in interlaboratory and intralaboratory quality control programs as recommended by the National Institute of Standards and Technology (NIST) and the EPA.

ASBESTOS BULK SAMPLING PROTOCOL

40 CFR 763.86 Sampling (AHERA Asbestos Sampling Protocol)

(a) **Surfacing material.** An accredited inspector shall collect, in a statistically random manner that is representative of the homogeneous area, bulk samples from each homogeneous area of friable surfacing material that is assumed to be ACM, and shall collect the samples as follows:

(1) At least three bulk samples shall be collected from each homogeneous area that is 1,000 square feet or less, except as provided in 763.87 (c) (2).

(2) At least five bulk samples shall be collected from each homogeneous area that is greater than 1,000 square feet but less than or equal to 5,000 square feet, except as provided in 763.87 (c) (2).

(3) At least seven bulk samples shall be collected from each homogeneous area that is greater than 5,000 square feet, except as provided in 763.87 (c) (2).

(b) Thermal system insulation

(1) Except as provided in paragraphs (b) (2) through (4) of this section and 763.87 (c), an accredited inspector shall collect, in a randomly distributed manner, at least three bulk samples from each homogeneous area of thermal system insulation that is not assumed to be ACM.

(2) Collect at least one bulk sample from each homogeneous area of patched thermal system insulation that is not assumed to be ACM if the patched section is less than six linear or six square feet.

(3) In a manner sufficient to determine whether the material is ACM or not ACM, collect bulk samples from each insulated mechanical system that is not assumed to be ACM where cement or plaster is used on fittings such as tees, elbows, or valves, except as provided under 763.87 (c) (2).

(4) Bulk samples are not required to be collected from any homogeneous area where the accredited inspector has determined that the thermal system insulation is fiberglass, foam glass, rubber, or other non-ACM.

(c) **Miscellaneous material.** In a manner sufficient to determine whether material is ACM or not ACM, an accredited inspector shall collect bulk samples from each homogeneous area of friable miscellaneous material that is not assumed to be ACM.

(d) **Nonfriable suspected ACBM.** If any homogeneous area of nonfriable suspected ACM, has been or will be rendered friable, then an accredited inspector shall collect, in a manner sufficient to determine whether the material is ACM or not ACM, bulk samples from the homogeneous area of nonfriable suspected ACBM that is not assumed to be ACM.

LABORATORY ANALYTICAL METHODS

(1) Stereoscopic Examination and Description:

- (a) The sample is examined with a stereomicroscope in a HEPA-filtered hood to determine color, general morphology, and the presence of distinct layers.
- (b) The sample is compared with the client description and discrepancies noted.
- (c) The sample is teased apart with forceps and tweezers. A description of the sample is entered into the laboratory notebook or directly into the computer.
- (d) The presence of fibers is noted, and their general physical characteristics such as morphology, color, elasticity, etc., are described.
- (e) Estimates of the percent by volume of each type of fiber in each individual layer is entered into the computer.
- (f) Mounts of the different fibers and matrix material are prepared for examination under the polarized light microscope.
- (g) If no fibers are observed during this examination, mounts of the matrix materials are made to search for very fine asbestos fibers.
- (h) Samples which are hard, or in which the asbestos is tightly bound, may be handled in various ways so that asbestos can be made available for analysis.

(2) Sample Preparation for viewing by PLM:

- (a) Two mounts of the sample, including fibers and matrix material, are usually made, one in 1.550 refractive index oil and the other in 1.680 refractive index oil. These oils are used for the two most common types of asbestos; Chrysotile and amosite. Two preparations should provide adequate material to characterize the material under the microscope.
- (b) If no fibers are noted, this step is repeated at least once.
- (c) Mechanical grinding of the mount using the eraser end of a pencil, or gentle heating of the sample may be required to free the fibers from the binder.

(3) Sample Examination by PLM:

- (a) Fibers in the sample are examined to determine if their morphological and crystallographic properties are consistent with those common to asbestos minerals. Optical properties examined include sign of elongation, extinction angles, and determination of the refractive index of the fibers using the Becke Line Method or dispersion staining color techniques.
- (b) Additional mounts are made as necessary in order to optically match the refractive index of the fiber to that of the oil. Dispersion staining colors are considered the definitive property on which the identification is based.

(4) Other Characteristics of Asbestos Minerals:

- Fibers will not burn.
- Fibers are resistant to acid.
- Fibers may change their sign of elongation after being subjected to intense heat.
- Fibers may exhibit higher refractive indices after being subjected to intense heat.

(5) Special treatment for samples in which the asbestos is tightly bound may be required for plasters, cements, floor tiles, roofing, and other nonfriable materials. In some cases, the fibers of interest may be found by simply breaking the sample to view a freshly broken surface. Visible fibers may be pulled out and mounted for further examination. If this is not possible, the sample may be broken into smaller pieces, and ground up using a mortar and pestle or dissolved using solvents and gravimetric techniques as recommended by the Research Triangle Institute Draft Test Method for the Determination of Asbestos in Bulk Building Material, July, 1991.

(6) Quantification of Materials Present:

(a) For the most part, if asbestos is present in amounts greater than 3%, quantification is fairly reliable. In the samples where the asbestos levels are closer to 1%, quantification is more difficult and often due to some subjectivity on part of the analyst.

(b) Quantification by weight or volume of asbestos in a sample is based on the relative volumes of asbestos compared to other material present. The quantification is subjective and makes the assumptions that the densities of materials present are approximately the same and that the volumes can be reasonably estimated from a two-dimensional view.

(c) Analysts are "calibrated" by analyzing known-weight samples and by reference samples provided by NIST.

(7) Final Evaluation and Recording:

(a) A description of the sample and all properties of asbestos fibers and their final percentages found during the analysis are recorded in the laboratory notebook or the computer.

(b) A final percentage by volume is reported for the non-asbestos fibers identified and reported in the same manner.

(c) Nonfibrous accessory phases, fillers, and binders are noted where identifiable.

(8) Completion of Sample Report:

(a) When the sample analysis and data recording is complete, the Chain-of-Custody form is signed by the analyst.

(b) The bulk data is stored in the computer of Lab Notebook includes the optical data justifying the analysis. Hard copies of the analytical data and computer backups are generated on a weekly basis.

(c) The final Bulk Sample Report is printed and reviewed by the analyst and/or Laboratory Manager who signs the computerized copy. The original signed copy is sent to the client along with a copy of the Chain-of-Custody, the original of which is maintained on file with the lab.

(9) Quality Control Issues:

(a) Contamination: All manipulation of the samples outside of the sample container is performed inside the HEPA-filtered hood. All laboratory work surfaces in and out of the hoods are kept clean before, during and after sample analysis using wet wipes to clean any debris which may result from sample manipulation. Tools used for analysis are cleaned before, during and after each sample analysis using wet wipes and chem wipes. Care is used to assure tools remain clean to avoid cross contamination between samples. Spray bottles of amended water are kept at each station preparation. Only clean microscope slides and coverslips are used. Each sample is completed and the sample container is closed before the next sample is begun.

Monthly air sampling is performed in the laboratory to ascertain the level of fibrous material in the air. If results of the PCM analysis show fiber levels greater than 0.01 fibers per cc of air, the sample will be sent for analysis by TEM.

(b) Intralaboratory and Interlaboratory Quality Control: In cases of a questionable analysis, such as when the asbestos is detected at or around 1%, when the asbestos has been altered, or when an uncommon type of asbestos is found, a split of the sample will be analyzed by a second analyst or will be sent to a NVLAP accredited laboratory for confirmation. Approximately 10% of all samples are submitted for blind reanalysis either as duplicate or replicate samples. These samples are chosen at random and include samples which contain asbestos, and those which do not. The samples may be analyzed by a different analyst by the original analyst. These results are recorded in the Laboratory QC Notebook, and compared with the original result.

The bulk laboratory participates in a Interlaboratory Quality Assurance Program (IQAP) round robin asbestos sample exchange program. Results from at least three other participating laboratories are returned to the laboratory for comparison. Any discrepancies are noted and the sample re-submitted to the analyst whose analysis resulted in a discrepancy. This analyst repeats the sample and records the repeat analysis. It is the Laboratory Manager's responsibility to notify the client of any change in analytical result from that which was originally reported, this notification is also kept on file by the laboratory.

Asbestos Material Summary


<u>SAMPLE#</u>	<u>HSA#</u>	<u>MATERIAL DESCRIPTION</u>	<u>LOCATIONS</u>	<u>QUANTITY</u>	<u>CONDITION</u>	<u>PHOTO#</u>	<u>% ASBESTOS</u>
T-01	01	Floor tile, 9x9, mustard/gold green	Lower bedroom, under carpet	150 sq. ft.	good	2	8% chrysotile
T-07	07	Floor tile, 9x9, beige with green spots	Furnace room, lower level	60 sq. ft.	good	3	10% chrysotile
T-13	13	Floor tile 9x9, tan with light brown spots	Utility room, lower level	170 sq. ft.	good	4	3% chrysotile
T-22	22	Gasket of furnace, brown	Furnace room,blower/furnace	1 sq. ft.	good	6	80% chrysotile
T-40	40	Cove base mastic, yellow	N. Upper Bathroom	30 ln ft.	good	11	2% chrysotile 5% Tremolite
T-43	43	Floor tile 9x9, brown with multi colors	Main floor laundry room	150 sq. ft.	Good	12	10% chrysotile
T-49	49	floor tile 9x9, tan with brown spots	Main floor, N. bedroom	120 sq. ft.	Good	13	10% chrysotile

COMMENTS: (HSA#) Represents homogeneous sampling areas of identical materials.
(Quantities) All quantities listed are approximate values.
(Condition) Condition of materials were assessed at date and time of inspection.
(Photo#) Photographs may not show specific sample location.


NOTE: All samples were collected by AHERA accredited inspectors and analyzed by NVLAP and AIHA laboratories.

CONDITIONS: Good / Fair / Poor


Picture No. 1




Picture No. 2




Picture No. 3




Picture No. 4




Picture No. 5




Picture No. 6




Picture No. 7



Picture No. 8



Picture No. 9




Picture No. 10




Picture No. 11




Picture No. 12




Picture No. 13



Picture No. 14



Picture No. 15



Bulk Asbestos Sample Analysis Summary

<u>Sample#</u>	<u>HSA#</u>	<u>Material Description</u>	<u>Sample Location</u>	<u>Photo#</u>	<u>% Asbestos</u>
T- 01	001	Floor tile, 9x9 mustard color	Lower bedroom,under carpet	2	8% chrysotile
T- 02	001	Floor tile, 9x9 mustard color	Lower bedroom,under carpet	2	Did not analyze
T- 03	001	Floor tile, 9x9 mustard color	Lower bedroom,under carpet	2	Did not analyze
T- 04	002	Mastic of floor tile 9x9, black	Lower bedroom,under carpet	2	0%
T- 05	002	Mastic of floor tile 9x9, black	Lower bedroom,under carpet	2	0%
T- 06	002	Mastic of floor tile 9x9, black	Lower bedroom,under carpet	2	0%
T- 07	003	Floor tile, 9x9, beige, brown spots	Furnace room, lower level	3	10% chrysotile
T- 08	003	Floor tile, 9x9, beige, brown spots	Furnace room, lower level	3	Did not analyze
T- 09	003	Floor tile, 9x9, beige, brown spots	Furnace room, lower level	3	Did not analyze
T- 10	004	Mastic of floor tile 9x9, black	Furnace room, lower level	3	0%
T- 11	004	Mastic of floor tile 9x9, black	Furnace room, lower level	3	0%
T- 12	004	Mastic of floor tile 9x9, black	Furnace room, lower level	3	0%
T-13	005	Floor tile, 9x9, tan w/light brown	Utility room, lower level	4	3% chrysotile
T-14	005	Floor tile, 9x9, tan w/light brown	Utility room, lower level	4	Did not analyze
T-15	005	Floor tile, 9x9, tan w/light brown	Utility room, lower level	4	Did not analyze
T-16	006	Mastic of floor tile 9x9, brown	Utility room, lower level	4	0%
T-17	006	Mastic of floor tile 9x9, brown	Utility room, lower level	4	0%
T-18	006	Mastic of floor tile 9x9, brown	Utility room, lower level	4	0%
T-19	007	Cove base mastic, yellow	Utility room, lower level	5	0%
T-20	007	Cove base mastic, yellow	Utility room, lower level	5	0%
T-21	007	Cove base mastic, yellow	Utility room, lower level	5	0%
T-22	008	Gasket of furnace, brown	Furnace room, lower level	6	80% Chrysotile
T-23	008	Gasket of furnace, brown	Furnace room, lower level	6	Did not analyze
T-24	008	Gasket of furnace, brown	Furnace room, lower level	6	Did not analyze

Bulk Asbestos Sample Analysis Summary

<u>Sample#</u>	<u>HSA#</u>	<u>Material Description</u>	<u>Sample Location</u>	<u>Photo#</u>	<u>% Asbestos</u>
T-25	009	Drywall taping compound	Furnace room, lower level	7	0%
T-26	009	Drywall taping compound	Furnace room, lower level	7	0%
T-27	009	Drywall taping compound	Furnace room, lower level	7	0%
T-28	010	Drywall patching compound	Furnace room, lower level	8	0%
T-29	010	Drywall patching compound	Furnace room, lower level	8	0%
T-30	010	Drywall patching compound	Furnace room, lower level	8	0%
T-31	011	Sheet rock, gray w/tan paper	Furnace room, lower level	9	0%
T-32	011	Sheet rock, gray w/tan paper	Furnace room, lower level	9	0%
T-33	011	Sheet rock, gray w/tan paper	Furnace room, lower level	9	0%
T-34	012	Sheet vinyl, gray&black w/colored specs.	Under carpet, main floor N. bathroom	10	0%
T-35	012	Sheet vinyl, gray&black w/colored specs.	Under carpet, main floor N. bathroom	10	0%
T-36	012	Sheet vinyl, gray&black w/colored specs.	Under carpet, main floor N. bathroom	10	0%
T-37	013	Mastic of sheet vinyl, black	N. bathroom, main floor	10	0%
T-38	013	Mastic of sheet vinyl, black	N. bathroom, main floor	10	0%
T-39	013	Mastic of sheet vinyl, black	N. bathroom, main floor	10	0%
T-40	014	Cove base mastic	N. bathroom, main floor	11	2% chrysotile 5% Tremolite
T-41	014	Cove base mastic	N. bathroom, main floor	11	Did not analyze
T-42	014	Cove base mastic	N. bathroom, main floor	11	Did not analyze
T-43	015	Floor tile 9x9, brown w/multi colors	Laundry room, main floor	12	10% chrysotile
T-44	015	Floor tile 9x9, brown w/multi colors	Laundry room, main floor	12	Did not analyze
T-45	015	Floor tile 9x9, brown w/multi colors	Laundry room, main floor	12	Did not analyze
T-46	016	Mastic of floor tile (9x9), black	Laundry room, main floor	12	0%
T-47	016	Mastic of floor tile (9x9), black	Laundry room, main floor	12	0%

Bulk Asbestos Sample Analysis Summary

<u>Sample#</u>	<u>HSA#</u>	<u>Material Description</u>	<u>Sample Location</u>	<u>Photo#</u>	<u>% Asbestos</u>
T-48	016	Mastic of floor tile (9x9), black	Laundry room, main floor	12	0%
T-49	017	Floor tile 9x9, tan w/brown spots	N. bedroom, main floor	13	10% chrysotile
T-50	017	Floor tile 9x9, tan w/brown spots	N. bedroom, main floor	13	Did not analyze
T-51	017	Floor tile 9x9, tan w/brown spots	N. bedroom, main floor	13	Did not analyze
T-52	018	Mastic of floor tile (9x9), black	N. bedroom, main floor	13	0%
T-53	018	Mastic of floor tile (9x9), black	N. bedroom, main floor	13	0%
T-54	018	Mastic of floor tile (9x9), black	N. bedroom, main floor	13	0%
T-55	019	Skimcoat, rough textured walls	Living room, main floor	14	0%
T-56	019	Skimcoat, rough textured walls	S. bedroom, main floor	14	0%
T-57	019	Skimcoat, rough textured walls	S. bathroom, main floor	14	0%
T-58	020	Ceiling texture, brocade	Foyer, main level	15	0%
T-59	020	Ceiling texture, brocade	Living room, main floor	15	0%
T-60	020	Ceiling texture, brocade	N.W. bedroom, main floor	15	0%
T-61	021	Roofing, three tab	Roof	N/A	0%
T-62	021	Roofing, three tab	Roof	N/A	0%
T-63	021	Roofing, three tab	Roof	N/A	0%



THREE RIVERS ENVIRONMENTAL

101 Hwy 216 Jacksonville, OR 97027
Phone (503) 557-2396 FAX: (503) 557-3025

1230 AM

CHAIN OF CUSTODY

Attention: _____
Company Name: _____
Billing Address: _____
TEL: () _____ FAX: () _____

SAMPLE TYPE

ASBESTOS
 PLAT (100%)
 PCM (AW)
 TBM (AW)

LEAD
 AA Flame (A)
 AA Flame (AW, Wipe)
 TCLP
 EPA 200503 Swire (Drinking Water)

SAMPLE TURNAROUND

Standard (5 day)
 Priority (3 day)
 Rush (24 hour)

Other (specify): _____

TRE Client Number: *1020*
 P.O. Number: _____
 Project Number: *1020-88*
 Date Sampled: *01/10/2000*
 Date Submitted: *01/10/2000*
 Special Instructions: _____

Sample ID	Date	Field Strip	Sample Description	Sample Location	Quantity (SFLP)	Photo #	Result
T-01	01-10-2000	X	FLOOR TILE, 9X9 TAN MUSTARD COLOR	LOWER BEDROOM, UNDER CARPET	150 SQ FT	#1 2	
T-02	"		" " "	"	"	"	
T-03	"		" " "	"	"	"	
T-04	01-10-2000	X	MASTIC OF FLOOR TILE (9X9) BLACK	LOWER BEDROOM, UNDER CARPET	150 SQ FT	#1 2	
T-05	"		" " "	"	"	"	
T-06	"		" " "	"	"	"	
T-07	01-10-2000	X	FLOOR TILE, 9X9 BIRBLE, BROWN SPOTS	FURNACE RM, LOWER LEVEL	60 SQ FT	#2 3	
T-08	"		" " "	"	"	"	
T-09	"		" " "	"	"	"	
T-10	01-10-2000	X	MASTIC OF FLOOR TILE (9X9) BLACK	FURNACE RM, LOWER LEVEL	60 SQ FT	#2 3	
T-11	"		" " "	"	"	"	
T-12	"		" " "	"	"	"	
T-13	01-12-2000	X	FLOOR TILE, 9X9, TAN W LIGHT BROWN SPOTS	UTILITY RM, LOWER LEVEL	70 SQ FT	#3 4	
T-14	"		" " "	"	"	"	
T-15	"		" " "	"	"	"	
T-16	01-12-2000	X	MASTIC OF FLOOR TILE (9X9) BROWN	UTILITY RM, LOWER LEVEL	70 SQ FT	#3 4	
T-17	"		" " "	"	"	"	
T-18	"		" " "	"	"	"	

Sampled By: (Sign) <i>[Signature]</i>	Relinquished By: (Sign) <i>[Signature]</i>	Date <i>01/10/00</i>	Time <i>1400</i>	Received By: (Sign) <i>[Signature]</i>	Date <i>1-11-00</i>	Time <i>9am</i>
				LAB:		



THREE RIVERS ENVIRONMENTAL

P.O. Box 216 Gladstone, OR 97027
Phone (503) 557-2396 FAX: (503) 557-3025

CHAIN OF CUSTODY

Attention: _____
 Company Name: _____
 Mailing Address: _____
 Phone: () _____ FAX: () _____

SAMPLE TYPE

ASBESTOS

PLM (bulk) PLM ALIENA Sample Cleanup (Woods only)

PCN (air)

TERN (air)

LEAD

AA Flame (air)

AA Flame (rub. wipe)

TCLP

EPA 100/500 Series (Drinking Water)

SAMPLE TURNAROUND

Standard (5 day)

Priority (3 day)

Rush (24 hour)

Other (specify): _____

TRE Client Number: 1020

P.O. Number: _____

Project Number: 1020-88

Date Sampled: 01-10-2000

Date Submitted: 01-10-2000

Special Instructions: _____

Sample ID	Date	Field Step	Sample Description	Sample Location	Quantity (SFL/F)	Volume	Result
T-19	01-10-2000	X	COVE BASE MASTIC, YELLOW	UTILITY RM, LOWER LEVEL	38 LB FT	#45	
T-20	"		"	"	"	↓	
T-21	"		"	"	"	↓	
T-22	01-10-2000	X	LOASKET OF FURNACE (BROWN)	FURNACE RM, BLOWER/FAN	1 LB FT	#56	
T-23	"		"	"	"	↓	
T-24	"		"	"	"	↓	
T-25	01-10-2000	X	DRYWALL TAPING COMPOUND	FURNACE RM, LOWER LEVEL	38 LB FT	#67	
T-26	"		"	"	"	↓	
T-27	"		"	"	"	↓	
T-28	01-10-2000	X	DRYWALL PATCHING COMPOUND	FURNACE RM, LOWER LEVEL	10 LB FT	#78	
T-29	"		"	"	"	↓	
T-30	"		"	"	"	↓	
T-31	01-10-2000	X	SHEET ROCK, GREY, W/TAU PAPER	FURNACE RM, LOWER LEVEL	80 LB FT	#89	
T-32	"		"	"	"	↓	
T-33	"		"	"	"	↓	
T-34	01-10-2000	X	SHEET VINYL, GREY, BLACK W COLORED SQUARES	UNDER CARPET MAIN BLDG, N. BATHROOM	40 LB FT	#910	
T-35	"		"	"	"	↓	
T-36	"		"	"	"	↓	

Sampled By: (Sign) <i>[Signature]</i>	Relinquished By: (Sign) <i>[Signature]</i>	Date 01/10/2000	Time 1400	Received By: (Sign) <i>[Signature]</i>	Date 01-11-2000	Time 9am
LAB:						



CHAIN OF CUSTODY

Attention: _____
 Company Name: _____
 Mailing Address: _____
 Phone: () _____ FAX: () _____

SAMPLE TYPE

ASBESTOS
 PCM (mat) PCM (air) PCM (soil)
 TERT (air)

LEAD

AA Flume (air) AA Flume (rain, water)
 TCLP EPA 200/300 Swine (Drinking Water)

SAMPLE TURNAROUND

Standard (5 day)
 Priority (3 day)
 Rush (24 hour)

Other (specify): _____

TRE Client Number: 1020
 P.O. Number: _____
 Project Number: 1020-88
 Date Sampled: 01-10-2000
 Date Submitted: _____
 Special Instructions: _____

Sample ID	Date	Public Step	Sample Description	Sample Location	Quantity (SQ FT)	FIGURE	Result
T-37	01-10-2000	X	MASTIC OF SHEET VINYL, BLACK	N. UPPER BATHROOM (MAIN FLOOR)	40 SQ FT	#9/10	
T-38	"		" " "	" "	"	↓	
T-39	"		" " "	" "	"	↓	
T-40	01-10-2000	X	COVE BASE MASTIC, YELLOW	N. UPPER BATHROOM "	30 SQ FT	#10/11	
T-41	"		" "	" "	"	↓	
T-42	"		" "	" "	"	↓	
T-43	01-10-2000	X	FLOOR TILE, 9x9, BROWN W/MULTI COLORS	MAIN FLOOR, LAUNDRY ROOM	150 SQ	#11/12	
T-44	"		" " "	" "	"	↓	
T-45	"		" " "	" "	"	↓	
T-46	01-10-2000	X	MASTIC OF FLOOR TILE (9x9) BLACK	MAIN FLOOR, LAUNDRY ROOM	150 SQ	#11/12	
T-47	"		" " "	" "	"	↓	
T-48	"		" " "	" "	"	↓	
T-49	01-10-2000	X	FLOOR TILE, 9x9, TAN W BROWN SPOTS	MAIN FLOOR, NO. BED ROOM	120 SQ FT	#12/13	
T-50	"		" " "	" "	"	↓	
T-51	"		" " "	" "	"	↓	
T-52	01-10-2000	X	MASTIC OF FLOOR TILE, BLACK	MAIN FLOOR, NO. BEDROOM	120 SQ FT	#12/13	
T-53	"		" " "	" "	"	↓	
T-54	"		" " "	" "	"	↓	

Sampled By: (Sign)	Relinquished By: (Sign)	Date	Time	Received By: (Sign)	Date	Time
<i>[Signature]</i>	<i>[Signature]</i>	01/10/2000	1400	<i>[Signature]</i>	1-11-00	9am
				LAB:		



THREE RIVERS ENVIRONMENTAL
 P.O. Box 216 Gladstone, OR 97127
 Phone: (503) 557-2396 FAX: (503) 557-3025

CHAIN OF CUSTODY

Attention: _____
 Company Name: _____
 Mailing Address: _____
 Phone: () _____ FAX: () _____

SAMPLE TYPE

ASBESTOS
 PLAIN (wall) PLAIN ATTIC/BLDG Sample Chain Holder only
 TCM (wall) TCM (air)
 TCM (air)

LEAD
 AA Plastic (air) Other (specify) _____
 AA Plastic (dust, wipe)
 TCM
 EPA 30050a Swine (Drinking Water)

TRE Client Number: 1020
 P.O. Number: _____
 Project Number: 1020-88
 Date Sampled: 01-10-2000
 Date Submitted: 01-10-2000
 Special Instructions: _____

Sample ID	Date	Pushes Stop	Sample Description	Sample Location	Quantity (SF/F)	PHOTO Volume	Result
T-55	01-10-2000	X	WALLCOAT, Rough Textured WALLS	Mainlevel Living Room	1400 Sq. FT	#4314	
T-56	"		"	Mainlevel, South BEDROOM	800 Sq. FT	"	
T-57	"		"	Mainlevel S. Bath Room	420 Sq. FT	"	
T-58	01-10-2000	X	CEILING TEXTURE, PROCAOZ	Mainlevel FOYER	600 Sq. FT	#4415	
T-59	"		"	Mainlevel Living Room	450 Sq. FT	"	
T-60	"		"	Mainlevel NW. BATHROOM	120 Sq. FT	"	
T-61	01-10-2000	A	ROOFING, THREE TAB.	ROOF	about 2000 Sq. FT	(None)	
T-62	"		"	"	"	"	
T-63	"		"	"	"	"	

Sampled By: (Sign) <i>Liiff</i>	Relinquished By: (Sign) <i>Liiff</i>	Date 01/09/00	Time 1400	Received By: (Sign) <i>Michael Moore</i>	Date 1-11-00	Time 9am
				LAB:		

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7489 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 FAX 804-275-4907

BULK ASBESTOS SAMPLE ANALYSIS SUMMARY

CLIENT: Three Rivers Environmental
P.O. Box 216
Gladstone, OR 97027

DATE OF RECEIPT: 11 JAN 2000
DATE OF ANALYSIS: 11 JAN 2000
DATE OF REPORT: 11 JAN 2000

CLIENT NUMBER: 88-2970
EHS PROJECT #: 01-00-0723
PROJECT: 1020-88

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
01	T-01/ Mustard/Gold Gran.	8% Chrysotile 8% Total Asbestos	92% Non-Fibrous
02	T-02/	DID NOT ANALYZE	
03	T-03/	DID NOT ANALYZE	
04	T-04/ Black Adhes.	NAD	5% Cellulose 1% Hair 94% Non-Fibrous
05	T-05/ Black Adhes.	NAD	5% Cellulose 95% Non-Fibrous
06	T-06/ Black Adhes.	NAD	6% Cellulose 94% Non-Fibrous
07	T-07/ Beige Gran.	10% Chrysotile 10% Total Asbestos	90% Non-Fibrous
08	T-08/	DID NOT ANALYZE	
09	T-09/	DID NOT ANALYZE	
10	T-10/ Black Adhes.	NAD	8% Cellulose 92% Non-Fibrous
11	T-11/ Black Adhes.	NAD	5% Cellulose 2% Hair 93% Non-Fibrous
12	T-12/ Black Adhes.	NAD	7% Cellulose 93% Non-Fibrous
13	T-13/ Tan Gran.	3% Chrysotile 3% Total Asbestos	97% Non-Fibrous
14	T-14/	DID NOT ANALYZE	

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 38-2970
 EHS PROJECT #: 01-00-0723
 PROJECT: 1020-88

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
15	T-15/	DID NOT ANALYZE	
16	T-16/ Gold Adhes.	NAD	15% Cellulose 85% Non-Fibrous
17	T-17/ Gold Adhes.	NAD	12% Cellulose 88% Non-Fibrous
18	T-18/ Gold Adhes.	NAD	15% Cellulose 85% Non-Fibrous
19	T-19/ Yellow Adhes.	NAD	10% Cellulose 90% Non-Fibrous
20	T-20/ Yellow Adhes.	NAD	7% Cellulose 93% Non-Fibrous
21	T-21/ Yellow Adhes.	NAD	4% Cellulose 96% Non-Fibrous
22	T-22/ Brown Fib.	80% Chrysotile 80% Total Asbestos	2% Cellulose 18% Non-Fibrous
23	T-23/	DID NOT ANALYZE	
24	T-24/	DID NOT ANALYZE	
25	T-25/ White Brittle; Beige Fib.	NAD	55% Cellulose 45% Non-Fibrous
26	T-26/ White Brittle; Beige Fib.	NAD	55% Cellulose 45% Non-Fibrous
27	T-27/ White Brittle; Beige Fib.	NAD	55% Cellulose 45% Non-Fibrous
28	T-28/ White Brittle	NAD	5% Cellulose 95% Non-Fibrous
29	T-29/ White Brittle	NAD	5% Cellulose 95% Non-Fibrous
30	T-30/ White Brittle	NAD	10% Cellulose 90% Non-Fibrous
31	T-31/ Pale Gray/Tan Fib.	NAD	30% Cellulose 70% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 38-2970
 EHS PROJECT #: 01-00-0723
 PROJECT: 1020-88

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
32	T-32/ Pale Gray/Tan Fib.	NAD	30% Cellulose 70% Non-Fibrous
33	T-33/ Pale Gray/Tan Fib.	NAD	30% Cellulose 70% Non-Fibrous
34	T-34/ Black/Multi-Colored Vinyl-Like; Black Fib.	NAD	45% Cellulose 15% Hair 40% Non-Fibrous
35	T-35/ Black/Multi-Colored Vinyl-Like; Black Fib.	NAD	45% Cellulose 15% Hair 40% Non-Fibrous
36	T-36/ Black/Multi-Colored Vinyl-Like; Black Fib.	NAD	45% Cellulose 15% Hair 40% Non-Fibrous
37	T-37/ Black Adhes.	NAD	7% Cellulose 3% Hair 90% Non-Fibrous
38	T-38/ Black Adhes.	NAD	8% Cellulose 2% Hair 90% Non-Fibrous
39	T-39/ Black Adhes.	NAD	7% Cellulose 2% Hair 91% Non-Fibrous
40	T-40/ Brown Adhes.	2% Chrysotile 5% Tremolite 7% Total Asbestos	2% Cellulose 4% Fibrous Glass 87% Non-Fibrous
41	T-41/	DID NOT ANALYZE	
42	T-42/	DID NOT ANALYZE	
43	T-43/ Brown Gran.	10% Chrysotile 10% Total Asbestos	90% Non-Fibrous
44	T-44/	DID NOT ANALYZE	
45	T-45/	DID NOT ANALYZE	
46	T-46/ Black Adhes.	NAD	20% Cellulose 80% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 38-2970
 EHS PROJECT #: 01-00-0723
 PROJECT: 1020-88


EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
47	T-47/ Black Adhes.	NAD	15% Cellulose 85% Non-Fibrous
48	T-48/ Black Adhes.	NAD	15% Cellulose 85% Non-Fibrous
49	T-49/ Tan Gran.	10% Chrysotile 10% Total Asbestos	90% Non-Fibrous
50	T-50/	DID NOT ANALYZE	
51	T-51/	DID NOT ANALYZE	
52	T-52/ Black Adhes.	NAD	5% Cellulose 95% Non-Fibrous
53	T-53/ Black Adhes.	NAD	7% Cellulose 93% Non-Fibrous
54	T-54/ Black Adhes.	NAD	5% Cellulose 95% Non-Fibrous
55	T-55/ White/Pink Brittle	NAD	1% Cellulose 99% Non-Fibrous
56	T-56/ White/Off-White Brittle	NAD	1% Cellulose 99% Non-Fibrous
57	T-57/ White/Pink Brittle	NAD	2% Cellulose 98% Non-Fibrous
58	T-58/ White/Pink Brittle	NAD	1% Cellulose 99% Non-Fibrous
59	T-59/ White/Green Brittle	NAD	2% Cellulose 98% Non-Fibrous
60	T-60/ White/Pink Brittle	NAD	2% Cellulose 98% Non-Fibrous
61	T-61/ Black Fib.; Gray/Brown Aggregate	NAD	35% Cellulose 65% Non-Fibrous
62	T-62/ Black Fib.; Gray/Brown Aggregate	NAD	35% Cellulose 65% Non-Fibrous
63	T-63/ Black Fib.; Gray/Brown Aggregate	NAD	35% Cellulose 65% Non-Fibrous

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

CLIENT NUMBER: 38-2970
EHS PROJECT #: 01-00-0723
PROJECT: 1020-88

QC SAMPLE: MI-1993-1
REPORTING LIMIT: 1% Asbestos
METHOD: Polarized Light Microscopy, EPA Method 600/R-93/116
ANALYST: Mark Case

Reviewed By Authorized Signatory:


Howard Varner, Laboratory Director
Irma Faszewski, Quality Assurance Coordinator
David Xu, MS, Senior Chemist
Feng Jiang, MS, Senior Geologist

Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C. California Certification #2319

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy ((TEM), for enhanced detection capabilities) for materials regulated by the EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

LEGEND NAD = no asbestos detected
 SCF = suspected ceramic fibers


pim1.dov01 APR 1999/ mec

— PAGE 05 of 05 — END OF REPORT —

Certificate of Completion

This is to certify that
Robert C. Montgomery
has satisfactorily completed
4 hours of refresher training as a
Building Inspector
in compliance with TSCA Title II
AHERA Accredited

Sep 23, 1999



Training Coordinator

Exp. Date: Sep 22, 2000



Prezant



Cert. #99-1931

Conducted at:

PacPro - Gresham, OR


Prezant Associates, Inc. • 330 Sixth Avenue North, Suite 200 • Seattle, Washington 98109 • (206) 281-8858

Certificate of Completion

Irvin D. Jones

has successfully completed the requisite training and examination for
accreditation under TSCA Title II
EPA AHERA (Asbestos Hazard Emergency Response Act),
and ASHARA Model Accreditation Program requirements

AHERA INSPECTOR COURSE
as presented by
Clayton Environmental Consultants



Garry Rossing
INSTRUCTOR


Course Date: 09/21/99 through 09/23/99

Certification # 244-88-8571 Examination Date: 09/23/99

Certificate Expiration Date: 09/22/00

Clayton
ENVIRONMENTAL
CONSULTANTS

Clayton Environmental Consultants is a Division of Clayton Group Services, Inc.
11675 SW 66th Ave. Portland, Oregon 97223 •(503) 968-2112 •fax (503) 968-2213



THE AMERICAN
ASSOCIATION
FOR LABORATORY
ACCREDITATION

ACCREDITED LABORATORY

A2LA has accredited

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.
Richmond, VA


for technical competence in the field of

Environmental Testing

The accreditation covers the specific tests and types of tests listed on the agreed scope of accreditation. This laboratory meets the requirements of ISO/IEC Guide 25-1990 "General Requirements for the Competence of Calibration and Testing Laboratories" (equivalent to relevant requirements of the ISO 9000 series of standards) and any additional program requirements in the identified field of testing.

Presented this 12th day of January, 1999.





President
For the Accreditation Council
Certificate Number 716.01
Valid to 08/31/2000

For tests or types of tests to which this accreditation applies, please refer to the laboratory's Environmental Scope of Accreditation.



THE AMERICAN ASSOCIATION
FOR LABORATORY ACCREDITATION


A2LA has accredited

Environmental Hazards Services, L.L.C.
Richmond, VA

under the

**ENVIRONMENTAL LEAD (Pb) TESTING
LABORATORY ACCREDITATION PROGRAM**

By virtue of the on site assessment of this laboratory's environmental lead (Pb) testing capabilities and successful participation in the Environmental Lead Proficiency Analytical Testing Program (ELPAT), this laboratory has been found to meet the A2LA Environmental Lead (Pb) Program Requirements. As such, this laboratory is recognized under the EPA Office of Pollution Prevention and Toxics' (OPPT) National Lead Laboratory Accreditation Program (NLLAP) for the matrices of dust, soil and paint chips (residue). The laboratory's A2LA accreditation covers the following matrices: dust, soil, paint chips (residue), air and building debris.



Presented this 12th day of January, 1999.

Peter Abry

President

For the Accreditation Council

Certificate Number 716.01


Valid to 08/31/2000

United States Department of Commerce
National Institute of Standards and Technology

NVLAP[®]

ISO/IEC GUIDE 25:1990
ISO 9002:1987

Certificate of Accreditation



ENVIRONMENTAL HAZARDS SERVICES, L.L.C.
RICHMOND, VA

is recognized under the National Voluntary Laboratory Accreditation Program for satisfactory compliance with criteria established in Title 15, Part 285 Code of Federal Regulations. These criteria encompass the requirements of ISO/IEC Guide 25 and the relevant requirements of ISO 9002 (ANSI/ASQC Q92-1987) as suppliers of calibration or test results. Accreditation is awarded for specific services, listed on the Scope of Accreditation for:

BULK ASBESTOS FIBER ANALYSIS

December 31, 1999

Effective through

For the National Institute of Standards and Technology

NVLAP Lab Code: 101882-0



American Association for Laboratory Accreditation

SCOPE OF ACCREDITATION TO ISO/IEC GUIDE 25-1990

ENVIRONMENTAL HAZARDS SERVICES, L.L.C.

7469 White Pine Road

Richmond, VA 23237

Irma Faszewski Phone: 804 275 4783

ENVIRONMENTAL

Valid To: August 31, 2000

Certificate Number: 0716-01

In recognition of the successful completion of the A2LA evaluation process, accreditation is granted to this laboratory to perform recognized EPA methods using the following testing technologies and in the analyte categories identified below:

Testing Technologies: Atomic Absorption/ICP-AES Spectrometry, Atomic Absorption-Flame, Hazardous Waste Characteristics Tests

Nonpotable Water

Metals: Al, Sb, As, Ba, Be, Cd, Ca, Cr, Co, Cu, Fe, Pb, Mg, Mn, Hg, Mo, Ni, K, Se, Ag, Na, Tl, Sn, Ti, V, Zn-

per EPA test methods SW 6010, 7420, 7470

Solid/Hazardous Waste

Metals: Al, Sb, As, Ba, Be, Cd, Ca, Cr, Co, Cu, Fe, Pb, Mg, Mn, Hg, Mo, Ni, K, Se, Ag, Na, Tl, Sn, Ti, V, Zn

per EPA test methods SW 6010, 7420, 7470

Hazardous Waste Characteristics Test: TCLP

per EPA test method SW 1311

Environmental Lead: soil, paint chips (residue), dust, air, building debris

sample preparation

per EPA test methods SW3050A (soils, building debris); 3050A modified (paints, wipes)

per NIOSH test method 7082 (air)

per EPA test method 600/R-93/200 (sonification - air, paint, soil)

sample analysis

per EPA test methods SW 6010A, 7420

per NIOSH methods 7082, 7300



REINSPECTIONS

This section reflects requirements outlined in 40 CFR 763.85 (b) (1) through (c)

ACTION: Reinspection is recommended every 3 years.

TRAINING: Accredited Inspector/Management Planner.
Decide if you will train in-house people or not.

FORM: Update management plan using Inspector's report format.

At least once every three years, after the Management Plan is in effect, all buildings should be reinspected by an accredited Inspector. This differs from the periodic surveillance and is more comprehensive because the material is actually touched to determine friability or change in friability, along with noting assessment criteria such as condition. The reinspection may also include additional samples of suspect material, accessing previously inaccessible areas, and other activities. The person performing these tasks should, at least, be an accredited Inspector. An accredited Management Planner may be necessary to recommend additional response actions.

The decisions an LEA must make prior to this reinspection is to either train their in-house staff to perform the reinspection or utilize an outside consultant.

The AHERA-accredited Inspector training course is three days long, with a 50-question exam that must be passed. An AHERA Management Planner training course is an additional two days with another 50-question exam. If a person is presently an accredited Inspector or Management Planner, they must have an annual refresher course to keep their accreditation current.

RECORDKEEPING:

Keep the reinspection records in this TAB section, along with any new data. New sample locations should be noted on copies of the drawings in TAB 7, and then filed in this section.

AHERA

Three Year Asbestos Reinspection

**WEST LINN
SCHOOL DISTRICT #3Jt**

OF

**West Linn High School
5464 West "A" Street
West Linn, OR 97068**

Project No. 1020-68

Prepared by:



P.O. Box 216 Gladstone, OR 97027 Phone (503) 557-2396 Fax (503) 557-3025

AHERA Re-inspection

Material: Boiler/tank insulation/mechanical insulation, USA 01

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: N. boiler, S. boiler, DHW tank

Quantity: Approximately 600 sq. ft.
600 sq. ft.
300 sq. ft.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action:

AHERA Re-inspection

Material: Gasket, USA 01

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Boiler, gasket on B1 E. side

Quantity: Approximately 4 sq. ft.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Low pressure steam/MJP on pipe covering, USA 01

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Joints; between boiler #1 & #2 E. side

Quantity: Approximately 25 ln. ft.-10 in. O.D. low pressure steam
30 ln. ft.-12 in. O.D. low pressure steam
25 ln. ft.-14 in. O.D. low pressure steam
39 ln. ft.-6 in. O.D. low pressure steam

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Domestic hot water/MJP on corrugated pipe cover, USA 01

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Joints; between boiler #1 & #2 E. side

Quantity: Approximately 35 ln. ft.-4 in. O.D. domestic hot water
22 ln. ft.-6 in. O.D. domestic hot water

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Domestic hot water/corrugated pipe cover, USA 01

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Piping; between boiler #1 & #2 E. side

Quantity: Approximately 110 ln. ft.-4 in. O.D. domestic hot water
75 ln. ft.-6 in. O.D. domestic hot water

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Domestic cold water/corrugated pipe cover, USA 01

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Piping; between boiler #1 & #2 E. side

Quantity: Approximately 110 ln. ft.-4 in. O.D. domestic cold water
75 ln. ft.-6 in. O.D. domestic cold water

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Low pressure steam/pipe covering, USA 01

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Piping, between boiler #1 & #2 E. side

Quantity: Approximately 100 ln. ft.-10 in. O.D. low pressure steam
130 ln. ft.-12 in. O.D. low pressure steam
50 ln. ft.-14 in. O.D. low pressure steam
15 in. O.D. low pressure steam

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Boiler/tank insulation, USA 02

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Boiler, DHW exchange tanks

Quantity: Approximately 60 sq. ft.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Domestic hot water/MJP on corrugated pipe cover, USA 02

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Joints, S.W. corner

Quantity: Approximately 30 ln. ft.-4 in. O.D. domestic hot water
25 ln. ft.-6 in. O.D. domestic hot water
19 ln. ft.-8 in. O.D. domestic hot water

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Domestic hot water/corrugated pipe cover, USA 02

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Piping; S.W. corner

Quantity: Approximately 175 ln. ft.-4 in. O.D. domestic hot water
65 ln. ft.-6 in. O.D. domestic hot water
65 ln. ft.-8 in. O.D. domestic hot water

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Low pressure steam/pipe covering, USA 03

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: All floors in building

Quantity: Approximately 150 ln. ft.-4 in. O.D.
850 ln. ft.-6 in. O.D.
980 ln. ft.-8 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no
Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Reassess quantity and location, maintain in an intact and undamaged condition

AHERA Re-inspection

Material: Low pressure team/MJP on pipe covering, USA 04

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: All floors in building

Quantity: Approximately 200 ln. ft.-4 in. O.D.
165 ln. ft.-6 in. O.D.
150 ln. ft.-8 in. O.D.
20 ln. ft.-12 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Reassess quantity and location, maintain in an intact and undamaged condition

AHERA Re-inspection

Material: Domestic hot water/pipe covering, USA 05

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: All floors in building

Quantity: Approximately 1,500 ln. ft.-4 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Reassess quantity and location, maintain in an intact and undamaged condition

AHERA Re-inspection

Material: Domestic hot water/MJP on pipe covering, USA 06

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: All floors in building

Quantity: Approximately 330 ln. ft.-4 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Reassess quantity and location, maintain in an intact and undamaged condition

AHERA Re-inspection

Material: Domestic cold water/corrugated pipe covering, USA 07

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: All floors in building

Quantity: Approximately 925 ln. ft.-4 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Reassess quantity and location, maintain in an intact and undamaged condition

AHERA Re-inspection

Material: Domestic cold water/MJP on corrugated pipe cover, USA 08

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: All floors in building

Quantity: Approximately 145 ln. ft.-4 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Reassess quantity and location, maintain in an intact and undamaged condition

AHERA Re-inspection

Material: Acoustical/thermal plaster, USA 11

Description: Surfacing

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: First floor

Quantity: Approximately 21,531 sq. ft.

Potential for disturbance:

Potential for contact:

Effect of vibration:

Potential for air erosion:

Overall condition:

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Low pressure steam/pipe covering, USA 50

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Gym

Quantity: Approximately 5 ln. ft.-8 in. O.D.
5 ln. ft.-6 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no
Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Reassess quantity and location, maintain in an intact and undamaged condition

AHERA Re-inspection

Material: Low pressure steam/MJP on pipe covering, USA 50

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Gym

Quantity: Approximately 2 in. ft.-8 in. O.D.
3 in. ft.-6 in. O.d.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no
Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Reassess quantity and location, maintain in an intact and undamaged condition

AHERA Re-inspection

Material: Low pressure steam/pipe covering, USA 52

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Swimming pool, front room

Quantity: Approximately 20 ln. ft.-8 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Low pressure steam/pipe covering, USA 53

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Tunnel access S. rm. 554

Quantity: Approximately 40 ln. ft.-4 in. O.D.
10 ln. ft.-8 in. O.D.
8 ln. ft.-6 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes
Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Low pressure steam/MJP on pipe covering, USA 54

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Tunnel access S. rm. 554

Quantity: Approximately 4 ln. ft.-14 in. O.D.
2 ln. ft.-8 in. O.D.
12 ln. ft.-6 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Low pressure steam/pipe covering, USA 55

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Main building A., custodial office

Quantity: Approximately 12 ln. ft.-8 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Low pressure steam/pipe covering, USA 56

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Tunnels

Quantity: Approximately 460 ln. ft.-12 in. O.D.
60 ln. ft.-8 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Low pressure steam/MJP on pipe covering, USA 57

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Tunnels

Quantity: Approximately 15 ln. ft.-12 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Domestic cold water/corrugated pipe covering, USA 58

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Tunnels

Quantity: Approximately 60 ln. ft.-6 in. O.D.
200 ln. ft.-4 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes
Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Domestic cold water/MJP on corrugated pipe cover, USA 59

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Tunnels

Quantity: Approximately 40 ln. ft.-4 in. O.D.
38 ln. ft.-6 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Domestic hot water/pipe covering, USA 60

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Tunnels

Quantity: Approximately 200 ln. ft.-4 in. O.D.
50 ln. ft.-6 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Domestic hot water/MJP on pipe covering, USA 61

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Tunnels

Quantity: Approximately 45 ln. ft.-4 in. O.D.
28 ln. ft.-6 in. O.D.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes
Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category: Unchanged

Recommended response action:

AHERA Re-inspection

Material: Vinyl floor tile, USA 97

Description: Miscellaneous

Sampled or Assumed: Surfacing

Friable or Non-Friable: Non-friable

Locations: All floors in building

Quantity: Approximately 50,000 sq. ft.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Transite siding, USA 98

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: All floors in building

Quantity: Approximately 400 sq. ft.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action: Reassess quantity and location

AHERA Re-inspection

Material: Vinyl floor tile, USA 99

Description: Miscellaneous

Sampled or Assumed: Sampled

Friable or Non-Friable: Non-friable

Locations: All floors in building

Quantity: Approximately 86,055 sq. ft.

Potential for disturbance:

Potential for contact: high

Effect of vibration: low

Potential for air erosion: low

Overall condition: fair

Change in condition from last inspection: yes

Assessment noted: 8 locations W. end of Cafeteria and library, material torn loose from floor (20 sq. ft.)

Previous AHERA category: ACBM with potential for damage

New AHERA category: Damaged miscellaneous material

Recommended response action: Repair damaged area and maintain in an intact and undamaged condition.

AHERA Re-inspection

Material: Mag Lines

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Under old building (E & W)

Quantity: Approximately 600 ln. ft. of piping with approx. 50 hard fittings

Potential for disturbance:

Potential for contact: low-piping running under building and over ceiling

Effect of vibration: low

Potential for air erosion: low

Overall condition: poor

Change in condition from last inspection: yes

Assessment noted: Exposed mag with debris, 40 ln. ft. of damage at hangers and floor extrusion, 30-40 sq. ft. debris in crawl space (access closet W. end hallway)

Previous AHERA category: ACBM with potential for damage

New AHERA category: Damaged or significantly damaged TSI

Recommended response action: Repair damaged area and maintain in an intact and undamaged condition.

AHERA Re-inspection

Material: Sheet Vinyl

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Library

Quantity: Approximately 300 sq. ft.

Potential for disturbance:

Potential for contact: high-vinyl flooring

Effect of vibration: moderate-heavy to moderate traffic

Potential for air erosion: low

Overall condition: fair

Change in condition from last inspection: yes

Assessment noted: Abated Summer 1999

Previous AHERA category: ACBM with potential for damage

New AHERA category:

Recommended response action:

AHERA Re-inspection

Material: Corrugated Pipe Cover

Description: TSI

Sampled or Assumed: Sampled

Friable or Non-Friable: Friable

Locations: Rm. E. side of weight room

Quantity: Approximately 40 in. ft.

Potential for disturbance:

Potential for contact: high-in storage room

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition

AHERA Re-inspection

Material: Hard Fittings

Description: TSI

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Wood shop entrance

Quantity: Approximately 16 hard fittings

Potential for disturbance:

Potential for contact: moderate-above drop ceiling by heating duct

Effect of vibration: low

Potential for air erosion: low

Overall condition: fair

Change in condition from last inspection: yes

Assessment noted: Patch & repair, 4 hard fittings damaged, w/debris 6 sq. ft. on drop ceiling (foyer of entrance to wood shop)

Previous AHERA category: ACBM with potential for damage

New AHERA category: Damaged or significantly damaged TSI

Recommended response action: Clean-up debris and repair damaged area and maintain in an intact and undamaged condition

AHERA Re-inspection

Material: Drywall taping compound

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Sheet vinyl mastic

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Under sheet vinyl, various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition, conduct six-month inspection cycle

AHERA Re-inspection

Material: Sheet vinyl

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Window putty

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Throughout school (on exterior windows)

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Fire doors

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Cove base mastic

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Chalkboards

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: In classrooms throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Paint, interior

Description: Surfacing

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: high

Effect of vibration: low

Potential for air erosion: moderate

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: Any remaining friable ACBM or friable suspect ACBM

New AHERA category: Any remaining friable ACBM or friable suspect ACBM

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Electrical wire casing

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Stage lights

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: Any remaining friable ACBM or friable suspect ACBM

New AHERA category: Any remaining friable ACBM or friable suspect ACBM

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Drop-in ceiling tile

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: moderate

Effect of vibration: low

Potential for air erosion: moderate

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: Any remaining friable ACBM or friable suspect ACBM

New AHERA category: Any remaining friable ACBM or friable suspect ACBM

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Transite siding, USA 98

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: All floors in building

Quantity: Approximately 10 sq. ft.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: Unchanged

Recommended response action: Reassess quantity and location

AHERA Re-inspection

Material: Vinyl floor tile, USA 99

Description: Miscellaneous

Sampled or Assumed: Sampled

Friable or Non-Friable: Non-friable

Locations: All floors in building

Quantity: Approximately 11,000 sq. ft.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: Unchanged

Recommended response action: Reassess quantity and locations

AHERA Re-inspection

Material: Drywall taping compound

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Sheet vinyl mastic

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Under sheet vinyl, various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Sheet vinyl

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Window putty

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Throughout school (on exterior windows)

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Fire doors

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Cove base mastic

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Chalkboards

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: In classrooms throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Paint, interior

Description: Surfacing

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: high

Effect of vibration: low

Potential for air erosion: moderate

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: Any remaining friable ACBM or friable suspect ACBM

New AHERA category: Any remaining friable ACBM or friable suspect ACBM

Recommended response action: Maintain in an intact and undamaged condition, conduct six-month inspection cycle

AHERA Re-inspection

Material: Electrical wire casing

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Stage lights

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: Any remaining friable ACBM or friable suspect ACBM

New AHERA category: Any remaining friable ACBM or friable suspect ACBM

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Drop-in ceiling tile

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: moderate

Effect of vibration: low

Potential for air erosion: moderate

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: Any remaining friable ACBM or friable suspect ACBM

New AHERA category: Any remaining friable ACBM or friable suspect ACBM

Recommended response action: Maintain in an intact and undamaged condition, conduct six-month inspection cycle

AHERA Re-inspection

Material: Vinyl floor tile, USA 99

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: All floors in building

Quantity: Approximately 10,000 sq. ft.

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: Unchanged

Recommended response action: Reassess quantity and locations

AHERA Re-inspection

Material: Drywall taping compound

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Sheet vinyl mastic

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Under sheet vinyl, various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition, conduct six-month inspection cycle

AHERA Re-inspection

Material: Sheet vinyl

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Window putty

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Throughout school (on exterior windows)

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Fire doors

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Cove base mastic

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: Throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Chalkboards

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Non-friable

Locations: In classrooms throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: ACBM with potential for damage

New AHERA category: ACBM with potential for damage

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Paint, interior

Description: Surfacing

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: high

Effect of vibration: low

Potential for air erosion: moderate

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: Any remaining friable ACBM or friable suspect ACBM

New AHERA category: Any remaining friable ACBM or friable suspect ACBM

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Electrical wire casing

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Stage lights

Quantity: Not quantified

Potential for disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: Any remaining friable ACBM or friable suspect ACBM

New AHERA category: Any remaining friable ACBM or friable suspect ACBM

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA Re-inspection

Material: Drop-in ceiling tile

Description: Miscellaneous

Sampled or Assumed: Assumed

Friable or Non-Friable: Friable

Locations: Various locations throughout school

Quantity: Not quantified

Potential for disturbance:

Potential for contact: moderate

Effect of vibration: low

Potential for air erosion: moderate

Overall condition: good

Change in condition from last inspection: no

Assessment noted:

Previous AHERA category: Any remaining friable ACBM or friable suspect ACBM

New AHERA category: Any remaining friable ACBM or friable suspect ACBM

Recommended response action: Maintain in an intact and undamaged condition,
conduct six-month inspection cycle

AHERA

Three Year Asbestos Reinspection

for

WEST LINN-WILSONVILLE SCHOOL DISTRICT 3JT

West Linn High School
5464 West "A" St.
West Linn, OR

Project No. 1020-15

September 1998

Prepared by



P.O. Box 216, Gladstone, Oregon 97207 (503) 557-2396 Fax (503) 557-3025

AHERA Re-inspection

Material: Boiler/Tank Insulation/Mechanical Insulation USA 01

Description: TSI, Sampled, Friable

Locations: North Boiler, South Boiler, DHW Tank

Quantity: Approximately: 600 sq. ft.
600 sq. ft.
300 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Gasket, USA 01

Description: Miscellaneous, Non Friable

Locations: Boiler; Gasket on B1 E. Side

Quantity: Approximately 4 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/MJP on Pipe Covering, USA 01

Description: TSI, Sampled, Friable

Locations: Joints, Between Boiler 1 & 2 E. Side

Quantity: Approximately: 25-10 in. O.D. Low Pressure Steam
30-ft. 12 in. O.D. Low Pressure Steam
25-ft. 14 in. O.D. Low Pressure Steam
39-ft. 6 in. O.D. Low Pressure Steam

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/MJP on Corrugated Pipe Cover USA 01

Description: TSI, Sampled, Friable

Locations: Joints; Between Boiler 1 & 2 E. Side

Quantity: Approximately: 35-4 in. O.D. Domestic Hot Water
22-6 in. O.D. Domestic Hot Water

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/Corrugated Pipe Covering USA 01

Description: TSI, Sampled, Friable

Locations: Piping; Between Boiler 1 & 2 E. Side

Quantity: Approximately: 110-4 in. O.D. Domestic Hot Water
75-6 in. O.D. Domestic Hot Water

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Cold Water/Corrugated Pipe Covering, USA 01

Description: TSI, Sampled, Friable

Locations: Piping; Between Boiler 1 & 2 E. Side

Quantity: Approximately: 110-4 in. O.D. Domestic Cold Water
75-6 in. O.D. Domestic Cold Water

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 01

Description: TSI, Sampled, Friable

Locations: Piping; Between Boiler 1 & 2 E. Side

Quantity: Approximately: 100-10 in. O.D. Low Pressure Steam
130-12 in. O.D. Low Pressure Steam
50-14 in. O.D. Low Pressure Steam
15 in. O.D. Low Pressure Steam

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Boiler/Tank Insulation, USA 02

Description: TSI, Sampled, Friable

Locations: Boiler; DHW Exchange Tanks

Quantity: Approximately 60 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/MJP on Corrugated Pipe Covering, USA 02

Description: TSI, Sampled, Friable

Locations: Joints; SW Corner

Quantity: Approximately: 30-4 in. O.D. Domestic Hot Water
25- 6 in. O.D. Domestic Hot Water
19-8 in. O.D. Domestic Hot Water

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/Corrugated Pipe Covering, USA 02

Description: TSI, Sampled, Friable

Locations: Piping, SW Corner

Quantity: Approximately: 175-4 in. O.D. Domestic Hot Water
65-6 in. O.D. Domestic Hot Water
65-8 in. O.D. Domestic Hot Water

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 03

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately: 150-4 in. O.D.
850-6 in. O.D.
980-8 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/MJP on Pipe Covering, USA 04

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately: 200-4 in. O.D.
165-6 in. O.D.
150-8 in. O.D.
20-12 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/Pipe Covering, USA 05

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately 1500-4 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/MJP on Pipe Covering, USA 06

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately 330-4 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Cold Water/Corrugated Pipe Covering, USA 07

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately 925-4 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Cold Water/MJP on Corrugated Pipe Covering, USA 08

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately 145-4 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Acoustical/Thermal Plaster, USA 11

Description: Surfacing, Sampled, Friable

Locations: First Floor

Quantity: Approximately 21,531 sq. ft.-Removed

Potential For Disturbance:

Potential for contact:

Effect of vibration:

Potential for air erosion:

Overall Condition:

Previous AHERA Category: Removed

New AHERA Category:

Recommendations:

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 50

Description: TSI, Sampled, Friable

Locations: Gym

Quantity: Approximately: 5-8 in. O.D.
5-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/MJP on Pipe Covering, USA 50

Description: TSI, Sampled, Friable

Locations: Gym

Quantity: Approximately: 2-8 in. O.D.
3-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 52

Description: TSI, Sampled, Friable

Locations: Swimming Pool, Front Room

Quantity: Approximately 20-8 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 53

Description: TSI, Sampled, Friable

Locations: Tunnel Access South, Rm. 554

Quantity: Approximately: 40-14 in. O.D.
10-8 in. O.D.
8-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/MJP on Pipe Covering, USA 54

Description: TSI, Sampled, Friable

Locations: Tunnel Access South, Rm. 554

Quantity: Approximately: 4-14 in. O.D.
2-8 in. O.D.
12-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 55

Description: TSI, Sampled, Friable

Locations: Main Building A, Custodial Office

Quantity: Approximately 12-8 in.O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 56

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately: 460-12 in. O.D.
60-8 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/MJP on Pipe Covering, USA 57

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately 15-12 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Cold Water/Corrugated Pipe Covering, USA 58

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately: 60-6 in. O.D.
200-4 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Cold Water/MJP on Corrugated Pipe Cover, USA 59

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately: 40-4 in. O.D.
38-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/Pipe Covering, USA 60

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately: 200-4 in. O.D.
50-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/MJP on Pipe Covering, USA 61

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately: 45-4 in. O.D.
28-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Vinyl Floor Tile, USA 97

Description: Miscellaneous, Sampled, Non Friable

Locations: All Floors in Building

Quantity: Approximately 50,000 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Transite Siding, USA 98

Description: Miscellaneous, Assumed, Non Friable

Locations: All Floors in Building

Quantity: Approximately 400 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Vinyl Floor Tile, USA 99

Description: Miscellaneous, Sampled, Non Friable

Locations: All Floors in Building

Quantity: Approximately 86,055 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Transite Siding, USA 98

Description: Miscellaneous, Non Friable

Locations: All Floors in Building.

Quantity: Approximately 10 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Vinyl Floor Tile, USA 99

Description: Miscellaneous, Sampled, Non Friable

Locations: All Floors in Building.

Quantity: Approximately 11,000 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Vinyl Floor Tile, USA 99

Description: Miscellaneous, Sampled, Non Friable

Locations: All Floors in Building.

Quantity: Approximately 10,000 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged




Recommendations: 6 Month Periodic Surveillance




AHERA Reinspection Signature Page

Three Rivers Environmental, Inc. utilized only inspectors accredited as per the EPA Model Accreditation Plan, 40 CFR 763, Subpart E, Appendix C at a minimum. In addition, all inspectors utilized on projects in states which require additional training, qualifications and licensing, met these qualifications and were so licensed in that state. In addition to the EPA required training, Three Rivers Environmental, Inc. inspectors receive extensive field training and further examination prior to project assignment.

The inspection was conducted by the following Three Rivers Environmental, Inc. personnel:

JEFF SMITH Name	98-08185 Accreditation	 Signature
MATT JOHNSON Name	98-08182 Accreditation	 Signature
SHAWN OLSON Name	98-08184 Accreditation	 Signature

The Management Plan recommendation was developed by the following Three Rivers Environmental, Inc. personnel:

JEFF SMITH Name	98-08179 Accreditation	 Signature
 Name	 Accreditation	 Signature
 Name	 Accreditation	 Signature

AHERA

Three Year Asbestos Reinspection

for

WEST LINN-WILSONVILLE SCHOOL DISTRICT 3JT

West Linn High School
5464 West "A" St.
West Linn, OR

Project No. 1020-07

May/June 1995

Prepared by




170 E Arlington Gladstone, Oregon 97027 (503) 656-4601




AHERA Re-inspection Signature page

Three Rivers Environmental utilized only inspectors accredited as per the EPA Model Accreditation Plan, 40 CFR 763, Subpart E, Appendix C at a minimum. In addition, all inspectors utilized on projects in states which require additional training, qualifications and licensing, met these qualifications and were so licensed in that state. In addition to the EPA required training, Three Rivers Environmental inspectors receive extensive field training and further examination prior to project assignment.

The inspection was conducted by the following Three Rivers Environmental personnel:

<u>JEFF SMITH</u> Name	<u>PDR-95-7811</u> Accreditation #	<u></u> Signature
_____ Name	_____ Accreditation #	_____ Signature
_____ Name	_____ Accreditation #	_____ Signature

The Management Plan recommendation was developed by the following Three Rivers Environmental personnel:

<u>JEFF SMITH</u> Name	<u>PDR-95-7811</u> Accreditation #	<u></u> Signature
_____ Name	_____ Accreditation #	_____ Signature
_____ Name	_____ Accreditation #	_____ Signature

AHERA Re-inspection

Material: Transite Siding, USA 98

Description: Miscellaneous, Non Friable

Locations: All Floors in Building.

Quantity: Approximately 10 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Vinyl Floor Tile, USA 99

Description: Miscellaneous, Sampled, Non Friable

Locations: All Floors in Building.

Quantity: Approximately 11,000 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Boiler/Tank Insulation/Mechanical Insulation USA 01

Description: TSI, Sampled, Friable

Locations: North Boiler, South Boiler, DHW Tank

Quantity: Approximately: 600 sq. ft.
600 sq. ft.
300 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Gasket, USA 01

Description: Miscellaneous, Non Friable

Locations: Boiler; Gasket on B1 E. Side

Quantity: Approximately 4 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/MJP on Pipe Covering, USA 01

Description: TSI, Sampled, Friable

Locations: Joints, Between Boiler 1 & 2 E. Side

Quantity: Approximately: 25-10 in. O.D. Low Pressure Steam
30-ft. 12 in. O.D. Low Pressure Steam
25-ft. 14 in. O.D. Low Pressure Steam
39-ft. 6 in. O.D. Low Pressure Steam

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/MJP on Corrugated Pipe Cover USA 01

Description: TSI, Sampled, Friable

Locations: Joints; Between Boiler 1 & 2 E. Side

Quantity: Approximately: 35-4 in. O.D. Domestic Hot Water
22-6 in. O.D. Domestic Hot Water

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/Corrugated Pipe Covering USA 01

Description: TSI, Sampled, Friable

Locations: Piping; Between Boiler 1 & 2 E. Side

Quantity: Approximately: 110-4 in. O.D. Domestic Hot Water
75-6 in. O.D. Domestic Hot Water

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Cold Water/Corrugated Pipe Covering, USA 01

Description: TSI, Sampled, Friable

Locations: Piping; Between Boiler 1 & 2 E. Side

Quantity: Approximately: 110-4 in. O.D. Domestic Cold Water
75-6 in. O.D. Domestic Cold Water

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 01

Description: TSI, Sampled, Friable

Locations: Piping; Between Boiler 1 & 2 E. Side

Quantity: Approximately: 100 10 in. O.D. Low Pressure Steam
130-12 in. O.D. Low Pressure Steam
50-14 in. O.D. Low Pressure Steam
15 in. O.D. Low Pressure Steam

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Boiler/Tank Insulation, USA 02

Description: TSI, Sampled, Friable

Locations: Boiler; DHW Exchange Tanks

Quantity: Approximately 60 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/MJP on Corrugated Pipe Covering, USA 02

Description: TSI, Sampled, Friable

Locations: Joints; SW Corner

Quantity: Approximately: 30-4 in. O.D. Domestic Hot Water
25- 6 in. O.D. Domestic Hot Water
19-8 in. O.D. Domestic Hot Water

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/Corrugated Pipe Covering, USA 02

Description: TSI, Sampled, Friable

Locations: Piping, SW Corner

Quantity: Approximately: 175-4 in. O.D. Domestic Hot Water
65-6 in. O.D. Domestic Hot Water
65-8 in. O.D. Domestic Hot Water

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 03

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately: 150-4 in. O.D.
850-6 in. O.D.
980-8 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/MJP on Pipe Covering, USA 04

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately: 200-4 in. O.D.
165-6 in. O.D.
150-8 in. O.D.
20-12 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/Pipe Covering, USA 05

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately 1500-4 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/MJP on Pipe Covering, USA 06

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately 330-4 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Cold Water/Corrugated Pipe Covering, USA 07

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately 925-4 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Cold Water/MJP on Corrugated Pipe Covering, USA 08

Description: TSI, Sampled, Friable

Locations: All Floors in Building

Quantity: Approximately 145-4 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Acoustical/Thermal Plaster, USA 11

Description: Surfacing, Sampled, Friable

Locations: First Floor

Quantity: Approximately 21,531 sq. ft.-Removed

Potential For Disturbance:

Potential for contact:

Effect of vibration:

Potential for air erosion:

Overall Condition:

Previous AHERA Category: Removed

New AHERA Category:

Recommendations:

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 50

Description: TSI, Sampled, Friable

Locations: Gym

Quantity: Approximately: 5-8 in. O.D.
5-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/MJP on Pipe Covering, USA 50

Description: TSI, Sampled, Friable

Locations: Gym

Quantity: Approximately: 2-8 in. O.D.
3-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 52

Description: TSI, Sampled, Friable

Locations: Swimming Pool, Front Room

Quantity: Approximately 20-8 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 53

Description: TSI, Sampled, Friable

Locations: Tunnel Access South, Rm. 554

Quantity: Approximately: 40-14 in. O.D.
10-8 in. O.D.
8-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/MJP on Pipe Covering, USA 54

Description: TSI, Sampled, Friable

Locations: Tunnel Access South, Rm. 554

Quantity: Approximately: 4-14 in. O.D.
2-8 in. O.D.
12-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 55

Description: TSI, Sampled, Friable

Locations: Main Building A, Custodial Office

Quantity: Approximately 12-8 in.O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/Pipe Covering, USA 56

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately: 460-12 in. O.D.
60-8 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Low Pressure Steam/MJP on Pipe Covering, USA 57

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately 15-12 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Cold Water/Corrugated Pipe Covering, USA 58

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately: 60-6 in. O.D.
200-4 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Cold Water/MJP on Corrugated Pipe Cover, USA 59

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately: 40-4 in. O.D.
38-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/Pipe Covering, USA 60

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately: 200-4 in. O.D.
50-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Domestic Hot Water/MJP on Pipe Covering, USA 61

Description: TSI, Sampled, Friable

Locations: Tunnels

Quantity: Approximately: 45-4 in. O.D.
28-6 in. O.D.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Vinyl Floor Tile, USA 97

Description: Miscellaneous, Sampled, Non Friable

Locations: All Floors in Building

Quantity: Approximately 50,000 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Transite Siding, USA 98

Description: Miscellaneous, Assumed, Non Friable

Locations: All Floors in Building

Quantity: Approximately 400 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Vinyl Floor Tile, USA 99

Description: Miscellaneous, Sampled, Non Friable

Locations: All Floors in Building

Quantity: Approximately 86,055 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance

AHERA Re-inspection

Material: Vinyl Floor Tile, USA 99

Description: Miscellaneous, Sampled, Non Friable

Locations: All Floors in Building.

Quantity: Approximately 10,000 sq. ft.

Potential For Disturbance:

Potential for contact: low

Effect of vibration: low

Potential for air erosion: low

Overall Condition: good

Previous AHERA Category: ACBM With Potential for Damage

New AHERA Category: Unchanged

Recommendations: 6 Month Periodic Surveillance