

A periodic surveillance must be conducted of each school building that contains ACBM or is assumed to contain ACBM at least once every 6 months. Visually inspect all areas that are identified in your AHERA Management Plan to observe current conditions. Note both damage and change in condition by circling the appropriate category below using the comment section for details. Date and sign this surveillance then submit a copy of the record to the Designate Person for inclusion in the AHERA Management Plan.

DO NOT TOUCH ASBESTOS - CONTAINING MATERIAL WITHOUT PROPER TRAINING

Cedaroak Park Primary School (CPPS)

Material	Location	Quantity	Damaged	Changed
Cement Asbestos Board	Chalkboards presumed throughout (none observed during inspection but may be obscured by cork boards or white boards)		Yes <input type="radio"/> No <input checked="" type="radio"/>	Yes <input type="radio"/> No <input checked="" type="radio"/>
Cement Asbestos Board	North Classrooms - behind heat register cabinets		Yes <input type="radio"/> No <input checked="" type="radio"/>	Yes <input type="radio"/> No <input checked="" type="radio"/>
Fire Door	Throughout		Yes <input type="radio"/> No <input checked="" type="radio"/>	Yes <input type="radio"/> No <input checked="" type="radio"/>
Gypsum Wallboard	Throughout		Yes <input type="radio"/> No <input checked="" type="radio"/>	Yes <input type="radio"/> No <input checked="" type="radio"/>
Sheet Floor Covering	Throughout		Yes <input type="radio"/> No <input checked="" type="radio"/>	Yes <input type="radio"/> No <input checked="" type="radio"/>
Vinyl Floor Tile	Throughout (9"x9" observed in storage room off of activity room B)		Yes <input type="radio"/> No <input checked="" type="radio"/>	Yes <input type="radio"/> No <input checked="" type="radio"/>
Asbestos Pipe Insulation/Hard	Throughout (presumed in inaccessible walls and ceiling spaces)		Yes <input type="radio"/> No <input checked="" type="radio"/>	Yes <input type="radio"/> No <input checked="" type="radio"/>
Covebase/Mastic	Throughout (tested negative in Activity Room B)		Yes <input type="radio"/> No <input checked="" type="radio"/>	Yes <input type="radio"/> No <input checked="" type="radio"/>
Window Glazing Compound	Throughout on exterior windows		Yes <input type="radio"/> No <input checked="" type="radio"/>	Yes <input type="radio"/> No <input checked="" type="radio"/>

Comments: Localized window glazing damage on classroom 22, localized damage to window glazing on classroom 5 and 9 (worker was there replacing windows) - this section of the school seems to be a newer addition; localized water damage to pipe in boiler room; localized LCT damage to a tile in classroom 12; temporary plastic ceiling in place of gyp wallboard in boiler room.

By: Taylor Cook **Title:** IH Tech **Date of Observation:** 10/19-20/2022