A periodic surveillance must be conducted of each school building that contains ACBM or is assumed to contain ACBM at least once every 6 months. Visually inspect all areas that are identified in your AHERA Management Plan to observe current conditions. Note both damage and change in condition by circling the appropriate category below using the comment section for details. Date and sign this surveillance then submit a copy of the record to the Designate Person for inclusion in the AHERA Management Plan.

DO NOT TOUCH ASBESTOS - CONTAINING MATERIAL WITHOUT PROPER TRAINING

Wood Middle School (WMS)									
Material	Location	Quantity	Damaged	Changed					
Cement Asbestos Board	Chalkboards presumed throughout (none observed during inspection but may be obscured by cork boards or white boards)		Yes (No)	Yes No					
Transite Pipe	Exterior siding		Yes No	Yes (No)					
Window Glazing Compound	Exterior windows throughout		Yes No	Yes No					
HVAC Sealant	Mezzanine level mech. and attic storage rooms	3000 sf	Yes No	Yes No					
Asbestos Insulated Wiring	Potentially throughout (not observed during inspection but possibly in inaccessible areas)		Yes No	Yes No					
Sheet Floor Covering	Small areas located throuhgout the building		Yes (No)	Yes No					
Fire Door	Throughout		Yes No	Yes No					
Gypsum Wallboard	Throughout (material tested negative for asbestos in the staff lounge)		Yes No	Yes No					
Covebase/Mastic	Throughout (some areas tested negataive for asbestos but not enough samples to make a determination)		Yes No	Yes (No)					
Vinyl Floor Tile	Various areas remain throughout building		Yes No	Yes No					

Comm	CIILO.	Walked site with custodian. HVAC sealant has been taped over, tape is falling off but sealant remains undamaged; localized damage to gyp in cafe storage room, F hall, and room F113;								
	lo	localized tile damage in A100; localized sheet floor peeling in bathroom near room 168.								
Ву:	Taylor C	ook	Title:	IH Tech		Date of Observation:	10/20/2022			