

## PERIODIC SURVEILLANCE REPORT

Client: West Linn School District

Page #: 1 of 3

Campus: West Linn High School

Address: 5464 West "A" Street

Building: 700 Building

Date of Surveillance: March 2014

AHERA Designated Person: Tim Woodley

Person Conducting Surveillance: Tulla Stocker

**SUMMARY:** Hard-fittings on fiberglass were removed in January 2008 associated with a roof/HVAC leak. All suspect asbestos-containing building materials observed in this surveillance appeared to be in good condition.

Material Description: Domestic Hot Water/MJP on Aircell/Fiberglass  
Homogeneous area(s): Domestic piping throughout building (suspect hidden areas)

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

Material Description: Vinyl Floor Tile/Mastic  
Homogeneous area(s): Throughout building

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

Material Description: Sheet Flooring, Gypsum Wallboard & Plaster,  
Window Putty, Fire Doors, Cove Base/Mastic, Chalk Boards, Electrical  
Wiring

Homogeneous area(s): Throughout building

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

PERIODIC SURVEILLANCE REPORT

Client: West Linn School District

Page #: 2 of 3

Campus: West Linn High School

Address: 5464 West "A" Street

Building: Main

Date of Surveillance: March 2014

AHERA Designated Person: Tim Woodley

Person Conducting Surveillance: Tulla Stocker

**SUMMARY:** Extensive amounts of asbestos-containing building materials were abated during the demolition of the south and north wings at the site. The gymnasium roof was abated during the summer of 2005. Gymnasium remodel activities were completed in 2005. Only the gymnasium building, with lower level remains of earlier main building construction, continues under AHERA.

**Material Description:** Domestic Hot Water/MJP on Aircell/Fiberglass  
(potential concealed)

**Homogeneous area(s):** Domestic piping in hidden spaces throughout building

**Last Material Condition:** Good

**New Material Description:** Same

**Change in material condition:** No

PERIODIC SURVEILLANCE REPORT

Client: West Linn School District

Page #: 3 of 3

Campus: West Linn High School

Address: 5464 West "A" Street

Building: Music

Date of Surveillance: March 2014

AHERA Designated Person: Tim Woodley

Person Conducting Surveillance: Tulla Stocker

SUMMARY: Hard fittings on fiberglass pipe insulation, vinyl floor tile and mastic were removed from the building during the 2005 remodeling project. All identified asbestos-containing materials have been removed from this building.

Material Description: Domestic Hot Water/MJP on Aircell/Fiberglass (potential concealed)

Homogeneous area(s): Domestic piping in hidden spaces throughout building (suspect hidden materials)

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

Material Description: Vinyl Floor Tile/Mastic, Sheet Flooring, Gypsum Wall Board & Plaster, Window Putty, Fire Doors, Cove Base/Mastic, Chalk Boards, Electrical Wiring

Homogeneous area(s): Potential hidden spaces throughout building

Last Material Condition: Good

New Material Description: Same

Change in material condition: No

SIGNATURES:

AHERA Inspector:

Management Planner

\_\_\_\_\_  
Tulla R. Stocker  
Accreditation #:32162IR

\_\_\_\_\_  
Tulla R. Stocker  
Accreditation #:32175IR