

PERIODIC SURVEILLANCE REPORT

Client: West Linn School District

Page #: 1 of 1

Campus: Cedar Oak Park Primary
Address: 4515 South Cedar Oak Drive

Building: Main
Date of Surveillance: March 2014

AHERA Designated Person: Tim Woodley
Person Conducting Surveillance: Tulla Stocker

SUMMARY: Removal of visible thermal system insulation (TSI) and pipe insulation occurred in the boiler room and tunnels during the summer bond remodeling project of 2004. Like material may continue to exist in hidden spaces. Non-friable materials observed such as floor tile, sheet flooring, cove base/mastic, gypsum wallboard, plasters, chalkboards, window putty, electrical wiring, etc, remain in good condition from previous inspections.

Material Description: Sheet Flooring, Vinyl Floor Tile (USA 99), Gypsum Wallboard & Plaster, Window Putty, Fire Doors, Cove base/Mastic, Chalkboards, Electrical Wiring Casing
Homogeneous area(s): Various Locations

Floor Tile: minor cracks in floor tiles Activity room C

SIGNATURES:

AHERA Inspector:

Management Planner

Tulla R. Stocker
Accreditation #: 32162IR

Tulla R. Stocker
Accreditation #:32175 IR