WLWSD QUARTERLY SAFETY INSPECTIONS

ISSUE LOG

DATE: April 12 2016 FACILITY: Boones Page:

Number	Location	Issue Code	Notes	W.O.
	Rm1004		Cord under rug	
	Rm 802		Cord under rug	
	Rm 801		Cord under rug	
	Rm 1101		Cord under rug	
	1105 Porch		Items hanging from lights	
	Rm 902		Cord under rug	
	Rm 903		Cord under rug	
	110		Staff lounge - No GFI plug next to sink	
	Rm 604		Cord under rug	
	Rm 603		Cord under rug	
	Rm 401		Cord under rug	
	Rm 501		Cord under rug	
	Rm 503		Cord under rug	
	Rm 504		Cord under rug	