

WLWSD QUARTERLY SAFETY INSPECTIONS

ISSUE LOG

DATE: May, 5 2016

FACILITY: Stafford

Page:

Number	Location	Issue Code	Notes	W.O.
	Rm. 6		Electric cord under rug No GFI next to sink	
	Rm. 7		Electric cord under rug No GFI next to sink	
	Rm. 8		No GFI next to sink	
	Rm. 9		Electric cord under rug No GFI next to sink	
	Rm. 10		No GFI next to sink	
	Rm. 11		Items stored in front of electric panel	
	Rm. 14		Electric cord under rug	No GFI next to sink
	Gym storage		Items stored in front of electric panels	
	Rm. 16		No GFI next to sink	
	Rm. 17		No GFI next to sink	
	Rm. 20		Items hanging from lights	
	Rm. 21		Items hanging from lights	

	Rm. 23		Lights hanging from ceiling, items hanging from lights, electric cord under rug	
	Rm. 26		Items hanging from lights	
	Rm. 27		Items hanging from lights	
	Rm.28		Lights hanging from ceiling, items hanging from lights	
	Rm. 29		Lights hanging from ceiling, items hanging from lights	
	Electric room 002		Items in front of electric panels	